

15/5/2010

INS. CASE OWNER:

CC 4/EQ1900

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

15/1/19
uit

JAH 593-X

YP 8480P-4

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

(S x days)

Loss of Income (LOI):

SS

(S x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

Global Sum SS:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

w/p \$160.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Surveyor

Xhe.

REF:

60

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Kivile Enterprise

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$1200

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Confirm us \$1000.00 with 3 working days

(Red. #3254 76.1.)

Veh No:

JAH 593

Yr Regn:

17 Aug 2014

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha 135 LC

c.c.

135

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

25247

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PMYUGOY 10E.0235828

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90-17

R:

90/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIZ / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

11-01-19

Survey held at

u/s

5:30pm

Des. of Damages: Fr / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, St

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI19000692/Gpb3		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 11-01-2019		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 8480P	Veh. Inspected	JQH 593	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Cdometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/12/2018	Inspection Date		
Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQI19000692/Gpb3

Date: 16.01.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

IQH593


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11.01.2019 at the premises of M/s Kivile Enterprise and have the following to report:-

Workshop Estimate Amount	: S\$	4,254.00
Revised Estimate Amount	: S\$	2,684.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front Portion & N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser



吉维利企业

KIVILE ENTERPRISE

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2553

EMAIL: KIVILEPC@GMAIL.COM WEBSITE: KIVILEPC.COM

ROC NO.: 53114844X GST REG NO.: M90370110N

Acknowledged by Repairer

Signature:
Date:

Vehicle No.: JQH593

Model: Yamaha 135LC (T135)

HANDLE BAR / BT	75 /
HANDLE BAR HOLDER X NN	45
BALANCE / Cut	30 /
GRIP / Cut	28 /
BRAKE LEVER / Cut	38 /
MIRROR / Cut	40 /
HEAD LAMP / Cut	220 /
TOP COWLING(?) / Cut	145 /
FRONT FAIRING / CRA	110 /
FRONT FAIRING STAY X Repair.	60
FRONT FAIRING GUARD X Cut NN	85
SIDE FAIRING RH / Cut	155 /
SIGNAL LIGHT RH / BR	35 /
SIDE FAIRING GUARD RH X NN	95
SIDE FAIRING LH / Cut	155 /
SIGNAL LIGHT LH / CRA	35 /
SIDE FAIRING GUARD LH / Cut	95 /
FRONT MUDGUARD / Cut	75 /
METER X NN	260
METER CABLE / BR	30 /
FRONT FORK / BT	330 /
STEERING STAY / Acc	75 /
RIM X Cut NN	220
DISC X NN	75
WHEEL SHAFT / BT	65 /
CENTER GUARD X	80
CENTER BOX X } NN	75
SEAT BAR / Cut NN	65 /
SIDE COMB LH X	80
FRONT FOOTREST / BT	38 /
FOOTREST RUBBER / Cut	35 /
REAR BOX / Cut	155 /
REAR MUDGUARD / Cut.	80 /
IU UNIT / Cut	165 /
IU HOLDER X NN	35
FRONT BODY FRAME REPAIR X NN	250
FRONT NUMBER PLATE / CRA	20 / 10
TRANSPORT	50 30
spray	250 X NN
labour	300 150.
2284	4254

Gmo Qiang (UKK)

11/1/19 3Days. After repair photos.

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Friday, 11 January 2019 11:17 AM
To: assignments
Subject: FW: yp8480p/jqh593(acc on 24/12/18) - DM18HO03529-JT
Attachments: YP8480P.PDF

11:36 am @ 11/1/19
vehicle in
person @ Anna

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Friday, 11 January 2019 10:58 AM
To: Admin A <admin-a@lkkauto.com>
Subject: RE: yp8480p/jqh593(acc on 24/12/18) - DM18HO03529-JT

Dear LKK

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Joel Goh
Sent: Friday, January 11, 2019 10:57 AM
To: 'Kivile Enterprise'
Cc: 'Admin A'
Subject: RE: yp8480p/jqh593(acc on 24/12/18) - DM18HO03529-JT

Without Prejudice

Dear Irene

Thank you for your confirmation.
We will arrange accordingly.

Dear LKK

Please assist on the following PRS.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Kivile Enterprise [mailto:kivilepc@gmail.com]
Sent: Thursday, January 10, 2019 2:56 PM
To: Joel Goh
Subject: Re: yp8480p/jqh593(acc on 24/12/18) - DM18HO03529-JT

Dear Joel Goh ,
LKK Auto Consultants Pte Ltd survey , thank you.

On Thu, Jan 10, 2019 at 2:46 PM Joel Goh <joel.goh@eqinsurance.com.sg> wrote:

Without Prejudice

Save As To Costs

Dear Irene

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are

deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) Infiniti Appraisal Service Tel: 96684818 / 90099001 Fax: 64587432	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify 1

From: Kivile Enterprise [<mailto:kivilepc@gmail.com>]

Sent: Thursday, January 10, 2019 12:44 PM

To: EQI PRS

Subject: yp8480p/jqh593(acc on 24/12/18)

Dear Officer Incharge, pls arrange survey to inspect my jqh593, thank you.

--

Best Regards

Irene Toh

Kivile Enterprise

Blk 3007 Ubi Road 1

#01-408, S408701

Tel: 6748 8645 Fax: 6748 2533

--
Best Regards

Irene Toh

Kivile Enterprise

Blk 3007 Ubi Road 1

#01-408, S408701

Tel: 6748 8645 Fax: 6748 2533



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6259
www.police.gov.sg

Our Ref : TP/IP/70345/2018
Date : 15 March, 2019

TAN SONG SHING
C/O 160 PAYA LEBAR ROAD
#07-06 ORION@PAYA LEBAR
SINGAPORE 409022

Dear Sir/Madam

**ACCIDENT INVOLVING SMD7649H, JQH593 & YP8480P ALONG PIE (TUAS) ON
24 DECEMBER 2018 AT 1623 HRS.**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of **YP8480P** has committed an offence of Inconsiderate Driving under Section 65(a) of the Road Traffic Act, Chapter 276. Action has been initiated against the driver for the said offence.
3. If you have any queries, please contact the Investigation Officer, Muhammad Zickie at telephone number 6547 6356 or via email at Muhammad_ZICKIE@spf.gov.sg.

Yours faithfully

HAFIZ FAIZAL
for HEAD TRAFFIC INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQI19000692/Gwb3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 12-09-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 8480P	Veh. Inspected	JQH 593	
Policy No.	DMCOHQ18-000178	Coverage (\$)	0.00	
Claim No.	DM18HO03529-JT	Excess (\$)	0.00	
Assign From		Assign Date	11/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA 135LC	c.c	135	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	PMYUG0410E0235828	Colour	RED	
Odometer	25247	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90-17	MICHELIN	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90/80-17	MICHELIN	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/12/2018	Inspection Date	11/01/2019	
Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JQH 593

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HANDLE BAR	BENT	75.00	75.00
1	HANDLE BAR HOLDER	NOT NECESSARY	45.00	-
1	BALANCE	CUT	30.00	30.00
1	GRIP	CUT	28.00	28.00
1	BRAKE LEVER	CUT	38.00	38.00
1	MIRROR	CUT	40.00	40.00
1	HEAD LAMP	CUT	220.00	220.00
1	TOP COWLING	CUT	145.00	145.00
1	FRONT FAIRING	CRACKED	110.00	110.00
1	FRONT FAIRING STAY	TO REPAIR SEE LABOUR	60.00	-
1	FRONT FAIRING GUARD	NOT NECESSARY	85.00	-
1	SIDE FAIRING RH	CUT	155.00	155.00
1	SIGNAL LIGHT RH	BROKEN	35.00	35.00
1	SIDE FAIRING GUARD RH	NOT NECESSARY	95.00	-
1	SIDE FAIRING LH	CUT	155.00	155.00
1	SIGNAL LIGHT LH	CRACKED	35.00	35.00
1	SIDE FAIRING GUARD LH	CUT	95.00	95.00
1	FRONT MUDGUARD	CUT	75.00	75.00
1	METER	NOT NECESSARY	260.00	-
1	METER CABLE	BROKEN	30.00	30.00
1	FRONT FORK	BENT	330.00	330.00
1	STEERING STAY	NECESSARY	75.00	75.00
1	RIM	NOT NECESSARY	220.00	-
1	DISC	NOT NECESSARY	75.00	-
1	WHEEL SHAFT	BENT	65.00	65.00
1	CENTER GUARD	NOT NECESSARY	80.00	-
1	CENTER BOX	NOT NECESSARY	75.00	-
1	SEAT BAR	CUT	65.00	65.00
1	SIDE COMB LH	NOT NECESSARY	80.00	-
1	FRONT FOOTREST	BENT	38.00	38.00

Report Ref No. CC4/EQI19000692/Gwb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FOOTREST RUBBER	CUT	35.00	35.00
1	REAR BOX	CUT	155.00	155.00
1	REAR MUDGUARD	CUT	80.00	80.00
1	IU UNIT	CUT	165.00	165.00
1	IU HOLDER	NOT NECESSARY	35.00	-
1	FRONT BODY FRAME REPAIR	NOT NECESSARY	250.00	-
1	FRONT NUMBER PLATE	CRACKED	20.00	10.00
			3,654.00	2,284.00
	LABOUR			
	TRANSPORT.		50.00	30.00
	SPRAY.	NOT NECESSARY	250.00	-
	LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FAIRING STAY.		300.00	150.00
			600.00	180.00
	GRAND TOTAL		4,254.00	2,464.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CC4/EQ19000692/Gwb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.