



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19000704/T1qd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 18-03-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3646L	Veh. Inspected	GBD 9392P
Policy No.		Coverage (\$)	0.00
Claim No.	D19000322MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	10/01/2019

2. Vehicle Particulars & Condition

Make & Model	ISUZU NHR85AUE4AA	c.c	2999
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JAANHR85EF7100105	Colour	WHITE
Odometer	59477	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/90 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/90 R15	YOKOHAMA	6 mm
R/H Rear Tyre	145 R13	YOKOHAMA	6/6 mm
L/H Rear Tyre	145 R13	YOKOHAMA	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/01/2019	Inspection Date	15/01/2019
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS.
B)DAMAGES CONSISTENT TO ACCIDENT REPORT.
C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**