

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : CHING LYE FURNITURE
 BLK 3018 BEDOK NORTH ST 5 #05-29
 EASTLINK SINGAPORE 486132

Estimate No: EST1504443
Date: 08 Jan 2019
Policy No: DMCPHQ18-005917
Veh Reg No: GT4097G
Make/Model: TOYOTA DYNA 150 D
Chassis No: LY2120003820
Engine No: 5L4967995
Reg. Date: 04/09/2000

ATTN: FIRST CAPITAL
Your Ref No: TP 0119-5358
Claim Type: Third Party
Accident Date: 07/01/2019
TP Veh Reg No: SHB 3593 E

Veron

Estimate Repair Cost to Vehicle No :GT4097G

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR TAILGATE <i>Dented</i>	1,080.600	1 PC	1,080.60	✓
2 TAILGATE TOYOTA - BLACK COLOUR <i>new</i>	120.6000	1 PCS	120.60	✓
3 TAILGATE DYNA STICKER <i>new</i>	58.6000	1 PCS	58.60	✓
4 TAILGATE HINGE - RH <i>Best</i>	96.7000	1 PCS	96.70	✓
5 TAILGATE HINGE SIDE STOPPER - LH <i>new</i>	85.4000	1 PCS	85.40	✓
6 TAILGATE HINGE SIDE STOPPER - RH <i>new</i>	85.4000	1 PCS	85.40	✓
7 REAR SPARE TYRE BRACKET <i>new</i>	380.6000	1 PC	380.60	✓
8 REAR EXHAUST PIPE <i>new</i>	498.6000	1 PC	498.60	✓
9 REAR EXHAUST PIPE MOUNTING <i>new</i>	50.6000	1 PC	50.60	✓
10 TAILLAMP ASSY - LH <i>new</i>	160.7000	1 PCS	160.70	✓
11 TAILLAMP BRACKET - LH <i>new</i>	85.4000	1 PCS	85.40	✓
12 TAILLAMP ASSY - RH <i>Best</i>	160.7000	1 PCS	160.70	✓
13 TAILLAMP BRACKET - RH <i>Best</i>	85.4000	1 PCS	85.40	✓
14 REAR NUMBER PLATE BRACKET <i>Best</i>	240.6000	1 PC	240.60	✓
			3,189.90	
		Less 25%	797.48	2,392.43
Special Net				
15 REAR NUMBER PLATE <i>Best</i>	30.0000	1 PC	30.00	✓
16 70 KM/H STICKER <i>new</i>	10.0000	1 PCS	10.00	✓
17 10 PAX STICKER <i>new</i>	10.0000	1 PCS	10.00	✓
			50.00	50.00
Labour				
18 TO KNOCK OUT DENTS, REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	700.0000	1 JOB	700.00	500
19 TO RESPRAY PAINT ON ACCIDENT PORTIONS	700.0000	1 JOB	700.00	450
20 TO CHECK WIRING	20.0000	1 JOB	20.00	✓
21 TO REMOVE, REPLACE REAR EXHAUST PIPE	80.0000	1 JOB	80.00	✓
22 TO TUFF-KOTE	30.0000	1 JOB	30.00	✓
			1,530.00	1,530.00

970

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : CHING LYE FURNITURE
BLK 3018 BEDOK NORTH ST 5 #05-29
EASTLINK SINGAPORE 486132

Estimate No: **EST1504443**
Date: 08 Jan 2019
Policy No: DMCPHQ18-005917
Veh Reg No: **GT4097G**
Make/Model: TOYOTA DYNA 150 D
Chassis No: LY2120003820
Engine No: 5L4967995.
Reg. Date: 04/09/2000


ATTN: FIRST CAPITAL
Your Ref No: TP 0119-5358
Claim Type: Third Party
Accident Date: 07/01/2019
TP Veh Reg No: SHB 3593 E

Estimate Repair Cost to Vehicle No :GT4097G

Description	U/Price	Quantity	Price S\$	Amount S\$
Total				S\$ 3,972.43
Add GST @ 7%				278.07
Total Amount Payable				S\$ 4,250.50

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND TWO HUNDRED FIFTY AND CENTS FIFTY ONLY

For Progressive Car Care Pte Ltd



AUTHORISED SIGNATURE

Adrian Lim
1/5 11/03/19.

04 Days.

total: 2466.45
1/5 1950