

REF: CS/FCI/19000707/TITD3

n2

ASS. REC. BY:

Special Instruction:

SURVEYOR

ASSIGNMENT (Office)

CWS

From (Person): May chua

of

FCI

Date/Time: 3:43pm @ 11/1/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 6240R

Insured:

SHD 6610J

at Workshop m/s

Cycle & Camiage Automotive
209 perden Gardens

Tel:

6568 4555

of

Policy No:

Claim No:

D19000310MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Ds'

H.O.D. Endorsement:

Date/Time: 3:49pm @ 11/1/19

Person Contacted:

Edwin

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLX 6240R-X
	SHD 6610J - CS/FCI/18010012/Krbn 2
20/2-@ 5:02pm-	revised. via email preli advise
	Part by Part \$2,116 (Red: 1449, 40%)

JWA: 31/5/2018

Taufik

642


FCI

SAFETY

Date: _____
Estimated Value: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
Collision Report Vehicle No: _____
at Work/Dispute: _____
at: _____
Insured: _____
Policy No: _____
Claim No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Vehicle: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res: Yes or No
Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Edwin

SLX 624 OR 20/8 April.

Type: ☒ Car / ☐ Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or

Make: Mitsubishi Space Star 1193

Colour: Maroon A/C Insured / Std / NI / NA

Sp Reading: 11147 T/Radio: Insured / Std / NI / NA

Eng No: MMCXTA034JH020950

C/Nr:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: E: 175/55R15
R: 175/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: 6 mm Rear: 6 mm
R/Bal: 6 mm L/Bal: 6 mm
D.O.A: 19/2/18

Survey held at: CR - Pader Goh

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 APR 2019

Copy/Time File Pass to: ☐ : Proli. Report

by BLH Typist ☒ : Final Report

Copy/Time File Return to:

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. \$

☐ Inter-view \$

☐ Test Fee \$

☐ Other Fee \$

Survey Fee

Transportation

Other

Other

Other

Other

Other

130

50

21

201

Report Format:

Lump Sum / L.B. Fee: 2116



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000310MFSH

Date: 20/2/2019

Our Ref: CS/FC119000707/T1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLX 6240R

Please be informed that we had conducted the inspection of the abovementioned vehicle
19/2/2019 at the premises of M/s Cycle and Carriage have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,565.00</u>
Revised Estimate Amount	: S\$ <u>2,116.00</u>
"Check" Items Amount	: S\$ <u>287.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	09-01-2019	Our Ref No. D19000310MFSH
Accident Date	07-01-2019	Claim Type. Third Party
Insured Vehicle	SHD6610J	Third Party Vehicle. SLX6240R
Survey Location	209 PANDAN GARDENS	
Contact Person.	EDWIN CAINA	
Contact No.	65684555/ 0	Fax No. 65691056
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 20 February 2019 5:02 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000310MFSH/1
Attachments: PRELI ADVISED SLX 6240R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLX 6240R**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 11 January 2019 3:55 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000310MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 11 January 2019 3:43 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000310MFSH/1

Dear Sir/Mdm,



CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Loh Joon Poh Anthony
Period of Insurance : 03 Apr 2018 To 02 Apr 2020
Engine No. : 3A92UGX0190
Chassis No. : MMCXTA03AJH020950

Vehicle No. : SLX6240R
Policy No. : 1800029082
Endorsement No. :
Issued Date : 24 Apr 2018

ABOUT THE COVER

Make/Model : MITSUBISHI Space Star 1.2 CVT
Engine Capacity/Tonnage : 1,193.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : Yes
First Year of Registration : 2018
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use: 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0. Own Damage - \$600. Theft - \$0. Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Loh Joon Poh Anthony - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre Add: 20 Leng Kee Rd Singapore 159094 64708688
2. Cycle & Carriage Authorised Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504623206

FULCOMIP2 - JN
22 UBI ROAD 4 FULCO BUILDING
SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

88CS2B

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S1761627G**

Name: **LOH JOON POH ANTHONY**

Birth Date: **15 Aug 1966**

Issue Date: **21 Dec 2002**

1000060140D

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1761627G**

Name: **LOH JOON POH ANTHONY**

盧潤波

Race: **CHINESE**

Date of Birth: **15-08-1966** Sex: **M**

Country of Birth: **SINGAPORE**

YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2000 kilograms

PASS DATE: **25 Aug 1994**

NP 428A

Licence No: **S1761627G**

FOR C&C USE ONLY

0137414

NRIC No: **S1761627G**

Blood Group: **AB+** Date of issue: **19-07-1994**

Address: **APT BLK 566 HOUGANG STREET 51
#10-464
SINGAPORE 1953**



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Loh Anthony	Cust No/Name	/Loh Anthony
BLK 566 HOUGANG ST 51	Reg No/Reg Date	SLX6240R / 03/04/201
#10-464	Date In/Mileage	/ 0
SINGAPORE 530566	Chassis No	MMCXTA03AJH020950
Contact No Mobile: 97672431	Engine No	3A92UGX0190
	Make/Model	MIT/18MY SPACE STAR 1.2 CVT (T83)
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CSM00041	Cash	09/01/2019/ 21:43	QUE	261 / Edwin Caina	34986	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW & RE-ALIGN RR DAMAGED PORTION: -RENEW RR BUMPER -REPAIR RR END PNL			LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			550. 1100.00
E PNT98000 RESPRAY RR BUMPER AND RR END PNL						420 900.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM						30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST			Acknowledged by Repairer Signature: Date:			200.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS						80.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING						80.00
M SUNDRY RE-SEAL WEEKEND PLATE						120.00
E PNT88000 REMOVE AND REFIT REVERSE SENSOR						100.00
M SUNDRY SUPPLY REVERSE SENSOR						220.00
M SUNDRY Sundries						30.00
M FACE,RR BUMPER			1.00	584.00	00.00	584.00
M BRACKET,RR BUMPER SIDE,LH			1.00	10.00	00.00	10.00
M BRACKET,RR BUMPER SIDE,RH			1.00	10.00	00.00	10.00
M BRACKET,RR BUMPER			1.00	67.00	00.00	67.00
M CLIP,RR BUMPER			4.00	3.00	00.00	12.00
M REFLECTOR LH			1.00	22.00	00.00	22.00
SURVEYOR NAME: Tanjin 97495749						
SURVEYOR SIGNATURE: [Signature]			03 days.			
DATE: 19/2/19 @ 3:45pm						
Confirm & accepted by						
REMARKS: WP Resing before paint sure 1/1/2020						
			7% GST on		Nett 3565.00	3,565.00 249.55
			Total Payable			3,814.55
Authorized signatory and company stamp						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : Taufikh - LKK
Company : 1ST CAPITAL
DOA : 07/01/2019
CSE : Edwin
Date of Survey : 19/02/2019

VEHICLE NO : SLX6240R
MODEL : MIT/ 18MY SPACE STAR 1.2 CVT
WIP : 34986

Email :

Material	:	\$	616.00
Labour	:	\$	1,500.00
Sub-Total	:	\$	2,116.00
Less Excess	:	\$	-
Total	:	\$	2,116.00
GST 7%	:	\$	148.12
Grand Total	:	\$	2,264.12
Finalise By/Date	:	JoJo dtd 12/04/2019	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS + 2 Days (1) Weekends
+ Days () Public Holiday
TOTAL DAYS REPAIR TOOK = 5


☒ TP Claim 1ST CAPITAL - SHD6610J

☐ Claim GIA / LTA fee

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
FIRST CAPITAL INSURANCE LIMITED MOTOR CLAIMS DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 Contact No 19/02/	Cust No/Name	/Loh Anthony
	Reg No/Reg Date	SLX6240R / 03/04/2018
	Date In/Mileage	19/02/2019/ 11149
	Chassis/Package	MMCXTA03AJH020950 /DC17S3C
	Engine No	3A92UGX0190
	Make/Model	MIT/18MY SPACE STAR 1.2 CVT (T83)
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	12/04/2019/ 11:34	TLE	881 / Jojo Cheng	34986			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								550.00
RENEW & RE-ALIGN RR DAMAGED PORTION: RENEW RR BUMPER								
E PNT98000								420.00
RESPRAY RR BUMPER								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
E PNT88000								80.00
REMOVE AND REFIT REVERSE SENSOR								
M SUNDRY								20.00
SUNDRIES								
S SPECIALISTJOB								80.00
TO SUPPLY ONE PC OF REAR LICENSE PLATE WITH PLASTIC FRAME--(OPC)								
S SPECIALISTJOB								120.00
OPC RE-SEAL FOR REAR LICENSE PLATE								
X	FACE,RR BUMPER				1.00	584.00	00.00	584.00
X	BRACKET,RR BUMPER SIDE,LH				1.00	10.00	00.00	10.00
X	BRACKET,RR BUMPER SIDE,RH				1.00	10.00	00.00	10.00
X	CLIP,RR BUMPER				4.00	3.00	00.00	12.00
Z TEXT								
FIRST CAPITAL TP CLAIM SHD6610J								
DOA: 07/01/2019								
SURVEYOR: TAUFIKH LKK 19/02/2019								

Cycle & Carriage celebrates 120 years.
Visit www.cyclecarriage.com/120 for more info!

Parts	616.00	Nett	2,116.00
Labour	1,280.00	7% GST on	148.12
Standard Menu	0.00		
Specialist Job	200.00	Total Payable	2,264.12
Diagnostics Job	0.00		
Sundry/Others	20.00		
Total(w/o GST)	2,116.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000707/T1td3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6610J	Veh. Inspected	SLX 6240R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000310MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	11/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi space star	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MMCXTA03AJH020950	Colour	MAROON	
Odometer	11149	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/55 R15	YOKOHAMA	6 mm	
L/H Front Tyre	175/55 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	175/55 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	175/55 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/01/2019	Inspection Date	19/02/2019	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 6240R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FACE,RR BUMPER (SN)	CRACKED	584.00	584.00
1	BRACKET,RR BUMPER SIDE,LH (SN)	NECESSARY	10.00	10.00
1	BRACKET,RR BUMPER SIDE,RH (SN)	NECESSARY	10.00	10.00
1	BRACKET,RR BUMPER (SN)	NOT NECESSARY	67.00	-
4	CLIP,RR BUMPER (SN)	NECESSARY	12.00	12.00
1	REFLECTOR LH (SN)	NOT NECESSARY	22.00	-
1	SUNDRIES (SN)	NECESSARY	30.00	20.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	220.00	-
1	RR NUMBER PLATE WITH CASING (SN)	BENT	80.00	80.00
			1,035.00	716.00
	LABOUR			
	RENEW & RE-ALIGN RR DAMAGED PORTION: -RENEW RR BUMPER. -REPAIR RR END PNL.		1,100.00	550.00
	RESPRAY RR BUMPER AND RR END PNL.		900.00	420.00
	CHECK WIRING ELECTRICAL SYSTEM.		30.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	RE-SEAL WEEKEND PLATE.		120.00	120.00
	APPLY ANTI CORROSION ON AFFECTED AREAS.	NOT NECESSARY	80.00	-
	REMOVE AND REFIT REVERSE SENSOR.		100.00	80.00
			2,530.00	1,400.00
	GRAND TOTAL		3,565.00	2,116.00
	RECOMMENDED COST OF REPAIRS			2,116.00

Report Ref No. CS/FCI19000707/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.