



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SDZ9028C

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

### Vehicle & Document Information

WIP No **30038**  
Reg No/Reg Date **SDZ9028C / 19/12/2018**  
Date In/Mileage **0**  
Chassis No **WDD2130452A5625216**  
Engine No **27492031678902**  
Make/Model **MB/MB E 250 SEDAN AVANTGARDE/AVANTGARDE**  
Colour/Trim **027 775 Iridium Sil/ 042 201 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WL001605	Credit	11/01/2019/ 12:42	AQ	305 / Alan Quek Ai Lun					
<p>M BPNSUN POLICY NO/ACC DATE : 1800151697 // 10-01-2019 DRIVE IN: 10-01-2019 // TP CAR NO: SKU2361D (LONPAC INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :</p>									
A BPILAB								0.10	380.00
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT									
A BPILAB									2400.00
REMOVE & REPLACE REAR BUMPER, REAR BOOT LID & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.									
A BPIRES									1500.00
RESPRAY REAR BUMPER & REAR BOOT LID									
M	REAR BUMPER					1.00	1956.71	00.00	1956.71
M	REAR BOTTOM PANEL					1.00	269.37	00.00	269.37
M	REAR BOTTOM GARNISH					1.00	312.57	00.00	312.57
M	CT/R PARKING SENSOR					4.00	177.22	00.00	708.88
M	CT/R PARKING SENSOR SEAL					4.00	6.42	00.00	25.68
M	CT/R BASIC MOUNTING FOR BUMPER					1.00	82.65	00.00	82.65
M	LH/R BASIC MOUNTING FOR BUMPER					1.00	50.96	00.00	50.96
M	RH/R BASIC MOUNTING FOR BUMPER					1.00	50.96	00.00	50.96
M	REAR CROSS MEMBER					1.00	789.61	00.00	789.61
M	REAR BOOT LID					1.00	2273.48	00.00	2273.48
M	REAR BOOT LID SEAL					1.00	245.91	00.00	245.91
M	REAR BOOT LID GARNISH					1.00	139.10	00.00	139.10
M	REAR STAR EMBLEM					1.00	48.25	00.00	48.25
M	GROMMET					3.00	2.29	00.00	6.87
M	E250 EMBLEM					1.00	85.16	00.00	85.16

**Alan Quek**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **11,326.16**  
7% GST on **11326.16** **792.83**

Authorized signatory and company stamp

**Total Payable 12,118.99**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg