

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0059/2019/NK  
**Date** : 14-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SLG 5576 T**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : M/S Hitachi Capital Asia Pacific Pte Ltd  
**Address** : 55 Jalan Bahagia  
#01-03  
: (S) 320055  
**Telephone** : HP +65 96477689- Ms Eng  
**Type of Claim** : Third Party Claims  
**Policy No.** : G300013698 MCY  
**Vehicle No** : **SLM 2568 E**  
**Model Code** : Audi A1 SB 1.0 TFSI (A)  
**Model / Year** : 24/3/2017  
**Engine No** : CHZ152657  
**Chassis No** : WAUZZZ8X5HB033852  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 10-Jan-19

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLM 2568 E

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function.	S/N	\$ 280.00	
2	To remove and transfer RHS front door and RHS rear doors multi- lock system and power window devices. Inspect for damages.	S/N	\$ 560.00	
4	To renew RHS 1/4 glass to facilitate fender renewal.	S/N	\$ 300.00	
4	To dislodge and reinstall rear wire harness for lights, battery manager fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00	
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00	
TOTAL LABOUR CHARGES		:	<u>\$ 3,940.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLM 2568 E

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To dismantle rear bumper, rear lid, RHS front and RHS rear door. Cut out and weld RHS rear fender. To renew rear bumper, RHs front door and RHs rear door. Reorganise crash managements components. Reinstall all parts removed.	\$ 6,000.00	
7	To rep spray rear bumper, RHS front door, RHS rear door and RHS rear fender, RHS sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 5,300.00	
8	To renew RHS rear rim and carry out wheel alignment.	S/N \$ 280.00	
9	To carry diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 15,712.00	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLM 2568 E

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR RHS	\$ 1,841.00	
2	FRONT DOOR ATTACHMENTS PARTS	\$ 121.00	
3	FRONT DOOR CATCH	\$ 81.00	
4	FRONT DOOR CATCH COVER	\$ 21.00	
5	DATA PLATE FOR TYRE PRESSURE	\$ 35.00	
6	REAR DOOR RHS	\$ 1,841.00	
7	REAR DOOR ATTACHMENT PARTS RHS	\$ 76.00	
8	REAR DOOR CATCH RHS	\$ 81.00	
9	REAR DOOR CATCH COVER RHS	\$ 21.00	
10	STONE CHIP GUARD FOIL REAR RHS	\$ 39.00	
11	CHAFE GUARD	2 \$ 60.00	
12	SECTIONAL PART REAR RH	\$ 1,772.00	
13	1/4 GLASS	\$ 255.00	
14	WHEEL HOUSING LINER RHS	\$ 166.00	
15	WHEEL HOUSING LINER ATTACHMENTS PARTS RHS	\$ 36.00	
16	REAR BUMPER	\$ 1,306.00	
17	REAR BUMPER GUIDE SECTION RH	\$ 44.00	
18	ALUMINIUM RIM RHS	\$ 651.00	
19	RUBBER VALVE	4 \$ 13.00	
20	ACYRLIC SEALER	S/N \$ 180.00	
<b>SUB SPARE PARTS CHARGES</b>		<b>: \$ 8,640.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLM 2568 E

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	CAVITY WAX	S/N \$ 140.00	
22	STONE CHIP GUARD FOIL REAR RHS	S/N \$ 180.00	
23	METAL FILLER POWDER	S/N \$ 280.00	
24	1/4 GLASS SEALANT	S/N \$ 100.00	
25	SUNDRIES	\$ 800.00	
TOTAL SPARE PARTS CHARGES		:	\$ 10,140.00
TOTAL LABOUR CHARGES			\$ 15,712.00
GRAND TOTAL			\$ 25,852.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

## Please Note

: This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant