


REF: MSIG

Summit Hare Jia

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SMB1615E** Yr Regn: **3 Feb 2015**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Man A22** C.C. **10518**
 Colour: **multi Colour** A/C Insured / Std / NI / NA
 Sp. Reading: **280294** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **WMAA222Z3F7002596**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **275/70R22.5**
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Continental**

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>7</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>7</u> mm
D.O.A. 28/11/18	D.O.I. 10/1/19

Survey held at **Smrt**
 Des. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SMB1615E - CC3/A1916021029 / 1C1mb3
	SKG 486SL - CC6/CT117021818 / 11h639.2
16/01/19 @ 14:12 p.m.	revised IA to Chh'a Nyala Pui via minier.
	Confirmed L/S \$6150/- 4 days of repair. (\$ 1,161.08 Red - 16%)

[Signature]
 26/2/2019

RECEIVED 27 JUN 2019

Date/Time: File Pass to? **27/06/19**
 1) Typist
 Date/Time: File Return to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: **4**
 Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:
 Transportation
 S + PS SI
 Photos
 Others

Report Format :
 Lump Sum / I.B.I: (\$ **6,150/- 4S**)

200
11
211

TOTAL

Shirley Hiew (LKK Auto)

From: Hwee Jie (LKK Auto) <hweejie@lkkauto.com>
Sent: Wednesday, 26 June 2019 10:26 AM
To: Catherine Lee Sau Chan (Auto Svcs/ARC/AR & SC/Buses)
Cc: Shirley Hiew (LKK Auto)
Subject: RE: Finalisation - SMB1615E (BUS/11/18/5056) - MSIG

Hi,

Finalized L/S \$6,150/- 4days of repair.

Best Regards,
Hwee Jie | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/ARC/AR & SC/Buses) [mailto:catherineleesc@smrt.com.sg]
Sent: Monday, 24 June, 2019 5:31 PM
To: Hwee Jie (LKK Auto); SUR; Admin A
Cc: Koo Yew Chung (Auto Svcs/ARC/AR & SC); AutoSvs-ARC (Bus)
Subject: Finalisation - SMB1615E (BUS/11/18/5056) - MSIG

Hi Hwee Jie,

Attached herewith our copy of the bus repair estimate for the case.
Our finalised amount is \$6,150/- @ 4 working days under lump sum repair. Attached after repair photos for your perusal.

Please confirm the COR by return email ASAP.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg



Moving People, Enhancing Lives

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 14 January 2019 4:59 PM
To: margaret_loh@sg.msig-asia.com; 'Catherine Thia'
Cc: SUR; Accounts (LKKAuto); KKLau; yiqian_low@sg.msig-asia.com
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD ,DOA: 28/11/2018 ,SMB 1615E (TP VEHICLE), SKG 4865C (OI VEHICLE)
Attachments: TP GIA REPORT.pdf; ESTIMATE.pdf

Dear Margaret/Catherine,

Please be informed that we had inspected the vehicle SMB 1615E at M/s: SMRT AUTOMOTIVE SERVICES PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 on 10/1/2019

Enclosed herewith a copy of TP GIA report and estimated cost of repair.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 16 Jan 2019

Preliminary Advice

Insured Vehicle No	: SKG4865C	Accident Date	: 28/11/2018
TP Vehicle No	: SMB1615E	Assignment Date	: 15/01/2019
Make	: MAN NL320F (A22)	Est. Duration of Repair	: 4 days
Date of Inspection	: 10/01/2019		
Inspection At	: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,650.00
Revised Amount	:S\$	6,611.08
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,611.08

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	29/11/2018 15:25
Date Of Accident	28/11/2018 10:40
Exact Location Of Accident	UPPER BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMB1615E
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81111111
Vehicle Particulars	
Manufacturer	MAN
Model	12M SINGLE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-II027592MFBP
Cover Note Number	
Driver	
Name of Driver	WANG LIANG
Passport No/FIN	G8558159M
Date Of Birth	29/11/1981
Occupation	OUTDOOR
Date Of Driving Pass	05/12/2017
Driving Experience	0 YEAR AND 11 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 6 ANG MO KIO ST 62

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 7

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

A PRIVATE CAR SKG4865C COLLIDED ONTO MY BUS RIGHT REAR PORTION AFTER TURNING RIGHT FROM CHOA CHU KANG ROAD. NO INJURY WAS REPORTED.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PEND DOWNLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKG4865C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


[Signature] 26/5/20

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



29 NOV 2018

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to report.

DECLARATION

I/We declare the foregoing ^{BUS} particulars are true in every respect.



Policyholder's Signature
Date & Time:

26450
Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



Case Details

Case Reference Number : BUS/11/18/5056

Type of Repair : Accident Repair

Vehicle Registration Number : SMB1615E

Company Type : SMRT Buses Ltd

Estimation ID : EST-5291-ID

Assigned By : Audrey Woo Yee Shin

Insurance Company Name : MSIG Insurance (S) Pte Ltd

Accident Date and Time : 28/11/2018 02:40 AM

Vehicle Age(In Months) : 45

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
Standard	Main	BODY RH	6009987	PANEL,SIDE:R6,FOR MAN A22 BUS	1	1,776.80	1,776.80	10.00	1,599.12	Replace	1	1,599.12	Replace ▾ DD
Standard	Main	BODY RH	6009988	PANEL,SIDE:R7,FOR MAN A22 BUS	1	885.50	885.50	10.00	796.95	Replace	1	796.95	Replace ▾ DD
Standard	Main	BODY RH	6009989	PANEL,SIDE:R8,FOR MAN A22 BUS	1	330.70	330.70	100.00	0.00	Repair	1	0.00	Repair ▾
Standard	Main	BODY RH	6009989	PANEL,SIDE:R8,FOR MAN A22 BUS	1	330.70	330.70	100.00	0.00	Repair	1	0.00	Repair ▾
Standard	Main	BODY RH	6009990	PANEL,SIDE:R9 WITH FRAME,FOR MAN A22 BUS	1	710.70	710.70	100.00	0.00	Repair	1	0.00	Repair ▾
Standard	Main	BODY RH	6009991	PANEL,SIDE:R10,FOR MAN A22 BUS	1	192.70	192.70	100.00	0.00	Repair	1	0.00	Repair ▾
Standard	Main	BODY RH	6009992	PANEL,SIDE:R11,FOR MAN A22 BUS	1	1,782.50	1,782.50	100.00	0.00	Repair	1	0.00	Repair ▾
Standard	Main	Body	6010062	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1	974.70	974.70	100.00	0.00	Repair	1	0.00	Repair ▾
Standard	Main	CONSUMABLE	4006314	ADHESIVE:DIRECT GLAZING	8	37.00	296.00	0.00	296.00	Replace	8	0.00	Replace ▾ NEC
Standard	Main	Body	6010330	TRIM,WHEELARCH:FOR MB OC500 LE BUS	1	124.20	124.20	10.00	111.78	Replace	1	111.78	Replace ▾ DD
Total Spare Part Cost									2,803.85	Surveyor Total	2,507.85		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)	20		
Final Spare Part Cost									2,243.08	Final Sur Total	2,006.28		

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,590.00	1,060	
Total:		1,590.00	1,060.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	-----------	-------------------------	-------------------------	---------

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO PUTTY & RESPRAY	1,558.00	1,388	
Total:		1,558.00	1,388.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	ADVERTISEMENT STICKER <i>nc</i>	1,920.00	1,920.00	
Total:		1,920.00	1,920.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,243.08	2,006.28
Total Labour Cost	1,590.00	1,060.00
Total Spray Painting	1,558.00	1,388.00
Other	1,920.00	1,920.00
Overall Total	7,311.08	6,374.28
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	7,650.00	6,350.00
Surveyor Approved Amount		6,350.00
No of Repair Days*	5	4
Remarks	-	US repair, photo after paint.
Surveyor Name		Hwee Jie
Signature	<i>J</i>	<i>Hwee Jie</i> <i>[Signature]</i> 16/1/19
Survey Date	10/01/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12472-50



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 24/06/2019

User ID : CatherineLee

Section A - Accident Details

Registration Number	SMB1615E
Case Reference Number	BUS/11/18/5056
Registration Date	3/2/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Wang Liang
Type of Accident	Side Swipe
Accident Date and Time	28/11/2018 10:40 AM
Accident Reported Date and Time	28/11/2018 12:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099631
Special Instruction to ARC, if any	SMB1615E - RIGHT REAR PORTION DAMAGED SKG4865C - TP INSURED WMSIG - LEFT FRONT PORTION DAMAGED
Prepared Date and Time	10/1/2019 11:58 AM
Chassis Number	WMAA22Z3F7002596
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,060.00
Total Spray Cost	\$1,558.00	\$1,388.00
Total Spare Part Cost	\$1,797.24	\$1,797.24
Total Other Cost	\$1,920.00	\$1,920.00
TOTAL COST	\$6,865.24	\$6,165.24
Lump Sum Total	\$6,850.00	\$6,150.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Jeong Choon Hwee	Hwee jie
ARC / Surveyor Sign Off Date	10/01/2019 3:09 PM	10/01/2019 4:03 PM
Signature		
Remarks		U/S repair, photo after paint.

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63855592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/06/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$1,590.00	\$1,060.00
Total Labour	\$1,590.00	\$1,060.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$1,558.00	\$1,388.00
Total Spray Painting & Panel Beating	\$1,558.00	\$1,388.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
ADVERTISEMENT STICKER	\$1,920.00	\$1,920.00
Total Other Costs	\$1,920.00	\$1,920.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009987	BODY RH	A01001-CW568	PANEL, SIDE: R6, FOR MAN A22 BUS	1.00	\$1,776.80	30.00	\$1,243.76	Replace	Replace
6009988	BODY RH	A01001-CW567	PANEL, SIDE: R7, FOR MAN A22 BUS	1.00	\$885.50	30.00	\$619.85	Replace	Replace
6009989	BODY RH	A01001-CW566	PANEL, SIDE: R8, FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	Repair
6009990	BODY RH	A01001-CW565	PANEL, SIDE: R9 WITH FRAME, FOR MAN A22 BUS	1.00	\$710.70	100.00	\$0.00	Repair	Repair
6009991	BODY RH	4000F06-ACCE4526	PANEL, SIDE: R10, FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	Repair
6009992	BODY RH	A01001-CW564	PANEL, SIDE: R11, FOR MAN A22 BUS	1.00	\$1,782.50	100.00	\$0.00	Repair	Repair
6010062	Body	F01001-CW273	COVER: REAR TAIL LAMP, RH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE: DIRECT GLAZING	8.00	\$37.00	0.00	\$296.00	Replace	Replace
6010330	Body	5029	TRIM, WHEELARCH FOR MB OC500 LE BUS	1.00	\$124.20	30.00	\$86.94	Replace	Replace
Total					\$6,814.80		\$2,246.55		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Nov 2018		15 Jan 2019 17:24 Edit Adj Rpt	S\$6,150.00 Edit Estimates	S\$6,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SGRENTACAR PTE LTD , Co. Reg. No.: 201329402W									
Main Claimant: SMRT BUSES LTD , Co. Reg. No.: 198202292D									
Vehicle Reg. No.:	SMB1615E	Date of Loss:	28/11/2018 10:00 - :59 [45 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 577686	Policy/Cover Note No.:	A29059306MKF(TPFT) (TP, Fire & Theft) Coverage: 05/01/2018 - 04/01/2019						
Vehicle Reg. No. (Insured):	SKG4865C	Policy No. (Claimant):							
		Excess:	S\$3,500.00						
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 14/02/2019]								
Driver/Custodian (Insured):	MUHAMMAD IFWAT BIN JUMAIN (), NRIC: S9142260C, Tel: +6592708766 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMB1615E (577686)**
[SKG4865C]
TP
SMRT BUSES LTD
Nov 28 2018 10:00AM
[SGRENTACAR PTE LTD]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser
Assessment Reports		1 per page <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)
1	15/01/19 17:22	Accident Statement From: SC - Reg. No: SKG4865C, Claimant: SGRENTACAR PTE LTD
		Thumbnail Load HTM Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)
1	16/01/19 14:12	Adjuster Immediate Advice
		Thumbnail Load HTM
Photos/Images		3 per page <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	26/06/19 10:25	General View
2	26/06/19 10:25	General View
3	26/06/19 10:25	General View
4	26/06/19 10:25	General View
5	26/06/19 10:25	General View
6	26/06/19 10:25	General View
7	26/06/19 10:25	General View
8	26/06/19 10:25	General View
9	26/06/19 10:25	General View
10	26/06/19 10:25	General View
11	26/06/19 10:25	General View
12	26/06/19 10:25	General View
13	26/06/19 10:25	General View
14	26/06/19 10:25	General View
15	26/06/19 10:25	General View
16	26/06/19 10:25	General View
17	26/06/19 10:25	General View
18	26/06/19 10:25	General View
19	26/06/19 10:25	General View
20	26/06/19 10:25	General View
21	26/06/19 10:25	Photo After Spray
22	26/06/19 10:25	Photo After Spray
23	26/06/19 10:25	Photo After Spray
24	26/06/19 10:25	Photo After Spray
Documentation		1 per page <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)
1	15/01/19 17:22	SMB1615E TP E-FILE REPORT From: SC - Reg. No: SKG4865C, Claimant: SGRENTACAR PTE LTD
2	15/01/19 17:23	EMAIL FROM LKK - DIRECT SURVEY
		Thumbnail Load PDF Print

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19000740/JSD3E2

Date: 08/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29059306MKF(TPFT)

Claimant Vehicle No : SMB1615E

Insured Vehicle No : SKG4865C

Date of Loss: 28/11/2018

Nature of Claim: TP

Claim No: 577686

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMB1615E**

Make & Model: MAN NL320F (A22), 10.5 D ABS TURBO (A)

Engine No: 50339550983946

Reg. Date: 03/02/2015 (Man. Year: 2014)

Chassis No: WMAA22ZZ3F7002596

Colour: Multi-colour

Odometer: 280294 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,324.50	4,166.55	5,157.95	55.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,148.00	2,448.00	700.00	22.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,472.50	6,614.55	5,857.95	46.97
Approved Total (Overridden) (S\$)		6,150.00		
Nett Amount (S\$)	12,472.50	6,150.00	6,322.50	50.69

INSPECTION

Date of Assignment: 15/01/2019

Date Inspected: 10/01/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Jul 2019)	
Parts:	N/A	MAN NL320F (A22) 10.5 D ABS TURBO (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB1615E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL, SIDE:R6, FOR MAN A22 BUS	Dented	1,776.80 F	*1,776.80 FL
2	1		*PANEL, SIDE:R7, FOR MAN A22 BUS	Dented	885.50 F	*885.50 FL
3	1		*TRIM, WHEELARCH:FOR MB OC500 LE BUS	Dented	124.20 F	*124.20 FL
4	8		*ADHESIVE:DIRECT GLAZING	Necessary	296.00 FS	*296.00 FS
5	1		*PANEL, SIDE:R8, FOR MAN A22 BUS	Repair	330.70 F	*- FL
6	1		*PANEL, SIDE:R8, FOR MAN A22 BUS	Repair	330.70 F	*- FL
7	1		*PANEL, SIDE:R9 WITH FRAME, FOR MAN A22 BUS	Repair	710.70 F	*- FL
8	1		*PANEL, SIDE:R10, FOR MAN A22 BUS	Repair	192.70 F	*- FL
9	1		*PANEL, SIDE:R11, FOR MAN A22 BUS	Repair	1,782.50 F	*- FL
10	1		*COVER, REAR TAIL LAMP, RH, FOR MAN A22 BUS	Repair	974.70 F	*- FL
11	1		*ADVERTISEMENT STICKER	Necessary	1,920.00 FS	*1,920.00 FS
					Sub Total (\$\$)	9,324.50 5,002.50
					- List Item Discount on L Items 0.00/30.00% (\$\$)	0.00 835.95
					Total Parts (\$\$)	9,324.50 4,166.55

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,590.00	1,060.00
2	TO PUTTY & RESPRAY	New	1,558.00	1,388.00
Gross Labour Cost (\$\$)			3,148.00	2,448.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >