

83228813
Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 11/01/2019
TP Vehicle No. : SFB-6262-P
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : KRISTALBLU FOOD EQUIPMENT SERVICES
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5090542925-01
Vehicle No. : GBF-7934-D
Make & Model : TOYOTA HIACE 3.0 TURBO VAN EURO IV G (M) 5DR

Accident Date: 10/01/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	FRONT BUMPER ✓	\$598.20
10	FRONT BUMPER CLIPS <i>nc</i>	\$50.00 <i>20</i>
1	FRONT BUMPER RETAINER RH <i>X</i>	\$170.30
1	FRONT BUMPER RETAINER LH ✓	\$170.30
1	FRONT BUMPER BRACKET RH <i>X</i>	\$125.60
1	FRONT BUMPER BRACKET LH ✓	\$125.60
1	FRONT BUMPER FOG LAMP GARNISH LH <i>X</i>	\$120.70
1	LH FRONT DOOR <i>X R</i>	\$1,580.60
1	LH FRONT DOOR HINGE BOTTOM <i>X</i>	\$161.90
1	LH FRONT DOOR HINGE UPPER <i>X</i>	\$161.90
1	LH FRONT STEP PANEL GARNISH ✓	\$185.50
1	LH FRONT DOOR STEP PANEL ✓ <i>X</i>	\$215.90
1	LH HEADLAMP ✓	\$890.40
1	LH HEADLAMP LOWER BRACKET <i>X</i>	\$150.60
Sub Total		\$4,707.50
Discount 25% on Parts		(\$1,176.88)
<i>Before spray 28/2/19 11:35am</i>		\$3,530.63

Special Nett

1	LH FRONT DOOR STICKER ✓	\$50.00
Sub Total		\$50.00

Labour & Misc

TO CHECK LIGHTING AND FOCUS HEADLAMP	\$180.00 <i>30</i>
TO TRANSFER & REFIX LH DOOR FIXTURE & FITTING	\$250.00 <i>X</i>
TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,800.00 <i>400</i>
TO SPRAY PAINT ON AFFECTED AREAS	\$1,800.00 <i>400</i>
Sub Total	\$4,030.00

Sub Total \$7,610.63