

27/03/2002

ASS. REC. BY:

REF

OS/FCI19000770/Kvd3/n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

CWS

Joanne Yung

of

FCI

Date/Time: 9:57am @ 14/1/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 6338C

Insured:

SHA 5727D

at Workshop m/s:

Hui Yung Motor

Tel:

645.15752

of

Blk 176 Sin Ming Drive #04-02

Policy No:

Claim No:

D19000378MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 09/01/2019

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

10:49am @ 14/1/19

Person Contacted:

Belle

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMA 6338C - CC6 / AIG 18014572 / Aea3q2

DUA: 1/8/18

SHA 5727D - CC3 / LER 18009880 / Klwb3q2

DUA: 27/5/18

16/1/19

Email preli revised to FCI

17/1

61 Lys & 8000 Cadan (Red 1011.70, 53M)

ASS. REC. BY:

REF: 15021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____ 1 hr Yang

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 892k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNA 63380 Yr Regn: 06, 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Privs c.c. 1797

Colour: M. L. Brown A/C: Insured / Std / NI / NA

Sp. Reading 48015 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 8VW40 002P175

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD ATRlm or

Tyre Size: F: 205/60R16
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 9/1/19

Survey held at

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 13/1/19

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/1 File pass to Car

RECEIVED 17 JAN 2019

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 17/1 - typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Report Format :

CWS

Lump Sum / I.B.I. (\$) 900/-

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + P.S. SI

Factors

Others

TOTAL

100
50
50
11
211



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000378MFSH

Our ref: CS/FCI19000770/Kvd3

Date : 16/1/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMA 6338C

We thank for your instruction on 14/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/1/2019 at the premises of M/s HUI YANG MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$1,911.70
Revised Estimate Amount	: S\$1,166.43
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:
The vehicle sustained damages at the rear o/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	11-01-2019	Our Ref No. D19000378MFSH
Accident Date	09-01-2019	Claim Type. Third Party
Insured Vehicle	SHA5727D	Third Party Vehicle. SMA6338C
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	NA	
Contact No.	6451 5752/ 0	Fax No. 6451 4658
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 16 January 2019 2:08 PM
To: 'CWS Motor Claims'
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000378MFSH/1, SMA 6338C
Attachments: SMA 6338C PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMA 6338C
Date of survey: 15/1/2019
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 14 January 2019 10:53 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000378MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 14 January 2019 9:57 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000378MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

MS First Cap
15/1/19
after 10am
Lkk

09/01/2019

Owner: ACE FLEET MANAGEMENT PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SMA6338C

1pc	rear bumper	Bu	\$	981.90	✓
1pc	rear bumper RH side retainer	Sn	\$	132.45	X
1pc	rear bumper RH side refector	Sn	\$	181.25	X
				\$	1,295.60
less 25%				\$	323.90
				\$	971.70
wiring				\$	40.00 100
spray painting				\$	500.00 2200
labour charges				\$	400.00 2000
Total				\$	1,911.70

Not Withstand
1/1/19 @ 900h
Recovery After Rain
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000770/Kvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 5727D	Veh. Inspected	SMA 6338C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000378MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	14/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZVW400029175	Colour	METALLIC LIGHT BROWN	
Odometer	48015	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	BRIDGESTONE	7 mm	
L/H Front Tyre	205/60 R16	BRIDGESTONE	7 mm	
R/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/01/2019	Inspection Date	15/01/2019	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 6338C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	981.90	981.90
1	REAR BUMPER RH SIDE RETAINER	SERVICEABLE	132.45	-
1	REAR BUMPER RH SIDE REFLECTOR	SERVICEABLE	181.25	-
	LESS 25% DISCOUNT		-323.90	-245.47
			971.70	736.43
	<u>LABOUR</u>			
	WIRING.		40.00	10.00
	SPRAY PAINTING.		500.00	220.00
	LABOUR CHARGES.		400.00	200.00
			940.00	430.00
	GRAND TOTAL		1,911.70	1,166.43
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			900.00

Report Ref No. CS/FCI19000770/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.