	Mr. Jim	ASSI	F 19000772	(e) ·		
From (Person) Estimated Cost	Fruncie th	M of	SpF	Eta	te/Time	·58u
1	TP RES / OD RI		Bill to			-
To Inspect Veh	icle No:	SLF	SSRIM	Ingurad	Q x 5249P	
at Workshop m	/8	MSCC	IV Auto	Tel	9725 4442	
of	8 kuki	Bukit Ave	4 # 01-07		1103 -1-12	
Policy No:		1.1	Claim No	AEMO/LOD	(00/2019/00)	
Sum Insured			Excess		1,000	
Make of Veh: (Client's Record)				D.0	O.A	
CA / REV /	REP. / REV 24 H	res lups				
Date/Time: 1	11 mo 14/1/	Person Conts	octed. Dame	nd Vahi	O.D. Endorsement:	T-
				A CHI	111001	-
Date Tine	Action/Instruction	(X) Esti	mate			
	SFC 52811	4- MA/INCI	6020 928 /r3	3	20A 30/10/2016	2
	Qx5249F)-X				
	0		- Lu arnt	Cont	10001000 100	
	SUBMART					/ /
	Sulamit	iump sum	\$11,050	· ala:	10981.84, 490	0

TOTAL PROPERTY.

2 E 15 7	GNMENT
1. 10. 10. 1	ILLINITE INT
- B. C. P. J. P. J	

From D	Date: 14/1/19	Veh No SLE 558) M Yr Regn. 26/7/2016
Estimated Cost	1111	Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA	A / INV / MV	Truck / Trailer or
To Inspect Vehicle No: S'LE 3	5581 M	Make: MITSUBISH EX 6.0 1590
at Workshop m/s M S AuTo		Colour GREY A/C: Insured / Std / NI / NA
OI 8 KAKI BUKIT AVE 2	4 # 01-07	Sp.Reading 37052 T/Radio: Insured / Std / NI / NA
Insured		Eng/No: 4A92CJ7199
Policy No.		CÃO: JMYSRCYIAGUOO5778.
Claims No.		Gen. Cond: Good / Fair / Burnt
Sum Insured. E	Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)		Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:		Modi: Nil / SIRIm / STD A/Rim or
		Tyre Size: F: 205/60/16
(Policy Condition)		R: 205/60/16
Remark: The veh had commenced its	N/S O/	
repair at the time of inspect		TOYO / YOKO or
P. I I.		Front Rear
Bal. or Market Value:	sistent? : Yes or No	R/Bal. /- mm R/Bal. /- mm
IDAO AGGIGAT TIPOTE	sistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
OIA TTY OCCIT		
/ 4	Res.: Yes or No	D.O.A. 10/1/19 D.O.I. 14/1/19
Lum Sum: %	3 Val.: Yes or No	Survey held at M.5 Au70
CA / REV / REP. / 24 HRS		Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contact	Vehicle: IN / C	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction		The dic / Chassis traile / Body Structure allested dis to solitonic.
Date / Time Action / Instruction	Lim	
MV 58,000	D/c	seo my remarks 8
PV 52,582	oxylose.	seo my remarks 8
NV	WELL	Pin. murto
5418		
	RECE	IVED 0 8 MAR 2019 / 22/).
Range	11,000/2 - 12	1008/2 TOTIN
		nu lui
Date/Time, File Pass to? : Preli	i. Report	Days Of Repair: 10
11 1	l Report	Resurvey No. of Trip: Survey Fee: 280
Dale/Time, File Return to?		Transportation:
2)	Add	Fee: Site Insp (\$.) s+RS_SI
		: Interview (\$) Photos
Report Format :		: Tech Invs (\$) others
Lump Sum / I.B.I: (\$ 1109	0 -	Weekend (\$)
		TOTAL 280

-Nivitha (LKK Auto)

From:

Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>

Sent:

Monday, 14 January 2019 10:58 AM

To:

Catherine Chong; assignments

Cc:

Olivia Lau (LKKAuto)

Subject:

RE: Pre-Repair Inspection for SLE5581M

Your reference: SLE5581M Our reference: QX5249P

Catherine,

Please conduct a Pre-Repair Inspection for SLE5581M at M/s Car Auto Pte Ltd, address: 8 Kaki Bukit Avenue 4 #01-07

Premier@ Kaki Bukit. Singapore 415875.

Please contact Mr Desmond @ 97254442 for appointment.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM

TRANSFORMATION 2025

One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Denise Tay (LKKAuto)

From:

Frankie THAY (SPF) < Frankie_THAY@spf.gov.sg>

Sent:

Thursday, 14 March 2019 5:26 PM

To:

Denise Tay (LKKAuto); Admin-D (LKKAuto); assignments

Cc:

SUR: Hafizul Farhan RAHMAT (SPF)

Subject:

RE: Pre-Repair Inspection for SLE5581M

Your reference: SLE5581M

Our reference: AEMD/105/009/2019/001

Dennis,

For your update please

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



TRANSFORMATION 2025 * One Home, One Team Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Sent: Thursday, 14 March 2019 5:05 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; assignments

<assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>

Subject: RE: Pre-Repair Inspection for SLE5581M

Dear Sir,

Please provide your ref no.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51. Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	11/01/2019 13:00
Date Of Accident	10/01/2019 12:30
Exact Location Of Accident	AYE ECP BEFORE NORTH BUONA VISTA RD
Country/State of Loss	SINGAPORE
THE RESERVE OF THE PARTY OF THE	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLE5581M
Insured/Policyholder	
Name Of Registered Owner	NSL ENTERPRISE
Co Reg No	53338965L
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91839938
Alternative Phone No	OFFICE-91839938
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	LANCER EX 1.6 AT LED TAIL LAMP
Exact Purpose for which vehicle was being used a time of accident	at
Are you claiming under your own insurance policy for repair to your vehicle?	, NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNCV2018-00000188
Cover Note Number	
Driver	
Name of Driver	NG SOON LEE
NRIC No	S7219705D
Date Of Birth	10/06/1972
Occupation	OUTDOOR
Date Of Driving Pass	08/08/1992
Driving Experience	26 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91839938
Fax Number	

NOEMAIL

Address

654BJURONG WEST STREET

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

3

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

2

Number of Passengers (Including Driver)

Passenger 1

NAME:

: CHRIS

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

JURONG NPP

Police Station Address

ROAD: 158 YUNG LOH ROAD #01-58, POSTCODE: 610158, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given? If Yes, against whom?

NO

Circumstances of Accident

refer to attached

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

QX5249P

Details Of Properties

Vehicle Category

GOVERNMENT

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJY338B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

NG SOON LEE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLE5581M

Were seat belts worn?


Was this injured conveyed to hospital by

ambulance?

Address

Postcode

Sketch Plan



Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any faise reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured wehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetany Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the soternal cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present end all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature
(If driver is not the policyholder)

Date & Time:

Reporting Centre Persons Name: NBIC/FIN No.: eg no: 2013132

qualitiest Shetchillaniform_VS





Police Station Of Origin: Jurong West N.P.C 700 Corporation Road, SINGAPORE 649818 Tel No: 1800-2689999 1 of 3 Report No. T/20190110/2145

REPORT OF A TRAFFIC ACCIDENT

		Made:	Vide Report No.: D/20190110/0054	Station Diary No.: 229					
Informant's Particulars									
Name of Informant: NG SOON LEE			Address: APT BLK 654B JURONG WEST STREET 61 #02-490 SINGAPORE 642654						
ID Type / NRIC NC	ID No.:) / S721970	05D	Contact No.: Home/Office:	Mobile: 91839938					
Nationality: SINGAPORE CITIZEN		EN	Email:						
Sex: Male	Age: 46	Date of Birth: 10/06/1972	Type of Informant: Driver						
Race: Chinese			Language: English	Institution / School Name:					
Occupation GO JEK I		e	Driving Licence Information: Class: 3,4	Date of Expiry:					

Type of Accident:	Non-Injury Government Vehicle	Drink Drive; No	Date/Time of Accident: 10/01/2019 12:30	Type of Location Straight Road		
	EXPRESSWAY TY, BEFORE NORTH BU					
Weather: Clear		Road Surface:		Road Speed Limit:		
Traffic Flow:		Traffic Control:		raffic Volume: loderate		
Type of Collisio Between Movin	n: g Vehicles - Head To Re	ar	а	nyone conveyed by mbulance:		

Details of Vehicle Involved								
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger		
QX5249P	Car	ТОУОТА		White	Seriously Damaged	3		
SJY338B	Car	MERCEDES BENZ		Black	Slightly Damaged	0		
SLE5581M	Car	MITSUBISHI		Grey	Seriously Damaged	1		





Report No. T/20190110/2145

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999

CONTINUATION OF REPORT

Details of Person		5 H. A. 10 H. K.		E (SIDE)		MICHIGANIS IN THE RESIDENCE	
Any Pedestrian	Involved: No						
No. of Pedestria	ns Injured: NIL		Line of De	-11-1	-		
Driver Triver		Use of Pe	destria	n Cross	sing: NA		
Name	NG SOON LEE		TOPE TO USE				
ennedernaste	NO OOON LEE			ID No	0.	S7219705D	
Related Vehicle	SLE5581M (Car)			01			
	(04.)	JEESCO IIII (Car)		Contact No.		91839938	
Hospital/Clinic	MOUNT ALVERNIA	HOSPITAL		01 1		19-00	
	THE TENENT HOSPITAL			Class	200	Class: 3,4 Date of Expiry: NIL	
		is a second of the second of t		Drivin	0		
				Licence &			
Date Treatment	10/04/0046			Expir	Date	2	
	10/01/2019		Date Disci	narge	10/01	/2010	
No. of Days gran	ted Medical Leave	05	Degree of	Injury	NIL	12019	

Brief Details.

On 10/1/2019 at about 1230hrs, I was driving on the extreme right lane of AYE towards city on my grey Mitsubishi car (SLE5581M) while doing Go Jek. I have one female passenger seated at the rear left seat. I was travelling about 80km/h and the traffic volume was moderate at that time. Suddenly, I felt a hard impact from the rear and it caused my car to jerk in front and collided with the black Mercedes car (SJY338B) in front. I then alighted and discovered that there was on Toyota police car (QX5249P) had collided with the rear of my car. I then exchanged particulars with the driver in front of me who was not carrying any passengers. To the best of my knowledge, nobody was injured at that moment. I then given my handphone number to the lady police officer. I observed that front and rear bumper of my car was dented badly. The rear bumper of my car was dislodged and I had difficulties driving the car as the rear left wheel and the rear bumper were hitting each other. After confirmation with the police, I then drove my car to the bus stop after North Buona Vista Road exit and called for towing services. I wish to state that I had an in-car camera which is not working.





Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No. 1800-2689999

3 of 3 Report No. T/20190110/2145

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
Sgt 3 MUHAMMAD FADHIL KAMRODEN	/ Jane
Signature Of Interpreter:	Date/Time:
Not applicable	10/01/2019 21:18
	10/01/2019 21.18
Officer In Charge Of Case:	Classification Of Case:
TP / GIA /	Classification of Case.
Staff Sgt WONG SIEU LUI	
Contact No.: 65476151	
0	
Authentication Stamp	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID: Vehicle Details	8965L
Vehicle No.:	SLE5581M
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	4A92CJ7199
Chassis No.:	JMYSRCY1AGU005778
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$14,677.00
Original Registration Date:	27 Jul 2016
First Registration Date:	27 Jul 2016
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$14,677.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2026
PARF Rebate Amount: Intended COE Rebate Details	\$11,007.00
COE Expiry Date:	26 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$41,578.00
Total Rebate Amount:	\$52,585.00

The information contained herein is correct as at 14 Jan 2019

OK

Dep 7,110/1917 593/mHZ

MV 58,600 PV 52,585 NV 7,194

15/1/19

Insurance

SGEARMART.COM

New Cars

Login Sign up

Sell My Car Articles Forum Resources 500+ dealers Sell ur Car for More Cash competed to Highest Price or Get \$100 Free **SELL YOUR CAR** buy my car! Get Paid Now, Handover Later (A)UOTZ

Products

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Used Cars

New 5 Years Coe Renewal Honda Stream 1.8A



Directory

2.88% a.a Lowest Interesting Cars Financing \$2000

GV Credit Pte Ltd Star40



Browse by Category 13 vehicles

Post an Ad

Mitsubishi Lancer



▼ 100 results/page ▼

Make

Advertiser Login

٠

Ways of Selling

Price Depreciation

Any

Mileage

Veh Type

Status

Search Selection

Mitsubishi Lancer

Any

\$7,070 /yr

2016

1.590 cc

Eng Cap

Anv

Available

Mitsubishi Lancer FX 1.64

\$62,827

15-Dec-2016

Reg Date

1.98% Promotion Rate. Flexible Loan Packages Available To Choose From. Low Mileage. High Trade In Value For Your Carl No Hidden Costs, GST

Edmund Motor Pte Ltd

Posted: 14-Jan-2019

Tags: 2016 Mitsubishi Lancer, 2016 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi Lancer, Incer, Used Mitsubishi

Included, For Further Information Or If You Have Any Question...

Mitsubishi Lancer EX 1.6A

\$58,800

\$7,550 /yr

13-Jan-2016

1.590 cc

75,000 km

Sedan

Available

1 Owner Only. High Loan Available. Fully Maintained By Cycle And Carriage! 10 Years Engine Warranty And 5 Years Unlimited Mileage Warranty By Agent. Please Call Or Visit Us Now For Further Details.

Pure Motors Pte Ltd

Posted: 12-Jan-2019

Tags: 2016 Mitsubishi Lancer, 2016 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, Isacer, Used Mitsubishi



Mitsubishi Lancer EX 1.6A

\$58,000

\$7,110 /yr

30-Mar-2016

1.590 cc

Available

The Maintenance History, Drive With Peace Of Mind, Test D...

Posted: 09-Jan-2019

Tags: 2016 Mitsubishi Lancer, 2016 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi Lancer, lancer, Used Mitsubish

Fully Serviced By Cycle & Carriage, 10 Years Warranty For Engine, Well Maintained, Low Mileage Done At 71k, Buy Direct From Owner, Get To Know



Mitsubishi Lancer EX 1.6A

N.A

05-Oct-2016

1.590 cc

SOLD

No Gimmiks! 100% Approval! We Are sgCarMart Premium Dealer! Buy With No Worries! No Hidden Costs! Car In Original Condition! Low Mileage! Accident Free! In House Loan Or Bank Loan Available! No Need G...

88 Motor Trading

Posted: 06-Jan-2019

Tags: 2016 Mitsubishi Lancer, 2016 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubish



Bridgestone Potenza Adrenalin RE003 15" Tyres

Bridgestone Potenza Adrenalin RE003 195/50 R15 Tyre @ \$95/pc

More info about this product



Mitsubishi Lancer EX 1.6A

19-May-2016

1,590 cc

SOLD

(Facelited Model With LED Tail Lamps And 5 Years Unlimited Mileage C&C Warranty) Buy With Confidence! No Hidden Cost! Low Mileage! 100% Accident Free! In House Loan Or Bank Loan Available! No Need Gua...

Posted: 23-Dec-2018 Tags: 2016 Mitsubishi Lancer, 2016 mitsubishi lancer, Mitsubishi lanc



Mitsubishi Lancer EX 1.6A Sports

11-Mar-2016

1,590 cc

SOLD

1 Owner C&C Unit. \$2,000 Republic Auto Warranty Workshop Service Credits, Agent Maintained. Still Under C&C Warranty. High Spec Sports Modell Down Payment \$17,340 Only! Exclusive Bank Interest Rates A...

Republic Auto

Posted: 16-Dec-2018 Tags: 2016 Mitsubishi Lancer, 2016 mitsubishi lancer, Mitsubishi lanc

\$64,888 \$7,320 /vr 20-Dec-2016

1,590 cc

Mitsubishi Lancer EX 1.6A itted Upholstery, Stylish Designer Colour, Regularly Serviced At Cycle And Carriage, Well Maintained By Lady Owner, Selling As Relocating.

35,000 km

Available DIRECT OWNER

sted: 16-Dec-2018 Tags: 2016 Mitsubishi Lancer, 2016 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi https://www.sgcarmart.com/used_cars/listing.php?MMO=Lancer&RPG=100&VEH=0&RGD=2016&MOD=Mitsubishi Ms Car

SLE 558/M

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N		QTY		UNIT LIST PRICE	T	TOTAL LIST PRICE]
	BONNET	1	\$	599.00	2	599.00	made
2	BONNET HINGE	2	\$	46.00		√ 92.00	- Part - 4
	BONNET LOCK	1	\$	62.00		62.00	V.
4	BONNET LOCK CATCH	1	\$	49.00		√ 62.00 √ 49.00	BTVX
5	BONNET WEATHER STRIP (OUTER)	1	\$	49.00	_	49:00	
6	FRONT WIPER LOWER GARNISH	2	\$	53.00			
7	FRONT BUMPER	1	\$	710.00		106.00	NNX.
8	FRONT BUMPER BEAM	1	\$	161.00		V 710.00	DDV
9	FRONT BUMPER LOWER GRILLE	1	\$	186.00		√161.00 ✓100.00	BIV
10	FRONT BUMPER FOG LAMP	2	\$	210.00		√186.00	BRV
11	FRONT BUMPER FOG LAMP GARNISH	2	\$	29.00		√ 420.00	BRV
12	FRONT BUMPER SIDE RETAINER	2	\$	61.00		√ 58.00	
13	FRONT BUMPER LOWER BRACKET	2	\$	55.00		v 122.00	
14	FRONT BUMPER LOGO	1	\$	32.00		110:00	NNX
15	FRONT GRILLE	2	\$		_	√32.00	NECV
	HEADLAMP	2		93.00		√ 186.00	
	HEADLAMP LOWER BRACEKT	2	\$	11) - 0,493.00		20.00 986.00	
18	HEADLAMP LOWER CLIP	2		39.00		78.00	BRV
19	FRONT SUPPORT PANEL	1	\$	6.00		√12.00	NEL
20	FRONT SUPPORT PANEL BRACKET	2	_	582.00	_	v 582.00	BTV
21	FRONT WASHER TANK	1	\$	38.00	_	76.00	BTV
22	BRACE PANEL LOCK	1	\$	88.00	\$	88:00	XNX
3 1	BATTERY TRAY		\$	48.00	_	J 48.00	
4	HORN	1	\$	35.00	-		メロス
	A/C CONDENSER	2	\$	65.00			NNX
	V CFAN MOTOR ASSY	1	\$	1,089.00	_	1,089.00	BRV
7 /	VC DRIER	1	\$	787.00	-	787.00	BRV.
	RADIATOR ASSY	1	\$	115.60	-	115.60	× ×
	RADIATOR MOUNTING	1	\$	791.00	\$	√791.00	BRS
OF	RADIATOR FAN BLADE	2	\$	28.00		√ 56.00	BTV
1 F	RADIATOR FAN MOTOR	1	\$	55.00	\$		XNN
2 5	RADIATOR SPARE TANK	1	\$		\$		KNY
3 5	RADIATOR BRACEKT	1	\$	49.00	\$	49.00	NNX
4 A	IR CLEANER BOX	2	\$	18.00	\$	√36.00	BT
	NGINE MOUNTING (SET)	1	\$	313.00	\$	040.00	NNX
6 0	OOT LID	1	\$	512.00	\$		NNY
	OOT LID TOP LOCK	1	\$	587.00	\$		DDV
	OOT LID TOP LOCK	1	\$	65.00	\$	/ 65.00	RT./
	OOT LID LOWER LOCK	1	\$	24.00	\$	J 24.00	27./
10	OOT LID WEATHER STRIP	1	\$	139.00	\$	/139.00 C	DIV.
	OOT LID LOGO	1	\$	42.00		/ 42.00 N	IFC
1 K	EARNUMBER PLATE GARNISH	1	\$			0'2197.00	SE /
2 K	EAR BUMPER LOWER SPOILER	1	\$	659.00	\$	659.00	TIT /
K	EAR BUMPER BEAM		\$	169.00	1-711		
IK	EAR BUMPER SIDE BRACEKT		\$	62.00		10100	BTV,
IK	EAR NUMBER PLATE LAMP (SET)		\$	57.00		√ 57.00 E	27 /
	AIL LAMP		\$	`386.00			
TA	AIL LAMP PANEL		\$		_	0 10	BRV
RI	EAR END PANEL		\$		\$ 15	-	DV
R	EAR END PANEL TOP GARNISH		\$			/ /	DOV
R	EAR FENDER INNER TRIM		\$		\$		BRV,
RE	EAR FLOOR PANEL BOARD		\$		\$		NV
P	EAR EXHAUST PIPE		\$		\$	165.00 A	INX

TOTAL PRICE \$ 13,577.60 LESS 10% \$ 1,357.76 SUB TOTAL PRICE \$ 12,219.84

S/N	DESCRIPTION	QTY	UN	IT S/NETT	TO	DTAL	S/NET
	FRONT NUMBER PLATE	1	\$	55.00	\$	25	a 55.0
	FRONT BUMPER CLIPS	10	\$	5.00	\$	20	
3	FRONT GRILLE CLIPS	4	\$	5.00	\$	-1	√20.0
	FRONT FENDER COWLING CLIPS	16	\$	5.00	\$	50.	
	REAR BUMPER CLIPS	10	\$	5.00	\$	70.	50.0
6	TAIL LAMP CLIPS	4	\$	4.50	\$)	18.0
7	REAR END PANEL TOP GARNISH CLIPS	2	\$	2.00	\$		/4.0
8	REAR FENDER INNER TRIM CLIPS	10	\$	5.00	\$	40	√50.0
9	REAR FLOOR PANEL INSULATION SEAL	1	\$	150.00	-	20.0	n 150:0
10	REVERSE SENSOR	1	\$	350.00	_		>350.0
11	FRONT BUMPER LOWER LIP	1	\$	850.00	_	_	#850.0
12	REAR BUMPER LOWER LIP	1 1	\$	850.00			
	REAR NUMBER PLATE	1	\$	55.00	_	26	0,850.0 55.0

TOTAL

\$ 2,582.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N			PRICE	ADJUSTED COST	APPROVED
1	TO KNOCK, PANEL BEAT, WELD, CUT, STRAIGHTEN, ADJUST, ALIGN, RESHAPE DAMAGED PARTS	\$	2,800 .00	1600 8	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$	2,400:00	1200 D	
3	WIRING BULB CHECKING	\$	<u>150:0</u> 0	50.00	
4	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	\$	250.00	10.0	
5	REMOVE AND REFIX REAR EXHAUST	\$	150:00	80.00	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$	150.00	60.00	
7	REMOVE AND REFIC A/C CONDENSER AND RECHARGE A/C GAS	\$	180:00	12000	
8	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$	150:00	60.00	
9	TOWING CHARGES	\$	150:00	NNX	
10	FRONT CHASSIS ALIGNMENT CHARGES	\$	250:00	100.00 X	
11	CONDUCT WATER LEAKAGE TEST	\$	150:00	60 00 X	
	SEAL REAR END PANEL	\$	1 50.0 0	60.00	
	REMOVE AND REFIX SPARE TYRE BOARD, SPARE TYRE, ATC TO FACILITATE REPAIR	\$	1 50:0 0	XNX	
14	TRANSFER BOOT LID MECHANISM	\$	150.00	инх	

Denice.

Ms Car

teepret

CLAIM DETAIL : PARTS

QUOTATION SUMMARY

CLA	AIM DETAIL : PARTS UNIT LIST TOTAL LIST					
S/N	DESCRIPTION		UNIT LIST PRICE		PRICE	
1652.2		1	•	599.00	6	√599.00
. *	BONNET	2	\$	46.00		92.00
	BONNET HINGE	1	\$	62.00		62.00
	BONNET LOCK	1	\$		\$	V49.00
	BONNET LOCK CATCH			49.00		49.00
	BONNET WEATHER STRIP (OUTER)	1	\$		\$	106.00
_	FRONT WIPER LOWER GARNISH	2	\$		\$	√710.00
	FRONT BUMPER	1	\$			/161.00
	FRONT BUMPER BEAM	1	\$	161.00	_	
	FRONT BUMPER LOWER GRILLE	1	\$		\$	V186.00
	FRONT BUMPER FOG LAMP	2	\$	210.00	\$	J420.00
	FRONT BUMPER FOG LAMP GARNISH	2	\$		\$	/ 58.00
	FRONT BUMPER SIDE RETAINER	2	\$	61.00	\$	
	FRONT BUMPER LOWER BRACKET	2	\$		\$	
	FRONT BUMPER LOGO	11	\$	32.00		
	FRONT GRILLE	2	\$	93.00		
	HEADLAMP	2	\$	493.00	_	
	HEADLAMP LOWER BRACEKT	2				44 · On 78.00
	HEADLAMP LOWER CLIP	2	\$	6.00	\$	
	FRONT SUPPORT PANEL	1	\$	582.00		
	FRONT SUPPORT PANEL BRACKET	2	\$	38.00	-	
21	FRONT WASHER TANK	1	\$	88.00	_	
2	BRACE PANEL LOCK	1	\$	48.00	\$	
23	BATTERY TRAY	1	\$	35.00		
24	HORN	2	\$	65.00		
25	A/C CONDENSER	1	\$	1,089.00		1,054 1,089.00
6	A/ CFAN MOTOR ASSY	1	\$	787.00	\$	
27	A/C DRIER	1	\$	115.60	\$	√ 115.60
28	RADIATOR ASSY	1	\$	791.00	\$	√ 791.00
	RADIATOR MOUNTING	2	\$	28.00	\$	√ 56.00
	RADIATOR FAN BLADE	1	\$	55.00	\$	55.00
	RADIATOR FAN MOTOR	1	\$	307.00	\$	307.00
	RADIATOR SPARE TANK	1	\$	49.00	\$	49.00
	RADIATOR BRACEKT	2	\$	18.00	_	
	AIR CLEANER BOX	1	\$	313.00	-	
	ENGINE MOUNTING (SET)	1	\$	512.00	\$	
	BOOT LID	1	\$	587.00	-	
_	BOOT LID TOP LOCK	1	\$	65.00	_	
	BOOT LID LOWER LOCK	1	\$	24.00	-	
_	BOOT LID WEATHER STRIP	1	\$	139.00	-	
_	BOOT LID LOGO	1	\$	42.00	_	
	REARNUMBER PLATE GARNISH	1	\$		_	50/2197.00
-	REAR BUMPER LOWER SPOILER	1	\$	659.00		600 -0659.00
	REAR BUMPER BEAM	1	\$	169.00		
	REAR BUMPER SIDE BRACEKT	2	\$	62.00	-	
	REAR NUMBER PLATE LAMP (SET)	1	\$	57.00	-	
_		2	\$	386.00	_	
_	TAIL LAMP PANEL	2	\$	82.00	_	
_	TAIL LAMP PANEL		\$	394.00	_	
_	REAR END PANEL TOP CARNISH	1	\$			
_	REAR END PANEL TOP GARNISH			185.00		267.0370.00
_	REAR FENDER INNER TRIM	2	\$		_	
	REAR FLOOR PANEL BOARD	1	\$			
52	REAR EXHAUST PIPE	1	\$	425.00	1 3	403.60 425.00

TOTAL PRICE LESS 10% SUB TOTAL PRICE \$ 13,577.60 1,357.76 12,219.84

S/N	DESCRIPTION	QTY	UNI	T S/NETT	TOT	AL S/NETT	
1	FRONT NUMBER PLATE	1	\$	55.00	\$:	25.0 55.00	BTV
2	FRONT BUMPER CLIPS	10	\$	5.00	\$	1 50.00)
3	FRONT GRILLE CLIPS	4	\$	5.00	\$	20.00	1
4	FRONT FENDER COWLING CLIPS	16	\$	5.00	\$	50.00 80.00	(,,-,
5	REAR BUMPER CLIPS	10	\$	5.00	\$	√ 50.00) NEC U
6	TAIL LAMP CLIPS	4	\$	4.50	\$	18.00	11
7	REAR END PANEL TOP GARNISH CLIPS	2	\$	2.00	\$	√4.00	1)
8	REAR FENDER INNER TRIM CLIPS	10	\$	5.00	\$	50.00]]
9	REAR FLOOR PANEL INSULATION SEAL	1	\$	150.00	\$ 6		γ
10	REVERSE SENSOR	1	\$	350.00	\$ 5	200/2350:00	CUTV
11	FRONT BUMPER LOWER LIP	1	\$	850.00	\$ 8	_{ന - എ850.00}	4 NEC
12	REAR BUMPER LOWER LIP	1	\$	850.00	\$	√850.00	1,000
13	REAR NUMBER PLATE	1	\$	55.00	\$ 2	25 55:00	1

TOTAL

2,582.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE		ADJUSTED COST	APPROVED
1	TO KNOCK, PANEL BEAT, WELD, CUT, STRAIGHTEN, ADJUST, ALIGN, RESHAPE DAMAGED PARTS	\$	2,800 .00	2006.00	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$	2, 400: 00	1800-00	
3	WIRING BULB CHECKING	\$	<u>150:0</u> 0	50.00	
4	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	\$	<u>250</u> .00	100·10	
5	REMOVE AND REFIX REAR EXHAUST	\$	150:00	80.00	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$	150.00	60.00	
7	REMOVE AND REFIC A/C CONDENSER AND RECHARGE A/C GAS	\$	180:00	120.00	
8	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$	150:00	60.00	
9	TOWING CHARGES	\$	150:00	NNX	
10	FRONT CHASSIS ALIGNMENT CHARGES	\$	250:00	100.00	
11	CONDUCT WATER LEAKAGE TEST	\$	150:00	60.00	
12	SEAL REAR END PANEL	\$	150:00	60.00	
13	REMOVE AND REFIX SPARE TYRE BOARD, SPARE TYRE, ATC TO FACILITATE REPAIR	\$	150.00	NNX	
	TRANSFER BOOT LID MECHANISM	\$	1 50. 00	хии	

Rear Bumper V#685-5 DDV

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,801.84 TOTAL LABOUR COST : \$ 7,230.00 TOTAL REPAIR COST : \$ 22,031.84

APPROVED DETAILS

EXCESS NO. OF DAYS RE-SURVEY

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY : 15/1 (19) 1430
SURVEYED BY : LIM Team Grant
CONTACT NUMBER : 9736 1577

Days of repair 10



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref: CS/SPF19000772/Btd3e2

ACCIDENT CLAIM SECTION (SPORE POLICE

FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD Date: 19-03-2019 POLICE ACADEMYSINGAPORE 298333



1.	S CENTRAL PROPERTY OF THE PARTY	Policy Particula	rs :- THIRD PARTY CLA	AIM .
	Insured Veh.	QX 5249P	Veh. Inspected	SLE 5581M
	Policy No.		Coverage (\$)	0.00
	Claim No.	AEMD/105/009/2019/001	Excess (\$)	0.00
	Assign From	FRANKIE THAY	Assign Date	14/01/2019
2.		Vehicle Pa	rticulars & Condition	
	Make & Model	MITSUBISHI LANCER EX	c.c	1590
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JMYSRCY1AGU005778	Colour	GREY
	Odometer	97052	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	POOR		
3.		Cond	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	GOODYEAR	6 mm
	L/H Front Tyre	205/60 R16	GOODYEAR	6 mm
	R/H Rear Tyre	205/60 R16	GOODYEAR	6 mm
	L/H Rear Tyre	205/60 R16	GOODYEAR	6 mm
4.	The Property of the	Descri	ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT AND REAR PORTI	ON.
	DAMAGES SEE D	ETAILS.		
5.			eral Information	
	Accident Date	10/01/2019	Inspection Date	14/01/2019
	Survey held at	MS CAR AUTO PTE LTD	•	
		8 KAKI BUKIT AVENUE 4 #0 SINGAPORE 415875	1-07 PREMIER @ KAKI BU	KIT
5a.			Remarks	THE RESERVE OF SHAPE
	A)THE INSPECTION B)IN ACCORDANG	ON WAS CONDUCTED ON A"VICE TO YOUR INSTRUCTIONS	NITHOUT PREJUDICE" BA , WE HAVE NOT AUTHORI	SIS. ISED REPAIRS.
5b.		Estima	ite Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	10 Working D	avs



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 5581M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)	
	REPLACEMENT OF PARTS				
1	BONNET	TO REPAIR SEE LABOUR	599.00	-	
2	BONNET HINGE @\$46.00	NOT NECESSARY	92.00	1/2	
1	BONNET LOCK	BENT	62.00	62.00	
1	BONNET LOCK CATCH	NOT NECESSARY	49.00	:-	
1	BONNET WEATHER STRIP (OUTER)	NOT NECESSARY	49.00		
2	FRONT WIPER LOWER GARNISH @\$53.00	NOT NECESSARY	106.00	15	
1	FRONT BUMPER	DENTED	710.00	710.00	
1	FRONT BUMPER BEAM	BENT	161.00	161.00	
1	FRONT BUMPER LOWER GRILLE	BROKEN	186.00	186.00	
2	FRONT BUMPER FOG LAMP @\$210.00	BROKEN	420.00	420.00	
2	FRONT BUMPER FOG LAMP GARNISH @\$29.00	BROKEN	58.00	58.00	
2	FRONT BUMPER SIDE RETAINER @\$61.00	NECESSARY	122.00	122.00	
2	FRONT BUMPER LOWER BRACKET @\$55.00	NOT NECESSARY	110.00		
1	FRONT BUMPER LOGO	NECESSARY	32.00	32.00	
2	FRONT GRILLE @\$93.00	BROKEN	186.00	186.00	
2	HEADLAMP @\$493.00	BROKEN	986.00	820.00	
2	HEADLAMP LOWER BRACKET @\$39.00	BROKEN	78.00	78.00	
2	HEADLAMP LOWER CLIP @\$6.00	NECESSARY	12.00	12.00	
1	FRONT SUPPORT PANEL	BENT	582.00	582.00	
2	FRONT SUPPORT PANEL BRACKET @\$38.00	BENT	76.00	76.00	
1	FRONT WASHER TANK	NOT NECESSARY	88.00		
1	BRACE PANEL LOCK	BENT	48.00	48.00	
1	BATTERY TRAY	NOT NECESSARY	35.00		
2	HORN @\$65.00	NOT NECESSARY	130.00	-	
1	A/C CONDENSER	BROKEN	1,089.00	1,089.00	
1	A/C FAN MOTOR ASSY	BROKEN	787.00	787.00	
1	A/C DRIER	NO SUCH PARTS	115.60		
1	RADIATOR ASSY	BROKEN	791.00	791.00	
2	RADIATOR MOUNTING @\$28.00	BENT	56.00	56.00	
1	RADIATOR FAN BLADE	NOT NECESSARY	55.00		
1	RADIATOR FAN MOTOR	NOT NECESSARY	307.00		
1	RADIATOR SPARE TANK	NOT NECESSARY	49.00		
2	RADIATOR BRACKET @\$18.00	BENT	36.00	36.00	

Report Ref No. CS/SPF19000772/Btd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts Condition		Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CLEANER BOX	NOT NECESSARY	313.00	-
1	SET ENGINE MOUNTING	NOT NECESSARY	512.00	-
1	BOOT LID	DENTED	587.00	587.00
1	BOOT LID TOP LOCK	BENT	65.00	65.00
1	BOOT LID LOWER LOCK	BENT	24.00	24.00
1	BOOT LID WEATHER STRIP	CUT	139.00	139.00
1	BOOT LID LOGO	NECESSARY	42.00	42.00
1	REAR NUMBER PLATE GARNISH	BROKEN	197.00	50.00
1	REAR BUMPER LOWER SPOILER	CUT	659.00	659.00
1	REAR BUMPER BEAM	BENT	169.00	169.00
2	REAR BUMPER SIDE BRACKET @\$62.00	DENTED	124.00	124.00
1	SET REAR NUMBER PLATE LAMP	BENT	57.00	57.00
2	TAIL LAMP @\$386.00	BROKEN	772.00	772.00
2	TAIL LAMP PANEL @\$82.00	DENTED	164.00	152.00
1	REAR END PANEL	DENTED	394.00	394.00
1	REAR END PANEL TOP GARNISH	BROKEN	137.00	137.00
2	REAR FENDER INNER TRIM @\$185.00	TORN	370.00	370.00
1	REAR FLOOR PANEL BOARD	NOT NECESSARY	165.00	7
1	REAR EXHAUST PIPE	NOT NECESSARY	425.00	_
	LESS 10% DISCOUNT		-1,357.76	-1,005.30
			12,219.84	9,047.70
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	55.00	25.00
10	FRONT BUMPER CLIPS @\$5.00 (SN)	NECESSARY	50.00	30.00
4	FRONT GRILLE CLIPS @\$5.00 (SN)	NECESSARY	20.00	20.00
16	FRONT FENDER COWLING CLIPS @\$5.00 (SN)	NECESSARY	80.00	50.00
10	REAR BUMPER CLIPS @\$5.00 (SN)	NECESSARY	50.00	30.00
4	TAIL LAMP CLIPS @\$4.50 (SN)	NECESSARY	18.00	18.00
2	REAR END PANEL TOP GARNISH CLIPS @\$2.00 (SN)	NECESSARY	4.00	4.00
10	REAR FENDER INNER TRIM CLIPS @\$5.00 (SN)	NECESSARY	50.00	40.00
	REAR FLOOR PANEL INSULATION SEAL (SN)	NECESSARY	150.00	120.00
	FRONT BUMPER LOWER LIP (SN) }	NECESSARY	850.00	900.00
	REAR BUMPER LOWER LIP (SN) }	NECESSARY	850.00	
	REVERSE SENSOR (SN) }	CUT	350.00	_

Report Ref No. CS/SPF19000772/Btd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	NECESSARY	55.00	25.00
			2,582.00	1,262.00
	LABOUR			
	TO KNOCK, PANEL BEAT, WELD, CUT, STRAIGHTEN, ADJUST, ALIGN, RESHAPE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF BONNET.		2,800.00	1,600.00
	TO PUTTY, SPRAY PAINT, POLISH, WAX.		2,400.00	1,500.00
	WIRING BULB CHECKING.		150.00	50.00
	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR.		250.00	60.00
	REMOVE AND REFIX REAR EXHAUST.	NOT NECESSARY	150.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		150.00	60.00
	REMOVE AND REFIX A/C CONDENSER AND RECHARGE A/C GAS.		180.00	120.00
	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.		150.00	60.00
	TOWING CHARGES.	NOT NECESSARY	150.00	-
	FRONT CHASSIS ALIGNMENT CHARGES.	NOT NECESSARY	250.00	
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	
	SEAL REAR END PANEL.		150.00	60.00
	REMOVE AND REFIX SPARE TYRE BOARD, SPARE TYRE, ATC TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	TRANSFER BOOT LID MECHANISM.	NOT NECESSARY	150.00	-
			7,230.00	3,510.00
	GRAND TOTAL		22,031.84	13,819.70

RECOMMENDED COST OF LUMP SUM REPAIRS	ENTERON DE LA COMPANION DE LA	11,050.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SPF19000772/Btd3e2

NOTES: THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$11,000-\$12,000

LIM TEOW GUAN

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.