



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJX8810G

ERGO INSURANCE PTE LTD


MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No **29986**
Reg No/Reg Date **SJX8810G / 11/01/2017**
Date In/Mileage **/ 0**
Chassis No **WDD2050402R205505**
Engine No **27491030691991**
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**
Colour/Trim **027 799 Diamond Whi/ 041 101 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator
WN000512	Credit	09/01/2019/ 22:50	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 5096121653 // 09-01-2019 DRIVE IN: 09-01-2019 // TP CAR NO: YN9879C (ERGO INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT	0.10	✓		380.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT		✓		120.00
A BPILAB REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL	240			300.00
A BPILAB RENEW REAR WINDSHIELD	0.07	✓		560.00
S BPNSUB SUPPLY IPC REAR WINDSHIELD SOLAR FILM PURCHASE ORDER NO:		✓		300.00
A BPILAB REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR FOR NECESSARY REPAIR.	960			1440.00
A BPILAB REMOVE & INSTALL REAR SUSPENSION & WHEEL BASE	1920?			2400.00
A BPILAB PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMEN	0.07	?		1000.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT		✓		540.00
A BPILAB TO SEAL PANEL JOINTS WITH SEALANT		✓		120.00
A BPILAB REMOVE & REPLACE REAR BUMPER, REAR BOOT LID, REAR END PANEL, REAR RIGHT FENDER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.	7680			9600.00



LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document. No signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally, additional parts or labour are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJX8810G

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No **29986**
Reg No/Reg Date **SJX8810G / 11/01/2017**
Date In/Mileage **/ 0**
Chassis No **WDD2050402R205505**
Engine No **27491030691991**
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**
Colour/Trim **027 799 Diamond Whi/ 041 101 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator		
WN000512	Credit	09/01/2019/ 22:50	AQ	305 / Alan Quek Ai Lun		
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
A BPIRES					0.02	2400 2800.00
RESPRAY REAR BUMPER, REAR BOOT LID, REAR END PANEL & REAR RIGHT FENDER						
M	REAR BUMPER		1.00	1590.64	00.00	de 1590.64
M	REAR BUMPER BOTTOM PANEL		1.00	215.55	00.00	de 215.55
M	REAR BUMPER BOTTOM GARNISH		1.00	253.67	00.00	ne 253.67
M	RH/R PARKING SENSOR		2.00	177.22	00.00	0.00 354.44
M	RH/R PARKING SENSOR SEAL		2.00	6.42	00.00	12.84
M	RH/R BUMPER SIDE BRACKET		1.00	51.46	00.00	51.46
M	RH/R BASIC MOUNTING FOR BUMPER		1.00	53.79	00.00	53.79
M	CT/R BASIC MOUNTING FOR BUMPER		1.00	87.26	00.00	87.26
M	RH/R BOTTOM BRACKET		1.00	31.03	00.00	31.03
M	RH/R TOP BASIC MOUNTING FOR BUMPER		1.00	30.90	00.00	30.90
M	RH/R TAIL LAMP		1.00	693.13	00.00	ax 693.13
M	REAR LICENSE PLATE LAMP		2.00	27.05	00.00	x 54.10
M	REAR BOOT LID		1.00	2110.79	00.00	bt 2110.79
M	REAR BOOT LID SEAL		1.00	181.16	00.00	ne 181.16
M	LH/R BOOT LID HINGE LEVER		1.00	247.09	00.00	? 247.09
M	RH/R BOOT LID HINGE LEVER		1.00	247.09	00.00	? 247.09
M	REAR BOOT LID GARNISH		1.00	131.28	00.00	cust 131.28
M	REAR BOOT LID LOCK		1.00	289.27	00.00	? 289.27
M	REAR STAR EMBLEM		1.00	48.25	00.00	ne 48.25
M	GROMMET		3.00	1.88	00.00	ne 5.64
M	C180 EMBLEM		1.00	84.56	00.00	ne 84.56
M	REAR END PANEL		1.00	1403.00	00.00	bt 1403.00
M	REAR CROSS MEMBER		1.00	646.76	00.00	bt 646.76
M	RH/R FENDER		1.00	2179.29	00.00	bkl 2179.29
M	RH/R FENDER INSULATION		1.00	60.05	00.00	reg 60.05
M	RH/R FENDER AIR FLAP		1.00	25.97	00.00	? 25.97
M	REAR WINDSHIELD		1.00	1085.42	00.00	ne 1085.42
M	REAR WINDSHIELD PAD		4.00	2.35	00.00	ne 9.40
M	GLAZING REPAIR KIT		3.00	157.83	00.00	ne 473.49
M	ADHESIVE SEALANT		1.00	781.76	00.00	ne 781.76

Alan Quek

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **32,999.08**
7% GST on **32999.08** **2309.94**
Total Payable 35,309.02

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany