



roh kin

Section A - Accident Details

Registration Number	SHB5063E
Case Reference Number	TAX/01/19/2039
Registration Date	12/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	KAHARUDIN BIN JUTI
Type of Accident	Head to Rear
Accident Date and Time	8/1/2019 11:47 PM
Accident Reported Date and Time	9/1/2019 2:39 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	9/1/2019 1:12 AM
Replacement Vehicle issued?	No
Job Card Number	24099612
Special Instruction to ARC, if any	TOWED \$ 40
Prepared Date and Time	9/1/2019 4:07 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



toyota

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,214.00	\$600.00
Total Spray Cost	\$1,856.00	\$650.00
Total Spare Part Cost	\$6,306.99	\$2,209.10
Total Other Cost	\$1,096.00	\$130.00
TOTAL COST	\$10,472.99	\$3,589.10 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	9.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	09/01/2019 4:53 PM	10/01/2019 3:04 PM
Signature		
Remarks	INITIAL ESTIMATE 7 DAYS REQUEST TO EXTEND 2 DAYS	P/P repair. photo before paint.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0300	Invoice Number	
Quotation Date	23.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$200.00	\$100.00
TO REPAIR REAR PORTION	\$1,014.00	\$500.00
Total Labour	\$1,214.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$200.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$50.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,856.00	\$650.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$50.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00
Total Other Costs	\$1,096.00	\$130.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63605092
Estimator Telephone Number : 63602625
Accident Reporting Number : 96602672

Date Generated : 25/4/2015
User ID : PohSuan

5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace	✓
5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace	✓
5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace	✓
5219147030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace	✓
5259247040	SEAL, RR BUMPER, LH	1.00	\$85.20	25.00	\$63.90	Replace	Replace	✓
5256647900	FILLER, RR BUMPER, LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace	✓
5256547900	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	✗
	SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	✓
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓
5257647040	RETAINER, RR BUMPER, LH	1.00	\$111.50	25.00	\$83.63	Replace	Replace	✓
5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	✗
5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check	✗
5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	✓
5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace	✓
5246147010	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace	✓
5839947030	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	✗
5839847050	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	✗
8159147010	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$486.80	10.00	\$438.12	Replace	Replace	✓
8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Check	✗
8218347020	WIRE, LUGGAGE ROOM	0.00	\$143.50	0.00	\$0.00	Replace	Not Given	✗
6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$929.60	100.00	\$0.00	Replace	Repair	✓
5611750140	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$27.90	0.00	\$0.00	Replace	Not Given	✗
7557147010	TAIL GATE MOULDING GLASS, BACK DOOR	0.00	\$29.70	0.00	\$0.00	Replace	Not Given	✗
6935047050	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$452.10	0.00	\$0.00	Replace	Check	✗
6932147010	TAIL GATE LOCK COVER, BACK DOOR	0.00	\$25.30	0.00	\$0.00	Replace	Check	✗
7557447040	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	✗
7557347110	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	✗
7557547051	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$19.70	0.00	\$0.00	Replace	Not Given	✗
7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-SEALANT W/SCREEN	1.00	\$891.20	100.00	\$0.00	Replace	Repair	✓
		0.00	\$37.00	0.00	\$0.00	Replace	Not Given	✗
7540348010	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace	✓
7544147090	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	✓
7544247130	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	✓
6943052050	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$24.90	0.00	\$0.00	Replace	Not Given	✗
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
6788147050	TAIL GATE WEATHERSTRIP, BACK	0.00	\$360.70	0.00	\$0.00	Replace	Check	✗
5830747090	END PANEL SUBASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Check	✗
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	✗
8156147151	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$438.10	0.00	\$0.00	Replace	Check	✗
Total			\$7,368.60		\$1,915.73			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace
		8999730100	ANTENNA, ELECTRICAL KEY	1.00	\$60.30	10.00	\$54.27	Replace	Replace
Total					\$379.10		293.37		

2209.10
 + 600.00
 + 780.00

 3589.10