

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 247P**AAD1901-093**

Not Notarised
C/Sy 8/18006

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 247P

VF1ABL15AUC282384

RENAULT

LATITUDE

10.1.2019

AIG

3/11/2015

	PART
1	FENDER PANEL REAR RH
1	FENDER PANEL INNER TRIM REAR
1	WHEELARCH REAR RH
1	ROCKER PANEL INNER GARNISH RH
1	ROCKER PANEL INNER RH
1	ROCKER PANEL CENTER RH
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER BRACKET SIDE RH REAR
1	BUMPER RETAINER RH REAR
1	REAR TAILAMP RH
1	DOOR PANEL REAR RH

LIST

\$	<i>R</i>	3,299.13	<i>X</i>
\$	<i>Sn</i>	671.45	<i>X</i>
\$	<i>Sn</i>	543.47	<i>X</i>
\$	<i>Sn</i>	466.51	<i>X</i>
\$	<i>R</i>	1,024.79	<i>X</i>
\$	<i>R</i>	990.25	<i>X</i>
\$	<i>Buclm</i>	1,108.46	<i>✓</i>
\$	<i>Sn</i>	768.84	<i>X</i>
\$	<i>R</i>	113.47	
\$	<i>Sn</i>	135.97	
\$	<i>Sn</i>	44.99	
\$	<i>Sn</i>	552.55	
\$	<i>R</i>	2,844.66	
\$		12,564.54	
10%	\$	1,256.45	
\$		11,308.08	

Special Nett

1SET	PARKING AID
1SET	REAR BUMPER CLIP
1SET	BUMPER BRACKET CTR CLIP
1SET	BUMPER BRACKET SIDE CLIP RH RR
1SET	BUMEP R RETAINER RH CLIP RR
1SET	BUMEP R BRACKET SIDE CLIP LH RR
1SET	BUMEP R RETAINER CLIP LH RR
1SET	BUMPER LOWER REAR RIVET
1SET	BUMPER LOWER REAR CLIP
1	REAR DOOR STICKER '6555-3333'

\$	<i>Sn</i>	700.00	<i>X</i>
\$	<i>na</i>	66.00	<i>✓</i>
\$	<i>na</i>	33.00	<i>✓</i>
\$	<i>na</i>	10.00	<i>X</i>
\$	<i>na</i>	20.00	<i>X</i>
\$	<i>na</i>	10.00	<i>X</i>
\$	<i>na</i>	20.00	<i>X</i>
\$	<i>na</i>	22.00	<i>X</i>
\$	<i>na</i>	66.00	<i>X</i>
\$	<i>na</i>	80.00	<i>60sn</i>
TOTAL	\$	1,027.00	

Trans-cab Auto Services Pte Ltd

AAD1901-093

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 247P

TOTAL PARTS	\$	12,335.08
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	400
Putty and spray painting of the affected portion.	\$	3,000.00	660
To rust-proofing of the affected areas.	\$	170.00	~ X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	~ X
To check steering geometry and computer wheel alignment	\$	220.00	~ X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ X
To Check Electrical Lighting Concerned.	\$	170.00	15
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	~ X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	380.00	~ X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	~ X

TOTAL	\$	8,250.00
--------------	-----------	-----------------

Over All Total	\$	20,585.08
-----------------------	-----------	------------------

PART-BY-PART (REPAIR DAY)**10 DAYS**

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: