

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Withheld
61 days @?
Resurvey After Paint

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **12.01.2019**

Accident Date : 07.01.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mitsubishi Colt" Reg. No. SKA939G Claiming Against Your Insured Reg. No. SLR5816T			
1pc	Tailgate		855.00 N ✓
1pc	Tailgate Glass Moulding		22.00 N ✓
1pc	Tailgate Center Emblem		40.80 N ✓
1pc	Tailgate Badge "Colt"		38.00 N ✓
1pc	Tailgate Badge "Mivec"		45.00 N ✓
1pc	Tailgate "C&C"		60.00 N ✓
1pc	Tailgate Outer Handle		94.00 N ?
1pc	Tailgate Lock		185.00 N ✓
1pc	Tailgate Lock Catch		36.00 N ✓
1pc	Tailgate Weatherstrip		182.00 N 50%
1pc	Tailgate Trim Board		415.00 N ✓
10pcs	Tailgate Trim Board Clips	3.00	30.00 N ✓
1pc	Tailgate Inner Handle Grip		99.00 N ✓
1pc	Tailgate Central Locking Device		365.00 N ✓
1pc	Rear Number Plate Lamp		46.00 N ?
1pc	Rear Bumper		636.00 N ✓
10pcs	Rear Bumper Clips	3.00	30.00 N ✓
2pcs	Rear Bumper Brackets	30.00	60.00 N ✓
1pc	Rear Bumper Lower Lip Seal		35.00 N ✓
1pc	End Panel		467.00 N ?
1pc	End Panel Garnish		315.00 N ?
			4,055.80
1pc	Tailgate Glass Sealant		50.00 SN 40%
1pc	Tailgate Glass Sealer		30.00 SN ✓
1pc	Tailgate Glass Fastener		50.00 SN 30%
1pc	Rear Number Plate		45.00 SN ✓
1pc	Rear Bumper Reverse Sensor		280.00 SN x
1pc	Rear Bumper Lower Lip (Rally Art)		535.00 SN ✓
1pc	Spare Tyre Panel Sound Insulation		280.00 SN ?
	To Dismantle / Refit Tailgate Fittings / Ancillary Accessories		150.00 60%
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc		120.00 70%
	To Supply End Panel Joint Sealant		60.00 ?
		C/F	5,655.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 12.01.2019

Accident Date : 07.01.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Mitsubishi Colt" Reg. No. SKA939G Claiming Against Your Insured Reg. No. SLR5816T		
		B/F	5,655.80
	To Dismantle / Refit Tailgate Fittings / Ancillary Accessories <i>5/5/11</i>		160.00 <i>120</i>
	To Dismantle / Transfer Rear Spare Tyre Panel Inner Trims Boards / Garnish and Rear Fenders Inner Trims Boards / Garnish to Facilitate Repair		80.00 <i>60</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 <i>?</i>
	To Dismantle / Refit Rear Audio System, Power AMP and Rewing		200.00 <i>?</i>
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Spare Tyre Panel, Cnt, Weld End Panel and Parts Replacement		1,100.00 <i>?</i>
	To Respray Affected Areas		1,050.00 <i>800</i>
	Total :		<u>8,345.80</u>