

INS. CASE OWNER:

CC 6 / III 1900 0790, 4443/2

LKK:
IDAC:

Surveyor:

MARCONI

DOI:

ASSIGNMENT

14/1/19

Date / Time:

14/1/19

Registered in Meriton:

14/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJW 12632

Name of Insured:

400W J00 SEMA

Insured Tel No.:

HP:

14/1/19

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

SEOW EN TE 31/1/19

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MPLM100000059

Policy No.:

DISMPL001446

Make / Model:

Kia

Place of Accident:

PTE to normal

OI GIA REPORT: YES / NO - TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SKK 37560



INSRS:

WSP:

Tel:

Liability:

RMKS:

400W J00 SEMA



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

16/1/19
HARVEY

06/1/19 [W/14/1/19] [W/14/1/19] [W/14/1/19]

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: OCS

Repair Cost:

L16 \$515,000

(14 days) Reduction:

67 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 14-01-19

Confirm with: H0001

Email ☒ Call ☐

Final Liability:

\$ 100

(Agreed / Assessed) BOLA S/N No.:

20

If NO or B 28, Ass. Lia: 0%

Repair Cost:

\$515,000.00

6 VER CC OCS 200

Loss of Rental (LOR):

\$5 -

(1 days)

Loss of Use (LOU):

\$5 1,600.00

(\$ 100 x 16 days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

\$57.45

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost:

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 4600

Total:

\$516,601.45

Global Sum \$5:

FINAL PAYMENT

Date/Time: 12-01-19

Confirm with: H0001

Email ☒ Call ☐

Payee 1:

\$516,601.45

Name 1: OCS MORAL SPANISH PAPER

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

08/11/13

wed

REF:

ASS. REC. BY: MARIS

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKX37TDat Workshop m/s Choo m/s

of _____

Insured: SW 1263L

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 886

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKX37TD Yr Regn: 12/15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Toyota Camry cc 2494Colour: White A/C: _____ Insured / Std / NI / NASp. Reading: 64895 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053AK500-4010027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55-17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 12/1/19 D.O.I. 14/1/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

have been 4746370g by 15/1/19next 24/1/1922/1/19 1/5 to 15,000 confirmed with Abu.

(RED: 30,408.01 67%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC6/III19000790/Ueb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 14-01-2019	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJW 1263L		Veh. Inspected	SKX 3755D
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	14/01/2019
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/01/2019		Inspection Date	14/01/2019
Survey held at	CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVENUE 6 #01-39 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

Not Authorized
Date
14/1/19
L/S \$15.000
Amount \$5 14 day.

Qty Particular SKX3755D

List Item:

1PCS BOOTLID	no/suc	\$1091.70 ✓
1PCS BOOTLID REAR LOGO	me	\$61.80 ✓
1PCS BOOTLID 'CAMRY' EMBLEM	me	\$59.60 ✓
1PCS BOOTLID '2.5' EMBLEM	me	\$52.90 ✓
2PCS BOOTLID HINGES @\$190.80	2	\$381.60 ✓
1PCS BOOTLID INNER LOCK	two	\$409.10 ✓
1PCS BOOTLID LOCK CATCH	17	\$66.50 ✓
1PCS BOOTLID KEYLESS SMART	sluph	\$209.10 ✓
1PCS BOOTLID INNER TRIM 366.50	20/trim	\$429.90 ✓
1PCS BOOTLID OUTER GARNISH 388.10	one	\$529.10 ✓
1PCS BOOTLID WEATHERSTRIP	two	\$285.75 ✓
2PCS BOOTLID REFLECTORS @\$329.10	one	\$658.20 ✓
1PCS REAR WINDSCREEN MOULDING	17	\$130.90 ✓
2PCS REAR FENDERS @\$969.80	2	\$1939.60 ✓
2PCS REAR FENDER INNER TRIMS @\$343.40	20/trim	\$686.80 ✓
1SET REAR FENDER INNER TRIM CLIPS	me	\$50.00 ✓
2PCS REAR FENDER UNDER COVERS @\$229.85	17/one	\$459.70 17c
2PCS REAR FENDER INNER AIR VENTS @\$109.75	17	\$219.50 ✓
2PCS TAILLAMPS @\$389.80	one	\$779.60 ✓
1PCS Rear bumper lower cover	two	\$330.20 ✓
1PCS REAR BUMPER	17.5	\$468.30 ✓
1PCS REAR BUMPER REINFORCEMENT	17.5	\$326.40 ✓

(257)

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

Qty	Particular	Amount S\$
<u>List Item:</u>		
2PCS	REAR BUMPER REFLECTORS @\$59.80	msc 1119.60 1pc
2PCS	REAR BUMPER SIDE RETAINERS @\$48.15	set 96.30 ✓
1SET	REAR BUMPER CLIPS	rev 50.00 ✓
1PCS	REAR END PANEL	3.44m 509.80 —
1PCS	REAR END PANEL INNER MEMBER	2.44m 429.90 ✓
1PCS	REAR END PANEL TOP GARNISH	7m 481.10 ✓
1PCS	REAR FLOOR PANEL	crumpled/suc 991.70 ✓
1PCS	REAR FLOOR PANEL TOP BOARD	brn 391.70 ✓
1PCS	REAR EXHAUST SILENCER	2 691.75 X
2PCS	REAR EXHAUST SILENCER MOUNTINGS @\$48.50	11 97.00 X
1PCS	REAR EXHAUST HEAT SHIELD	11 188.10 X
1PCS	REAR floor panel tools sponge 650x10	brn 2391.80 ✓
1PCS	BONNET	2 1267.40 X
2PCS	BONNET HINGES @\$52.60	11 105.20 X
1PCS	BONNET INSULATOR	11 356.85 X
1SET	BONNET INSULATOR CLIPS	11 50.00 X
1PCS	BONNET LOCK	11 81.62 X
1PCS	BONNET RUBBER	11 66.90 X
1PCS	FRONT BUMPER	2/2 521.10 ✓
1PCS	FRONT BUMPER REINFORCEMENT	3.44 340.19 ✓
2PCS	FRONT BUMPER SIDE RETAINERS @\$65.10	3.44 130.20 ✓
1PCS	FRONT BUMPER sponge	brn 221.70 ✓
2PCS	FRONT BUMPER FOG LAMPS @\$348.45	2 696.90 ✓

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>List Item:</u>		
2PCS	FRONT BUMPER FOG LAMP COVERS @\$43.05	117 \$86.10 X
1PCS	FRONT BUMPER chrome moulding	Che \$115.10 /
1PCS	FRONT GRILLE	Che \$439.52 /
1PCS	FRONT GRILLE LOGO	ser \$59.60 /
2PCS	HEADLAMPS @\$3212.10 H/D 2443-80 x 2 = 4887.60	Che \$6424.20 /
1PCS	FRONT SUPPORT PANEL top garnish 366.40	De/tern \$911.50 /
1PCS	FRONT BRACE PANEL	Two \$89.90 /
1PCS	FRONT bumper centre grille 382.50	tern \$1551.88 /
1PCS	FRONT bumper licence plate holder 145.50	tern \$281.26 /
1SET	FRONT FENDER INNER SHIELD CLIPS	11 \$50.00 X
1PCS	AIRCON CONDENSER	11 \$1485.91 X
1PCS	AIRCON FAN MOTOR ASSY	11 \$489.50 X
1PCS	RADIATOR	11 \$1689.35 X
1PCS	RADIATOR FAN MOTOR	11 \$385.60 X
1PCS	RADIATOR FAN COWLING	11 \$125.60 X
1PCS	AIR CLEANER BOX	11 \$857.84 X
1PCS	WIPER TANK	11 \$96.45 X
2PCS	AIR CON CONDENSER SIDE GARNISHES @\$98.10	11 \$196.20 X
1PCS	FRONT HORN UNIT	11 \$89.50 X
List Item Total:		35,328.07
(252)		18570.51
		13882.88

Special Nett Item:

1SET REAR BUMPER REVERSE SENSOR

shd \$300.00 /

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

Qty	Particular	Amount S\$
-----	------------	------------

Special Nett Item:

1PCS	REAR END PANEL SEALANT	RM \$50.00 ✓
1PCS	REAR LICENCE PLATE	RM \$30.00 X
1PCS	REAR WINDSCREEN SEALANT	RM \$50.00 X
1PCS	REAR FLOOR PANEL INSULATOR	RM \$180.00 ✓
1PCS	FRONT LICENCE PLATE	RM \$30.00 ✓
1SET	FRONT BUMPER SENSOR	RM \$300.00 X
1BOL	RADIATOR COOLANT	RM \$50.00 X
Special Nett Total:		\$990.00

Labour Charge:

TO CHECK WIRING.	\$80.00 30
TO DISMANTLE & REPLACING REVERSE SENSOR.	\$100.00 50
TO TRANSFER BOOTLID COMPONENTS.	\$100.00 60
TO DISMANTLE & REFIX SEAT ,CUSHION ,UPHOLSTERY.	\$180.00 100
TO DISMANTLE & REFIX REAR WINDNSCREEN.	RM \$150.00 X
TO DISMANTLE & REPLACING REAR EXHAUST.	\$100.00 60
TO CONDUCT CHASSIS ALIGNMENT.	RM \$380.00 X
TO DISMANTLE & REFIX PETROL TANK.	\$150.00 60
TO SPRAY ANTI RUST PROOFING.	\$200.00 100
TO REFILL AIR CON GAS.	\$150.00 100
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.	\$4500.00 2000

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	9011J

Vehicle Details

Vehicle No.:	SKX3755D
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.5 AUTO
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	2ARU270726
Chassis No.:	MR053AK5004010027
Maximum Power Output:	133.0 kW (178 bhp)
Open Market Value:	\$28,170.00
Original Registration Date:	09 Dec 2015
First Registration Date:	09 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$31,438.00 15 Jan 19

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Dec 2025
PARF Rebate Amount:	\$23,578.00

Intended COE Rebate Details

COE Expiry Date:	08 Dec 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$40,130.00
Total Rebate Amount:	\$63,708.00

The information contained herein is correct as at 14 Jan 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

500+ dealers competed to buy my car!

Sell ur Car for More Cash

Highest Price or Get \$100 Free

Get Paid Now, Handover Later

SELL YOUR CAR

QUOTZ

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic Offer! Best Deal!Fast Selling!Hurry Down Now!

Flexible Loan, Trade In Are Welcome. 100% Refund For Unapproved Loan. Classic Credit StarAd

CERTIFIED PRE-OWNED MERCEDES-BENZ

view our cars

Browse by Category

Sort by Date Posted

20 results/page

5 vehicles

Camry 2.5A

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Camry 2.5A		Any	Any	2015	Any	Any	Any	Available
	Toyota	Camry 2.5A	\$85,800	\$10,260 /yr	11-Nov-2015	2,494 cc	37,332 km	Luxury	Available
Full Loan Available! Other Loan Packages From Bank/In House/Balloon Scheme Available With Most Attractive And 100% Fast Approval Rates! 5 Years Warranty! Low Mileage Done! Most Popular, Reliable And C...									
Le Motor Enterprise									
Posted: 11-Jan-2019 Tags: 2015 Toyota Camry, 2015 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota									
	Toyota	Camry 2.5A	\$86,800	\$10,690 /yr	07-Sep-2015	2,494 cc	28,327 km	Luxury	Available
\$2000 Republic Auto Warranty Workshop Credit, Agent Unit, Low Mileage, 1 Owner, Well Maintained, Enjoy Exclusive Interest Rates At 2.28%, 70% Loan, Please Call/SMS/Whatsapp Now For Enquiry And Viewing...									
Republic Auto									
Posted: 10-Jan-2019 Tags: 2015 Toyota Camry, 2015 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota									
	Toyota	Camry 2.5A	\$85,800	\$10,670 /yr	15-Jul-2015	2,494 cc	50,000 km	Luxury	Available
Price To Sell \$85800. At Atlantic, We Go Extra Miles On Service. Go With Nice Number Plate! 1 Owner Only! Reliable Executive Luxury Car. Fully Maintained By Borneo Motors And Comes With Valid Agent 5 ...									
Atlantic Automobile Pte Ltd									
Posted: 05-Jan-2019 Tags: 2015 Toyota Camry, 2015 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota									
	Toyota	Camry 2.5A	\$83,800	\$10,160 /yr	31-Aug-2015	2,494 cc	36,000 km	Luxury	Available
1 Careful Owner Luxurious Executive Car, Fully Maintain And Service At Borneo Motors, Under Agent Warranty Till 08/2020. 1 Of The Lowest Mileage Driven In The Market, STA Evaluation Can Be Arranged Fo...									
Stanse Automobile									
Posted: 30-Dec-2018 Tags: 2015 Toyota Camry, 2015 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota									
	Toyota	Camry 2.5A	\$83,750	\$11,050 /yr	23-Mar-2015	2,494 cc	56,000 km	Luxury	Available
Best Features And Highest Specs In The Camry Family. Meticulously Taken Care Of By Owner. Condition Like New. Plastic Covers Still On. Original Mat Still Like New.									
Posted: 03-Dec-2018 Tags: 2015 Toyota Camry, 2015 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

https://www.sgcarmart.com/used_cars/listing.php?RGD=2015&MOD=Camry 2.5A&RPG=20&VEH=0... 14-Jan-19

sgCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Camry 2.5A

Price Range

Depreciation

2015

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Republic Auto » Toyota Camry 2.5A

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres

EAGLE® F1 Asymmetric J SUV

STAY IN CONTROL

W/ GRIP BOOSTER TECHNOLOGY

Toyota Camry 2.5A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Republic

Auto Pte Ltd

A member of the Jardine Cycle & Carriage Group

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price

\$86,800

Depreciation

\$10,690 /yr

View models with similar depreciation

Reg Date

07-Sep-2015

(6yrs 7mths 23days COE left)

Manufactured

2015

Mileage

28,327 km (8.4k /yr)

Transmission

Auto

Engine Cap

2,494 cc

Road Tax

\$1,792 /yr

Power

133.0 kW (178 bhp)

View specs of the Toyota Camry (2012-2015)

Curb Weight

1,475 kg

Features

2.5L 4 Cylinder Inline 16 Valve DOHC With VVT-i, 6-Speed Super ECT, 178Bhp, Keyless Entry/Start, HID Lights, Cruise Control, Airbags, ABS, HAC.

Accessories

Factory Fitted Audio System, Reverse Camera, Bluetooth, Driver Memory Seat, Rear Electric Blind, Sport Rims, Recording Camera, Auto Wiper/headlamp

Description

\$2000 Republic Auto Warranty Workshop Credit, Agent Unit, Low Mileage, 1 Owner, Well Maintained, Enjoy Exclusive Interest Rates At 2.28%, 70% Loan, Please Call/SMS/Whatsapp Now For Enquiry And Viewing Appointment.

COE

\$62,140

OMV

\$28,170

ARF

\$31,438

Dereg Value

\$64,897 as of today (change)

No. of Owners

1

Type of Veh

Luxury Sedan

Category

PAFF Car, Low Mileage Car

Availability

Available

Location Map

Price Analysis

Seller Information

Company

Republic Auto

+ dealer's pricelist

+ 186 vehs sold | 94 vehs available

Address

209 Pandan Gardens Level 3

Search cars nearby this location

Location

Cycle & Carriage Complex

Office No

65672000

Contact Person(s)

Evangeline Tan

98819889

Choose the speed you need

Show more

Complete

https://www.sgcarmart.com/used_cars/info.php?ID=795862&DL=1213

14-Jan-19

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7509011J



Name
**TAN THIAM SOON
(CHEN TIANSHUN)**

陈添顺

Race
CHINESE

Date of birth
22-02-1975 Sex **M**

Country of birth
SINGAPORE

S7509011J

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7509011J**



Name
**TAN THIAM SOON
(CHEN TIANSHUN)**

Birth Date **22 Feb 1975**

Valid Until **02 Dec 2004**



801303173G



3889087



NRIC No. **S7509011J**

Date of issue
17-03-2006

**381 CHOA CHU KANG AVENUE 3 #05-23
SINGAPORE 888884**

NRIC No. **S7509011J** Date: **18/08/2018**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

VALID DATE

Class 3 Motor cars $\leq$ 3000 kg with $\leq$ 7 passengers, exclusive of the driver, and motor tractors / vehicles $\leq$ 2500 kg

02 Dec 2004



Licence No: S7509011J

NP 428A



Name of Policyholder : Tan Thiam Soon (Chen Tianshun)
Period of Insurance : 09 Dec 2018 To 08 Dec 2019
Engine No. : 2ARU270726
Chassis No. : MR053AK5004010027

Vehicle No. : SKX3755D
Policy No. : 2100439797-03
Endorsement No. :
Issued Date : 03 Dec 2018

Make/Model : TOYOTA NEW CAMRY 2.5
Engine Capacity/Tonnage : 2,494.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2015
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 169) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Section 1
Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreens : \$100

Named Driver and Excess (where applicable)

Tan Thiam Soon (Chen Tianshun) - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OCBC Bank Ltd

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 185), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0030210000

AIG ASIA PACIFIC INSURANCE PL
78 SHENTON WAY #07-16 AIG BUILDING
SINGAPORE 079120

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manila

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

00000000

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	9011J

Vehicle Details

Vehicle No.:	SKX3755D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.5 AUTO
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	2ARU270726
Chassis No.:	MR053AK5004010027
Maximum Power Output:	133.0 kW (178 bhp)
Open Market Value:	\$28,170.00
Original Registration Date:	09 Dec 2015
First Registration Date:	09 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$31,438.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Dec 2025
PARF Rebate Amount:	\$23,578.00

Intended COE Rebate Details

COE Expiry Date:	08 Dec 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$40,146.00
Total Rebate Amount:	\$63,724.00

The information contained herein is correct as at 14 Jan 2019

OK

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 22736900M

Date : 22.02.2019

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

Attn: Motor Claim Department

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES : SKX 3755D / SJW 1263L AND OTHER ON 12.01.2019

We are the authorized repair workshop for the owner of motor vehicle no: **SKX 3755D**, which was involved in the captioned accident with your insured vehicle no: **SJW 1263L**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair	\$ 15,000.00
2) Loss of Use (14 days + 2 Sunday x S\$100.00)	\$ 1,600.00
3) LTA search fee	\$ 7.45
	<u>\$ 16,607.45</u>

We enclosed herewith the following documents to support the claims:

- | | |
|------------------------------------|--------------------------|
| a) Final Repair Invoice | b) LTA Search Result |
| c) Letter of Authorisation, etc... | d) GIA Report |
| e) I/C & Driving Licence | f) Insurance Certificate |
| g) Vehicle Registration Log Card | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)

For Choo Motor Spray Painter

DATE : 12.01.2019

TO : India International Insurance Pte Ltd

RE : ACCIDENT INVOLVING VEHICLE NO. Skx 375517 / 8JW1263L
And other

ALONG PIE Towards Changi

ON 12.01.2019

I/We, Tan Thiam Soon

of (NRIC No./ROC No.) 87509011J

of 361 Choa Chu Kang Avenue 3 #05-23 Singapore 689884

owner of vehicle no. Skx 375517 in consideration of M/s **CHOO MOTOR SPRAY PAINTER** repairing my/our vehicle Skx 375517 at my/our instruction and hereby authorise M/s **CHOO MOTOR SPRAY PAINTER** to demand claim settle receive whatever amount settled/payable by the Insurance Company and/or third party or to commence legal proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use, etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the abovementioned claim cost which may arise therewith.

Signature of Owner :



Name of Owner :

Tan Thiam Soon

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MPC2019D0000059
Claimant Ref: SKX 3755D

*** This Discharge Voucher applies only to the claimant's claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein should not be used as an evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.

We/I, CHOO MOTOR SPRAY PAINTER ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 15,000.00 (repair cost), S\$ 1,600.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SKX 3755D that was damaged pursuant to the accident which occurred on 12/01/2019 (date) at PIE TWDS CHANIR (location) involving vehicle no. SJW 1263L (insured vehicle). This is pursuant to the inspection conducted on 14/01/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN THIAM SOON (CHEN TIANSHUN) ("the third party claimant") of vehicle no. SKX 3755D to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKX 3755D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 16,607.45 to CHOO MOTOR SPRAY PAINTER

Dated this 15 day of Apr 20 19

CLAIMANT:

Signature: [Signature]

Name: TANG JUN ZHONG

NRIC: S8704986H

Address: 1 Kaki Bukit Avenue 6, #01-46/48/50

Nationality:

Occupation:

Signed by "the workshop" (with stamp)

TANG JUN ZHONG
S8704986H
1 Kaki Bukit Avenue 6, #01-46/48/50
AutoBay, Singapore 417883
Tel: 6746 5405 / 6745 2063 Fax: 6745 8520
Email: general@fastechauto.com.sg

WITNESS:

Signature: [Signature]

Name: LKK AUTO CONSULTANTS PTE LTD

NRIC: 199907198R

Address: 51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

Nationality:

Occupation:



CKS

Signed by appointed Surveyor

TAX INVOICE

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 22736900M

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Attn : Motor Claim Department

Tax Invoice : 20813

Date : 22.02.2019
Vehicle No : SKX 3755D
Make/Model : TOYOTA CAMRY
Chassis/Eng# :
Accident Date : 12.01.2019
Claim No :
Reference : 0119 -20813
Policy No :

		Amount
To proceed on lump sum repair	S\$	15000.00

E. & O. E.

Total : S\$

15000.00


for CHOO MOTOR SPRAY PAINTER

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 14 Jan 2019 / 09:08:57

Receipt Date/Time : 14 Jan 2019 / 09:08:57

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190114-000269

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SJW1263L As at 12 Jan 2019/12:40:00 Insurance Co: INDIA INT'L INS PTE LTD			
1	Insurance Enquiry - SJW1263L Enquiry Fee 20190114090804701592	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20190114090820919		Direct Debit: eNETS Debit (Internet Banking)	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jan 2019		14 Jan 2019 00:00	\$S15,000.00	\$S15,000.00 View Rpt		Pending for Survey Report

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SEOW JOO SENG , ID: -								
Main Claimant:	TAN THIAM SOON (CHEN TIANSHUN) , ID: S75090111								
Vehicle Reg. No.:	SKX3755D	Date of Loss:	12/01/2019 00:00 - :59 [37 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MPC2019D0000059	Policy/Cover Note No.:	D18MPC0001446						
Vehicle Reg. No. (Insured):	SJW1263L	Policy No. (Claimant):	2100439797-03						
		Excess:							
Repairer:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67453897								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (26/03/2019): Alert - Adj Mandate Approved (\$S16607.45) - SKX3755D - Claim Handler: C. Meenach... - III_SG (28/01/2019): Alert - Adj Mandate Approved (\$S0.00) - SKX3755D - Claim Handler: C. Meenachi									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX3755D (MPC2019D0000059)
[SJW1263L]
TP
TAN THIAM SOON (CHEN TIANSHUN)
Jan 12 2019 12:00AM
[SEOW JOO SENG]
Choo Motor Spray Painter

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	25/03/19 12:41	Odometer Reading					Load JPG	☒	
2	25/03/19 12:41	Chassis Number					Load JPG	☒	
3	25/03/19 12:41	General View					Load JPG	☒	
4	25/03/19 12:41	General View					Load JPG	☒	
5	25/03/19 12:41	General View					Load JPG	☒	
6	25/03/19 12:41	General View					Load JPG	☒	
7	25/03/19 12:41	General View					Load JPG	☒	
8	25/03/19 12:41	General View					Load JPG	☒	
9	25/03/19 12:41	General View					Load JPG	☒	
10	25/03/19 12:41	General View					Load JPG	☒	
11	25/03/19 12:41	General View					Load JPG	☒	
12	25/03/19 12:41	General View					Load JPG	☒	
13	25/03/19 12:41	General View					Load JPG	☒	
14	25/03/19 12:41	General View					Load JPG	☒	
15	25/03/19 12:41	General View					Load JPG	☒	
16	25/03/19 12:41	General View					Load JPG	☒	
17	25/03/19 12:41	General View					Load JPG	☒	
18	25/03/19 12:41	General View					Load JPG	☒	
19	25/03/19 12:41	General View					Load JPG	☒	
20	25/03/19 12:41	General View					Load JPG	☒	
21	25/03/19 12:41	General View					Load JPG	☒	
22	25/03/19 12:41	General View					Load JPG	☒	
23	25/03/19 12:41	General View					Load JPG	☒	
24	25/03/19 12:41	General View					Load JPG	☒	
25	25/03/19 12:41	General View					Load JPG	☒	
26	25/03/19 12:41	General View					Load JPG	☒	
27	25/03/19 12:41	General View					Load JPG	☒	
28	25/03/19 12:41	General View					Load JPG	☒	
29	25/03/19 12:41	General View					Load JPG	☒	
30	25/03/19 12:41	General View					Load JPG	☒	
31	25/03/19 12:41	General View					Load JPG	☒	
32	25/03/19 12:41	General View					Load JPG	☒	
33	25/03/19 12:41	General View					Load JPG	☒	
34	25/03/19 12:41	General View					Load JPG	☒	
35	25/03/19 12:41	General View					Load JPG	☒	
36	25/03/19 12:41	General View					Load JPG	☒	
37	25/03/19 12:41	General View					Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/03/19 12:41	General View	 Load JPG	☒
39	25/03/19 12:41	General View	 Load JPG	☒
40	25/03/19 12:41	General View	 Load JPG	☒
41	25/03/19 12:41	General View	 Load JPG	☒
42	25/03/19 12:41	General View	 Load JPG	☒
43	25/03/19 12:41	General View	 Load JPG	☒
44	25/03/19 12:41	General View	 Load JPG	☒
45	25/03/19 12:41	General View	 Load JPG	☒
46	25/03/19 12:41	General View	 Load JPG	☒
47	25/03/19 12:41	General View	 Load JPG	☒
48	25/03/19 12:41	General View	 Load JPG	☒
49	25/03/19 12:41	General View	 Load JPG	☒
50	25/03/19 12:41	General View	 Load JPG	☒
51	25/03/19 12:41	General View	 Load JPG	☒
52	25/03/19 12:41	General View	 Load JPG	☒
53	25/03/19 12:41	General View	 Load JPG	☒
54	25/03/19 12:41	General View	 Load JPG	☒
55	25/03/19 12:41	General View	 Load JPG	☒
56	25/03/19 12:41	General View	 Load JPG	☒
57	25/03/19 12:41	General View	 Load JPG	☒
58	25/03/19 12:41	General View	 Load JPG	☒
59	25/03/19 12:41	General View	 Load JPG	☒
60	25/03/19 12:41	General View	 Load JPG	☒
61	25/03/19 12:41	General View	 Load JPG	☒
62	25/03/19 12:41	General View	 Load JPG	☒
63	25/03/19 12:41	General View	 Load JPG	☒
64	25/03/19 12:41	General View	 Load JPG	☒
65	25/03/19 12:41	General View	 Load JPG	☒
66	25/03/19 12:41	General View	 Load JPG	☒
67	25/03/19 12:41	General View	 Load JPG	☒
68	25/03/19 12:41	General View	 Load JPG	☒
69	25/03/19 12:41	General View	 Load JPG	☒
70	25/03/19 12:41	General View	 Load JPG	☒
71	25/03/19 12:41	General View	 Load JPG	☒
72	25/03/19 12:41	General View	 Load JPG	☒
73	25/03/19 12:41	General View	 Load JPG	☒
74	25/03/19 12:41	General View	 Load JPG	☒
75	25/03/19 12:41	General View	 Load JPG	☒
76	25/03/19 12:41	General View	 Load JPG	☒
77	25/03/19 12:41	General View	 Load JPG	☒
78	25/03/19 12:41	General View	 Load JPG	☒
79	25/03/19 12:41	General View	 Load JPG	☒
80	25/03/19 12:41	General View	 Load JPG	☒
81	25/03/19 12:41	General View	 Load JPG	☒
82	25/03/19 12:41	General View	 Load JPG	☒
83	25/03/19 12:41	General View	 Load JPG	☒
84	25/03/19 12:41	General View	 Load JPG	☒
85	25/03/19 12:41	General View	 Load JPG	☒
86	25/03/19 12:41	General View	 Load JPG	☒
87	25/03/19 12:41	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	25/03/19 12:41	General View		☒
89	25/03/19 12:41	General View		☒
90	25/03/19 12:41	General View		☒
91	25/03/19 12:41	General View		☒
92	25/03/19 12:41	General View		☒
93	25/03/19 12:41	General View		☒
94	25/03/19 12:41	Reinspection Photo		☒
95	25/03/19 12:41	Reinspection Photo		☒
96	25/03/19 12:41	Reinspection Photo		☒
97	25/03/19 12:41	Reinspection Photo		☒
98	25/03/19 12:41	Reinspection Photo		☒
99	25/03/19 12:41	Reinspection Photo		☒
100	25/03/19 12:41	Reinspection Photo		☒
101	25/03/19 12:41	Reinspection Photo		☒
102	25/03/19 12:41	Reinspection Photo		☒
103	25/03/19 12:41	Reinspection Photo		☒
104	25/03/19 12:41	Reinspection Photo		☒
105	25/03/19 12:41	Reinspection Photo		☒
106	25/03/19 12:41	Reinspection Photo		☒
107	25/03/19 12:41	Reinspection Photo		☒
108	25/03/19 12:41	Reinspection Photo		☒
109	25/03/19 12:41	Reinspection Photo		☒
110	25/03/19 12:41	Reinspection Photo		☒
111	25/03/19 12:41	Reinspection Photo		☒
112	25/03/19 12:41	Reinspection Photo		☒
113	25/03/19 12:41	Reinspection Photo		☒
114	25/03/19 12:41	Reinspection Photo		☒
115	25/03/19 12:41	Reinspection Photo		☒
116	25/03/19 12:46	Reinspection Photo		☒
117	25/03/19 12:46	Reinspection Photo		☒
118	25/03/19 12:46	Reinspection Photo		☒
119	25/03/19 12:46	Reinspection Photo		☒
120	25/03/19 12:46	Reinspection Photo		☒
121	25/03/19 12:46	Reinspection Photo		☒
122	25/03/19 12:46	Reinspection Photo		☒
123	25/03/19 12:46	Reinspection Photo		☒
124	25/03/19 12:46	Reinspection Photo		☒
125	25/03/19 12:46	Reinspection Photo		☒
126	25/03/19 12:46	Reinspection Photo		☒
127	25/03/19 12:46	Reinspection Photo		☒
128	25/03/19 12:46	Reinspection Photo		☒
129	25/03/19 12:46	Reinspection Photo		☒
130	25/03/19 12:46	Reinspection Photo		☒
131	25/03/19 12:46	Reinspection Photo		☒
132	25/03/19 12:46	Reinspection Photo		☒
133	25/03/19 12:46	Reinspection Photo		☒
134	25/03/19 12:47	Reinspection Photo		☒
135	25/03/19 12:47	Reinspection Photo		☒
136	25/03/19 12:47	Reinspection Photo		☒
137	25/03/19 12:47	Reinspection Photo		☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
139	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
140	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
141	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
142	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
143	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
144	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
145	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
146	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
147	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
148	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
149	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
150	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
151	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
152	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
153	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
154	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
155	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
156	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
157	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
158	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
159	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
160	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
161	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
162	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
163	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
164	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
165	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
166	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
167	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
168	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
169	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
170	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
171	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
172	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
173	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
174	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
175	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
176	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
177	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
178	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
179	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
180	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
181	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
182	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
183	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
184	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
185	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
186	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
187	25/03/19 12:47	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
188	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
189	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
190	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
191	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
192	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
193	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
194	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
195	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
196	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
197	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
198	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
199	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
200	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
201	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
202	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
203	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
204	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
205	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
206	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
207	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
208	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
209	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
210	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
211	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
212	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
213	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
214	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
215	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
216	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
217	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
218	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
219	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
220	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
221	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
222	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
223	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
224	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
225	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
226	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
227	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
228	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
229	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
230	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
231	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
232	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
233	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
234	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
235	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
236	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
237	25/03/19 12:47	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
238	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
239	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
240	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
241	25/03/19 12:47	Reinspection Photo	 Load JPG	☒
242	25/03/19 12:47	Photo After Spray	 Load JPG	☒
243	25/03/19 12:47	Photo After Spray	 Load JPG	☒
244	25/03/19 12:47	Photo After Spray	 Load JPG	☒
245	25/03/19 12:47	Photo After Spray	 Load JPG	☒
246	25/03/19 12:47	Photo After Spray	 Load JPG	☒
247	25/03/19 12:47	Photo After Spray	 Load JPG	☒
248	25/03/19 12:47	Photo After Spray	 Load JPG	☒
249	25/03/19 12:47	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/01/19 19:03	TP GIA REPORT	 Load PDF	
2	21/03/19 14:13	LTA SEARCH	 Load PDF	
3	21/03/19 14:13	LOD	 Load PDF	
4	21/03/19 14:13	WORKSHOP INVOICE	 Load PDF	
5	10/05/19 11:09	DISCHARGE VOUCHER	 Load PDF	
6	10/05/19 11:09	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	15/01/19 08:59	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19000790/UEB3Q2

Date: 10/05/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MPC0001446
Claimant Vehicle No :	SKX3755D	Insured Vehicle No :	SJW1263L
Date of Loss:	12/01/2019	Nature of Claim:	TP
		Claim No:	MPC2019D0000059

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX3755D	Engine No:	2ARU270726
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053AK5004010027
Reg. Date:	09/12/2015 (Man. Year: 2015)	Odometer:	64895 km
Colour:	White		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,318.07	14,442.88	21,875.19	60.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,090.00	4,360.00	4,730.00	52.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,408.07	18,802.88	26,605.19	58.59
Approved Total (Overridden) (S\$)		15,000.00		
Nett Amount (S\$)	45,408.07	15,000.00	30,408.07	66.97
+ Loss of Use (16.0 x S\$100.00/day) (S\$)		1,600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		16,607.45		

INSPECTION

Date of Assignment:	14/01/2019	
Date Inspected:	14/01/2019 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883

Estimated Period of Repair: 14.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2019)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX3755D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	1,091.70 F	*1,091.70 FL
2	1		*BOOTLID REAR LOGO	Necessary	61.80 F	*61.80 FL
3	1		*BOOTLID CAMRY EMBLEM	Necessary	59.60 F	*59.60 FL
4	1		*BOOTLID 2.5 EMBLEM	Necessary	52.90 F	*52.90 FL
5	2		*BOOTLID HINGES	Repair	381.60 F	*- FL
6	1		*BOOTLID INNER LOCK	Twisted	409.10 F	*409.10 FL
7	1		*BOOTLID LOCK CATCH	Not Necessary	66.50 F	*- FL
8	1		*BOOTLID KEYLESS SMART	Shorted	209.10 F	*209.10 FL
9	1		*BOOTLID INNER TRIM	Deformed / Torn	429.90 F	*366.50 FL
10	1		*BOOTLID OUTER GARNISH	Cracked	529.10 F	*388.10 FL
11	1		*BOOTLID WEATHERSTRIP	Twisted	285.75 F	*285.75 FL
12	2		*BOOTLID REFLECTORS	Cracked	658.20 F	*658.20 FL
13	1		*REAR WINDSCREEN MOULDING	Not Necessary	130.90 F	*- FL
14	2		*REAR FENDERS	Repair	1,939.60 F	*- FL
15	2		*REAR FENDER INNER TRIMS	Deformed / Torn	686.80 F	*686.80 FL
16	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 F	*50.00 FL
17	1		*REAR FENDER UNDER COVERS	N/S Deformed	459.70 F	*229.85 FL
18	2		*REAR FENDER INNER AIR VENTS	Not Necessary	219.50 F	*- FL
19	2		*TAILLAMPS	Cracked	779.60 F	*779.60 FL
20	1		*REAR BUMPER LOWER COVER	Torn	330.20 F	*330.20 FL
21	1		*REAR BUMPER	Distorted	468.30 F	*468.30 FL
22	1		*REAR BUMPER REINFORCEMENT	Distorted	326.40 F	*326.40 FL
23	1		*REAR BUMPER REFLECTORS	N/S Cracked	119.60 F	*59.80 FL
24	2		*REAR BUMPER SIDE RETAINERS	Bent	96.30 F	*96.30 FL
25	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
26	1		*REAR END PANEL	Badly Dented	509.80 F	*509.80 FL
27	1		*REAR END PANEL INNER MEMBER	Badly Dented	429.90 F	*429.90 FL
28	1		*REAR END PANEL TOP GARNISH	Twisted	481.10 F	*481.10 FL
29	1		*REAR FLOOR PANEL	Crumpled / Buckled	991.70 F	*991.70 FL
30	1		*REAR FLOOR PANEL TOP BOARD	Torn	391.70 F	*391.70 FL
31	1		*REAR EXHAUST SILENCER	Repair	691.75 F	*- FL
32	2		*REAR EXHAUST SILENCER MOUNTINGS	Not Necessary	97.00 F	*- FL
33	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	188.10 F	*- FL
34	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	2,391.80 F	*650.10 FL
35	1		*BONNET	Repair	1,267.40 F	*- FL
36	2		*BONNET HINGES	Not Necessary	105.20 F	*- FL
37	2		*BONNET INSULATOR	Not Necessary	356.85 F	*- FL
38	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
39	1		*BONNET LOCK	Not Necessary	81.62 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*BONNET RUBBER	Not Necessary	66.90 F	*- FL
41	1		*FRONT BUMPER	Dented / Deformed	521.10 F	*521.10 FL
42	1		*FRONT BUMPER REINFORCEMENT	Bent	340.19 F	*340.19 FL
43	2		*REAR BUMPER SIDE RETAINERS	Bent	130.20 F	*130.20 FL
44	1		*FRONT BUMPER SPONGE	Torn	221.70 F	*221.70 FL
45	2		*FRONT BUMPER FOG LAMPS	Cracked	696.90 F	*696.90 FL
46	2		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	86.10 F	*- FL
47	1		*FRONT BUMPER CHROME MOULDING	Cracked	115.10 F	*115.10 FL
48	1		*FRONT GRILLE	Cracked	439.52 F	*439.52 FL
49	1		*FRONT GRILLE LOGO	Necessary	59.60 F	*59.60 FL
50	2		*HEADLAMPS	Cracked	6,424.20 F	*4,887.60 FL
51	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed / Torn	911.50 F	*366.40 FL
52	1		*FRONT BRACE PANEL	Twisted	89.90 F	*89.90 FL
53	1		*FRONT BUMPER CENTRE GRILLE	Torn	1,551.88 F	*382.50 FL
54	1		*FRONT BUMPER LICENCE PLATE HOLDER	Torn	281.26 F	*145.50 FL
55	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 F	*- FL
56	1		*AIRCON CONDENSER	Not Necessary	1,485.91 F	*- FL
57	1		*AIRCON FAN MOTOR ASSY	Not Necessary	489.50 F	*- FL
58	1		*RADIATOR	Not Necessary	1,689.35 F	*- FL
59	1		*RADIATOR FAN MOTOR	Not Necessary	385.60 F	*- FL
60	1		*RADIATOR FAN COWLING	Not Necessary	125.60 F	*- FL
61	1		*AIR CLEANER BOX	Not Necessary	857.84 F	*- FL
62	1		*WIPER TANK	Not Necessary	96.45 F	*- FL
63	2		*AIR CON CONDENSER SIDE GARNISHES	Not Necessary	196.20 F	*- FL
64	1		*FRONT HORN UNIT	Not Necessary	89.50 F	*- FL
65	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*300.00 FS
66	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
67	1		*REAR LICENCE PLATE	Serviceable	30.00 FS	*- FS
68	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
69	1		*REAR FLOOR PANEL INSULATOR	Necessary	180.00 FS	*180.00 FS
70	1		*FRONT LICENCE PLATE	Bent	30.00 FS	*30.00 FS
71	1		*SET FRONT BUMPER SENSOR	Not Necessary	300.00 FS	*- FS
72	1		*BOL RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	36,318.07	19,070.51
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	4,627.63
Total Parts (\$\$)	36,318.07	14,442.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	100.00	50.00
3	TO TRANSFER BOOTLID COMPONENTS	New	100.00	60.00
4	TO DISMANTLE & REFIX SEAT ,CUSHION ,UPHOLSTERY	New	180.00	100.00
5	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
6	TO DISMANTLE & REPLACING REAR EXHAUST	New	100.00	60.00
7	TO CONDUCT CHASSIS ALIGNMENT	New	380.00	0.00
8	TO DISMANTLE & REFIX PETROL TANK	New	150.00	60.00
9	TO SPRAY ANTI RUST PROOFING	New	200.00	100.00
10	TO REFILL AIR CON GAS	New	150.00	100.00
11	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS	New	4,500.00	2,000.00
12	TO PUTTY & SPRAY PAINTING	New	3,000.00	1,800.00
Gross Labour Cost (\$\$)			9,090.00	4,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >