

SERVICE ESTIMATE

97296 - C00001 SL: SERVICE SALES - PC

Mr Chin Mun Leong

818a Choa Chu Kang Ave 1

#18-108

Singapore 681818

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 28/02/2019

WIP No. : 56401

Veh.In/Out:

*Tel.No. : Mobile: 96986509

Reg.No. : SKQ4505P

Reg.date : 28/11/2014

Mileage : 0

Chassis No: VF1LZLF0E51746547

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Chin Mun Leong

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER, FRT BRACKET, ETC.	0		1350.00	0		1,350.00 S	450.
800	TO PUTTY SPRAY PAINT ON FRT BUMPER, ETC	0		800.00	0		800.00 S	400
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0		330.00	0		330.00 S	✓
	BUMPER FRT RADAR 2/3	1.0	EA	874.50			874.50 S	Rx
	BUMPER BRACKET FRT L	1.0	EA	167.80			167.80 S	?
	BUMPER BRACKET FRT R	1.0	EA	167.30			167.30 S	?
	AIR GRILLE LOWER FRT	1.0	EA	318.50			318.50 S	x
	FOG LAMP TRIM OUTER	1.0	EA	315.40			315.40 S	x
	FOG LAMP OUTER TRIM	1.0	EA	95.50			95.50 S	✓
	RETAINER BUMPER FRT	1.0	EA	87.50			87.50 S	x
	BUMPER FRT AIR GRILL	1.0	EA	296.00			296.00 S	x
	BUMPER FRT GRILLA TO REINFORCEMENT FRT M3	1.0	EA	320.90			320.90 S	x
		1.0	EA	618.10			618.10 S	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanji 97495744
4/3/18 1045
03days 'wp'
tanji@lkkauto.com
sw@lkkauto.com

SERVICE ESTIMATE

97296 - C00001 SL: SERVICE SALES - PC

Mr Chin Mun Leong
818a Choa Chu Kang Ave 1
#18-108

Singapore 681818

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Chin Mun Leong

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 28/02/2019
WIP No. . : 56401
Veh.In/Out:
*Tel.No. . : Mobile: 96986509
Reg.No. . : SKQ4505P
Reg.date. : 28/11/2014
Mileage . : 0
Chassis No: VF1LZLF0E51746547

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	HEADLAMP RH L332 / L	1.0 EA	467.50			467.50	SX
	HEADLAMP LH L332 / L	1.0 EA	467.50			467.50	SX
	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10	SX

			Gross Total.	7,225.60
Labour Total	2,480.00	Net.....	7,225.60	
Parts Total	4,745.60	GST @ 7.0%	505.79	
Package Total	0.00	Total.....	7,731.40	
			Paid.....	0.00
			Please Pay..	7,731.40

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated