

INS. CASE OWNER:

Lynnkhoy. cc 4, Asm 1900 0795, T1 ea 357 LKK: 92876 IDAC: 92876

Toufikh

ASSIGNMENT

DOI: 14/1/19

Date/Time: 14.1.19

Registered in Merit: -

Pre-assign / CCU / FTE



Insured Vehicle No. : SLV 32494

Name of Insured : SLOW CHRON GMA

Insured Tel No. : _____

HP: _____

Excess Sec II :SS _____

D.O.A: 11.1.19

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident : _____

If NO, Driver Name / Age : _____

Driver Tel No. : _____

(V/L: YES / NO)

Claim No. : 59m01A3L

Policy No. : _____

Make / Model : _____

Place of Accident : _____

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability : % Final ? Yes / No

SME 6148m



INSRS: WSP: Tel: Liability: RMKS:

1 cah motor



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
17/1/19	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	24/1/19
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

29/6/19

PLS see VIEWS

19/8/19

File -> MC tu ctus

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	\$\$	(days) Reduction: %
FINAL SETTLEMENT	Date/Time: 27/8/19	Confirm with: Desmuel
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. : 27.
Repair Cost:	u/gst \$1338.79	
Loss of Rental (LOR):	u/gst \$1070.00	(10 days) X \$110
Loss of Use (LOU):	\$\$ - (\$ x days)	
Loss of Income (LOI):	\$\$ - (\$ x days)	
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	(Tick only one)
GIA/LTA Search	\$\$ -	
Medical:	\$\$ -	
Disbursement:	\$\$ -	(e.g. Tow/ Independent)
Legal Cost	\$\$ -	
Total:	SS 14208.79	Global Sum SS:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS 14208.79	Name 1: Cah Motor Co sdn Bhd
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

COPY SENT 27/8/19

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: C/P
- 3) Survey fee: \$350.00

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5344F
Vehicle Details	
Vehicle No.:	SME6148M
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	R16B25501979
Chassis No.:	MRHFC5650JT001711
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,645.00
Original Registration Date:	08 Oct 2018
First Registration Date:	08 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$20,903.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Oct 2028
PARF Rebate Amount:	\$15,677.00
Intended COE Rebate Details	
COE Expiry Date:	07 Oct 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,997.00
COE Rebate Amount:	\$31,123.00
Total Rebate Amount:	\$46,800.00

The information contained herein is correct as at 15 Jan 2019

OK



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

Registration No : SME6148M

Chassis No : MRHFC5650JT001711

Model : CIVIC 1.6 VTI YM2018

Owner's Name : CAESIAPEAH LIM GUEK NGOR

Ins Policy No. :

Date of Accident : 11/1/2019

Document No. : SQT19000197

Date : 11. Jan 2019

Customer No. : WZA006

Svc Advisor : NG SIN HAI

Engine No : R16B25501979

Date | Time : 11. Jan 2019 8:58:39 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:CAESIAPEAH LIM GUEK NGOR OWNER INSURER:AVIVA ACC DATE:11/01/2019 SURVEYED BY: DATE: REF NO: TP INSURER:AXA TP VEH:SLV3249Y						
66100-TEC-307ZZ	PANEL SETRR.	bt 1	243.10	25	182.32	12.76	195.08
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	de 1	26.70	25	20.02	1.40	21.42
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	de 1	26.70	25	20.02	1.40	21.42
68500-TEA-N00ZZ	LID COMP TRUNK	bt 1	486.20	25	364.65	25.53	390.18
74865-TEA-T01	WEATHERSTRIPTRUNK LID	tu 1	70.00	25	52.50	3.68	56.18
74851-TEA-003	LOCK ASSYTRUNK	bt 1	74.30	25	55.72	3.90	59.62
74862-TEA-003	STRIKERTRUNK LID	nn x 1	7.10	25	5.32	0.37	5.69
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	de 1	100.60	25	75.45	5.28	80.73
75701-TBA-A10	EMBLEM,H-MARK	ne 1	12.20	25	9.15	0.64	9.79
90301-ST0-003	NUTPUSH 3MM	ne 2	2.10	25	3.15	0.22	3.37
75722-TBA-A00	EMBLEM SETRR.	ne 1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	EMBLEMRR.	ne 1	11.00	25	8.25	0.58	8.83
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	de 1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	de 1	36.40	25	27.30	1.91	29.21
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	bt 1	164.70	25	123.52	8.65	132.17
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	nn x 1	2.30	25	1.72	0.12	1.84
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	ne 1	2.30	25	1.72	0.12	1.84
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	ne 1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	ne 1	11.50	25	8.62	0.60	9.22
33505-TEA-T01	REFLECTOR ASSYR.RR.	nn x 1	7.20	25	5.40	0.38	5.78
33555-TEA-T01	REFLECTOR ASSYL.RR.	nn x 1	7.20	25	5.40	0.38	5.78



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SME6148M

Chassis No : MRHFC5650JT001711

Model : CIVIC 1.6 VTI YM2018

Owner's Name : CAESIAPEAH LIM GUEK NGOR

Ins Policy No. :

Date of Accident : 11/1/2019

Document No. : SQT19000197 Page 2

Date : 11. Jan 2019

Customer No. : WZA006

Svc Advisor : NG SIN HAI

Engine No : R16B25501979

Date | Time : 11. Jan 2019 8:58:39 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
91505-TM8-003	CLIP,BUMPER	ac ✓ 7	2.30	25	12.07	0.84	12.91	
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	dl ✓ 1	50.30	25	37.72	2.64	40.36	
84521-TEA-Q01ZA	LID ASSYSPARE TIRE	X ✓ 1	60.20	25	45.15	3.16	48.31	
84601-TEA-Q01ZA	LINING ASSYR.TRUNK SIDE	na } X ✓ 1	48.90	25	36.67	2.57	39.24	
84651-TEA-Q01ZA	LINING ASSYL.TRUNK SIDE	(2) ✓ 1	48.90	25	36.67	2.57	39.24	
34150-TEX-Y01	LIGHT ASSYR.LID	dan ✓ 1	122.30	25	91.72	6.42	98.14	
34155-TEX-Y01	LIGHT ASSYL.LID	? 1 ✓	122.30	25	91.72	6.42	98.14	
33500-TEA-T01	TAILLIGHT ASSYR.	cu ✓ 1	261.40	25	196.05	13.72	209.77	
33550-TEA-T01	TAILLIGHT ASSYL.	cu ✓ 1	281.30	25	210.97	14.77	225.74	
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS.	X ✓ 1	28.10	25	21.07	1.47	22.54	
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	① ? 4 ✓	145.80	25	109.35	437.40	30.62	468.02
39670-TEX-Y01	SENSOR UNITPARKING	un ✓ 1	62.50	25	46.87	3.28	50.15	
65550-TEA-T00ZZ	PAN COMPSPARE TIRE	ht ✓ 1	216.70	25	162.52	11.38	173.90	
Sum Item					2877.20	201.40	3,078.60	

BOSUN	SUNDRIES	1 ✓	100.00		100.00	7.00	107.00
BOJSE	SEALANT FOR REAR END PANEL	1 ✓	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1 ✓	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR TRUNK	1 ✓	80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1 ✓	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS-(N)	1 ✓	180.00		180.00	12.60	192.60
BOMISC1	REMOVE, CHECK AND INSTALL SMART ENTRY SENSOR1	1 ✓	380.00		380.00	26.60	406.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES-(N)	1 ✓	560.00		560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1 ✓	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TRUNK. ADJUST &	1 ✓	560.00		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1 ✓	5000.00		5000.00	350.00	5350.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1 ✓	3000.00		3000.00	210.00	3210.00
BOMISC1	REMOVE, INSTALL AND CALIBRATE REAR CAMERA	1 ✓	380.00		380.00	26.60	406.60
Sum Labor					11140.00	779.80	11,919.80

Printed on 11/1/2019 9:09:11 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 96203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
Registration No : SME6148M
Chassis No : MRHFC5650JT001711
Model : CIVIC 1.6 VTI YM2018
Owner's Name : CAESIAPEAH LIM GUEK NGOR
Ins Policy No. :
Date of Accident : 11/1/2019

Document No. : SQT19000197 **Page** 3
Date : 11. Jan 2019
Customer No. : WZA006
Svc Advisor : NG SIN HAI
Engine No : R16B25501979
Date | Time : 11. Jan 2019 8:58:39 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

Survey By Tan Jia Min 97495749
 Date & Time 14/1/19 @ 1130 **Total Amount** 14,017.20 981.20 14,998.40
 Excess WP **Total (Inclusive of GST)** 14,998.40
 Status _____
 Signature [Signature]

*12 days.
 surellwants.com
 * Resurvey before paint.
 14165-014*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Supp

Customer: ****5344F / CAESIAPEAH LIM
 Chassis No: MRHFC5650JT001711
 License No: SME6148M
 Mileage: 1047
 Engine No: R16B25501979

Document No: SVO19003201
 Printed By: SHNG
 Order Date: 14. January 2019
 Order Time: 8:18:01 PM
 Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
35070	ADDITIONAL PART BO-NUM-COMP-L NUMBER PLATE WITH CASING-L	1	45.00		45.00 ✓ <i>bt</i>	3.15	48.15
			SUM EXCESS:		45.00	3.15	48.15
38387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30	25	44.47 ✓ <i>crq</i>	3.11	47.58
74940-SZW-003	BUZZER ASSYSMART	1	61.30	25	45.97 ✓ <i>crq</i>	3.22	49.19
71506-TEX-Y00	COVERRR.TOWING HOOK	1	8.70	25	6.52 ✓ <i>de</i>	0.46	6.98
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.80	25	5.85 ✓ <i>de</i>	0.41	6.26
			SUM PARTS:		102.81	7.20	110.01
			TOTAL SGD		147.81	10.35	158.16

Total Payable (SGD)

158.16

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
 Chassis No: MRHFC5650JT001711
 License No: SME6148M
 Mileage: 1047
 Engine No: R16B25501979

Document No: SVO19003201
 Printed By: SHNG
 Order Date: 14. January 2019
 Order Time: 8:18:01 PM
 Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:CAESIAPEAH LIM GUEK NGOR OWNER INSURER:AVIVA ACC DATE:11/01/2019 SURVEYED BY:TAUFIKH DATE:14/01/2019 REF NO: TP INSURER:AXA TP VEH:SLV3249Y ADDITIONAL PART BO-NUM-COMP-L NUMBER PLATE WITH CASING-L	1	45.00		45.00	3.15	48.15
	SUM EXCESS:				45.00	3.15	48.15
66100-TEC-307ZZ	PANEL SETRR.	1	243.10	25	182.32	12.76	195.08
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
68500-TEA-N00ZZ	LID COMP TRUNK	1	486.20	25	364.65	25.53	390.18
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74851-TEA-003	LOCK ASSYTRUNK	1	74.30	25	55.72	3.90	59.62
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	100.60	25	75.45	5.28	80.73
75701-TBA-A10	EMBLEM,H-MARK	1	12.20	25	9.15	0.64	9.79
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
75722-TBA-A00	EMBLEM SETRR.	1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	EMBLEMRR.	1	11.00	25	8.25	0.58	8.83
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	164.70	25	123.52	8.65	132.17
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.30	25	1.72	0.12	1.84
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
33500-TEA-T01	TAILLIGHT ASSYR.	1	261.40	25	196.05	13.72	209.77
33550-TEA-T01	TAILLIGHT ASSYL.	1	281.30	25	210.97	14.77	225.74
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	1	145.80	25	109.35	7.65	117.00
65550-TEA-T00ZZ	PAN COMPSPARE TIRE	1	216.70	25	162.52	11.38	173.90
38387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30	25	44.47	3.11	47.58
74940-SZW-003	BUZZER ASSYSMART	1	61.30	25	45.97	3.22	49.19
71506-TEX-Y00	COVERRR.TOWING HOOK	1	8.70	25	6.52	0.46	6.98
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.80	25	5.85	0.41	6.26
	SUM PARTS:				2,264.25	158.49	2,422.74
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BOJSE	1718 SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BOJSE	1718 SEALANT FOR REAR FLOOR PANEL	1	80.00		80.00	5.60	85.60
BOJSE	1718 SEALANT FOR TRUNK	1	80.00		80.00	5.60	85.60



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: MRHFC5650JT001711
License No: SME6148M
Mileage: 1047
Engine No: R16B25501979

Document No: SVO19003201
Printed By: SHNG
Order Date: 14. January 2019
Order Time: 8:18:01 PM
Service Advisor: NG SIN HAI

BML02I	0701 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00	180.00	12.60	192.60
BA02R	1466 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	180.00	12.60	192.60
BOMISC1	1438 REMOVE, CHECK AND INSTALL SMART ENTRY SENSOR. RESET MEMORY. (N)	1	380.00	380.00	26.60	406.60
BMF00D	1438 RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00	560.00	39.20	599.20
BMI03D	1466 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	560.00	560.00	39.20	599.20
BKTG02R	1438 REMOVE & TRANSFER ITEMS TO NEW TRUNK. ADJUST & ALIGN TRUNK.(N)	1	280.00	280.00	19.60	299.60
BKRP02M	1466 CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	4,480.00	4,480.00	313.60	4,793.60
BP05R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2,700.00	2,700.00	189.00	2,889.00
BOMISC1	1718 REMOVE, INSTALL AND CALIBRATE REAR CAMERA	1	380.00	380.00	26.60	406.60
SUM LABOUR:				9,970.00	697.90	10,667.90
TOTAL SGD				12,279.25	859.54	13,138.79

Total Payable (SGD)

13,138.79

GST Amount is calculated from individual line(s)

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 14 January 2019 11:15 AM
To: assignments
Subject: FW: 3rd party direct settlement SME6148M/ & your insured SLV3249Y/DOA:11/01/2019/Est \$
Attachments: 1011_001.pdf

11. asun@14/1/19
vehicle in
perun@sin Hai
SUR@Turbich

Hi Nivitha,

TP smart. Kindly assist.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Friday, 11 January, 2019 9:15 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: RE: 3rd party direct settlement SME6148M/ & your insured SLV3249Y/DOA:11/01/2019/Est \$

Dear Motor Claims,

Please arrange for a survey for this vehicle on 14/01/2019.

Please refer to the attached pdf, we are assisting our insured vehicle SME6148M to file a 3rd party claim against your insured vehicle SLV3249Y and to request for direct settlement.

Please assist and expedite to check the claim liability soonest.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

Report Remarks Entry - CC4/ASM19000795/T1pa3

Remarks

Remarks

Add

<input type="checkbox"/>	Remarks 1	By	On
<input type="checkbox"/>	SME 6148M ; SLV 3249Y	HMK	14/1/2019 3:39:45 PM
<input type="checkbox"/>	EST : \$14017.20 --- SUR : MTH --- WKSP : KAH MOTOR CO SDN BERHAD	HMK	14/1/2019 3:40:13 PM
<input type="checkbox"/>	S9M01A3L // 92876 // KHONG Lynn	HMK	14/1/2019 3:41:31 PM
<input type="checkbox"/>	Services Pending verification - Direct Settlement	HMK	14/1/2019 3:41:34 PM
<input type="checkbox"/>	14/1/19 9:00 AM *** SLV3249Y Head to rear - Proceed to DS - KHONG Lynn	HMK	14/1/2019 3:41:44 PM
<input type="checkbox"/>	LIABILITY CLEAR SENT BY EMAIL	JIB	14/1/2019 3:59:16 PM
<input type="checkbox"/>	FILE PASS TO ASHER	HMK	17/1/2019 2:03:09 PM
<input type="checkbox"/>	18/1/19 6:30 PM *** SLV3249Y Any IA? - KHONG Lynn	HMK	21/1/2019 10:08:23 AM
<input type="checkbox"/>	15/4/19 2:55 PM *** Message Kindly advise IA / IA mandate. Thanks - KHONG Lynn	HMK	15/4/2019 7:33:07 PM
<input type="checkbox"/>	FILE TRANSFER TO HT	SRY	30/5/2019 3:14:06 PM

Hsiao Tong (LKKAuto)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Friday, 12 July 2019 8:00 PM
To: Admin A; Hsiao Tong (LKKAuto)
Cc: Jerome Tan; Winson Chow
Subject: FW: SME6148M - TP CLAIM AGAINST SLV3249Y DOA: 11.01.2019
Attachments: 3408_001.pdf

Your Ref: SLV3249Y

Our Ref: SLM6148M

M/s: AXA Insurance Singapore Pte Ltd
C/o: LKK Auto Consultants Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Case Handler

Dear All,

Above is the attached document for third party direct settlement claim.

Kindly provide us your finalized settlement & payment as your soonest.

We'll appreciate if you could reply to us once receive this mail.

Best Regards

Desmond Toh

Kah Motor Co Sdn Bhd

Website : www.honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



<TP - Mandate IA> - S9M01A3L [ACCIDENT INVOLVING SLV 3249Y(OI) & SME 6148M(TP) ON 11/01/2019]

Type

🔗 Question

Message

Liability: 100%. Insured driver rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$14,208.80(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 24 July 2019

Reply



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 24/7/2019

Survey Details:

Date of loss	11-Jan-19
Date of appointment	14-Jan-19
Date of survey	14-Jan-19
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SME6148M
Make and Model	HONDA CIVIC 1.6 VTI CVT - 1597cc
Date of registration	8-Oct-18
Parf Rebate	
Market Value	\$ 86,000.00
Parf Rebate	\$ 41,274.00
Nett Loss	\$ 44,726.00

Repair details:

Initial Estimate	14,165.01
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 2,161.44
Check items (estimate)	NIL
Labour	\$ 9,970.00
Supplementary	\$ 147.81
Total	\$ 12,279.25
Lump Sum(if applicable)	

Number of days for repair	<u>12 days</u>
---------------------------	----------------



Remarks:

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best.

Mandate:

Liability(TP)		100%	
Proposed repair cost (w/GST)	\$	13,138.80	
Loss of use		NIL	
Loss of rental (w/GST)	\$	1,070.00	(10days x \$100.00)
Loss of income		NIL	
LTA search fees		NIL	
Others		NIL	
Proposed Total	\$	14,208.80	

Hsiao Tong (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Monday, 5 August 2019 6:33 PM
To: Hsiao Tong (LKKAuto)
Subject: FW: New message for service request 92876, vehicle number SME6148M

5/8/19 5:50 PM*** Proceed as proposed. Thanks - KHONG Lynn

-----Original Message-----

From: lynn.khong@axa.com.sg [mailto:lynn.khong@axa.com.sg]
Sent: Monday, 5 August, 2019 5:51 PM
To: admin-d@lkkauto.com
Subject: New message for service request 92876, vehicle number SME6148M

AXA Insurance has sent you a message for claim number S9M01A3L.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal. This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 7 August 2019 8:29 AM
To: Desmond Toh
Cc: Jerome Tan; Winson Chow; Admin A
Subject: RE: SME6148M - TP CLAIM AGAINST SLV3249Y DOA: 11.01.2019 //LKK REF: CC4/ASM19000795/T1pa3
Attachments: EXPRESS SETTLEMENT FORM_SME6148M.pdf

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$13,138.79
2. Loss of Rental (10days x \$100.00)(w/GST)	\$ 1,070.00
TOTAL	\$14,208.79

If our offer is acceptable by your client, please duly sign the document enclosed and return to us for our necessary action.

Thank you.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Desmond Toh <desmondtoh@honda.com.sg>

Sent: Friday, 12 July 2019 8:00 PM

To: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Jerome Tan <jerometan@honda.com.sg>; Winson Chow <winsonchow@honda.com.sg>

Subject: FW: SME6148M - TP CLAIM AGAINST SLV3249Y DOA: 11.01.2019

Your Ref: SLV3249Y

Our Ref: SLM6148M

M/s: AXA Insurance Singapore Pte Ltd

C/o: LKK Auto Consultants Pte Ltd

8 Shenton Way
#27-01 AXA Tower
Singapore 068811



Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)
Body Repair & Paint Centre
6A Mandai Estate
Singapore 729903
Tel : +65 6841 3838
Fax : +65 6362 5015
www.honda.com.sg

M/s: AXA Insurance Singapore Pte Ltd

Lkk

8 Shenton Way

#27-01

Singapore 068811

Date : 9/7/2019

Attn: Motor Claims Department

Your ref : SLV3249Y

Our ref : SME6148M

Dear All,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SME6148M AND SLV3249Y ON 11/01/2019.

We refer to the item(s) marked (✓) below:

- (✓) We refer to your email dated 14/01/2019
- (✓) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- () Kindly forward the discharge voucher for our client's signature within **2 weeks** via email to : desmondtoh@honda.com.sg
- (✓) We return your discharge voucher duly completed.
- (✓) Kindly expedite settlement the following :-
 - Repair Cost **SS13,138.19** payable to **Kah Motor Co. Sdn. Bhd.**
 - Loss of RENTAL **SS107.00 X 10days=SS1,070.00** payable to **CAESIAPEAH LIM GUEK NGOR**

Loss of Use

LTA Search

- (✓) Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.
- (✓) Letter of Authority, Car Rental Rental

Thank you.

Yours faithfully,

Ng Sin Hai



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19000795/T1pa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: LYNN KHONG

Date : 28-08-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 3249Y	Veh. Inspected	SME 6148M
Policy No.	P2048346	Coverage (\$)	0.00
Claim No.	S9M01A3L	Excess (\$)	0.00
Assign From	LYNN KHONG	Assign Date	14/01/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC 1.6	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MRHFC5650JT001711	Colour	BLACK
Odometer	006264	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R16	HANKOOK	6 mm
L/H Front Tyre	215/55 R16	HANKOOK	6 mm
R/H Rear Tyre	215/55 R16	HANKOOK	6 mm
L/H Rear Tyre	215/55 R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/01/2019	Inspection Date	14/01/2019
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **12 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 6148M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	PANEL SETRR. (SN) (CONSISTENT)	BENT	182.32	182.32
1	STIFFENER,R.RR.PANEL SIDE (SN) (CONSISTENT)	DEFORMED	20.02	20.02
1	STIFFENERL.RR.PANEL SIDE (SN) (CONSISTENT)	DEFORMED	20.02	20.02
1	LIP COMP TRUNK (SN) (CONSISTENT)	BENT	364.65	364.65
1	WEATHERSTRIP TRUNK LID (SN) (CONSISTENT)	TWISTED	52.50	52.50
1	LOCK ASSYTRUNK (SN) (CONSISTENT)	BENT	55.72	55.72
1	STRIKERTRUNK LID (SN) (CONSISTENT)	NOT NECESSARY	5.32	-
1	GARNISH ASSYRR.LICENSE (SN) (CONSISTENT)	DEFORMED	75.45	75.45
1	EMBLEM,H-MARK (SN) (CONSISTENT)	NECESSARY	9.15	9.15
2	NUTPUSH 3MM (SN) (CONSISTENT)	NECESSARY	3.15	3.15
1	EMBLEM SETRR. (SN) (CONSISTENT)	NECESSARY	8.85	8.85
1	EMBLEMRR. (SN) (CONSISTENT)	NECESSARY	8.25	8.25
1	FACE ASSY,RR.BUMPER (SN) (CONSISTENT)	DEFORMED	462.90	462.90
1	GARNISH,RR.BUMPER LOWER (SN) (CONSISTENT)	DEFORMED	27.30	27.30
1	BEAM COMPRR.BUMPER (SN) (CONSISTENT)	BENT	123.52	123.52
1	BRACKETR.RR.BUMPER SIDE (SN) (CONSISTENT)	NOT NECESSARY	1.72	-
1	BRACKETL.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	1.72	1.72
1	SPACERR.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	8.62	8.62
1	SPACERL.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	8.62	8.62
1	REFLECTOR ASSYR.RR. (SN) (CONSISTENT)	NOT NECESSARY	5.40	-
1	REFLECTOR ASSYL.RR. (SN) (CONSISTENT)	NOT NECESSARY	5.40	-
7	CLIP, BUMPER (SN) (CONSISTENT)	NECESSARY	12.07	12.07
1	LINING ASSYRR.PANEL (SN) (CONSISTENT)	DEFORMED	37.72	37.72
1	LID ASSYSPARE TIRE (SN) (CONSISTENT)	NOT NECESSARY	45.15	-
1	LINING ASSYR.TRUNK SIDE (SN) (CONSISTENT)	NOT NECESSARY	36.67	-
1	LINING ASSYL.TRUNK SIDE (SN) (CONSISTENT)	NOT NECESSARY	36.67	-
1	LIGHT ASSYR.LID (SN) (CONSISTENT)	NOT NECESSARY	91.72	-
1	LIGHT ASSYL.LID (SN) (CONSISTENT)	NOT NECESSARY	91.72	-
1	TAILLIGHT ASSYR. (SN) (CONSISTENT)	CRACKED	196.05	196.05
1	TAILLIGHT ASSYL. (SN) (CONSISTENT)	CRACKED	210.97	210.97

Report Ref No. CC4/ASM19000795/T1pa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUB CORDRR.BUMPER CORNER SENS (SN) (CONSISTENT)	NOT NECESSARY	21.07	-
4	SENSOR ASSY, PARKING (SN) (CONSISTENT)	NOT WORKING	437.40	109.35
1	SENSOR UNITPARKING (SN) (CONSISTENT)	NOT NECESSARY	46.87	-
1	PAN COMPSPARE TIRE (SN) (CONSISTENT)	BENT	162.52	162.52
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	30.00
1	SEALANT FOR REAR END PANEL (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	SEALANT FOR REAR FLOOR PANEL (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	SEALANT FOR TRUNK (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	BO-NUM-COMP-L NUMBER PLATE WITH CASING-L (SN) (CONSISTENT) (ADDITIONAL)	BENT	45.00	45.00
1	ANTENNA ASSYL.F. (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	44.47	44.47
1	BUZZER ASSYSMART (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	45.97	45.97
1	COVERRR.TOWING HOOK (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	6.52	6.52
1	GARNISHL.RR.BUMPER SIDE (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	5.85	5.85
			3,365.01	2,579.25
LABOUR				
INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.			180.00	180.00
REMOVE & RENEW REVERSE SENSORS.			180.00	180.00
REMOVE, CHECK AND INSTALL SMART ENTRY SENSOR.			380.00	380.00
RREMOVE & INSTALL FUEL TANK FUEL PIPES.			560.00	560.00
REMOVE & INSTALL REAR COMPARTMENT LININGS.			560.00	560.00
REMOVE & TRANSFER ITEMS TO NEW TRUNK. ADJUST &.			560.00	280.00
CUT OFF & RENEW RR PANEL. STRAIGHTEN.			5,000.00	4,480.00
SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.			3,000.00	2,700.00
REMOVE, INSTALL AND CALIBRATE REAR CAMERA.			380.00	380.00
			-	-
			-	-
			-	-
			10,800.00	9,700.00



GRAND TOTAL		14,165.01	12,279.25
RECOMMENDED COST OF REPAIRS			12,279.25

Report Ref No. CC4/ASM19000795/T1pa3s2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.