



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer :	AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No. :	SQT19000197	Page	1
Registration No :	SME6148M	Date :	11. Jan 2019	Customer No. :	WZA006
Chassis No :	MRHFC5650JT001711	Svc Advisor :	NG SIN HAI	Engine No :	R16B25501979
Model :	CIVIC 1.6 VTI YM2018	Date Time :	11. Jan 2019 8:58:39 PM	Surveyor Name :	
Owner's Name :	CAESIAPEAH LIM GUEK NGOR	Survey Date :		Authorisation Date :	
Ins Policy No. :					
Date of Accident :	11/1/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:CAESIAPEAH LIM GUEK NGOR OWNER INSURER:AVIVA ACC DATE:11/01/2019 SURVEYED BY: DATE: REF NO: TP INSURER:AXA TP VEH:SLV3249Y						
66100-TEC-307ZZ	PANEL SETRR.	bt 1	243.10	25	182.32	12.76	195.08
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	? 1	26.70	25	20.02	1.40	21.42
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	? 1	26.70	25	20.02	1.40	21.42
68500-TEA-N00ZZ	LID COMP TRUNK	bt 1	486.20	25	364.65	25.53	390.18
74865-TEA-T01	WEATHERSTRIPTRUNK LID	tu 1	70.00	25	52.50	3.68	56.18
74851-TEA-003	LOCK ASSYTRUNK	bt 1	74.30	25	55.72	3.90	59.62
74862-TEA-003	STRIKERTRUNK LID	px 1	7.10	25	5.32	0.37	5.69
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	de 1	100.60	25	75.45	5.28	80.73
75701-TBA-A10	EMBLEM,H-MARK	nh 1	12.20	25	9.15	0.64	9.79
90301-ST0-003	NUTPUSH 3MM	ne 2	2.10	25	3.15	0.22	3.37
75722-TBA-A00	EMBLEM SETRR.	ne 1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	EMBLEMRR.	ne 1	11.00	25	8.25	0.58	8.83
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	de 1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	de 1	36.40	25	27.30	1.91	29.21
71530-TEA-T00ZZ	BEAM COMP RR.BUMPER	bt 1	164.70	25	123.52	8.65	132.17
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	? 1	2.30	25	1.72	0.12	1.84
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	? 1	2.30	25	1.72	0.12	1.84
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	ne 1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	ne 1	11.50	25	8.62	0.60	9.22
33505-TEA-T01	REFLECTOR ASSYR.RR.	? 1	7.20	25	5.40	0.38	5.78
33555-TEA-T01	REFLECTOR ASSYL.RR.	? 1	7.20	25	5.40	0.38	5.78



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SME6148M
Chassis No : MRHFC5650JT001711
Model : CIVIC 1.6 VTI YM2018
Owner's Name : CAESIAPEAH LIM GUEK NGOR
Ins Policy No. :
Date of Accident : 11/1/2019

Document No. : SQT19000197 **Page** 2
Date : 11. Jan 2019
Customer No. : WZA006
Svc Advisor : NG SIN HAI
Engine No : R16B25501979
Date | Time : 11. Jan 2019 8:58:39 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
84521-TEA-Q01ZA	LID ASSYSPARE TIRE	1	60.20	25	45.15	3.16	48.31
84601-TEA-Q01ZA	LINING ASSYR.TRUNK SIDE	1	48.90	25	36.67	2.57	39.24
84651-TEA-Q01ZA	LINING ASSYL.TRUNK SIDE	1	48.90	25	36.67	2.57	39.24
34150-TEX-Y01	LIGHT ASSYR.LID	1	122.30	25	91.72	6.42	98.14
34155-TEX-Y01	LIGHT ASSYL.LID	1	122.30	25	91.72	6.42	98.14
33500-TEA-T01	TAILLIGHT ASSYR.	1	261.40	25	196.05	13.72	209.77
33550-TEA-T01	TAILLIGHT ASSYL.	1	281.30	25	210.97	14.77	225.74
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS	1	28.10	25	21.07	1.47	22.54
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	4	145.80	25	437.40	30.62	468.02
39670-TEX-Y01	SENSOR UNITPARKING	1	62.50	25	46.87	3.28	50.15
65550-TEA-T00ZZ	PAN COMPSPARE TIRE	1	216.70	25	162.52	11.38	173.90
Sum Item					2877.20	201.40	3,078.60

BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BOJSE	SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR TRUNK	1	80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOMISC1	REMOVE, CHECK AND INSTALL SMART ENTRY SENSOR1	1	380.00		380.00	26.60	406.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00		560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TRUNK. ADJUST &	1	560.00		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	5000.00		5000.00	350.00	5350.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	3000.00		3000.00	210.00	3210.00
BOMISC1	REMOVE, INSTALL AND CALIBRATE REAR CAMERA	1	380.00		380.00	26.60	406.60
Sum Labor					11140.00	779.80	11,919.80

Printed on 11/1/2019 9:09:11 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
 Registration No : SME6148M
 Chassis No : MRHFC5650JT001711
 Model : CIVIC 1.6 VTI YM2018
 Owner's Name : CAESIAPEAH LIM GUEK NGOR
 Ins Policy No. :
 Date of Accident : 11/1/2019

Document No. : SQT19000197 Page 3
 Date : 11. Jan 2019
 Customer No. : WZA006
 Svc Advisor : NG SIN HAI
 Engine No : R16B25501979
 Date | Time : 11. Jan 2019 8:58:39 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

Survey By	<u>Tan Jiah 97495749</u>							
Date & Time	<u>14/1/19 @ 1130</u>							
Excess	<u>WP</u>							
Status								
Signature	<u>[Signature]</u>							
					Total Amount	14,017.20	981.20	14,998.40
					Total (Inclusive of GST)			14,998.40

12 days.
 surellauto.com
 # Resurvey before paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: