



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE	Document No.	: SQT19000184	Page	1
	64 CECIL STREET	Date	: 11. Jan 2019		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZI007		
	SINGAPORE 049711	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SMC6117M	Engine No	: L13B11030912		
Chassis No	: JHMGK3850JX225541	Date Time	: 11. Jan 2019 11:40:02 AM		
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: YEO CHYE HENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 11/1/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: YEO CHYE HENG						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 11/01/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE						
	TP VEH: SHB4295J						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY,TAILGATE	1	78.90	25	59.17	4.14	63.31
84521-T5A-901ZA	LID ASSYSPARE TIRE	1	189.80	25	142.35	9.96	152.31
84550-T5A-J30	BOX ASSY,CARGO FLOOR GATE	1	117.40	25	88.05	6.16	94.21
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	25	45.60	3.19	48.79
84651-TAR-Z03ZA	LINING ASSYL.TRUNK	1	169.00	25	126.75	8.87	135.62
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
34155-T5A-J01	LIGHT ASSYL.LID	1	81.70	25	61.27	4.29	65.56
34150-T5A-J01	LIGHT ASSYR.LID	1	81.70	25	61.27	4.29	65.56
33550-T5A-J02	TAILLIGHT ASSYL.	1	223.90	25	167.92	11.75	179.67
33500-T5A-J02	TAILLIGHT ASSY,R.	1	223.90	25	167.92	11.75	179.67
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70	25	369.52	25.87	395.39
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M20005022

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
 64 CECIL STREET
 #04-00 & #05-00 IOB BUILDING
 SINGAPORE 049711
 Registration No : SMC6117M
 Chassis No : JHMGK3850JX225541
 Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
 Owner's Name : YEO CHYE HENG
 Ins Policy No. :
 Date of Accident : 11/1/2019

Document No. : SQT19000184
 Date : 11. Jan 2019
 Customer No. : WZ1007
 Svc Advisor : RUEBEN THOMAS
 Engine No : L13B11030912
 Date | Time : 11. Jan 2019 11:40:02 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71505-T5A-J50	GARNISH,RR.BUMPER	1	38.30	25	28.72	2.01	30.73
71507-T5A-J60	COVER,L.RR.BUMPER	1	20.70	25	15.52	1.09	16.61
71502-T5A-J60	COVER,R.RR.BUMPER	1	20.70	25	15.52	1.09	16.61
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
Sum Item					2428.17	169.97	2,598.14
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BOMISC1	REMOVE, INSTALL & ADJUST REAR VIEW CAMERA (N)	1	320.00		320.00	22.40	342.40
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00		350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	350.00		350.00	24.50	374.50
BKRP02M	CUT OFF & RENEW RR PANEL. KNOCK FLOOR	1	2400.00		2400.00	168.00	2568.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2900.00		2900.00	203.00	3103.00
Sum Labor					7350.00	514.50	7,864.50

Survey By : Mercus Hah
 Date & Time : 14-1-19
 Excess : No f Adult
 Status : the plus repair party.
 Signature : Tdy.

Total Amount 9,778.17 684.47 10,462.64
 Total (Inclusive of GST) 10,462.64

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 11/1/2019 12:37:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)