

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

14/01/2019 21:03

OWNER'S PARTICULARS

JOB-NO: 50111318

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA8680J

TRANS: AUTO

CHASSIS: KMHLB41UMHU095239

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU683656

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	200
2 REMOVE & REFIT SPARE TYRE & CARPET & SIDE TRIM	1.00	120.00	0.00	120.00		Y	X
3 REMOVE & RE-DRILL REAR REVERSE SENSOR	1.00	120.00	0.00	120.00		Y	30
4 RESPRAY REAR BUMPER	1.00	220.00	0.00	220.00		Y	200
5 RESPRAY REAR BUMPER DIFFUSER	1.00	220.00	0.00	220.00		Y	100
6 RESPRAY REVERSE SENSOR	1.00	100.00	0.00	100.00		Y	30
TOTAL:		1,780.00	0.00	1,780.00			560

MATERIALS

1 REAR BUMPER	1.00	599.68	119.94	479.74	L	Y	de
2 REAR BUMPER REINFORCEMENT	1.00	438.40	87.68	350.72	L	Y	X
3 REAR BUMPER REINFORCEMENT BRACKET LHS	1.00	95.63	19.13	76.50	L	Y	X
4 REAR BUMPER REINFORCEMENT BRACKET RHS	1.00	95.63	19.13	76.50	L	Y	X
5 REAR BUMPER REINFORCEMENT SPONGE	1.00	150.15	30.03	120.12	L	Y	X
6 REAR BUMPER RETAINER LHS	1.00	49.14	9.83	39.31	L	Y	X
7 REAR BUMPER RETAINER RHS	1.00	49.14	9.83	39.31	L	Y	X
8 REAR BUMPER REFLECTOR RHS	1.00	42.50	8.50	34.00	L	Y	X
9 REAR BUMPER DIFFUSER	1.00	218.40	43.68	174.72	L	Y	awa
10 REAR END PANEL	1.00	526.00	105.20	420.80	L	Y	X
11 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	nr
12 REAR BUMPER RUBBER PROTECTOR PAD	1.00	160.00	0.00	160.00	S	Y	de
13 REAR BUMPER REVERSE SENSOR	1.00	220.00	0.00	220.00	S	Y	200 nr
14 REAR BUMPER ADS STICKER	1.00	160.00	0.00	160.00	S	Y	nr
TOTAL:		2,839.67	452.95	2,386.72			

TOTAL PARTS & LABOUR : 4,619.67 452.95 4,166.72

EXCESS/LOADING:S\$ 0.00

No. Of Day: 2

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: 14, 01, 19

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
SURVEYED BY: <u>Tanjin</u>							
CONTACT NO: <u>9749574</u> FAX NO: _____							

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

*Review after repair
sure amount.com.*

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: