

22/03/2002

ASS. REC. BY:

REF: CS/AIG19000809/KVD30

Special Instruction:

Surveyor: Kenneth Menmen

ASSIGNMENT (Office)

From (Person): Hor Yinnal

of

AIG

Date/Time:

14/11/19 @ 10:30am

Estimated Cost:

Bill to:

OD WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 6679D

Insured:

SLS 25502

at Workshop m/s

Auburn Auto

Tel:

9619 1525

of

176 Sin Ming Drive #04-18

Policy No:

1700053075

Claim No:

8842709626 SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/01/2019

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

15/01/19

Date/Time:

11:50am @ 14/11/19

Person Contacted:

ERIC

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

Repairer average on 15/01/19 as estimate was not done today.

SJT 6679D - X

SLS 25502 - X

22/11

11/19 @ 3:00pm email (un-confirm)

ASS. REC. BY:

REF: ALG

Kenneth


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Auburn
 of 04-11-18
 Insured: _____
 Policy No. 68782
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJT 6679D Yr Regn: 10, 09
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mazda 3 c.c. 1598
 Colour: M. Grey A/C: Insured / Std / NI / NA
 Sp. Reading 176635 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM6BL1071A 0114536
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: NII / S/Rim / STD A/Rim or _____
 Tyre Size: F: Pir 205/55R16
 R: mic
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 3 mm
 L/Bal. 5 mm L/Bal. 3 mm
 D.O.A. 4/1/19 D.O.I. 16/1/19
 Survey held at _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 15k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Eric Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>17/1</u>	<u>File pass to Car, GIA will email over.</u>

RECEIVED 20 MAR 2019

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: 2

2) 263- typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	<u>290</u>
Transportation:	_____
Photos	_____
Others	<u>10</u>
TOTAL	<u>260</u>

Report Format: meimen

Lump Sum / I.B.I.: (\$)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jan 2019 Edit Reg		14 Jan 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]					
Insured:	CHUAN LUCK PTE LTD , Co. Reg. No.: 200514549C								
Main Claimant:	-								
Vehicle Reg. No.:	SJT6679D	Date of Loss:	04/01/2019 00:00 - :59						
Claim Type:	TP / 8842709626SG	Policy/Cover Note No.:	1700053075 (Comprehensive) Coverage: 15/09/2017 - 14/09/2019						
Vehicle Reg. No. (Insured):	SLS2550Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/01/2019]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (15/01/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Pre repair inspection request - SJT6679D VS SLS2550Z (OI) DOA: 04/01/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Md Ishak, Mohd Imran, Mithoosingh, Aashweenjeetkaur
Sent: 14/1/2019 10:30:27 AM
Attachments:  11012019131326.pdf

Hi,

Please refer to the enclosed request from **CENTRO-LEGAL LAW CORPORATION**

Claim no : 8842709626SG003
Case Owner : WEI ZHONG BENNIE TAN

If you have any queries/concerns, please let us know.
*Kindly assist to assign **KENNETH KONG** as Single Joint Expert as requested.*

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: ling@centrollc.com.sg [mailto:ling@centrollc.com.sg]
Sent: Monday, January 14, 2019 9:31 AM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS2550Z AND SJT6679D ON 04/01/2019

WITHOUT PREJUDICE

Dear Yin Rul,

We choose Kenneth Kong (LKK Auto Consultants Pte Ltd) as single joint expert.

Thank you and have a nice day.

Best Regards,

MR LING

Centro-Legal Law Corporation
151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939
H/P: 96628304

From: Hor, Yinrul
Sent: Fri, 11 Jan 2019 06:07:50 +0000
To: ling@centrollc.com.sg
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Md Ishak, Mohd Imran, Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS2550Z AND SJT6679D ON 04/01/2019

Without Prejudice

Your Reference : CLLC.PD.010.2019 L1
Our Reference : 8842709626SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd

Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: ling@centrollc.com.sg [mailto:ling@centrollc.com.sg]

Sent: Friday, January 11, 2019 2:00 PM

To: Hor, Yinrul

Cc: Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS2550Z AND SJT6679D ON 03/01/2019

WITHOUT PREJUDICE

Dear Sir/Madam,

DOA : 04 / 01 / 2019

Thank you and have a nice day.

Best Regards,

MR LING

Centro-Legal Law Corporation
151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939

H/P: 96628304

From: Hor, Yinrul

Sent: Fri, 11 Jan 2019 05:52:11 +0000

To: ling@centrollc.com.sg

Cc: Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Md Ishak, Mohd Imran, Mithoosingh, Aashweenjeetkaur

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS2550Z AND SJT6679D ON 03/01/2019

Hi Mr Ling,

Thank you for the notice.

However there is a conflicting D.O.A. as OI GIA REPORT (04/01/2019) and your notice (03/01/2019) indicating different D.O.A.
Kindly assist to confirm the correct D.O.A. for our necessary action.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: ling@centrollc.com.sg [mailto:ling@centrollc.com.sg]
Sent: Friday, January 11, 2019 1:22 PM
To: Lim, Sheng Yang; Chan, Yoke Shi
Subject: PRE-REPAIR INSPECTION - OUR REF: CLLC.PD.010.2019 YOUR REF: SLS2550Z
Importance: High

WITHOUT PREJUDICE

Dear Sir/Madam,

Kindly refer to the attachment. (PRE-REPAIR INSPECTION)

Thank you and have a nice day.

Best Regards,

MR LING

Centro-Legal Law Corporation
151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939
H/P: 96628304

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Centro-Legal Law Corporation

ADVOCATES AND SOLICITORS

151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939

Your ref : SLS2550Z
Our ref : CLLC.PD.010.2019 LI

11 JANUARY 2019

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way #07-16 AIG Building
Singapore 079120
Fax: 6835 7416

BY FAX & EMAIL

Attn: **Officer-In-Charge**

Dear Sirs,

NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASE

We act for **COVE RENTALS PTE LTD**, the owner of motor vehicle **SJT6679D**, who has appointed us to act on his behalf to claim against your insured's vehicle no **SLS2550Z** in regards to the road traffic accident on **03.01.2019**

AUBURN AUTO PTE LTD.
176, SIN MING DRIVE
#04-18 SIN MING AUTOCARE
SINGAPORE 575721

Kindly contact: **ERIC CHAN - 9619 1525**

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

CENTRO-LEGAL LAW CORPORATION

Cc: **ERIC CHAN**

auburnauto.work@gmail.com / goldencharter@hotmail.com

UEN NO.201302032G

CENTRO-LEGAL LAW CORPORATION is incorporated as a company in Singapore

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/01/2019 14:38
Date Of Accident	04/01/2019 12:00
Exact Location Of Accident	CTE TOWARDS TOWN NEAR BENDEMEER SEC SCH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT6679D
Insured/Policyholder	
Name Of Registered Owner	COVE RENTALS PTE LTD
Co Reg No	201626878M
Email Address	COVERENTS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87978998
Alternative Phone No	OFFICE-87978998

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5105091044 (TP)
Cover Note Number	

Driver

Name of Driver	JEREMY LLOYD GOH SWEE HUAT
NRIC No	S1542380C
Date Of Birth	11/08/1962
Occupation	OUTDOOR
Date Of Driving Pass	30/10/1982
Driving Experience	36 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84881338
Fax Number	
Contact Number	OTHERS-84881338
E Mail Address	LNMSINCE1985-ADM@YAHOO.COM.SG

Address 33 TERRASSE LANE #01-73
 Postcode 544780
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? NO
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : UNKNOWN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: UNABLE TO UPLOAD
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLS2550Z
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver KEVIN HAO YU
 NRIC/Passport Number S8785699B
 Contact Number 93804156
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name	JEREMY LLOYD GOH SWEE HUAT
Approximate Age	
Injuries Sustain	WHIP LASH
Injured person in which vehicle?	SJT6679D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : 6363 0123

Email: auburnauto.work@gmail.com

*A101 Not Notified
Kenneth (Ukk) Li Sing 83800k
Resurvey After Paint*

15-Jan-19

5 days

Vehicle No.: SJT 6679 D
Model: Mazda 3

<u>QTY</u>	<u>Description</u>		<u>AMT</u>	<u>SS</u>	
	<u>List Items</u>				
1	Rear boot lid	949.30	\$	By	949.30 ✓
1	Rear boot lock		\$	By	148.80 ✓
1	Rear boot rubber		\$	By	118.80 X
2	Rear boot hinges		\$	R	216.40 X
1	Rear boot "3" emblem		\$	By	40.50 ✓
1	Rear boot "mazda" emblem		\$	By	48.60 ✓
1	Rear boot logo		\$	By	56.90 ✓
2	Rear boot lamps		\$	By	522.90 X
2	Rear taillamps		\$	By	2,076.80 X
1	Rear end panel		\$	R	321.80 X
1	Rear end panel inner garnish		\$	R	162.80 X
1	Rear bumper	1039	\$	By	1,026.70 ✓
2	Rear bumper brackets		\$	CM	30.00 ✓
1	Rear bumper reinforcement		\$	By	454.50 ✓
2	Rear bumper side retainers		\$	By	77.00 X
2	Rear bumper reflectors		\$	CM	117.00 ✓
1	Rear spare tyre board		\$	By	411.10 X
1	Rear spare tyre panel		\$	R	2,221.00 X
1	Rear exhaust silencer	954	\$	By	953.80 ✓
2	Rear exhaust mountings		\$	By	91.00 X
2	Rear fender inner trims		\$	By	319.00 X
			\$		10,364.70
			\$	Less 20%	2,072.94
			\$		8,291.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

c/f: \$ 8,291.76

Special Nett Items

1	Rear bumper clip (1 set)	\$	<i>Nu</i> 45.00	<i>✓</i>
1	Rear number plate with holder	\$	<i>CMA</i> 50.00	<i>45sn</i>
1	Rear reverse sensor (1 set)	\$	<i>DD</i> 350.00	<i>200sn</i>
		\$	<u>445.00</u>	

S/N. Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	<i>20l</i>
2	To remove and refit inner garnishes.	\$	150.00	<i>60l</i>
3	To remove and refit rear reverse sensor.	\$	150.00	<i>50l</i>
4	To transfer boot lid mechanism and wiring assembly.	\$	120.00	<i>50l</i>
5	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	<i>60l</i>
6	To apply tuff kote.	\$	<i>Nu</i> 150.00	<i>X</i>
7	Panel beating.	\$	1,600.00	<i>500l</i>
8	To respray painting.	\$	1,500.00	<i>660l</i>
		\$	<u>3,900.00</u>	

Total Repair Cost : \$ 12,636.76

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jan 2019 Edit Reg		14 Jan 2019 00:00 Edit Adj Rpt	S\$3,800.00 Edit Estimates	S\$3,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CHUAN LUCK PTE LTD , Co. Reg. No.: 200514549C								
Main Claimant:	-								
Vehicle Reg. No.:	SJT6679D	Date of Loss:	04/01/2019 00:00 - :59 [110 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8842709626SG	Policy/Cover Note No.:	1700053075 (Comprehensive) Coverage: 15/09/2017 - 14/09/2019						
Vehicle Reg. No. (Insured):	SLS2550Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (15/01/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJT6679D (8842709626SG)**
[SLS2550Z]
TP
-
Jan 4 2019 12:00AM
[CHUAN LUCK PTE LTD]
Auburn Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print	
1	15/01/19 12:04	Accident Statement From:OD - Reg. No: SLS2550Z, Claimant: CHUAN LUCK PTE LTD							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
2	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
3	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
4	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
5	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
6	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
7	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
8	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
9	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
10	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
11	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
12	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
13	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
14	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
15	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
16	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
17	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
18	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
19	17/01/19 12:07	General View							Load JPG	<input checked="" type="checkbox"/>	
20	26/03/19 11:00	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
21	26/03/19 11:00	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
22	26/03/19 11:00	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
23	26/03/19 11:00	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
24	26/03/19 11:00	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
25	26/03/19 11:00	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	17/01/19 12:06	TP GIA REPORT							Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
----------------------------	--------------------------------------	-------------------------------------	--------------------------------------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19000809/KVD3E2

Date: 27/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700053075
Claimant Vehicle No : SJT6679D	Insured Vehicle No :	SLS2550Z
Date of Loss: 04/01/2019	Nature of Claim:	TP
		Claim No: 8842709626SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT6679D	Engine No:	Z6808910
Make & Model:	HONDA CITY, 1.5 (A)	Chassis No:	JM6BL10Z1A0114535
Reg. Date:	26/10/2009 (Man. Year: 2009)	Odometer:	176635 km
Colour:	Metallic Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,736.76	3,350.88	5,385.88	61.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,400.00	2,500.00	64.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,636.76	4,750.88	7,885.88	62.40
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	12,636.76	3,800.00	8,836.76	69.93

INSPECTION

Date of Assignment:	14/01/2019	
Date Inspected:	16/01/2019 Inspected At:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE Singapore 575721
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	949.30 FL	*949.30 FL
2	1		*REAR BOOT LOCK	Dented	148.80 FL	*148.80 FL
3	1		*REAR BOOT RUBBER	Serviceable	118.80 FL	*- FL
4	2		*REAR BOOT HINGES	Repair	216.40 FL	*- FL
5	1		*REAR BOOT 3 EMBLEM	Necessary	40.50 FL	*40.50 FL
6	1		*REAR BOOT MAZDA EMBLEM	Necessary	48.60 FL	*48.60 FL
7	1		*REAR BOOT LOGO	Necessary	56.90 FL	*56.90 FL
8	2		*REAR BOOT LAMPS	Serviceable	522.90 FL	*- FL
9	2		*REAR TAILLAMPS	Serviceable	2,076.80 FL	*- FL
10	1		*REAR END PANEL	Repair	321.80 FL	*- FL
11	1		*REAR END PANEL INNER GARNISH	Serviceable	162.80 FL	*- FL
12	1		*REAR BUMPER	Buckled	1,026.70 FL	*1,026.70 FL
13	2		*REAR BUMPER BRACKETS	Cracked	30.00 FL	*30.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	454.50 FL	*454.50 FL
15	2		*REAR BUMPER SIDE RETAINERS	Serviceable	77.00 FL	*- FL
16	2		*REAR BUMPER REFLECTORS	Cracked	117.00 FL	*117.00 FL
17	1		*REAR SPARE TYRE BOARD	Serviceable	411.10 FL	*- FL
18	1		*REAR EXHAUST SILENCER	Bent	953.80 FL	*953.80 FL
19	2		*REAR EXHAUST MOUNTINGS	Serviceable	91.00 FL	*- FL
20	2		*REAR FENDER INNER TRIMS	Serviceable	319.00 FL	*- FL
21	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
22	1		*REAR NUMBER PLATE WITH HOLDER	Cracked	50.00 FS	*45.00 FS
23	1		*SET REAR REVERSE SENSOR	Dented	350.00 FS	*200.00 FS
24	1		*REAR SPARE TYRE PANEL	Repair	2,221.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,809.70	4,116.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,072.94	765.22
Total Parts (\$\$)	8,736.76	3,350.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	50.00
5	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	60.00
6	TO APPLY TUFF KOTE	New	150.00	0.00
7	PANEL BEATING	New	1,600.00	500.00
8	TO RESPRAY PAINTING	New	1,500.00	660.00
Gross Labour Cost (S\$)			3,900.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >