

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05907

Vehicle Insured : SGS7572L

Accident Date : 10-Jan-2019

Date : 12-Jan-2019

Our Ref : 219006 (AXA) / CHAN

PAGE : 1

NG LIMOUSINE

BLK 474 TAMPINES STREET 43

#04-100

Singapore 520474

*Not Authorised
Return B4 paint*

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE SUPPER GL PC6537Z

- 1 pc Tail gate
- 1 pc Tail gate logo
- 1 pc Tail gate "HIACE" emblem
- 1 pc Tail gate "SUPER GL" emblem
- 1 pc Rear bumper fascia
- 4 pcs Rear bumper bracket
- 1 pc Rear bumper step panel
- 1 pc End panel -outer
- 1 pc End panel top garnish

	2,150.70	✓
	66.20	✓
	46.30	✓
	51.90	✓
	393.70	✓
@ S\$ 23.40	93.60	?
	237.60	?
	309.40	?
	158.60	x
	3,508.00	
Less 25% :	877.00	

- 1 pc Tail gate glass sealant
- 1 pc Tail gate 70km/h sticker
- 1 pc Tail gate "EMERGENCY" sticker
- 1 pc Rear bumper reverse sensor(set

2,631.00	40sn
60.00	sn
15.00	sn
15.00	sn
300.00	sn ?

To remove & refix rear windscreen glass and conduct water leak test.

150.00 120

To apply undersealing

60.00 ?

To putty and spray replaced parts

900.00 600

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

800.00 ?

Total : S\$ 4,931.00

Singapore Dollars Four Thousand Nine Hundred and Thirty One Only

LKK Auto Consultants Home Notice

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: