

ASS. REC. BY:

REF:

08/FCS19000812/ Jt d3 n2

Special Instruction:

Surveyor:

Hwe Jie

ASSIGNMENT (Office)

CWS

From (Person):

May chua

of

Pef

Date/Time: 2.28pm @ 14/1/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

8MD 5841G

Insured:

SHA8730Z

at Workshop m/s

Keh Motor

Tel:

68413838

of

1Subi Rd 4

Policy No:

Claim No:

D19000382MF84

Sum Insured:

Excess:

Make of Veh

(Client's Record)

D.O.A.

11/01/2019

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

3.21pm @ 14/1/19

Person Contacted:

Desmond

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

8MD 5841G-X

SHA8730Z-CS/FCS15016036/UH62

DVA: 21/1/19

Part by part \$2069.40 (Red: 590; 22%)

REF: FCI

Hwee Jie

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SMD 58416 Yr Regn: 27 Aug 2018

Type: M/Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz C.C. 1318

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 8263 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMGK3850JX226718

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 11/1/19 D.O.I. 2/4/19

Survey held at Kah motor

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Roof top or

N/S front

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 12 APR. 2019

Date/Time. File Pass to?

1) 12/4 Typist ☐ Preli. ReportDate/Time. File Return to? ☒ Final Report

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ + P5.00 SI

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format: TP

Lump Sum / I.S. (\$): 2069.40

110

50

30

19

229



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000382MFSH

Date: 3/4/2019

Our Ref: CS/FCI19000812/Jtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMD 5841G

Please be informed that we had conducted the inspection of the abovementioned vehicle
2/4/2019 at the premises of M/s Kah Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>2,659.40</u>
Revised Estimate Amount	: S\$ <u>1,889.40</u>
"Check" Items Amount	: S\$ <u>00.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Hwee Jie

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	11-01-2019	Our Ref No. D19000382MFSH
Accident Date	11-01-2019	Claim Type. Third Party
Insured Vehicle	SHA8730Z	Third Party Vehicle. SMD5841G
Survey Location	15 UBI ROAD 4	
Contact Person.	DESMOND TOH	
Contact No.	68413838/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 3 April 2019 5:47 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000382MFSH/1
Attachments: PRELI ADVISED SMD 5841G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMD 5841G**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 14 January 2019 3:24 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000382MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 14 January 2019 2:28 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000382MFSH/1

Dear Sir/Mdm,

Denise Tay (LKKAUTO)

From: Hwee Jie (LKK Auto)
Sent: Friday, 12 April 2019 9:29 AM
To: Anikka Lai
Cc: Denise Tay (LKKAUTO)
Subject: RE: SMD5841G - FINALIZATION

Hi anikka,

Finalized P/P \$2,069.40/- 3days.

Best Regards,

Hwee Jie | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai [<mailto:anikkalai@honda.com.sg>]
Sent: Tuesday, 9 April, 2019 8:32 PM
To: Hwee Jie (LKK Auto)
Cc: SUR; Hsiao Tong (LKKAUTO)
Subject: SMD5841G - FINALIZATION

Dear Hwee Jie,

We enclosed the total final repair costs for,

Vehicle No.	SMD5841G
Final Repair Costs (exclude GST)	\$2069.40
Repair Period* (Days)	3 days

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9796C
Vehicle Details	
Vehicle No.:	SMD5841G
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	L13B11031069
Chassis No.:	JHMGK3850JX226718
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,769.00
Original Registration Date:	27 Aug 2018
First Registration Date:	27 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$5,769.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Aug 2028
PARF Rebate Amount:	\$4,326.00
Intended COE Rebate Details	
COE Expiry Date:	26 Aug 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,000.00
COE Rebate Amount:	\$23,487.00
Total Rebate Amount:	\$27,813.00

The information contained herein is correct as at 03 Apr 2019

OK



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877
Registration No : SMD5841G
Chassis No : JHMGK3850JX226718
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : AW KAH HOE
Ins Policy No. :
Date of Accident : 11/1/2019

Document No. : SQT19000193 **Page** 1
Date : 11. Jan 2019
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L13B11031069
Date | Time : 11. Jan 2019 3:49:36 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:AW KAH HOE OWNER INSURER:TOKIO MARINE INS ACC DATE:11/01/2019 SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:SHA8730Z						
71193-T5A-000	SPACERR.FR.BUMPER <i>rec</i>	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER <i>rec</i>	1	10.40	25	7.80	0.55	8.35
42700-T5S-M72	WHEEL,DISK AL 15X7 <i>SCR</i>	1	418.40	25	313.80	21.97	335.77
Sum Item					329.40	23.07	352.47
BOSUN	SUNDRIES <i>rec</i>	1	50.00	20	50.00	3.50	53.50
GSG96R	INSTALL RIMS WITH TYRES	1	100.00	80	100.00	7.00	107.00
BKFE21K	STRAIGHTEN ALIGN FR L FENDER.	1	800.00	560	800.00	56.00	856.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 1	1	1200.00	900	1200.00	84.00	1284.00
Sum Labor					2150.00	150.50	2,300.50
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

Survey By Hwee Jie-LKK
 Date & Time 2/4/19
 Excess -
 Status P/P 3days.
 Signature [Signature]

Total Amount 2,659.40 186.17 2,845.57
Total (Inclusive of GST) 2,845.57

Printed on 2/4/2019 2:07:06 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

LKK Auto Consultants hereby notify the Repairer of the following:
 before after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK3850JX226718
License No: SMD5841G
Mileage: 8262
Engine No: L13B11031069

Document No: SVO19021028
Printed By: ANIKKALAI
Order Date: 2. April 2019
Order Time: 3:02:43 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld Amount	GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:AW KAH HOE OWNER INSURER:TOKIO MARINE INS ACC DATE:11/01/2019 SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:SHA8730Z						
71193-T5A-000	SPACERR.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
42700-T5S-M72	WHEEL,DISK AL 15X7	1	418.40	25	313.80	21.97	335.77
	SUM PARTS:				329.40	23.07	352.47
BOSUN		1	20.00		20.00	1.40	21.40
	SUNDRIES						
GSG96R		1	80.00		80.00	5.60	85.60
	INSTALL RIMS WITH TYRES						
BKFE21K	1466	1	560.00		560.00	39.20	599.20
	STRAIGHTEN ALIGN FR L FENDER.						
BP05R	1718	1	900.00		900.00	63.00	963.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.						
	SUM LABOUR:				1,560.00	109.20	1,669.20
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	SUM EXT SERVICE:				180.00	12.60	192.60
	TOTAL SGD				2,069.40	144.87	2,214.27
	Total Payable (SGD)						2,214.27

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000812/Jtd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8730Z	Veh. Inspected	SMD 5841G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000382MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	14/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ	c.c	1318	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JHMGK3850JX226718	Colour	GREY	
Odometer	8263	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	175/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	175/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	175/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/01/2019	Inspection Date	02/04/2019	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 5841G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SPACERR FR BUMPER (SN)	NECESSARY	7.80	7.80
1	SPACERL FR BUMPER (SN)	NECESSARY	7.80	7.80
1	WHEEL,DISK AL 15X7 (SN)	SCRATCHED	313.80	313.80
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			379.40	349.40
	LABOUR			
	INSTALL RIMS WITH TYRES.		100.00	80.00
	STRAIGHTEN ALIGN FR L FENDER.		800.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		1,200.00	900.00
	WHEEL ALIGNMENT X4.		180.00	180.00
			2,280.00	1,720.00
	GRAND TOTAL		2,659.40	2,069.40
	RECOMMENDED COST OF REPAIRS			2,069.40

Report Ref No. CS/FCI19000812/Jtd3n2

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.