

VANTAGE AUTOMOTIVE LIMITED

MS1110 Toms

(A Sime Darby Motors Company)
Co. Regs. No. 192600045M GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942

Service Booking: 6477 7369
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300



Finalized

SERVICE TAX INVOICE RE-PRINT

REPAIR ORDER NO. B9 46104	Date IN 17/01/2019	Invoice Number	Page No. 1 of 1
	Payment Term 30 Days From Invoice	Invoice Date ??	
	Customer Service Advisor Chong Min Seng	Invoice By Katherine Chong Fui Poh	

CUSTOMER INFORMATION	INVOICE TO 77
Sime Darby Services Private Limited 305 Alexandra Road #02-01 Vantage Automotive Centre Singapore 159942	Axa Insurance Pte Ltd No. 8 Shenton Way #24-01 Axa Tower Singapore 068811

REGISTRATION No. SLP3513R	CHASSIS No. KNAFJ411MH5714335	STOCK No. 800427	REGISTRATION DATE 01/06/2017	MODEL	MILEAGE 31370
-------------------------------------	---	----------------------------	--	-------	-------------------------

CODE	DESCRIPTION	UNITS	DISC %	NETT
	TO CONDUCT TP CLAIM - AXA AGAINST SDR388P DOA.27/11/2018	0	0.00	0.00
	SUNDRIES	1	0.00	30.00
	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING.(NETT)	1	0.00	150.00
	TO REMOVE AND REFIX REAR BUMPER REVERSE SENSOR, CONDUCT DISTANCE SETTING(NETT)	1	0.00	150.00
	LABOUR TO REMOVE,REPLACE REAR BUMPER.	1	0.00	600.00
	LABOUR TO PUTTY AND RESPRAY REAR BUMPER	1	0.00	600.00
Sub-Total :				1,530.00
CODE	DESCRIPTION	UNITS	DISC %	NETT
N KS86611A7800	REAR BUMPER	1	10.00	601.20
N KS86695A7800	REAR BUMPER CENTER COVER	1	10.00	423.00
N KS86613A7001	REAR BUMPER BRACKET LH	1	10.00	29.70
N KS86614A7001	REAR BUMPER BRACKET RH	1	10.00	29.70
Sub-Total :				1,083.60

Attending CSO : Min Seng
Should you require further explanation, please reach me at 83833190

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	2,613.60
Labour Charges	1,530.00	Less Insurance Excess	S\$	0.00
Parts Charges	1,083.60	GST @ 7%	S\$	182.95
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	2,796.55
		Less Deposit/Voucher	S\$	0.00

Computer generated invoice. No signature is required.	Amount Payable	Sub-Tot S\$	2,796.55
---	-----------------------	-------------	-----------------

All amounts are in Singapore Dollars.
Work was carried out subject to the Company's Terms and Conditions of Service.
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.
For credit purchases, interest @1% per month will be debited on overdue amounts.



BMW Distributor

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401659N GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159942
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

896, Dunearn Road #01-01
Sime Darby Centre
Singapore 589472
Tel. 63190500 (Sales)
63190555 (AfterSales)
Fax 64691709 (Sales)

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190800 (Sales)
63190888 (AfterSales)
Fax. 63441332



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b9 4003
Date Estimated : 11/01/2019
Prepared By : Chong Min Seng

Page No. : 1 of 2

<p>- ESTIMATE REPAIR FOR - Sime Darby Services Private Limited 305 Alexandra Road #02-01 Vantage Automotive Centre Singapore 159942</p>	<p>- ACCOUNT - 610020 Sime Darby Services Private Limited 305 Alexandra Road #02-01 Vantage Automotive Centre Singapore 159942</p>
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP3513R	KNAFJ411MH5714	01/06/2017		0

DESCRIPTION	VALUE
TO CONDUCT TP CLAIM - AXA	0.00
SUNDRIES	150.00
ELETRICAL WIRING CHECK FOR PROPER FUNCTIONING (NETT)	150.00
TO REMOVE AND REFIX REAR BUMPER REVERSE SENSOR CONDUCT DISTANCE TEST(NETT)	150.00
TO REPAIR, REPLACE REAR BUMPER	1,200.00
TO PUTTY, SPRAY PAINT REAR REAR BUMPER.	1,000.00
TUFF KOTE BODY CAVITY PRESERVATION(PER PANEL @ \$60 NETT)	120.00
Total Labour 1:	2,770.00

PART NUMBER	DESCRIPTION	QTY	PRIC	DISC	VALUE
86611-A7800	REAR BUMPER DE	1	668.00	10.00	601.20
86694-A7800	REAR BUMPER CENTER COVER DE	1	47.00	10.00	42.30
86631A7800	REAR BUMPER BEAM ? X SRC	1	313.00	10.00	281.70
86614A7001	REAR BUMPER BRACKET RH DE	1	33.00	10.00	29.70
86613A7001	REAR BUMPER BRACKET LH DE	1	33.00	10.00	29.70
	REVERSE SENSOR EYE (RH) ? X SRC	1	33.00	10.00	29.70
Total Parts :					984.60



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

896, Dunearn Road #01-01
Sime Darby Centre
Singapore 889472
Tel. 63190500 (Sales)
63190555 (AfterSales)
Fax 64691709 (Sales)

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190800 (Sales)
63190888 (AfterSales)
Fax. 63441332

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b9 4003	Page No.	: 2 of 2
Date Estimated	: 11/01/2019		
Prepared By	: Chong Min Seng		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP3513R	KNAFJ411MH57143	01/06/2017		0

Resin
By 9000068
3 days
15/01/19 @ 1400hrs
Resin by paint

Labour 1	:	2,770.00
Parts	:	984.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	262.82
Grand Total	:	4,017.42

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** GST AMOUNT SUBJECT TO CHANGE **