

ASS. REC. BY:

REF

cs/III 9000819/Usd301

Special Instruction:

Surveyor

From (Person)

Morris

Gabriel Wee

ASSIGNMENT (Office)

of III

Date/Time: 14/11/19 @ 4.13pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJB 6343Y

Insured:

SHD 3182Y

at Workshop m/s

Polymath Garage

Tel:

8228 9818

of

1 Kaki Bukit Ave 6 # 02-02

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/01/19

CA / REV / REP. / REV 24 HRS^{up}

15/1/19

H.O.D. Endorsement:

Date/Time:

5:17pm 14/11/19

Person Contacted:

Nigel

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

Morris

SJB 6343Y

NA/CTI 19000727/KA

DUA: 11/1/19

SHD 3182Y - NA/CTI 19000727/KA

DUA: 11/1/19

Marus

REF:

III

ASSIGNMENT

From Date 15/01/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJB 6393Y
at Workshop m/s Polymath Garage
of 1kaki Bukit Ave 6 #02/02

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

44500

IDAC Accident Rpt:

Consistent? : Yes or No

CA / PR Sec:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

(wp)

LTA 34493

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SJB 6393Y Yr Regn: 4 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota wish

C.C 1794

Colour:

Silver

A/C Insured / Std / NI / NA

Sp. Reading:

171001

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

2NE 100305715

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/1/19

D.O.I.

15/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25-4-2016 7.15 AM.
quently estimate. left 10007.

21/1/19 2/5 @ 10,020 confirmed with N. gal
(\$ 20,737.49 Red - 68%)

RECEIVED 21 FEB 2019

Date/Time: File Pass to?

21/02/19

1) Typist

Date/Time: File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 16

Resurvey No. of Trip: 3

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

)

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

Lump Sum / I.B.I: \$ 10,000/- H/S

450

10

460

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 14 January 2019 4:13 PM
To: Ruby Ong; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Polymath Garage Pte Ltd; Sherini Pillai; Zuhaidah Samsuri
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY FOR SJB 6393Y [OUR REF. TCL.GCN.RO.50021.19.PG]

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJB6393Y and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: 14 January, 2019 2:49 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Polymath Garage Pte Ltd <enquiry@polymathgarage.com.sg>
Subject: REQUEST FOR PRE-REPAIR SURVEY FOR SJB 6393Y [OUR REF. TCL.GCN.RO.50021.19.PG]
Importance: High

Your ref: SHD 3182Y
Our ref: TCL.GCN.ro.50021.19.pg

WITHOUT PREJUDICE

14 January 2019

India International Insurance Pte Ltd
Motor Claims Department
64 Cecil Street
#04-02 IOB Building
Singapore 069428

By Email Only

VERY URGENT

Dear Sirs

CLAIMANT: WONG MUN KIT ROBIN

NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - ACCIDENT INVOLVING SJB 6393Y, SHD 3182Y, SHB 4967D & SHB 5248P AT JUNCTION OF SENGKANG WEST AVENUE & FERNVALE ROAD ON 11 JANUARY 2019 @ 2000HRS

We are instructed by Wong Mun Kit Robin to notify you of a road traffic accident on 11 January 2019 at about 2000hrs at junction of Sengkang West Avenue & Fernvale Road involving our client's vehicle registration number SJB 6393Y and vehicle registration number SHD 3182Y driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, our client proposes to appoint Marcus of LKK Auto Consultants Pte Ltd as the single joint expert to carry out the pre-repair survey for SJB 6393Y.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : **POLYMATH GARAGE PTE LTD**
1 Kaki Bukit Avenue 6
#02-02 Autobay
Singapore 417883

Contact Person : **Mr Nigel Ong / Mr John Phoon @ 8228 9818**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our clients' right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this

message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	12/01/2019 13:38
Date Of Accident	11/01/2019 20:00
Exact Location Of Accident	JUNC OF SENGKANG WEST AVE AND FERNVALE RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJB6393Y
Insured/Policyholder	
Name Of Registered Owner	WONG MUN KIT ROBIN
NRIC No	S7734441A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92377392
Alternative Phone No	OTHERS-92377392
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH 1.8 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3093121802
Cover Note Number	
Driver	
Name of Driver	WONG MUN KIT ROBIN
NRIC No	S7734441A
Date Of Birth	17/11/1977
Occupation	OUTDOOR
Date Of Driving Pass	07/10/1999
Driving Experience	19 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92377392
Fax Number	
Contact Number	OTHERS-92377392
Email Address	NOEMAIL

Address	BLK 430B FERNVALE LINK #11-221
Postcode	792430
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIAN WEN YAN, GINA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800 - 3438999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20190112/2013

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REVERT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD3182Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOK CHIN NAM
NRIC/Passport Number	S0056342J

Contact Number 96269436
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHB4967D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHB5248P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver NG BEE TIAN
NRIC/Passport Number S1212242Z
Contact Number 91052598
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name WONG MUN KIT ROBIN
Approximate Age
Injuries Sustain SLIGHT
Injured person in which vehicle? SJB6393Y
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name LIAN WEN YAN, GINA
Approximate Age
Injuries Sustain SLIGHT
Injured person in which vehicle? SJB6393Y
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 11/1/19


Driver's Signature
(if driver is not the policyholder)
Date & Time: 11/1/19


Reporting Centre Personnel's Signature
Name: 12/1/2019
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



A: 57B6593Y
B: 57D3182Y
C: 5HB4967D
D: 5HD5248P

3000000 WEST AVE X FERNVALE RD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE STATED DATE / TIME AND LOCATION, I WAS
TRAVELING ON SAUGKANG WEST AVE ON MY WAY HOME
I STOPPED BEHIND A VEHICLE DUE TO RED LIGHT
ALL OF A SUDDEN VEHICLE "B" COLLIDED ONTO MY REAR
AND MY VEHICLE MOVE FORWARD AND HITS ONTO MY
FRONT VEHICLE. AFTER THAT I REALISE I WAS INVOLVE
IN A 4 CARS ACCIDENT WE PROCEED TO INSURANCES

PLS Ref. to the Police Report
T/2019042/2019

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: 11/1/19

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

12/11/2019

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance


Articles

Forum

Resources

IS YOUR CAR DUE FOR SCRAP OR EXPORT?

Use Our **FREE** Service To Get The Best Selling Price!



SGCARMART **QUOTZ**
Getting More From Your Car

Toyota Wish

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Thrive Auto » Toyota Wish 1.8A (COE till 05/2026)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres



With advanced charting and analysis tools



TRADE NOW

This advertisement has not been reviewed by the Monetary Authority of Singapore. Leverage trading is high risk. Losses can exceed investments.

Compare

Toyota Wish 1.8A (COE till 05/2026)

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

- Add to Shortlist
- Add to Compare
- Add a Note
- Report Error
- More Actions
- Share

Car Details

Price	\$42,800	?
Depreciation	\$5,800 /yr	?
Reg Date	18-Jul-2006 (7yrs 4mths 16days COE left)	
Manufactured	2006	?
Mileage	70,000 km (5.6k /yr)	
Transmission	Auto	
Engine Cap	1,794 cc	
Road Tax	\$1,264 /yr	?
Power	97.0 kW (130 bhp)	
Curb Weight	1,300 kg	?
Features	Powerful Yet Fuel Efficient DOHC 16 Valves VVT-i Engine. Smooth ECT Steptronic Transmission. Digital Climate Control Aircon. Airbags. ABS.	
Accessories	Leather Interior. Reverse Sensors. Sports Rims. Retractable Side Mirrors. Knockdown Rear Seats.	
Description	Super Low Mileage Done 70,000km Only, Very Well Maintained, View To Appreciate.	
COE	\$46,048	?
OMV	\$18,563	?
ARF	\$20,420	?
Dereg Value	\$33,975 as of today (change)	?
No. of Owners	2	?
Type of Veh	MPV	
Category	COE Car, Low Mileage Car	
Availability	Available	

- Add to Shortlist
- Add to Compare
- Add a Note

Posted on: 08-Jan-2019 | Last Updated on: 14-Jan-2019
Tags: Toyota Wish, toyota wish, 2006 Toyota Wish, 2006 toyota wish, Toyota, Wish, wish, Used Toyota

Upfront Payment

» more Financial info

Transfer Fee	\$25	?
Down Payment	\$12,840 (change)	Maximum 70% Loan ?
1st Instalment	\$450	?
	\$1,346 onwards	



Seller Information

Company	Thrive Auto
	» dealer's pricelist
	» 21 vehs sold 16 vehs available
Address	61 Ubi Avenue 2 #03-07 Search cars nearby this location
Location	Automobile Megamart
Office No	64750078
Contact Person(s)	Carven 84985097 Steven Tan 97480076

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Free Car Valuation

Unsure of how much your car is worth?
Let us tell you how much is the value - no charges & no obligations!

Toyota Wish Price Range Depreciation > 10 year(s) Vehicle Type Submit Advanced Search

Home » Used Cars » GB Auto Pte Ltd » Toyota Wish 1.8A (COE till 06/2026)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres



1 X

Toyota Wish 1.8A (COE till 06/2026)

Overview Financial Insurance Accessories Similar Research Photos Map


Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$44,800	?
Depreciation	\$6,010 /yr	?
Reg Date	19-Jul-2006 (7yrs 5mths 15days COE left)	?
Manufactured	2006	?
Mileage	188,000 km (15k /yr)	?
Transmission	Auto	?
Engine Cap	1,794 cc	?
Road Tax	\$1,264 /yr	?
Power	97.0 kW (130 bhp) View specs of the Toyota Wish (2008-2009)	?
Curb Weight	1,300 kg	?
Features	Powerful 16 Valves VVT-i DOHC Engine, 7 Seater, 4 Speed Steptronic Gearbox, Digital Climate Control Aircon, SRS Airbags, ABS.	?
Accessories	Elegant Silver MPV, Sports Rims, Leather Upholstery, Reverse Sensor, Solar Films, Knockdown Rear Seats, Remote Key Alarm, Original Paintwork Condition	?
Description	Festive Of Giving, My Loss Your Gain, High Loan Available, High Paper Value Of \$36K Plus. Low Maintenance, Low Fuel Consumption, Well Maintained, Flexible In House Loan Packages Available. Call Or SMS To Arrange For A Viewing Now. Trade In Available.	?
COE	\$48,479	?
OMV	\$18,674	?
ARF	\$20,542	?
Dereg Value	\$36,167 as of today (change)	?
No. of Owners	2	?
Type of Veh	MPV	?
Category	COE Car	?
Availability	Available	?

Add to Shortlist Add to Compare Add a Note

Posted on: 19-Dec-2018 | Last Updated on: 10-Jan-2019
Tags: Toyota Wish, toyota wish, 2006 Toyota Wish, 2006 toyota-wish, Toyota, Wish, wish, Used Toyota



Seller Information

Company	GB Auto Pte Ltd * dealer's pricelist * 4 vehs sold 4 vehs available
Address	7030 Ang Mo Kio Avenue 5 #05-30 Search cars nearby this location
Location	Northstar @ AMK
Office No	65706614
Contact Person(s)	Gerald 81800459

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Upfront Payment » more Financial Info

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4441A
Vehicle Details	
Vehicle No.:	SJB6393Y
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1ZZ2566294
Chassis No.:	ZNE100305715
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,128.00
Original Registration Date:	26 Apr 2006
First Registration Date:	26 Apr 2006
Transfer Count:	3
Actual ARF Paid:	\$19,941.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$47,450.00
COE Rebate Amount:	\$34,493.00
Total Rebate Amount:	\$34,493.00

The information contained herein is correct as at 17 Jan 2019

OK



14/1/2019

Estimated repair checklist

Vehicle Registration No. : SJB6393Y

Vehicle Make/Model : Toyota / Wish

Qty List Items

1	Tailgate	1208.10
1	set Tailgate glass moulding	
1	Tailgate logo	
1	Tailgate chrome moulding	
2	Tailgate licence lamps @ 48.60	
1	Tailgate wiper motor	
1	Tailgate inner lock	
1	Tailgate inner pull pocket	
1	Tailgate inner trim board	
1	Tailgate w/strip	
2	Tailgate dampers - R/L @ 210.91	
2	Tailgate hinges- R/L @ 55.60	
2	Taillamps - L/R @ 481.50	
1	Taillamp panel - LH	
2	Taillamp side clips @ 12.60	
1	Rear bumper	483.10
2	Rear bumper reflectors - L/R @ 86.20	
2	Rear bumper brackets - L/R @ 89.50	
2	Rear bumper side retainers - L/R @ 64.43	
6	Rear bumper clips @ 4.50	
1	Rear end panel	
1	Rear end panel inner member	
1	Rear end panel trim	
1	Rear exhaust silencer	
2	Rear exhaust mountings @ 28.80	
1	Rear floor board	
1	Rear floor panel	1100.10
1	Rear fender - LH	
1	Rear fender 1/4 glass moulding	
1	Rear fender air vent	
2	Rear fender inner trim boards - L/R @ 681.43	
2	Rear fender inner shields - L/R @ 116.42	
1	Rear fender inner panel - LH	
1	Rear fuel lid	
1	Rear door - LH	
1	Rear door inner lock	
1	Rear door w/strip	

Amount \$

1,465.50	✓
297.54	✓
68.50	✓
383.95	✓
97.20	✓
581.60	✓
497.34	✓
89.90	✓
341.60	✓
285.53	✓
421.82	✓
111.20	✓
963.00	✓
297.60	✓
25.20	✓
680.60	✓
172.40	✓
179.00	✓
128.86	✓
27.00	✓
581.60	✓
441.90	✓
281.30	✓
822.65	✓
57.60	✓
341.60	✓
1,435.60	✓
1,013.50	✓
181.90	✓
186.95	✓
1,362.86	✓
223.84	✓
841.60	✓
126.90	✓
1,260.90	✓
481.50	✓
211.60	✓



14/1/2019

Estimated repair checklist

Vehicle Registration No. : SJB6393Y

Vehicle Make/Model : Toyota / Wish

Qty List Items

1	Rear	spare wheel carrier
1	Rear	side chassis member - LH
2	Rear	shock absorbers - L/R @ 441.50
1	Rear	axle beam
2	Rear	wheel hub with bearings - L/R
1	Front	bonnet
1	Front	bonnet chrome moulding
1	Front	bonnet lock
1	Front	bonnet seal
1	Front	bonnet insulator
10	Front	bonnet insulator clips @ 4.50
1	Front	bumper
1	Front	bumper: grille centre
1	Front	bumper sponge
1	Front	bumper reinforcement
2	Front	bumper side retainers - L/R @ 64.43
10	Front	bumper clips @ 4.50
1	Front	grille
2	Front	grille top holders @ 12.60
2	Front	headlamps - L/R @ 830.60
1	Front	brace panel
1	Front	support panel
1	Front	support top garnish
2	Horns @ 89.90	
1	Air con condenser	
1	Radiator assy	

Amount \$

Turn/Jan	381.60	2
11	641.50	X
11	883.00	X
11	2,017.60	X
11	761.90	X
11	891.60	X
one	341.63	2
11	122.65	1
11	68.60	X
11	211.43	X
one	45.00	1
10/Dec	683.60	1
10/Dec	179.90	2
10/Dec	140.63	2
Sub	477.37	2
11	128.86	1
one	45.00	1
one	191.62	2
one	25.20	2
11/Dec one	1,661.20	2
11	100.95	1
11	861.90	X
11	126.20	X
11	179.80	X
one	1,297.60	X
11	1,694.50	X
Sub-total	31,129.98	
Less 25%	7,782.50	
Total List	23,347.49	

Special Nett Items

1 set	Tailgate glass sealant
1 set	Rear fender 1/4 glass sealant
1	Rear no. plate
1 set	Rear reverse sensor
1	Front no. plate

Total Special Nett 530.00

335



Polymath Garage Pte Ltd
AutoBay@Kaki Bukit, 1 Kaki Bukit Ave 6 #02-02.
Singapore 417883
24 Hour : +65 8228 9818
Phone: +65 6871 8861 | Fax: +65 6871 8814
Email : enquiry@polymathgarage.com.sg

Estimated repair checklist

Vehicle Registration No. : SJB6393Y

Vehicle Make/Model : Toyota / Wish

Labour charges

To remove, refix tailgate glass / fender 1/4 glass	300.00	200
Towing charges	100.00	50
To check front & rear electrical wiring	80.00	30
To remove, refix rear interior trims to assist repair	150.00	80
To remove, refix rear undercarriage	300.00	x
To check wheel alignment	120.00	x
To remove, refix rear reverse sensor	80.00	50
To remove, refix A/C condenser & refill A/C gas	180.00	100
To respray undercoating	150.00	120
To respray painting and etc	2,200.00	1800
Panel beating, cut, weld remove & replacing above parts	3,200.00	2200
Total Labour	6,860.00	

4630

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

30,737.49

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Feb 2019 12:38 Edit Reg		14 Jan 2019 00:00 Edit Adj Rpt	S\$10,000.00 Edit Estimates	S\$10,000.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: WONG MUN KIT ROBIN , ID: S7734441A									
Vehicle Reg. No.: SJB6393Y		Date of Loss: 11/01/2019 20:00 - :59 [152 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHD3182Y		Policy No. (Claimant):							
		Excess:							
Repairer: Polymath Garage Pte Ltd (HQ) 1 KAKI BT AVENUE 6 #02-02 AUTOBAY, 417883 Kaki Bukit - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/01/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents


*SJB6393Y
[SHD3182Y]
TP
WONG MUN KIT ROBIN
Jan 11 2019 8:00PM
[-]
Polymath Garage Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/02/19 14:11	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
3	21/02/19 14:11	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
4	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
5	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
6	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
7	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
8	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
9	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
10	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
11	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
12	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
13	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
14	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
15	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
16	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
17	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
18	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
19	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
20	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
21	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
22	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
23	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
24	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
25	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
26	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
27	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
28	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
29	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
30	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
31	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
32	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
33	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
34	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
35	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
36	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>
37	21/02/19 14:11	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
52	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
53	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
54	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
55	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
56	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
57	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
58	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
59	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
60	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
61	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
62	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
63	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
64	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
65	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
66	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
67	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
68	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
69	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
70	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
71	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
72	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
73	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
74	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
75	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
76	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
77	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
78	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
79	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
80	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
81	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
82	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
83	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
84	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
85	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
86	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
87	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
89	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
90	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
91	21/02/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
92	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
184	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	21/02/19 14:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	15/01/19 08:41	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19000819/USD3E2

Date: 22/02/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SJB6393Y

Insured Vehicle No : SHD3182Y

Date of Loss: 11/01/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJB6393Y

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2566294

Reg. Date: 26/04/2006 (Man. Year: 2006)

Chassis No: ZNE100305715

Colour: Silver

Odometer: 191001 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,877.48	10,951.50	12,925.98	54.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,860.00	4,630.00	2,230.00	32.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,737.48	15,581.50	15,155.98	49.31
Approved Total (Overridden) (S\$)		10,000.00		
Nett Amount (S\$)	30,737.48	10,000.00	20,737.48	67.47

INSPECTION

Date of Assignment: 14/01/2019

Date Inspected: 15/01/2019 Inspected At:

Polymath Garage Pte Ltd (HQ)

1 KAKI BT AVENUE 6 #02-02 AUTOBAY

Singapore 417883

Estimated Period of Repair: 16.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJB6393Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,465.50 FL	*1,208.10 FL
2	1		*SET TAILGATE GLASS MOULDING	Necessary	297.54 FL	*297.54 FL
3	1		*TAILGATE LOGO	Necessary	68.50 FL	*68.50 FL
4	1		*TAILGATE CHROME MOULDING	Bent / Cracked	383.95 FL	*383.95 FL
5	2		*TAILGATE LICENCE LAMPS	Not Necessary	97.20 FL	*- FL
6	1		*TAILGATE WIPER MOTOR	Not Necessary	581.60 FL	*- FL
7	1		*TAILGATE INNER LOCK	Dented / Jammed	497.34 FL	*497.34 FL
8	1		*TAILGATE INNER PULL POCKET	Not Necessary	89.90 FL	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Deformed / Twisted	341.60 FL	*341.60 FL
10	1		*TAILGATE W/STRIP	Twisted	285.53 FL	*285.53 FL
11	2		*TAILGATE DAMPERS - R/L	Not Necessary	421.82 FL	*- FL
12	1		*TAILLAMPS - L/R	O/S Not Necessary / N/S Broken	963.00 FL	*481.50 FL
13	1		*TAILLAMP PANEL - LH	Dented	297.60 FL	*297.60 FL
14	2		*TAILLAMP SIDE CLIPS	Not Necessary	25.20 FL	*- FL
15	1		*REAR BUMPER	Distorted	680.60 FL	*483.10 FL
16	1		*REAR BUMPER REFLECTORS - L/R	N/S Cracked	172.40 FL	*86.20 FL
17	1		*REAR BUMPER BRACKETS - L/R	N/S Bent	179.00 FL	*89.50 FL
18	2		*REAR BUMPER SIDE RETAINERS - L/R	Cracked / Bent	128.86 FL	*128.86 FL
19	6		*REAR BUMPER CLIPS	Necessary	27.00 FL	*27.00 FL
20	1		*REAR END PANEL	Badly Dented	581.60 FL	*581.60 FL
21	1		*REAR END PANEL INNER MEMBER	Badly Dented	441.90 FL	*441.90 FL
22	1		*REAR END PANEL TRIM	Twisted	281.30 FL	*281.30 FL
23	1		*REAR EXHAUST SILENCER	Not Necessary	822.65 FL	*- FL
24	2		*REAR EXHAUST MOUNTINGS	Not Necessary	57.60 FL	*- FL
25	1		*REAR FLOOR BOARD	Torn	341.60 FL	*341.60 FL
26	1		*REAR FLOOR PANEL	Crumpled / Buckled	1,435.60 FL	*1,100.10 FL
27	1		*REAR FENDER - LH	Badly Dented / Buckled	1,013.50 FL	*1,013.50 FL
28	1		*REAR FENDER 1/4 GLASS MOULDING	No such part	181.90 FL	*- FL
29	1		*REAR FENDER AIR VENT	Twisted	186.95 FL	*186.95 FL
30	2		*REAR FENDER INNER TRIM BOARDS - L/R	Deformed / Cracked	1,362.86 FL	*1,362.86 FL
31	2		*REAR FENDER INNER SHIELDS - L/R	Not Necessary	223.84 FL	*- FL
32	1		*REAR FENDER INNER PANEL - LH	Repair	841.60 FL	*- FL
33	1		*REAR FUEL LID	Repair	126.90 FL	*- FL
34	1		*REAR DOOR - LH	Repair	1,260.90 FL	*- FL
35	1		*REAR DOOR INNER LOCK	Not Necessary	481.50 FL	*- FL
36	1		*REAR DOOR W/STRIP	Not Necessary	211.60 FL	*- FL
37	1		*SPARE WHEEL CARRIER	Torn / Jammed	381.60 FL	*381.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*REAR SIDE CHASSIS MEMBER - LH	Repair	641.50 FL	*- FL
39	2		*REAR SHOCK ABSORBERS - L/R	Not Necessary	883.00 FL	*- FL
40	1		*REAR AXLE BEAM	Not Necessary	2,017.60 FL	*- FL
41	2		*REAR WHEEL HUB WITH BEARINGS - L/R	Not Necessary	761.90 FL	*- FL
42	1		*FRONT BONNET	Repair	891.60 FL	*- FL
43	1		*FRONT BONNET CHROME MOULDING	Cracked	341.63 FL	*341.63 FL
44	1		*FRONT BONNET LOCK	Twisted	122.65 FL	*122.65 FL
45	1		*FRONT BONNET SEAL	Not Necessary	68.60 FL	*- FL
46	1		*FRONT BONNET INSULATOR	Not Necessary	211.43 FL	*- FL
47	10		*FRONT BONNET INSULATOR CLIPS	Necessary	45.00 FL	*45.00 FL
48	1		*FRONT BUMPER	Dented / Deformed	683.60 FL	*581.40 FL
49	1		*FRONT BUMPER GRILLE CENTRE	Torn	179.90 FL	*179.90 FL
50	1		*FRONT BUMPER SPONGE	Torn	140.63 FL	*140.63 FL
51	1		*FRONT BUMPER REINFORCEMENT	Bent	477.37 FL	*477.37 FL
52	2		*FRONT BUMPER SIDE RETAINERS - L/R	Bent	128.86 FL	*128.86 FL
53	10		*FRONT BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
54	1		*FRONT GRILLE	Cracked	191.62 FL	*191.62 FL
55	2		*FRONT GRILLE TOP HOLDERS	Necessary	25.20 FL	*25.20 FL
56	2		*FRONT HEADLAMPS - L/R	Holder Cracked	1,661.20 FL	*1,407.40 FL
57	1		*FRONT BRACE PANEL	Twisted	100.95 FL	*100.95 FL
58	1		*FRONT SUPPORT PANEL	Repair	861.90 FL	*- FL
59	1		*FRONT SUPPORT TOP GARNISH	Not Necessary	126.20 FL	*- FL
60	2		*HORNS	Not Necessary	179.80 FL	*- FL
61	1		*AIR CON CONDENSER	Serviceable	1,297.60 FL	*- FL
62	1		*RADIATOR ASSY	Not Necessary	1,694.50 FL	*- FL
63	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
64	1		*SET REAR FENDER 1/4 GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
65	1		*REAR NO. PLATE	Cracked	45.00 FS	*15.00 FS
66	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
67	1		*FRONT NO. PLATE	Cracked	45.00 FS	*40.00 FS
68	2		*TAILGATE HINGES - R/L	Not Necessary	111.20 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	31,659.98	14,490.34
- List Item Discount on L Items 25.00/25.00% (S\$)	7,782.50	3,538.84
Total Parts (S\$)	23,877.48	10,951.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX TAILGATE GLASS / FENDER 1/4 GLASS	New	300.00	200.00
2	TOWING CHARGES	New	100.00	50.00
3	TO CHECK FRONT & REAR ELECTRICAL WIRING	New	80.00	30.00
4	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	80.00
5	TO REMOVE, REFIX REAR UNDERCARRIAGE	New	300.00	0.00
6	TO CHECK WHEEL ALIGNMENT	New	120.00	0.00
7	TO REMOVE, REFIX REAR REVERSE SENSOR	New	80.00	50.00
8	TO REMOVE, REFIX A/C CONDENSER & REFILL A/C GAS	New	180.00	100.00
9	TO RESPRAY UNDERCOATING	New	150.00	120.00
10	TO RESPRAY PAINTING AND ETC	New	2,200.00	1,800.00
11	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	3,200.00	2,200.00
Gross Labour Cost (S\$)			6,860.00	4,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >