

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0069/2019/NK
Date	:	16-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SLW 6976 G**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Hio Bing Hong
Address	:	Blk 768 Choa Chu Kang St 54 #06-25
	:	(S) 680768
Telephone	:	HP +65 91733637
Type of Claim	:	Third Party Claims
Policy No.	:	170029927-01
Vehicle No	:	<b>SKC 9293 R</b>
Model Code	:	Audi A3 Sedan 1.4 TFSI (A)
Model / Year	:	24/7/2017
Engine No	:	CHZ 383428
Chassis No	:	WAUZZZ8VXH1078385
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	14-Jan-19

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKC 9293 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, foglamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle front bumper and lhs front fender. To repair front bumper. To renew LHS front fender. Reorganise crash managements components. Reinstall all parts removed.	\$ <del>2,100.00</del> 500	
3	To respray front bumper and LHS front fender	\$ <del>1,500.00</del> 1100	
4	To renew LHS front rim and carry out wheel alignment.	S/N \$ 280.00	✓
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>4,432.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKC 9293 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT FENDER LHS <i>Repair</i>	\$778.00	x
2	FRONT FENDER ATTACHMENTS PARTS <i>2</i>	\$65.00	x
3	FRONT FENDER BRACKETS LH <i>2</i>	\$60.00	x
4	FRONT FENDER BRACE <i>new</i>	\$88.00	x
5	WHEEL HOSUING LINERS LH <i>new</i>	\$158.00	x
6	WHEEL HOSUING LINERS ATTACHMENTS PARTS <i>new</i>	\$81.00	x
7	ALUMINIUM RIM <i>cut</i>	\$666.00	✓
8	RUBBER VALVE <i>3 new</i>	\$13.00	x
9	REAR BUMPER GUIDE SECTION LH	\$35.00	x
10	SUNDRIES <i>?</i>	\$300.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 2,244.00
TOTAL LABOUR CHARGES			\$ 4,432.00
GRAND TOTAL			\$ 6,676.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Ling.  
Surveyed Date : 18/01/19.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : ~~Not~~ Not Authorized, 02 hrs

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant