

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0061/2019/NK
Date : 14-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SKX 3755 D**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Goh Yeow hua
Address : 894 Upper Bukit Timah Road
#05-25
Telephone : (S) 678188
Type of Claim : HP +65 9743754
Policy No. : Third Party Claims
Vehicle No. : 1800143896
Model Code : **SMG 2415 H**
Model / Year : Audi A3 Sedan 1.4 TFSI (A)
Engine No : 12/12/2018
Chassis No : CZE 846719
Mileage : WAUZZZ8VXK1007520
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Jan-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 2415 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function.	S/N \$ 280.00	✓
2	To dismantle rear bumper. Reorganise crash managements components. Reinstall all parts removed.	\$ 900.00	500
3	To respray rear bumper.	\$ 800.00	550
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,172.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 2415 H

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>del</i>	\$1,793.00	✓
2	STICKY PAD ?	\$21.00	?
3	REAR BUMPER FIXING SETS <i>new</i>	\$175.00	X
4	WHEEL HOUSING LINERS ADAPTER LH / RH <i>2 new</i>	\$68.00	X
5	REAR BUMPER GUIDE SECTION LH / RH	\$30.00	X
6	LOCKING MECHANISM <i>new</i>	\$53.00	X
7	REAR BUMPER SPOILER <i>let</i>	\$216.00	✓
8	REAR LIGHT REFLECTOR LH / RH <i>2 new</i>	\$76.00	X
9	REAR SENSOR INNER / OUTER	\$462.00	X
10	SEAL RING <i>new</i>	\$12.00	X
11	REAR BUMPER REINFORCEMENT ?	\$522.00	?
12	REAR BUMPER BRACKET LH/ RH <i>new</i>	\$51.00	X
13	REAR BUMPER GUIDE SECTION LH / RH <i>new</i>	\$120.00	X
14	SUNDRIES ?	\$300.00	?
TOTAL SPARE PARTS CHARGES :		\$ 3,899.00	
TOTAL LABOUR CHARGES		\$ 2,172.00	
GRAND TOTAL		\$ 6,071.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Ling.*
Surveyed Date : *17/01/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 03 Days.*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant