

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9066 FAX: 6846 7483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0031/19

DATE : 14-JAN-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : HAI JING TRADING
ADDRESS : 32 ANG MO KIO INDUSTRIAL PARK 2
#01-09 SING INDUSTRIAL COMPLEX
S(569510)
TELEPHONE NO : 97043230 / 91446604

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 5099803170
VEHICLE NO : GBG1036E
MODEL CODE : MVL2RDRE26KW3GBR-D
MODEL/YEAR : NISSAN NV350 PANEL VAN MT EURO 5
ENGINE NO : YD25416863A
CHASSIS NO : JN1MC2E26Z0008004
MILEAGE : 55511 KM
DATE IN : 14/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER — 9645 0084
ACCIDENT DATE : 12/01/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

elmer@tanchoong.com

Not Acknowledged
LKK

31/1/19

The 3rd. party.

Tel. 62533531

4dy.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBG1036E

| S/NO | JOB CODE | NATURE OF JOB | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|----------|--|-------------------|---------------------------|
| 1 | ZZ/001 | LABOR CHARGES TO RENEW OUTER RH SIDE CENTER PANEL RNEW FRT RH SIDE OUTER PANEL & FRT RH DOOR AND 250 | 4680.00 | 1000 |
| 2 | ZZ/002 | FRT RH SLIDING DOOR | | |
| 3 | ZZ/003 | CHARGES TO SPRAY PAINTING SAME 200 | 1600.00 | 700 |
| 4 | ZZ/004 | APPLY SEALANT TO FRT RH DOOR, FRT RH SIDE OUTER PANEL & FRT RH SLIDING DOOR | 300.00 | 200 |
| 5 | ZZ/005 | REMOVE AND TRANSFER FRT RH DOOR MECHANISM TO THE NEW FRT RH DOOR MECHANISM | 80.00 | / |
| 6 | ZZ/006 | REMOVE AND TRANSFER FRT RH SLIDING DOOR MECHANISM TO THE NEW FRT RH SLIDING DOOR | 80.00 | / |
| 7 | ZZ/007 | SUPLY LTA STICKER new | 15.00 | / |
| TOTAL LABOUR CHARGES | | | 6755.00 | |

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBG1036E

| S/NO PARTS DESCRIPTION | PARTS NUMBER | DAMAGED PARTS & PRICES | | |
|---|--------------------------|------------------------|----------|----------------|
| | | NETT | LIST | S/NETT REMARKS |
| 1 SUNDRIES | NPN | | | 50.00 ? |
| 2 RH SIDE OUTER CENTER PANEL | G741B-3XBMA <i>R</i> | 1239.00 | <i>X</i> | |
| 3 FRT RH SLIDING DOOR | H210M-3XBMA <i>ro/sp</i> | 1255.70 | <i>—</i> | |
| 4 FRT RH DOOR WEATHERSTRIP | 80830-3XA0C <i>re</i> | 106.30 | <i>—</i> | |
| 5 FRT RH DOOR OUTER WINDOW MOLDING | 80820-3XA0B <i>re</i> | 149.00 | <i>X</i> | |
| 6 FRT RH DOOR | H010M-3XAMB <i>ro/sp</i> | 1015.00 | <i>—</i> | |
| SUB TOTAL | | 3765.00 | 0.00 | 50.00 |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) | | 753.00 | 0.00 | 0.00 |
| GRAND TOTAL | | 3012.00 | 0.00 | 50.00 |
| OVERALL TOTAL | | 3062.00 | | |

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBG1036E

| | |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES | 6755.00 |
| TOTAL SPARE PARTS CHARGES | 3062.00 |
| GRAND TOTAL | 9817.00 * |

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.