

INS CASE OWNER:

CC

1900

LKK:

IDAC:

ASSIGNMENT

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner? (YES / NO)

HP:

D.O.A:

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
18/1	18/1	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	7/26/4/19 - Khanchana
		After call ltr to OI:	
26/4/19 4.30pm	- Spoke to OI. He confirmed the mva. Informed OI on TP claims, agreed to settle and OI will be affected. OI said police informed him that he should turn only when green +/1 with turning signal. Requested Police letter/decree/PIR. *OI to do addendum. Sent email to OI.	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☒
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice	☒
		LTA / GIA :	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☒

PRELIMINARY ADVICE	Date/Time:	Send By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	US \$ 3700.00	(4 days) Reduction: \$ 2581.00 % 49	Email ☐ Call ☐

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
------------------	------------	---------------	--

Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	NIL
Repair Cost:	US \$ 2889.00		PIR AG. OI.
Loss of Rental (LOR):	US \$ -	(days)	
Loss of Use (LOU):	US \$ 80.00	(\$ 20 x 4 days)	
Loss of Income (LOI):	US \$ -	(\$ x days)	
LOR only ☐ LOU only ☐	☒ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	US \$ 2.00		
Medical:	US \$ -		
Disbursement:	US \$ -	(e.g. Tow/ Independent)	
Legal Cost	US \$ -		
Total:	US \$ 2971.00	Global Sum SS:	

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
---------------	------------	---------------	--

Payee 1:	US \$ 2971.00	Name 1:	Bun Hock Hin Co. Pte Ltd
Payee 2: (Strike if N.A.)	US \$ -	Name 2:	
Payee 3: (Strike if N.A.)	US \$ -	Name 3:	

XGHA

(08/11/13) wef

REF:

ASS. REC. BY: MORIS

AVA

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: F3F6902C

at Workshop n/a 31/11

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 4200

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / FR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time

Action / Instruction

21/11 568 Inform Raymont Max 3500?

L/S \$2700/- (Red = \$2581 / 49'1.)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



BAN HOCK HIN
Co., Pte Ltd

9

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33482

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

AXA INSURANCE SINGAPORE PTE LTD

VEHICLE NO : FBF6902C
MAKE/MODEL : YAM / FZ16

DATE : 14/01/2019
CLAIM NO : 11242
POLICY NO :
FROM : RAYMOND

Not Allowed
h/s 2700/?
4 days
16/1/19 2 hrs 30 mins after repair

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 44885	REPLACE	1.00	\$24.00	24.00
2	BALANCER SET (UNIVERSAL-HEAVY)	REPLACE	1.00	\$52.00	52.00
3	BAR FOOTREST FRONT RH P/N: 40315	REPLACE	1.00	\$16.00	16.00
4	BAR HANDLE (PROTAPER) 22MM	REPLACE	1.00	\$210.00	210.00
5	BEARING P/N: 50211	REPLACE	2.00	\$12.00	24.00
6	BOLT FOOTREST REAR P/N: 44888	REPLACE	1.00	\$5.00	5.00
7	BOX (SWMOTECH) TRAX EVO TOP BOX 38L	REPLACE	1.00	\$910.00	910.00
8	BRACKET UNDER FORK P/N: 52252	REPLACE	1.00	\$268.00	268.00
9	CAP END MUFFLER (BLACK) P/N: 43631	REPLACE	1.00	\$32.00	32.00
10	CLIP FRONT FOOTREST	REPLACE	1.00	\$4.50	4.50
11	COVER OIL ELEMENT P/N: 59799	REPLACE	1.00	\$35.00	35.00
12	COVER TAIL RH (RED)	REPLACE	1.00	\$48.00	48.00
13	COVER TANK RH (RED)	REPLACE	1.00	\$96.00	96.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0083
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
f4	CRANKCASE (CLUTCH SIDE)	REPLACE	1.00	\$96.00	96.00
15	EMBLEM P/N: 50204	REPLACE	1.00	\$8.50	8.50
16	FILTER OIL P/N: 40351	REPLACE	1.00	\$12.00	12.00
17	FORK FRONT ASSY LH (BLACK)	REPLACE	1.00	\$416.00	416.00
18	FORK FRONT ASSY RH (BLACK) P/N: 59801	REPLACE	1.00	\$416.00	416.00
19	GASKET CLUTCH COVER P/N: 52953	REPLACE	1.00	\$13.00	13.00
20	GRAPHIC 3 P/N: 45151	REPLACE	1.00	\$4.50	4.50
21	GRIP TANK (SS) FZ16 (TECHSPEC) P/N: 44874	REPLACE	1.00	\$125.00	125.00
22	HELMET (EVO) RS959 VII	REPLACE	1.00	\$135.00	135.00
23	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	Supply/Install	1.00	\$420.00	420.00
24	LAMP SIGNAL FRONT RH P/N: 45130	REPLACE	1.00	\$16.00	16.00
25	LEVER KICK STARTER	REPLACE	1.00	\$60.00	60.00
26	LEVER SET (RED)	REPLACE	1.00	\$70.00	70.00
27	MIRROR SET (AFTERMARKET)	REPLACE	1.00	\$65.00	65.00
28	MUDGUARD FRONT (RED) P/N: 55147	REPLACE	1.00	\$55.00	55.00
29	NUT SELF LOCKING	REPLACE	1.00	\$10.00	10.00
30	O-RING (WATER PUMP) P/N: 50377	REPLACE	1.00	\$3.50	3.50
31	O-RING OIL FILTER P/N: 46241	REPLACE	1.00	\$7.00	7.00
32	PANEL 2 P/N: 59798	REPLACE	1.00	\$22.00	22.00
33	PEDAL BRAKE P/N: 45125	REPLACE	1.00	\$26.00	26.00
34	PROTECTOR MUFFLER (SILVER) P/N: 40320	REPLACE	1.00	\$44.00	44.00



Quotation Nos : 33482

S/N	Description	Action	Qty	Unit Price	Amount
35	RIM SPORT FRONT (BLACK)	REPLACE	1.00	\$372.00	372.00 <i>2</i> ✓
36	RUBBER FOOTREST FRONT P/N: 40321	REPLACE	1.00	\$9.00	9.00 <i>(1)</i> ✓
37	SCOOP AIR RH (RED)	REPLACE	1.00	\$32.00	32.00 <i>1.7</i> ✓
38	SEAL OIL (11X18X6) CRANKCASE COVER - CLUTCH P/N: 24160	REPLACE	2.00	\$6.00	12.00 <i>2.0</i> ✓
39	SEAL OIL FRONT RIM	REPLACE	1.00	\$3.00	3.00 <i>1.1</i> ✓
40	SENA BLUETOOTH (SMH5-FM)	REPLACE	1.00	\$513.00	513.00 <i>2.0</i> ✓
41	SHROUD AIR P/N: 50471	REPLACE	1.00	\$35.00	35.00 <i>1.1</i> ✓
42	SLIDER FRONT AXLE (MOTOVATION)	REPLACE	1.00	\$425.00	425.00 <i>CRA</i> ✓
43	SPRING RETURN P/N: 45126	REPLACE	1.00	\$6.00	6.00 <i>1.1</i> ✓
44	STEERING CONE SET P/N: 33765	REPLACE	1.00	\$53.00	53.00 <i>1.1</i> ✓
45	STICKER (YAMAHA) LOGO & WORDING	REPLACE	2.00	\$12.00	24.00 <i>2.0</i> ✓
46	STICKER COVER TAIL LH	REPLACE	1.00	\$1.50	1.50 <i>2.0</i> ✓
47	TUBE TOOL (WITH LOCK)	REPLACE	1.00	\$45.00	45.00 <i>1.1</i> ✓
48	WASHER FRONT RIM	REPLACE	1.00	\$1.50	1.50 <i>2.0</i> ✓

SUB TOTAL

\$5,281.00

GST @ 7 %

\$369.67

GRAND TOTAL

\$5,650.67

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature subject to final approval from Insurance Company



LKK Auto Acknowledgement & Acceptance By the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Acknowledged by Repairer
Signature: _____
Date: _____





BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33482

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

AXA INSURANCE SINGAPORE PTE LTD

DATE : 14/01/2019

CLAIM NO. : 11242

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBF6902C

MAKE/MODEL : YAM / FZ16

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 44885	REPLACE	1.00	\$24.00	24.00
2	BALANCER SET (UNIVERSAL-HEAVY)	REPLACE	1.00	\$52.00	52.00
3	BAR FOOTREST FRONT RH P/N: 40315	REPLACE	1.00	\$16.00	16.00
4	BAR HANDLE (PROTAPER) 22MM	REPLACE	1.00	\$210.00	210.00
5	BEARING P/N: 50211	REPLACE	2.00	\$12.00	24.00
6	BOLT FOOTREST REAR P/N: 44888	REPLACE	1.00	\$5.00	5.00
7	BOX (SWMOTECH) TRAX EVO TOP BOX 38L	REPLACE	1.00	\$910.00	910.00
8	BRACKET UNDER FORK P/N: 52252	REPLACE	1.00	\$268.00	268.00
9	CAP END MUFFLER (BLACK) P/N: 43631	REPLACE	1.00	\$32.00	32.00
10	CLIP FRONT FOOTREST	REPLACE	1.00	\$4.50	4.50
11	COVER OIL ELEMENT P/N: 59799	REPLACE	1.00	\$35.00	35.00
12	COVER TAIL RH (RED)	REPLACE	1.00	\$48.00	48.00
13	COVER TANK RH (RED)	REPLACE	1.00	\$96.00	96.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0583
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	CRANKCASE (CLUTCH SIDE)	REPLACE	1.00	\$96.00	96.00
15	EMBLEM P/N: 50204	REPLACE	1.00	\$8.50	8.50
16	FILTER OIL P/N: 40351	REPLACE	1.00	\$12.00	12.00
17	FORK FRONT ASSY LH (BLACK)	REPLACE	1.00	\$416.00	416.00
18	FORK FRONT ASSY RH (BLACK) P/N: 59801	REPLACE	1.00	\$416.00	416.00
19	GASKET CLUTCH COVER P/N: 52953	REPLACE	1.00	\$13.00	13.00
20	GRAPHIC 3 P/N: 45151	REPLACE	1.00	\$4.50	4.50
21	GRIP TANK (SS) FZ16 (TECHSPEC) P/N: 44874	REPLACE	1.00	\$125.00	125.00
22	HELMET (EVO) RS959 VII	REPLACE	1.00	\$135.00	135.00
23	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$420.00	420.00
24	LAMP SIGNAL FRONT RH P/N: 45130	REPLACE	1.00	\$16.00	16.00
25	LEVER KICK STARTER	REPLACE	1.00	\$60.00	60.00
26	LEVER SET (RED)	REPLACE	1.00	\$70.00	70.00
27	MIRROR SET (AFTERMARKET)	REPLACE	1.00	\$65.00	65.00
28	MUDGUARD FRONT (RED) P/N: 55147	REPLACE	1.00	\$55.00	55.00
29	NUT SELF LOCKING	REPLACE	1.00	\$10.00	10.00
30	O-RING (WATER PUMP) P/N: 50377	REPLACE	1.00	\$3.50	3.50
31	O-RING OIL FILTER P/N: 46241	REPLACE	1.00	\$7.00	7.00
32	PANEL 2 P/N: 59798	REPLACE	1.00	\$22.00	22.00
33	PEDAL BRAKE P/N: 45125	REPLACE	1.00	\$26.00	26.00
34	PROTECTOR MUFFLER (SILVER) P/N: 40320	REPLACE	1.00	\$44.00	44.00



S/N	Description	Action	Qty	Unit Price	Amount
35	RIM SPORT FRONT (BLACK)	REPLACE	1.00	\$372.00	372.00 X
36	RUBBER FOOTREST FRONT P/N: 40321	REPLACE	1.00	\$9.00	9.00
37	SCOOP AIR RH (RED)	REPLACE	1.00	\$32.00	32.00 ?
38	SEAL OIL (11X18X6) CRANKCASE COVER - CLUTCH P/N: 24160	REPLACE	2.00	\$6.00	12.00
39	SEAL OIL FRONT RIM	REPLACE	1.00	\$3.00	3.00 X
40	SENA BLUETOOTH (SMH5-FM)	REPLACE	1.00	\$513.00	513.00 ?
41	SHROUD AIR P/N: 50471	REPLACE	1.00	\$35.00	35.00 ?
42	SLIDER FRONT AXLE (MOTOVATION)	REPLACE	1.00	\$425.00	425.00
43	SPRING RETURN P/N: 45126	REPLACE	1.00	\$6.00	6.00 ?
44	STEERING CONE SET P/N: 33765	REPLACE	1.00	\$53.00	53.00 X
45	STICKER (YAMAHA) LOGO & WORDING	REPLACE	2.00	\$12.00	24.00
46	STICKER COVER TAIL LH	REPLACE	1.00	\$1.50	1.50
47	TUBE TOOL (WITH LOCK)	REPLACE	1.00	\$45.00	45.00
48	WASHER FRONT RIM	REPLACE	1.00	\$1.50	1.50

SUB TOTAL

\$5,281.00

GST @ 7 %

\$369.67

GRAND TOTAL

\$5,650.67

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



Look After Consultants hence notify
the Reparat of the following:-

- To resolve before / or spray painting
- To repair damaged part(s) during rework
- To ensure work is done to satisfaction
- To ensure survey is on a "Without Prejudice" basis

• Signature very important and it is required and
is subject to final approval from Insurance Company

Acknowledged by Reparat

Signature:

Date:



CERT NO. 2002-1-0383
ISO 9001 : 2015

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0103Z

Vehicle Details

Vehicle No.: FBF6902C

Vehicle to be Exported: No

Intended Deregistration Date: 16 Jan 2019

Vehicle Make: YAMAHA

Vehicle Model: FZ 16

Primary Colour: Red

Manufacturing Year: 2011

Engine No.: 21C7012904

Chassis No.: ME121C079B2012896

Maximum Power Output: -

Open Market Value: \$2,112.00

Original Registration Date: 13 Oct 2011

First Registration Date: 13 Oct 2011

Transfer Count: 1

Actual ARF Paid: \$317.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 12 Oct 2021

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$2,078.00 ,

COE Rebate Amount: \$568.00

Total Rebate Amount: \$568.00

The information contained herein is correct as at 16 Jan 2019

OK

Listing Type	Paid Ad
Brand	Yamaha (/listing/usedbike/brand/yamaha/)
Model	Yamaha FZ16 (/listing/usedbike/model/yamaha-fz16/)
Engine Capacity	153cc
Classification	2B
Registration Date	18/03/2011
COE Expiry Date	17/03/2021 (2 years 2 months left)
Mileage	3682km
No. of owners	1
Type of Vehicle	Street Bikes (/listing/usedbikes/listing/?bike_type=7)

Price: ^{SGD}\$4000

DETAILS

2011 Yamaha FZ16. Bike in excellent condition. New tyres, IU unit and paintwork. Great for daily commute. Cash deal only. Keen buyers, please contact me for more details or viewing at Bt Batok.

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](/listing/usedbikes/listing/)



Yamaha FZ16

[\(/listing/usedbike/yamaha-yamaha-fz16/10709/\)](/listing/usedbike/yamaha-yamaha-fz16/10709/)



Yamaha FZ16



Yamaha FZ16

[\(/listing/usedbike/yamaha-yamaha-fz16/10711/\)](/listing/usedbike/yamaha-yamaha-fz16/10711/)



Yamaha FZ16

Enquire Transfer Fee

Enquire Transfer Fee			
Vehicle Details			
Vehicle No. :	FBF6902C		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	FZ 16		
Chassis No. :	ME121C079B2012896		
Propellant :	Petrol		
Engine No. :	21C7012904		
Engine Capacity :	153 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	330 kg		
Unladen Weight :	135 kg		
Year Of Manufacture :	2011		
Original Registration Date :	13 Oct 2011		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$2,078.00		
COE Expiry Date :	12 Oct 2021		
Road Tax Expiry Date :	12 Oct 2019		
Inspection Due Date :	12 Oct 2019		
Intended Transfer Date :	15 Jan 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No. : _____ Vehicle Registration No: SLX 4238L
Name (as shown in NRIC) : JAINUL ABADEEN
ABDUL MALIK NRIC/FIN/Passport No : 57163024B
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : 310C Punggol walk, #04-596 Singapore (823319)
Contact (Tel) : _____ Mobile No. : 82689602
Email Address : abdul.jainul@outlook.com
Date of Accident : 03/01/2019 Time of Accident : 9:32 PM
Place of Accident : Along Punggol Field
Insurance Company : AXA Insurance Ptd Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

" THE THIRD PARTY VEHICLE REGISTRATION NUMBER SHOULD BE FBF 6902C AND THE
VEHICLE CATEGORY SHOULD BE MOTORCYCLE. THAT'S ALL! "



Abdul Jainul

Policyholder / Driver's Signature
Date: 02 - MAY - 2019

MP

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/1/2020

Survey Details:

Date of loss	3-Jan-19
Date of appointment	15-Jan-19
Date of survey	16-Jan-19
Location of survey	BAN HOCK HIN CO.PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	FBF6902C
Make and Model	YAMAHA FZ 16 - 153cc
Date of registration	13-Oct-11
Parf Rebate	
Market Value	\$ 4,200.00
Parf Rebate	\$ 569.00
Nett Loss	\$ 3,631.00

Repair details:

Initial Estimate	5,281.00
------------------	----------

Proposed/Revised repair cost:

Parts	\$ 3,073.60
Check items (estimate)	\$ -
Labour	\$ 300.00
Total	\$ 3,373.60
Lump Sum(if applicable)	\$ 2,700.00

Number of days for repair	4 days
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 2,889.00	W/GST
Loss of use	\$ 80.00	4days x \$20
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ 2.00	
Others	\$ -	
Proposed Total	\$ 2,971.00	



<MANDATE IA> - S9M0194A {ACCIDENT INVOLVING SLX 4238L (OI) & FBF 6902C (TP) ON 03/01/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA: NIL (OI BEAT RED LIGHT CAUSED THE COLLISION) - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$2971.00 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 16/01/2020

Reply



Re:<MANDATE IA> - S9M0194A {ACCIDENT INVOLVING
SLX 4238L (OI) & FBF 6902C (TP) ON 03/01/2019}

Type

🔔 Question

Message

Hi Hsiao Tong Pls proceed as per IA-VO

Reply



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

20 JAN 2020

Your Ref :
Our Ref : TP/11242/FBF6902C/SLX4238L

BY FAX & HAND

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

ATTN: Motor Claims Dept

Dear Sir/Madam,

Accident Involving FBF6902C & SLX4238L on 03/01/2019

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$ 2,889.00
2. Loss of Use (4 days x \$20)	\$ 80.00
3. GIA Vehicle Insurance Search Fee	\$ 2.00
TOTAL	\$ 2,971.00

We attached our Tax Invoice and GIA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

Raymond Tan
Manager/Insurance Dept

bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

TAX INVOICE

GST Reg No. : M2-0010542-7

Customer :

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way,

#27-01 AXA Tower

Singapore 068811

MOTOR CLAIMS DEPT

Invoice No. : **DLCR40102788-I11242**

Invoice Date : 16/12/2019

Payment Due Date : 15/01/2020

CLAIM NO. : 11242
POLICY NO. :
VEHICLE NO. : FBF6902C
MAKE/MODEL : YAM / FZ16

S/N	Description	Amount
1	LUMPSUM REPAIR	\$2,700.00
SUB TOTAL		\$2,700.00
GST @ 7 %		\$189.00
GRAND TOTAL		\$2,889.00

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Printed by : RAYMOND

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001: 2015



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19000876/Uga3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: VALE OH

Date : 03-02-2020

Code : ASM



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 4238L	Veh. Inspected	FBF 6902C
Policy No.	P2093575	Coverage (\$)	0.00
Claim No.	S9M0194A	Excess (\$)	0.00
Assign From	VALE OH	Assign Date	15/01/2019

2. Vehicle Particulars & Condition

Make & Model	YAMAHA FZ 16	c.c	153
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	ME121C079B2012896	Colour	RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/70-17	BRIDGESTONE	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70 R17	BRIDGESTONE	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/01/2019	Inspection Date	16/01/2019
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 6902C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	AXLE WHEEL FRONT (CONSISTENT)	CUT	24.00	24.00
1	BALANCER SET (UNIVERSAL-HEAVY) (CONSISTENT)	SCRATCHED	52.00	52.00
1	BAR FOOTREST FRONT RH (CONSISTENT)	CUT	16.00	16.00
1	BAR HANDLE (PROTAPER) 22MM (CONSISTENT)	BENT	210.00	210.00
2	BEARING @ \$12.00 (CONSISTENT)	NOT NECESSARY	24.00	-
1	BOLT FOOTREST REAR (CONSISTENT)	NECESSARY	5.00	5.00
1	BOX (SWMOTECH) TRAX EVO TOP BOX 38L (CONSISTENT)	CUT	910.00	910.00
1	BRACKET UNDER FORK (CONSISTENT)	BENT	268.00	268.00
1	CAP END MUFFLER (BLACK) (CONSISTENT)	CUT	32.00	32.00
1	CLIP FRONT FOOTREST (CONSISTENT)	NECESSARY	4.50	4.50
1	COVER OIL ELEMENT (CONSISTENT)	CUT	35.00	35.00
1	COVER TAIL RH (RED) (CONSISTENT)	TO REPAIR SEE LABOUR	48.00	-
1	COVER TANK RH (RED) (CONSISTENT)	TO REPAIR SEE LABOUR	96.00	-
1	CRANKCASE (CLUTCH SIDE) (CONSISTENT)	CUT	96.00	96.00
1	EMBLEM (CONSISTENT)	NECESSARY	8.50	8.50
1	FILTER OIL (CONSISTENT)	NECESSARY	12.00	12.00
1	FORK FRONT ASSY LH (BLACK) (CONSISTENT)	TO REPAIR SEE LABOUR	416.00	-
1	FORK FRONT ASSY RH (BLACK) (CONSISTENT)	DENTED / BENT	416.00	416.00
1	GASKET CLUTCH COVER (CONSISTENT)	NOT NECESSARY	13.00	-
1	GRAPHIC 3 (CONSISTENT)	NECESSARY	4.50	4.50
1	GRIP TANK (SS) FZ16 (TECHSPEC) (CONSISTENT)	NECESSARY	125.00	125.00
1	HELMET (EVO) RS959 VII (CONSISTENT)	CUT	135.00	135.00
1	LAMP SIGNAL FRONT RH (CONSISTENT)	CUT	16.00	16.00
1	LEVER KICK STARTER (CONSISTENT)	TO REPAIR SEE LABOUR	60.00	-
1	LEVER SET (RED) (CONSISTENT)	CUT	70.00	70.00
1	MIRROR SET (AFTERMARKET) (CONSISTENT)	CUT	65.00	65.00
1	MUDGUARD FRONT (RED) (CONSISTENT)	TO REPAIR SEE LABOUR	55.00	-

Report Ref No. CC4/ASM19000876/Uga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	NUT SELF LOCKING (CONSISTENT)	NOT NECESSARY	10.00	-
1	O-RING (WATER PUMP) (CONSISTENT)	NECESSARY	3.50	3.50
1	O-RING OIL FILTER (CONSISTENT)	NECESSARY	7.00	7.00
1	PANEL 2 (CONSISTENT)	NOT NECESSARY	22.00	-
1	PEDAL FRAME (CONSISTENT)	CUT	26.00	26.00
1	PROTECTOR MUFFLER (SILVER) (CONSISTENT)	CUT	44.00	44.00
1	RIM SPORT (BLACK) (CONSISTENT)	TO REPAIR SEE LABOUR	372.00	-
1	RUBBER FOOTREST FRONT (CONSISTENT)	CUT	9.00	9.00
1	SCOOP AIR RH (RED) (CONSISTENT)	NOT NECESSARY	32.00	-
2	SEAL OIL (11X18X6) CRANKCASE COVER - CLUTCH @ \$6.00 (CONSISTENT)	NECESSARY	12.00	12.00
1	SEAL OIL FRONT RIM (CONSISTENT)	NOT NECESSARY	3.00	-
1	SENA BLUETOOTH (SMH5-FM) (CONSISTENT)	DAMAGED	513.00	513.00
1	SHROUD AIR (CONSISTENT)	NOT NECESSARY	35.00	-
1	SLIDER FRONT AXLE (MOTOVATION) (CONSISTENT)	CRACKED	425.00	425.00
1	SPRING RETURN (CONSISTENT)	NOT NECESSARY	6.00	-
1	SET STEERING CONE (CONSISTENT)	NOT NECESSARY	53.00	-
2	STICKER (YAMAHA) LOGO & WORDING @ \$12.00 (CONSISTENT)	NECESSARY	24.00	24.00
1	STICKER COVER TAIL LH (CONSISTENT)	NECESSARY	1.50	1.50
1	TUBE TOOL (WITH LOCK) (CONSISTENT)	CUT	45.00	45.00
1	WASHER FRONT RIM (CONSISTENT)	NECESSARY	1.50	1.50
	LESS 15% DISCOUNT		-	-542.40
			4,861.00	3,073.60
	LABOUR			
	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS. INCLUSIVE OF THE REPAIR OF COVER TAIL RH (RED), COVER TANK RH (RED), FORK FRONT ASSY LH (BLACK), LEVER KICK STARTER, MUDGUARD FRONT (RED) AND RIM SPORT (BLACK).		420.00	300.00
			420.00	300.00
	GRAND TOTAL		5,281.00	3,373.60

Report Ref No. CC4/ASM19000876/Uga3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00
---	--	--	----------

Report Ref No. CC4/ASM19000876/Uga3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.