



BAN HOCK HIN
Co., Pte Ltd

9

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33482

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

AXA INSURANCE SINGAPORE PTE LTD

VEHICLE NO. : FBF6902C
MAKE/MODEL : YAM / FZ16

DATE : 14/01/2019

CLAIM NO. : 11242

POLICY NO. :

FROM : RAYMOND

Not Allowed
h/s 2700/1?
4 days
16/1/19 2 hrs 30 mins after repair

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 44885	REPLACE	1.00	\$24.00	24.00
2	BALANCER SET (UNIVERSAL-HEAVY)	REPLACE	1.00	\$52.00	52.00
3	BAR FOOTREST FRONT RH P/N: 40315	REPLACE	1.00	\$16.00	16.00
4	BAR HANDLE (PROTAPER) 22MM	REPLACE	1.00	\$210.00	210.00
5	BEARING P/N: 50211	REPLACE	2.00	\$12.00	24.00
6	BOLT FOOTREST REAR P/N: 44888	REPLACE	1.00	\$5.00	5.00
7	BOX (SWMOTECH) TRAX EVO TOP BOX 38L	REPLACE	1.00	\$910.00	910.00
8	BRACKET UNDER FORK P/N: 52252	REPLACE	1.00	\$268.00	268.00
9	CAP END MUFFLER (BLACK) P/N: 43631	REPLACE	1.00	\$32.00	32.00
10	CLIP FRONT FOOTREST	REPLACE	1.00	\$4.50	4.50
11	COVER OIL ELEMENT P/N: 59799	REPLACE	1.00	\$35.00	35.00
12	COVER TAIL RH (RED)	REPLACE	1.00	\$48.00	48.00
13	COVER TANK RH (RED)	REPLACE	1.00	\$96.00	96.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-I-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	CRANKCASE (CLUTCH SIDE)	REPLACE	1.00	\$96.00	96.00
15	EMBLEM P/N: 50204	REPLACE	1.00	\$8.50	8.50
16	FILTER OIL P/N: 40351	REPLACE	1.00	\$12.00	12.00
17	FORK FRONT ASSY LH (BLACK)	REPLACE	1.00	\$416.00	416.00
18	FORK FRONT ASSY RH (BLACK) P/N: 59801	REPLACE	1.00	\$416.00	416.00
19	GASKET CLUTCH COVER P/N: 52953	REPLACE	1.00	\$13.00	13.00
20	GRAPHIC 3 P/N: 45151	REPLACE	1.00	\$4.50	4.50
21	GRIP TANK (SS) FZ16 (TECHSPEC) P/N: 44874	REPLACE	1.00	\$125.00	125.00
22	HELMET (EVO) RS959 VII	REPLACE	1.00	\$135.00	135.00
23	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$420.00	420.00
24	LAMP SIGNAL FRONT RH P/N: 45130	REPLACE	1.00	\$16.00	16.00
25	LEVER KICK STARTER	REPLACE	1.00	\$60.00	60.00
26	LEVER SET (RED)	REPLACE	1.00	\$70.00	70.00
27	MIRROR SET (AFTERMARKET)	REPLACE	1.00	\$65.00	65.00
28	MUDGUARD FRONT (RED) P/N: 55147	REPLACE	1.00	\$55.00	55.00
29	NUT SELF LOCKING	REPLACE	1.00	\$10.00	10.00
30	O-RING (WATER PUMP) P/N: 50377	REPLACE	1.00	\$3.50	3.50
31	O-RING OIL FILTER P/N: 46241	REPLACE	1.00	\$7.00	7.00
32	PANEL 2 P/N: 59798	REPLACE	1.00	\$22.00	22.00
33	PEDAL BRAKE P/N: 45125	REPLACE	1.00	\$26.00	26.00
34	PROTECTOR MUFFLER (SILVER) P/N: 40320	REPLACE	1.00	\$44.00	44.00



S/N	Description	Action	Qty	Unit Price	Amount
35	RIM SPORT FRONT (BLACK)	REPLACE	1.00	\$372.00	372.00 X
36	RUBBER FOOTREST FRONT P/N: 40321	REPLACE	1.00	\$9.00	9.00
37	SCOOP AIR RH (RED)	REPLACE	1.00	\$32.00	32.00 X
38	SEAL OIL (11X18X6) CRANKCASE COVER - CLUTCH P/N: 24160	REPLACE	2.00	\$6.00	12.00
39	SEAL OIL FRONT RIM	REPLACE	1.00	\$3.00	3.00 X
40	SENA BLUETOOTH (SMH5-FM)	REPLACE	1.00	\$513.00	513.00
41	SHROUD AIR P/N: 50471	REPLACE	1.00	\$35.00	35.00 X
42	SLIDER FRONT AXLE (MOTOVATION)	REPLACE	1.00	\$425.00	425.00
43	SPRING RETURN P/N: 45126	REPLACE	1.00	\$6.00	6.00 X
44	STEERING CONE SET P/N: 33765	REPLACE	1.00	\$53.00	53.00 X
45	STICKER (YAMAHA) LOGO & WORDING	REPLACE	2.00	\$12.00	24.00
46	STICKER COVER TAIL LH	REPLACE	1.00	\$1.50	1.50
47	TUBE TOOL (WITH LOCK)	REPLACE	1.00	\$45.00	45.00
48	WASHER FRONT RIM	REPLACE	1.00	\$1.50	1.50
SUB TOTAL					\$5,281.00
GST @ 7 %					\$369.67
GRAND TOTAL					\$5,650.67

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



Acknowledge & Accepted By

LIAT Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To replace damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

2. A claimant(s) is allowed

- Subsequent survey must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

