

**BH Auto Services Pte Ltd**  
**1 Sin Ming Industrial Est Sector C**  
**575636**

**Claim Reference:**  
**Assessment number: BA1045**  
**Version: 1712**  
**Date calculated: 01/17/2019 09:45 AM**

**Full Report**  
**Registration: SLZ3012S**  
**Printed: 01/17/2019 9:49 AM**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Janice Koh	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-12
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer:	HONDA
Model:	JAZZ (GK3/GK5/GK7)
Sub Model:	BASE MODEL
Model Sheet Number:	35 CK 01
Registration:	SLZ3012S
VIN number:	
Odometer:	


**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
Date of Inspection:

**Damage Areas**

**All**   
**Underbody**



**BH Auto Services Pte Ltd**  
**1 Sin Ming Industrial Est Sector C**  
**575636**

Claim Reference:  
 Assessment number: BA1045  
 Version: 1712  
 Date calculated: 01/17/2019 09:45 AM

Full Report  
 Registration: SLZ3012S  
 Printed: 01/17/2019 9:49 AM

**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
8101A2	RENEW FRONT BUMPER INCLUDES: R + R NECESSARY ATTACHED PARTS		9.0	40.50
<b>Labour Cost</b>			<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>			0.90	9.0
<b>Total of Labour</b>				40.50

**Paint**

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R		10.0	

**Paint Material Per Part**

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	39.79

<b>Labour Cost - Paint</b>		Hrs	WU	Price SGD
Factor	45.00 SGD/h			
Time Paint			10.0	
Preparation Comp. Work Plastic		0.70	7.0	31.50
<b>Total</b>	<b>10 WU/h</b>	<b>1.70</b>	<b>17.0</b>	<b>76.50</b>

<b>Material Cost - Paint</b>		Price SGD
New Part Painting - Plastic K1R		39.79
Material-constant Plastic		16.20
<b>Total</b>		<b>55.99</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0283	FRONT BUMPER / <i>ant</i>	71101T5LT10ZZ			600.00

**BH Auto Services Pte Ltd**  
**1 Sin Ming Industrial Est Sector C**  
**575636**

Claim Reference:  
 Assessment number: BA1045  
 Version: 1712  
 Date calculated: 01/17/2019 09:45 AM

Full Report  
 Registration: SLZ3012S  
 Printed: 01/17/2019 9:49 AM

Code	Description	Part Number	Supplier	Price SGD
0317	L/F OUT BUMPER BRKT	71198T5A000	✓ <i>ALL</i>	10.00
0318	R/F OUT BUMPER BRKT	71193T5A000	X <i>NN.</i>	10.00
1000	clip / <i>ALL.</i>	Front bumper		20.00
f: OEM Parts	<b>Savings</b>			0.00
n: Non-OEM Parts	<b>Subtotal</b>		630	640.00
u: Used parts	<b>Addition(+15.00%)</b>			96.00
	<b>Total</b>		724.5	736.00

**Final Calculation**

	SGD	SGD
<b>Parts</b>	640.00	
Addition(+15.00%)	96.00	
<b>Total Parts</b>		736.00
<b>Labour Time Base 10 WU/h</b>		
Total 9.0 WU X 45.00 SGD/h	40.50	
<b>Total of Labour</b>		40.50
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 17.0 WU X 45.00 SGD/h	76.50	
Material Cost	55.99	
<b>Total Paint Including Material</b>		132.49
<b>Repair Cost Excludes GST</b>	897.49	908.99
GST (+7.0%)		63.63
<b>Repair Cost Included GST</b>		972.62

**Comments**

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Audatex System Using Manufacturer Times  
 Acknowledged by Repairer  
 Signature:  
 Date:

*2 Days .  
 part by part .  
 before paint photos .  
 Guo Qun .  
 17/1/19 .*