

27/03/2002

ASS. REC. BY:

REF:

CS/FCI19000881/Jrd3 n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Joanne Yong (CWS) of FCI

Date/Time: 14/1/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SH 5478M

Insured: SH 6187M

at Workshop m/s World Auto.

Tel: 63621776

of No. 1 Kranji Loop

Policy No:

Claim No: D19000383MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 10/1/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate                            |
|-----------|------------------------------------------------------------|
|           | SH 5478M-X                                                 |
|           | SH 6187M-X.                                                |
| 16/1/19   | Email preli revised to FCI                                 |
| 7/2/19    | Final fig \$ 7256.40 confirmed by email (Red 6046.40, 45%) |

Surveyor Hwee Jie

REF:

FCI

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 3LH 5478M

at Workshop m/s World Auto

of No. 1 Kranji Loop

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 3LH 5478M Yr Regn: 9 Nov 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C. 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 115487 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU31215848

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 10/1/2019 D.O.I. 15/1/19

Survey held at World Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Hwee Jie, Pls see my remarks.

RECEIVED 11 FEB 2019

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

Date/Time, File Return to?

2) n/p - typist

Report Format : CWS

Lump Sum / I.B.I. (\$) 7256.40

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

3XU-45

|        |
|--------|
| 170+45 |
| 50     |
| 50     |
| 59     |
| 374    |



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000383MFSH

Our ref: CS/FCI19000881/Jvd3

Date: 16/1/2019

The Motor Claims Department  
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam


**PRELIMINARY ADVICE OF VEHICLE NO. SLH 5478M**

We thank for your instruction on 14/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle  
on 15/1/2019 at the premises of M/s WORLD AUTO PTE LTD  
and have the following to report:-

|                          |                |
|--------------------------|----------------|
| Workshop Estimate Amount | : S\$13,302.80 |
| Revised Estimate Amount  | : S\$8,103.60  |
| "Check" Items Amount     | : S\$675.20    |
| Market Value             | : S\$          |
| LTA Reimbursement Value  | : S\$          |
| Nett Value               | : S\$          |

Description of Damage:  
The vehicle sustained damages at the  
rear portion



Comments/Present Status:  
Damages Consistent

Yours faithfully,

**ONG HWEE JIE**  
**Automotive Assessor**

**MOTOR SURVEY ASSIGNMENT**

|                           |                                                             |                                      |
|---------------------------|-------------------------------------------------------------|--------------------------------------|
| <b>Date</b>               | 11-01-2019                                                  | <b>Our Ref No.</b> D19000383MFSH     |
| <b>Accident Date</b>      | 10-01-2019                                                  | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SH6187M                                                     | <b>Third Party Vehicle.</b> SLH5478M |
| <b>Survey Location</b>    | NO.1, KRANJI LOOP                                           |                                      |
| <b>Contact Person.</b>    | AINEE                                                       |                                      |
| <b>Contact No.</b>        | 63621776/ 0                                                 | <b>Fax No.</b> 63631250              |
| <b>Survey Type</b>        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                                |                                      |
| <b>Contact Person</b>     | NA                                                          | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA                                                          |                                      |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                    |                                |
|--------------------------|--------------------|--------------------------------|
| <b>Cc : Workshop</b>     | WORLD AUTO PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                 | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | JOANNEY            |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Veh In

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 16 January 2019 3:33 PM  
**To:** 'CWS Motor Claims'  
**Cc:** SUR; 'Joanne Yong Lai fong'  
**Subject:** RE: SURVEY ASSESSMENT - D19000383MFSH/1, SLH 5478M  
**Attachments:** SLH 5478M PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLH 5478M  
Date of survey: 15/1/2019  
Number of days : 7 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 16 January 2019 3:30 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** FW: SURVEY ASSESSMENT - D19000383MFSH/1

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Monday, 14 January 2019 5:49 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Joanne Yong Lai fong <[Joanneyong@msfirstcapital.com.sg](mailto:Joanneyong@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19000383MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## **Shirley Hiew (LKK Auto)**

---

**From:** Hwee Jie (LKK Auto) <hweejie@lkkauto.com>  
**Sent:** Thursday, 7 February 2019 8:57 AM  
**To:** tgttan@worldauto.com.sg  
**Cc:** Veron Chen (LKKAuto); SUR  
**Subject:** RE: SLH 5478 FINALIZATION

Hi Sophia,

Finalized P/P repair \$7256.40/- with 7days.

Best Regards,

**Hwee Jie | Assistant Automotive Assessor**

**LKK Auto Consultants**

Phone: 9180 3151 | Email: [Hweejie@lkkauto.com](mailto:Hweejie@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** tgttan@worldauto.com.sg [mailto:tgttan@worldauto.com.sg]  
**Sent:** Friday, 1 February, 2019 4:51 PM  
**To:** Hwee Jie (LKK Auto)  
**Subject:** RE: SLH 5478 FINALIZATION

Hi Hwee Jie

Finalised COR \$7256.40 and 7 repair days.

Rdgs  
Sophia

---

**From:** Hwee Jie (LKK Auto) <hweejie@lkkauto.com>  
**Sent:** Wednesday, 23 January 2019 12:15 PM  
**To:** tgttan@worldauto.com.sg  
**Subject:** RE: SLH 5478 FINALIZATION

Hi Sophia,

Please let me know once i can finalize with you, thank you.

Best Regards,

**Hwee Jie | Assistant Automotive Assessor**

**LKK Auto Consultants**

Phone: 9180 3151 | Email: [Hweejie@lkkauto.com](mailto:Hweejie@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** tgttan@worldauto.com.sg [mailto:tgttan@worldauto.com.sg]  
**Sent:** Wednesday, 23 January, 2019 12:18 PM

**To:** Hwee Jie (LKK Auto)  
**Subject:** RE: SLH 5478 FINALIZATION

Hi Hwee Jie

Cannot finalise at this point of time as the said car is still under repairs.

Kindly hold.

Rdgs  
Sophia

---

**From:** Hwee Jie (LKK Auto) <[hweejie@lkkauto.com](mailto:hweejie@lkkauto.com)>  
**Sent:** Wednesday, 23 January 2019 11:44 AM  
**To:** [tggtan@worldauto.com.sg](mailto:tggtan@worldauto.com.sg)  
**Subject:** SLH 5478 FINALIZATION

Hi Sophia,

Finalized amount is P/P repair \$7256.40/- with 7days. Please let me know if you're agree with this amount so I can proceed with finalize, thank you.  
Has spoken to kana about the adjusted price amount.

Best Regards,



**Hwee Jie | Assistant Automotive Assessor**

**LKK Auto Consultants**

Phone: 9180 3151 | Email: [Hweejie@lkkauto.com](mailto:Hweejie@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



### Sketch Plan #3



**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**MS FIRST CAPITAL INSSURANCE LIMITED**  
 6 RAFFLES QUAY,  
 #21-00 048580

Attention : Motor Claim Department  
 Contact : 6222 2311 Fax No. : 6222 3547

**Estimate : ES190016**

Date : 12/01/2019  
 Vehicle Num. : SLH 5478M (LCR)  
 Make/Model : HONDA VEZEL HYBRID  
 Chassis/Eng# :  
 Accident Date : 10/01/2019  
 Claim No. :  
 Reference :  
 Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

**LIST ITEMS :**

|     |   |                                            |       |                       |
|-----|---|--------------------------------------------|-------|-----------------------|
| 1.  | 1 | REAR BOOT LID <i>BUC</i>                   | 1100  | <del>1,300.00</del> ✓ |
| 2.  | 1 | REAR BOOT INNER TRIM BOARD <i>NN</i>       |       | 280.00 ✕              |
| 3.  | 1 | REAR BOOT LOCK ASSY <i>NN</i>              |       | 300.00 ✕              |
| 4.  | 1 | REAR BOOT REFLECTOR LAMP LH <i>SCR</i>     | 420   | <del>580.00</del> ✓   |
| 5.  | 1 | REAR WINDSCREEN GLASS MOULDING <i>NEC</i>  | 150   | <del>250.00</del> ✓   |
| 6.  | 1 | REAR BUMPER <i>BUC</i>                     | 760   | <del>900.00</del> ✓   |
| 7.  | 1 | REAR BUMPER REFLECTOR LENS - LH <i>SCR</i> |       | 180.00 ✓              |
| 8.  | 1 | REAR BOOT WEATHER STRIP <i>DEF</i>         | 150   | <del>180.00</del> ✓   |
| 9.  | 1 | REAR END PANEL <i>DD</i>                   | 550   | <del>860.00</del> ✓   |
| 10. | 1 | REAR END PANEL TOP GARNISH <i>BT</i>       | 155   | <del>260.00</del> ✓   |
| 11. | 1 | REAR SIDE BUMPER - LH <i>DEF</i>           |       | 250.00 ✓              |
| 12. | 1 | REAR TAIL LAMP - LH <i>SCR</i>             |       | 580.00 ✓              |
| 13. | 1 | REAR WHEEL ARCH MOULDING - LH <i>DEF</i>   |       | 250.00 ✓              |
| 14. | 1 | REAR BUMPER UNDERDUST COVER <i>BUC</i>     |       | 189.00 ✓              |
| 15. | 1 | REAR FENDER UNDERDUST COVER LH <i>NN</i>   |       | 250.00 ✕              |
| 16. | 1 | REAR FENDER INNER TRIM COVER LH <i>NN</i>  |       | 280.00 ✕              |
| 17. | 1 | REAR FLOOR PANEL <i>Buc Repair</i>         |       | 800.00 ✕              |
| 18. | 1 | REAR COMPARTMENT BOX <i>NN</i>             |       | 280.00 ✕              |
| 19. | 1 | REAR ANTENNA SENSOR <i>NN</i>              |       | 180.00 ✕              |
| 20. | 1 | SMART BUZZER SENSOR <i>CRA</i>             |       | 180.00 ✓              |
| 21. | 2 | REAR BUMPER RETAINER <i>NN</i>             | 89.00 | 178.00 ✕              |
| 22. | 1 | REAR FENDER AIR GRILLE LH <i>DEF</i>       |       | 56.00 ✓               |
| 23. | 1 | REAR WIPER COVER <i>MIS</i>                |       | 85.00 ✓               |
| 24. | 1 | REAR BOOT HYBRID EMBLEM (VEZEL) <i>NEC</i> |       | 89.00 ✓               |
| 25. | 1 | REAR BOOT VEZEL EMBLEM (VEZEL) <i>NEC</i>  |       | 89.00 ✓               |
| 26. | 1 | REAR WIPER ARM <i>NN</i>                   |       | 90.00 ✕               |

List TotalS\$ :

8,916.00

20.00% Discount S\$ :

1,783.20

7,132.80

CONTINUE / ...

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**MS FIRST CAPITAL INSSURANCE LIMITED**  
 6 RAFFLES QUAY,  
 #21-00 048580

Attention : Motor Claim Department  
 Contact : 6222 2311 Fax No. : 6222 3547

**Estimate : ES190016**

Date : 12/01/2019  
 Vehicle Num. : SLH 5478M (LCR)  
 Make/Model : HONDA VEZEL HYBRID  
 Chassis/Eng# :  
 Accident Date : 10/01/2019  
 Claim No. :  
 Reference :  
 Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|                                                                                                                                              |   |                                    |         |                            |
|----------------------------------------------------------------------------------------------------------------------------------------------|---|------------------------------------|---------|----------------------------|
| SPECIAL NETT ITEMS :                                                                                                                         |   |                                    |         |                            |
| 1.                                                                                                                                           | 1 | REAR BOOT INNER TRIM BOARD CLIP    | NEL     | 30 40.00 /                 |
| 2.                                                                                                                                           | 1 | REAR WINDSCREEN SEALANT            | NEC     | 60 100.00 /                |
| 3.                                                                                                                                           | 1 | REAR BUMPER CLIP                   | NEL     | 30 40.00 /                 |
| 4.                                                                                                                                           | 1 | REAR END PANEL TOP GARNISH CLIPS   | NN      | 20 40.00 X                 |
| 5.                                                                                                                                           | 1 | REAR TAILLAMP CLIPS                |         | 30 40.00 /                 |
| 6.                                                                                                                                           | 1 | REAR WHEEL ARCH MOULDING CLIPS     | } NEC   | 30 40.00 /                 |
| 7.                                                                                                                                           | 1 | REAR BUMPER UNDERDUST COVER CLIP   |         | 30 40.00 /                 |
| 8.                                                                                                                                           | 1 | REAR FENDER UNDERDUST COVER CLIPS  |         | 30 40.00 /                 |
| 9.                                                                                                                                           | 1 | REAR FENDER INNER TRIM BOARD CLIPS | NN      | 40.00 X                    |
| 10.                                                                                                                                          | 1 | REVERSE SENSOR                     | shorted | 200 280.00 /               |
| Special Nett Total S\$ :                                                                                                                     |   |                                    |         | 700.00                     |
| LABOUR :                                                                                                                                     |   |                                    |         |                            |
| TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES                                                                                              |   |                                    |         | 50 180.00                  |
| TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.                                                                              |   |                                    |         | 60 180.00                  |
| REMOVE & REFIT REAR WINDSCREEN GLASS                                                                                                         |   |                                    |         | 120 180.00                 |
| TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS. |   |                                    |         | 1000 2000 2,000.00<br>1200 |
| PUTTY AND SPRAY PAINT REAR AFFECTED AREAS INCLUDING (INNER/OUTER)                                                                            |   |                                    |         | 950 800 1,600.00           |
| TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS                                                                                       |   |                                    |         | 50 180.00                  |

CONTINUE / ...

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**MS FIRST CAPITAL INSSURANCE LIMITED**  
 6 RAFFLES QUAY,  
 #21-00 048580

Attention : Motor Claim Department  
 Contact : 6222 2311 Fax No. : 6222 3547

**Estimate : ES190016**

Date : 12/01/2019  
 Vehicle Num. : SLH 5478M (LCR)  
 Make/Model : HONDA VEZEL HYBRID  
 Chassis/Eng# :  
 Accident Date : 10/01/2019  
 Claim No. :  
 Reference :  
 Policy No. :

| S/N | Quantity | Particular                                                                                                                                                  | Unit Price | Amount S\$            |
|-----|----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-----------------------|
|     |          | <b>REVERSE SENSORS AND START/STOP UNIT CAPACITORS</b>                                                                                                       |            |                       |
|     |          | DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME. (HV HYBRID SYSTEM SAFETY PROCEDURES)                                  |            | 200 <del>450.00</del> |
|     |          | PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES) |            | 120 <del>450.00</del> |
|     |          | TO REMOVE AND REFIT FUEL TANK TO FACILITATE THE PANEL BEATER TO REPLACE AND CUT OUT DAMAGED PANELS.                                                         |            | 80 <del>250.00</del>  |
|     |          | Labour Total S\$ :                                                                                                                                          |            | 5,470.00              |

**E. & O.E.****Total S\$ : 13,302.80**

Total - \$7256.4

**for WORLD AUTO PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer :  
 Signature:  
 Date:

Hwee Jie

15/1/19

P/P 7 days

Photo before paint!

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                         |                             |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------|------------|-------------------------------------------------------------------------------------|
| MS FIRST CAPITAL INSURANCE LTD                                                                                                                                                         |                                                                                         | Ref : CS/FCI19000881/Jvd3n2 |            |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                         | Date : 11-02-2019           |            |  |
|                                                                                                                                                                                        |                                                                                         | Code : FCI2                 |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                         |                             |            |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SH 6187M                                                                                | Veh. Inspected              | SLH 5478M  |                                                                                     |
| Policy No.                                                                                                                                                                             |                                                                                         | Coverage (\$)               | 0.00       |                                                                                     |
| Claim No.                                                                                                                                                                              | D19000383MFSH                                                                           | Excess (\$)                 | 0.00       |                                                                                     |
| Assign From                                                                                                                                                                            | JOANNE YONG                                                                             | Assign Date                 | 14/01/2019 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                         |                             |            |                                                                                     |
| Make & Model                                                                                                                                                                           | HONDA VEZEL                                                                             | c.c                         | 1496       |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                  | Year of Reg.                | 2016       |                                                                                     |
| Chassis No.                                                                                                                                                                            | RU31215848                                                                              | Colour                      | SILVER     |                                                                                     |
| Odometer                                                                                                                                                                               | 115487                                                                                  | Steering                    | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                | Modification                | SPORTS RIM |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                                    |                             |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                         |                             |            |                                                                                     |
|                                                                                                                                                                                        | Size                                                                                    | Make                        | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                              | GITI                        | 6 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                              | GITI                        | 6 mm       |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                              | GITI                        | 6 mm       |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                              | GITI                        | 6 mm       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                         |                             |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                                                                             |                                                                                         |                             |            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                         |                             |            |                                                                                     |
| Accident Date                                                                                                                                                                          | 10/01/2019                                                                              | Inspection Date             | 15/01/2019 |                                                                                     |
| Survey held at                                                                                                                                                                         | WORLD AUTO PTE LTD<br>47 JALAN PEMIMPIN<br>#01-02/03 HALCYON 2 BLDG<br>SINGAPORE 577200 |                             |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                         |                             |            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                         |                             |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                         |                             |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                         | 7 Working Days              |            |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 5478M

| Qty                                | Description of Parts                 | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--------------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                      |                      |                           |                   |
| 1                                  | REAR BOOT LID                        | BUCKLED              | 1,300.00                  | 1,100.00          |
| 1                                  | REAR BOOT INNER TRIM BOARD           | NOT NECESSARY        | 280.00                    | -                 |
| 1                                  | REAR BOOT LOCK ASSY                  | NOT NECESSARY        | 300.00                    | -                 |
| 1                                  | REAR BOOT REFLECTOR LAMP LH          | SCRATCHED            | 580.00                    | 420.00            |
| 1                                  | REAR WINDSCREEN GLASS MOULDING       | NECESSARY            | 250.00                    | 150.00            |
| 1                                  | REAR BUMPER                          | BUCKLED              | 900.00                    | 760.00            |
| 1                                  | REAR BUMPER REFLECOR LENS-LH         | SCRATCHED            | 180.00                    | 180.00            |
| 1                                  | REAR BOOT WEATHERSTRIP               | DEFORMED             | 180.00                    | 150.00            |
| 1                                  | REAR END PANEL                       | DENTED               | 860.00                    | 550.00            |
| 1                                  | REAR END PANEL TOP GARNISH           | BENT                 | 260.00                    | 155.00            |
| 1                                  | REAR SIDE BUMPER-LH                  | DEFORMED             | 250.00                    | 250.00            |
| 1                                  | REAR TAIL LAMP-LH                    | SCRATCHED            | 580.00                    | 580.00            |
| 1                                  | REAR WHEEL ARCH MOULDING-LH          | DEFORMED             | 250.00                    | 250.00            |
| 1                                  | REAR BUMPER UNDERDUST COVER          | BUCKLED              | 189.00                    | 189.00            |
| 1                                  | REAR FENDER UNDERDUST COVER LH       | NOT NECESSARY        | 250.00                    | -                 |
| 1                                  | REAR FENDER INNER TRIM COVER LH      | NOT NECESSARY        | 280.00                    | -                 |
| 1                                  | REAR FLOOR PANEL                     | TO REPAIR SEE LABOUR | 800.00                    | -                 |
| 1                                  | REAR COMPARTMENT BOX                 | NOT NECESSARY        | 280.00                    | -                 |
| 1                                  | REAR ANTENNA SENSOR                  | NOT NECESSARY        | 180.00                    | -                 |
| 1                                  | SMART BUZZER SENSOR                  | CRACKED              | 180.00                    | 180.00            |
| 2                                  | REAR BUMPER RETAINER @\$89.00        | NOT NECESSARY        | 178.00                    | -                 |
| 1                                  | REAR FENDER AIR GRILLE LH            | DEFORMED             | 56.00                     | 56.00             |
| 1                                  | REAR WIPER COVER                     | MISSING              | 85.00                     | 85.00             |
| 1                                  | REAR BOOT HYBRID EMBLEM (VEZEL)      | NECESSARY            | 89.00                     | 89.00             |
| 1                                  | REAR BOOT VEZEL EMBLEM (VEZEL)       | NECESSARY            | 89.00                     | 89.00             |
| 1                                  | REAR WIPER ARM                       | NOT NECESSARY        | 90.00                     | -                 |
|                                    | LESS 20% DISCOUNT                    |                      | -1,783.20                 | -1,046.60         |
|                                    |                                      |                      | 7,132.80                  | 4,186.40          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                      |                      |                           |                   |
| 1                                  | REAR BOOT INNER TRIM BOARD CLIP (SN) | NECESSARY            | 40.00                     | 30.00             |

Report Ref No. CS/FCI19000881/Jvd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty                | Description of Parts                                                                                                                                                                  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1                  | REAR WINDSCREEN SEALANT (SN)                                                                                                                                                          | NECESSARY     | 100.00                    | 60.00             |
| 1                  | REAR BUMPER CLIP (SN)                                                                                                                                                                 | NECESSARY     | 40.00                     | 30.00             |
| 1                  | REAR END PANEL TOP GARNISH CLIPS (SN)                                                                                                                                                 | NOT NECESSARY | 40.00                     | -                 |
| 1                  | REAR TAILLAMP CLIPS (SN)                                                                                                                                                              | NECESSARY     | 40.00                     | 30.00             |
| 1                  | REAR WHEEL ARCH MOULDING CLIPS (SN)                                                                                                                                                   | NECESSARY     | 40.00                     | 30.00             |
| 1                  | REAR BUMPER UNDERDUST COVER CLIP (SN)                                                                                                                                                 | NECESSARY     | 40.00                     | 30.00             |
| 1                  | REAR FENDER UNDERDUST COVER CLIPS (SN)                                                                                                                                                | NECESSARY     | 40.00                     | 30.00             |
| 1                  | REAR FENDER INNER TRIM BOARD CLIPS (SN)                                                                                                                                               | NOT NECESSARY | 40.00                     | -                 |
| 1                  | REVERSE SENSOR (SN)                                                                                                                                                                   | SHORTED       | 280.00                    | 200.00            |
|                    |                                                                                                                                                                                       |               | 700.00                    | 440.00            |
|                    | <b>LABOUR</b>                                                                                                                                                                         |               |                           |                   |
|                    | TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.                                                                                                                                      |               | 180.00                    | 50.00             |
|                    | TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS.                                                                                                                        |               | 180.00                    | 60.00             |
|                    | REMOVE & REFIT REAR WINDSCREEN GLASS.                                                                                                                                                 |               | 180.00                    | 120.00            |
|                    | TO DISMANTLE REAR DAMAGE PARTS,CUT AND WELD REAR PANEL,KNOCK,STRAIGHTEN ABD RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL. |               | 2,000.00                  | 1,000.00          |
|                    | PUTTY AND SPRAY PAINT REAR AFFECTED AREAS INCLUDING (INNER/OUTER).                                                                                                                    |               | 1,500.00                  | 950.00            |
|                    | TO CHECK REAR WIRES,CONNECTORS,REPLACE DAMAGED LAMPS,REVERSE SENSORS AND START/STOP UNIT CAPACITORS .                                                                                 |               | 180.00                    | 50.00             |
|                    | DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME.(HV HYBRID SAFETY PROCEDURES).                                                                   |               | 450.00                    | 200.00            |
|                    | PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS (HV HYBRID SYSTEM SAFETY PROCEDURES).                            |               | 450.00                    | 120.00            |
|                    | TO REMOVE AND REFIT FUEL TANK TO FACILITATE THE PANEL BEATER TO REPLACE AND CUT OUT DAMAGED PANELS.                                                                                   |               | 250.00                    | 80.00             |
|                    |                                                                                                                                                                                       |               | 5,370.00                  | 2,630.00          |
| <b>GRAND TOTAL</b> |                                                                                                                                                                                       |               | <b>13,202.80</b>          | <b>7,256.40</b>   |

Report Ref No. CS/FCI19000881/Jvd3n2



|                             |  |  |          |
|-----------------------------|--|--|----------|
| RECOMMENDED COST OF REPAIRS |  |  | 7,256.40 |
|-----------------------------|--|--|----------|

Report Ref No. CS/FCI19000881/Jvd3n2

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.