

INS. CASE OWNER:

CC 4, UPC 1900

0896, Kha3n2

LKK:
IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

18/1/19

Date / Time:

18/1/19

Registered in Merimen:

Pre-assign / CCU / FTE

PC 3958 L



Insured Vehicle No.:

Entraco Marine by. KLC

Claim No.:

08/19/19/0030/021328

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SLV17465



INSRS:

WSP:

Tel:

Liability:

RMKS:

Optima



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
22/1/19	SLV17465-X; PC3958L-04/UPC17074-X9/GH03A2:08/19/19	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
02/02/19	- FILE REVIEWED. OIP MOVING OUT FROM OFFICER.	Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
02/02/19	- TYPE REPORT WHILE PENDING FOR TP LOD	Documentation Check List: Handler	Typist
	- REPORT DONE	Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
23/02/19	- TP LOD IN BY EMAIL	Release Voucher:	
01/03/19	- 90% WAIVER APPROVAL TO LPC	Final Repair Bill:	
	- LPC APPROVED WAIVER @ 50% IF NO TP VIDEO FOOTAGE.	Car Rental Invoice:	
12/06/19	- SEND 1st OFFER TO TP.	Towing Invoice:	
	- TP REJECTED OFFER. PROVIDED VIDEO	LTA / GIA:	
	- REBATE WAIVER.	Medical Bill:	
	- LPC APPROVED REVISED WAIVER.	PIR:	
14/06/19	- SEND 2ND OFFER TO TP.	Mandate/Reject Instruction:	
24/06/19	- TP ACCEPTED OFFER.	LOD	
		Payment Breakdown Form:	
PRELIMINARY ADVICE	Date/Time: 18/01/19	Post-Repair Photos:	
	Sent By: WK	Others:	

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: PIP	\$5 3,358.84	4 days) Reduction: 29 %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time	Confirm with	Email ☐ Call ☐
Final Liability:	% 100	(Assessed / Assessed) BOLA S/N No.:	NIL
Repair Cost: (w/60%)	\$5 3,572.56		
Loss of Rental (LOR):	\$5 -	(days)	
Loss of Use (LOU):	\$5 500.00	60 x 5 days)	
Loss of Income (LOI):	\$5 -	(5 x days)	
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	\$5 2.00		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost	\$5 -		
Total:	\$5 3,874.56	Global Sum \$5: -	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	\$5 3,874.56	Name 1:	OPTIMA WORKZ PTE LTD
Payee 2: (Strike if N.A.)	\$5 -	Name 2:	-
Payee 3: (Strike if N.A.)	\$5 -	Name 3:	-

ASS. REC. BY:

REF: LPC /Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s Optima

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLV17465 Yr Regn: 12.17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Land Rover c.c. 1496Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 5509 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: BU 1. 1229181Gen. Cond: Good / Fair / Poor / BurntSteering: In Order / Jammed / Leaked / Burnt orBrake: In Order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD / M. Rim orTyre Size: F: 215/60R16

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 14/1/19

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 15/1/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

01/1/19

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/1 File pass to CarPLP 93,838.84(Rto: 91,428.40 (29%))

Data/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Data/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Fees

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / L.B.I: (\$

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/19/19/VC30/021328
Our ref: CC4/LPC19000896/Kha3

Date: 18/01/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLV 1746S

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/01/2019 at the premises of M/s Optima Werkz Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	4,767.24
Revised Estimate Amount	: S\$	2,947.24
"Check" Items Amount	: S\$	520.00
Total (Including Check Items)	: S\$	3,467.24
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
O/S Front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 38921

Vehicle Details

Vehicle No: SLV17465
Vehicle to be Exported: No
Intended Deregistration Date: 14 Jan 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Silver
Manufacturing Year: 2017
Engine No: L15B4429185
Chassis No: RU11229181
Maximum Power Output: 96.0kW (128 bhp)
Open Market Value: \$21,514.00
Original Registration Date: 22 Dec 2017
First Registration Date: 22 Dec 2017
Transfer Count: 0
Actual ARF Paid: \$12,120.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 21 Dec 2027
PARF Rebate Amount: \$9,090.00

Intended COE Rebate Details

COE Expiry Date: 21 Dec 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,339.00
COE Rebate Amount: \$37,831.00
Total Rebate Amount: \$46,921.00

The information contained herein is correct as at 14 Jan 2019.

OK

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 14 JANUARY 2019

Third Party Insurer: LONPAC

Vehicle No: SLV1746S

Third Party Veh No: PC3958L

Model: HONDA VEZEL 1.5X

Date of Accident: 14 JANUARY 2019

Chassis: RU11229181 - 2017

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT SIDE MIRROR ASSY RH	1		701/424 \$666.70
2	FRONT DOOR RH	1		Ry \$963.30
3	FRONT DOOR GLASS OUTER MOULDING RH	1		Alu \$66.80
4	FRONT DOOR POWER WINDOW REGULATOR RH	1	489.50	715/7m \$650.00
5	RUNNING BOARD EXTENTION COVER RH	1		Wt \$406.00
6	FRONT BUMPER	1		REPAIR
7	FRONT FENDER RH	1		REPAIR
8	REAR DOOR RH	1		REPAIR
SUB TOTAL				\$2,752.80
LESS 20%				-\$550.56
PARTS TOTAL				\$2,202.24

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR BLACK FRAME STICKER RH	1		Alu \$45.00
2	RUNNING BOARD EXTENTION COVER CLIPS	1 SET		Alu \$50.00
S/N TOTAL				\$95.00

LABOUR CHARGES:

LABOUR CHARGES FOR KNOCKING / REPAIR & REPLACE ACCIDENT AREAS & ETC \$1,000.00 400f

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS \$1,200.00 660f

TO TUFF KOTE / ANTI-RUST \$60.00 30f

TO REMOVE & REFIX FRONT DOOR INNER TRIM RH, FRONT DOOR POWER WINDOW GLASS RH, DOOR INNER LOCK & ETC. TO EFFECT REPLACE ON FRONT DOOR RH \$150.00 60f

TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM BACK TO ORIGINAL CONDITIONS \$60.00 20f

LABOUR TOTAL \$2,470.00

ONG

Not Authorized
Resurvey B4 paint
4 days
8333 8.84 ✓ dlc

LRK Auto Consultants hence notify the Repairer of the following: \$4,767.24

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 14 JANUARY 2019

Third Party Insurer: LONPAC

Vehicle No: SLV1746S

Third Party Veh No: PC3958L

Model: HONDA VEZEL 1.5X

Date of Accident: 14 JANUARY 2019

Chassis: RU11229181 - 2017

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT SIDE MIRROR ASSY RH	1		<i>Ad/CM</i> \$666.70 ✓
2	FRONT DOOR RH	1		<i>R</i> \$963.30 ✓
3	FRONT DOOR GLASS OUTER MOULDING RH	1		<i>Ad</i> \$66.80 ✓
4	FRONT DOOR POWER WINDOW REGULATOR RH	1		\$650.00 ?
5	RUNNING BOARD EXTENTION COVER RH	1		<i>CM</i> \$406.00 ✓
6	FRONT BUMPER	1		REPAIR
7	FRONT FENDER RH	1		REPAIR
8	REAR DOOR RH	1		REPAIR
SUB TOTAL				\$2,752.80
LESS 20%				-\$550.56
PARTS TOTAL				\$2,202.24

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR BLACK FRAME STICKER RH	1		<i>Ad</i> \$45.00 —
2	RUNNING BOARD EXTENTION COVER CLIPS	1 SET		<i>Ad</i> \$50.00 —
S/N TOTAL				\$95.00

LABOUR CHARGES:

LABOUR CHARGES FOR KNOCKING / REPAIR & REPLACE ACCIDENT AREAS & ETC 400 \$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS 660 \$1,200.00

TO TUFF KOTE / ANTI-RUST 30 \$60.00

TO REMOVE & REFIX FRONT DOOR INNER TRIM RH, FRONT DOOR POWER WINDOW GLASS RH, DOOR INNER LOCK & ETC. TO EFFECT REPLACE ON FRONT DOOR RH 60 \$150.00

TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM BACK TO ORIGINAL CONDITION \$ 20 \$60.00

LABOUR TOTAL 400 \$2,470.00

ONG

Not Authorised
Repair B4 paint
4 days

LKK Auto Consultants hence notify the Repairer of the following: **\$4,767.24**

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:


Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 15 January, 2019 10:59 AM
To: fion.pee@ow.sg; MT_Claim_SG; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: sharon@ow.sg; Lily.Loi@ow.sg; hockkong.ong@ow.sg; puiheng.chong@ow.sg
Subject: Our Ref: 18/19/19/VC30/021328 RE: PRI - SLV1746S Claims against PC3958L DOA: 14/01/2019 (LONPAC)

Dear Catherine/Nivitha

Please arrange TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: fion.pee@ow.sg [mailto:fion.pee@ow.sg]
Sent: Tuesday, 15 January, 2019 10:51 AM
To: MT_Claim_SG
Cc: sharon@ow.sg; Lily.Loi@ow.sg; hockkong.ong@ow.sg; puiheng.chong@ow.sg
Subject: PRI - SLV1746S Claims against PC3958L DOA: 14/01/2019 (LONPAC)

Attn: Gerald

Dear Sirs,

Good Day.

Kindly arrange PRI for our vehicle SLV1746S at 9A Serangoon North Ave 5 S554500.

Thank you.

--
Best Regards,

Fion Pee (Ms)
Claims Executive, Motor Claims Department
D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE LTD

Head office: 6 Kung Chong Road Singapore 159143	T: +65 6472 1313	F: +65 6472 2112
Branch : 9A Serangoon North Ave 5 Singapore 554500	T: +65 6484 9919	F: +65 6481 1011
Branch : 551 Upp Thomson Road Singapore 574415	T: +65 6452 6868	F: +65 6452 9223

www.ow.sg

www.facebook.com/optimawerkz

Veh In
Kenneth

Mei Kwan (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 22 January, 2019 12:31 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG; Vic (LKKAUTO); CS A Team; Admin A
Subject: RE: Our Ref: 18/19/19/VC30/021328 RE: PRI - SLV1746S Claims against PC3958L
DOA: 14/01/2019 (LONPAC)
Attachments: PC3958L 140119.PDF


Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 22 January, 2019 9:14 AM
To: ONG LI LI
Cc: MT_Claim_SG; Vic (LKKAUTO); CS A Team; Admin A
Subject: RE: Our Ref: 18/19/19/VC30/021328 RE: PRI - SLV1746S Claims against PC3958L DOA: 14/01/2019 (LONPAC)

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 18/19/19/VC30/021328
LKK REF: CC4/LPC19000896/Kha3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SLV 1746S

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- TP GIA report

To: MT_Claim_SG

Cc: sharon@ow.sg; Lily.Loi@ow.sg; hockkong.ong@ow.sg; puiheng.chong@ow.sg

Subject: PRI - SLV1746S Claims against PC3958L DOA: 14/01/2019 (LONPAC)

Attn: Gerald

Dear Sirs,

Good Day.

Kindly arrange PRI for our vehicle SLV1746S at 9A Serangoon North Ave 5 S554500.

Thank you.

--

Best Regards,

Fion Pee (Ms)

Claims Executive, Motor Claims Department

D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE LTD

Head office: 6 Kung Chong Road Singapore 159143

T: +65 6472 1313

F: +65 6472 2112

Branch : 9A Serangoon North Ave 5 Singapore 554500

T: +65 6484 9919

F: +65 6481 1011

Branch : 551 Upp Thomson Road Singapore 574415

T: +65 6452 6868

F: +65 6452 9223

www.ow.sg

www.facebook.com/optimawerkz



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19000896/Kha3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 12-07-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 3958L	Veh. Inspected	SLV 1746S	
Policy No.	Z/18/VC30/101989	Coverage (\$)	0.00	
Claim No.	18/19/19/VC30/021328	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	15/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11229181	Colour	METALLIC GREY	
Odometer	5509	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	9 mm	
L/H Front Tyre	215/60 R16	DUNLOP	9 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	9 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/01/2019	Inspection Date	15/01/2019	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 1746S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT SIDE MIRROR ASSY RH	DENTED / CRACKED	666.70	666.70
1	FRONT DOOR RH	BENT	963.30	963.30
1	FRONT DOOR GLASS OUTER MOULDING RH	BUCKLED	66.80	66.80
1	FRONT DOOR POWER WINDOW REGULATOR WITH MOTOR,RH	DISTORTED / JAMMED	650.00	489.50
1	RUNNING BOARD EXTENSION COVER RH	CUT	406.00	406.00
1	FRONT BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR DOOR RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-550.56	-518.46
			2,202.24	2,073.84
SPECIAL NETT ITEMS				
1	FRONT DOOR BLACK FRAME STICKER RH (SN)	NECESSARY	45.00	45.00
1	SET RUNNING BOARD EXTENSION COVER CLIPS (SN)	NECESSARY	50.00	50.00
			95.00	95.00
LABOUR				
	LABOUR CHARGES FOR KNOCKING/REPAIR & REPLACE ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,FRONT FENDER RH AND REAR DOOR RH.		1,000.00	400.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS.		1,200.00	660.00
	TO TUFF KOTE/ANTI-RUST.		60.00	30.00
	TO REMOVE & REFIX FRONT DOOR INNER TRIM RH,FRONT DOOR POWER WINDOW GLASS RH,DOOR INNER LOCK & ETC.TO EFFECT REPLACE ON FRONT DOOR RH.		150.00	60.00
	TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM BACK TO ORIGINAL CONDITIONS.		60.00	20.00
			2,470.00	1,170.00

Report Ref No. CC4/LPC19000896/Kha3n2



GRAND TOTAL		4,767.24	3,338.84
RECOMMENDED COST OF REPAIRS			3,338.84

Report Ref No. CC4/LPC19000896/Kha3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.