



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/01/2019

User ID : GohKK2

Section A - Accident Details

Registration Number

SMB51M

Case Reference Number

BUS/01/19/1031

Registration Date

18/12/2008

Company Type

SMRT Buses Ltd

Make

MERCEDES

Model

MBOC500

Name of Driver

Zhang Yanwu

Type of Accident

Head to Rear

Accident Date and Time

11/01/2019 7:50 AM

Accident Reported Date and Time

11/01/2019 9:45 AM

Is Surveyor Required?

No

Survey by

Vehicle is Towed Back?

No

Towed Back Date and Time

Replacement Vehicle issued?

No

Job Card Number

Special Instruction to ARC,if any

SMB51M - FRONT RIGHT PORTION  
SHD7292L (TP) - REAR LEFT PORTION. INSURED WITH III. COMFORT TAXI

Prepared Date and Time

14/01/2019 11:49 AM

Chassis Number

WEB63442021000123

Mileage

Work Shop

Repair Completion Date and Time

Section B - Summary of Repair Estimates

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Cost

\$2,120.00

\$0.00

Total Spray Cost

\$446.00

\$0.00

Total Spare Part Cost

\$6,429.22

\$0.00

Total Other Cost

\$0.00

\$0.00

TOTAL COST

\$8,995.22

\$0.00

Lump Sum Total

\$9,000.00

\$0.00

Number of Repair Days

4.0

Prepared / Adjusted By

Kok Khoon Goh

ARC / Surveyor Sign Off Date

14/01/2019 11:57 AM

Signature

Remarks

Section C - Quotation and Accident Invoice Details

Quotation Number

Invoice Number

Quotation Date

Invoice Date

Invoice Amount

Prepared Date



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/01/2019

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$2,120.00						
Total Labour			\$2,120.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$446.00						
Total Spray Painting & Panel Beating			\$446.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER IU	1.00	\$35.00	0.00	\$35.00	Replace	
			STICKER SG LOVE	1.00	\$35.00	0.00	\$35.00	Replace	
6009351	GLASS		WINDSCREEN,FRT:CEN TRE, FOR MB OC500 BUS	1.00	\$6,210.00	10.00	\$5,589.00	Replace	
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE:DIRECT GLAZING	10.00	\$37.00	0.00	\$370.00	Replace	
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	
6009362	BODY RH		COVER,HEADLAMP:RH, FIBREGLASS,MB OC500	1.00	\$621.00	10.00	\$558.90	Replace	
6009508	VE		HEADLAMP FOR MERCEDES OC500 LE, RIGHT	1.00	\$1,276.50	10.00	\$1,148.85	Replace	
6009701	VE		LAMP,BLINKER:FRONT, RIGHT, FOR MB OC500 LE	1.00	\$155.30	10.00	\$139.77	Replace	
Total					\$8,529.80		\$8,036.52		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									