

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit
 #01-60/58, Singapore 417883
 Tel No. : 67477333 Fax No. : 67457138
 E-Mail : teesheng@singnet.com.sg
 Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. UNI DRUG HOUSE

Estimate : ES000821

Attention : Motor Claim Department
 Contact : 68484229

TP ALG
 Khanchna

Date : 14/01/2019
 Vehicle Num. : GBF 9556Z
 Make/Model : TOYOTA HIACE-2016
 Chassis/Eng# : JTFHT02P200215617/1KD2883186
 Accident Date : 10/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER <i>Distorted</i>		475.00 ✓
2.	1	REAR BUMPER REINFORCEMENT <i>new</i>		280.00 X
3.	1	REAR BUMPER BRACKET LH? <i>new</i>		30.00 ✓
4.	1	REAR BUMPER BRACKET RH? <i>Bent</i>		30.00 ✓
5.	1	REAR TRUNKLID OUTER GARNISH <i>new</i>		155.00 X
6.	1	BOOTLID LOCK <i>Damaged</i>		275.00 ✓
7.	1	FLOOR PANEL <i>Ripped</i>		850.00 X
8.	1	BOOTLID <i>Distorted</i>		2,150.00 1752
9.	1	BOOTLID HINGES LH? <i>new</i>		105.00 X
10.	1	BOOTLID HINGES RH? <i>new</i>		105.00 X
11.	1	TRUNKLID EMBLEM <i>new</i>		75.00 ✓
12.	6	TRUNKLID CLIPS <i>new</i>	4.00	24.00 X
13.	1	TRUNKLID INNER BOARD <i>new</i>		195.00 ✓
14.	1	TRUNKLID WEATHERSTRIP <i>cut</i>		395.00 ✓
15.	1	SPARE TYRE BRACKET <i>new</i>		23.50 X
16.	1	EXHAUST ASSY <i>new</i>		285.00 X
17.	2	TRUNKLID DAMPER RH/ LH <i>new</i>		710.00 X
18.	1	REAR END PANEL (INNER) ? <i>Dented</i>	355.00	1,155.00 781.50
19.	1	REAR END PANEL (OUTER) ? <i>Dented</i>		331.70 ✓
20.	1	REAR LAMPS <i>new</i>		301.00 X
21.	1	REAR END PANEL TOP MOULDING <i>new</i>		175.00 ✓
22.	1	TOYOTA STICKER <i>new</i>		15.00 ✓
23.	1	HIACE STICKER? <i>new</i>		15.00 ✓
24.	1	70KM STICKER ? <i>new</i>		15.00 ✓

CONTINUE / ...

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit
 #01-60/58, Singapore 417883
 Tel No. : 67477333 Fax No. : 67457138
 E-Mail : leesheng@singnet.com.sg
 Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. UNI DRUG HOUSE

Estimate : ES000821

Attention : Motor Claim Department
 Contact : 68484229

Date : 14/01/2019
 Vehicle Num. : GBF 9556Z
 Make/Model : TOYOTA HIACE-2016
 Chassis/Eng# : JTFHT02P200215617/1KD2683186
 Accident Date : 10/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	6	BOOTLID CLIPS <i>new</i>	4.00	24.00 <i>x</i>
26.	1	REAR NUMBER PLATE LAMP <i>new</i>		115.00 <i>x</i>
27.	2	REAR BUMPER RETAINER RH/LH <i>new</i>	50.00	100.00 <i>✓</i>
List Total S\$:				3247.95
30.00% Discount S\$:				8,389.20
25%				2,516.76
				5,872.44
SPECIAL NETT ITEMS :				
1.	1	REAR WINDSCREEN GLUM <i>new</i>		60.00 <i>✓</i>
2.	1	REVERSE SENSOR <i>P-2</i>	240	180.00 <i>✓</i>
3.	1	NO PLATE <i>new</i>		25.00 <i>x</i>
Special Nett Total S\$:				265.00
LABOUR :				
TO KNOCKING, JACKING, CUTTING OUT REAR END PANEL				
REMOVE & REFIX WIRING				
REMOVE & REFIX REAR WINDSCREEN				
REMOVE & REFIX EXHAUST				
SPRAY PAINTING ON BOOTLID / FENDER RH				
REAR END PANEL				
Labour Total S\$:				3,450.00

Total S\$: 9,587.44

LEE SHENG AUTO PTE LTD

Total: 5437.95
 w/s: 4350
 07 Days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: