

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0027/19
DATE : 09-JAN-2019

AUTOLUTION INDUSTRIAL PTE LTD
18 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : M/S FULL GOSPEL ASSEMBLY
ADDRESS : 15 PLAYFAIR ROAD
#03-01
S(367987)
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : PC7663K
MODEL CODE : TVL2RDKE26KWBHNT-D
MODEL/YEAR : NISSAN MICROBUS AT MY2018
ENGINE NO : YD25037687B
CHASSIS NO : JN1TC2E26Z0056069
MILEAGE : 408 KM
DATE IN : 09/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH - 96450079
ACCIDENT DATE : 08/01/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorized
17/1/19
The 3rd. Party.
Shy.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO PC7663K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO RENEW REAR BUMPER AND RH REAR SIDE PANEL.	1400.00	1250
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	700.00	600
3	ZZ/003	REMOVE AND INSTALL RH REAR WINDOW PANEL.	180.00	✓
4	ZZ/004	CHECK WHEEL ALIGNMENT.	98.00	✓
5	ZZ/005	REMOVE AND INSTALL FUEL TANK.	180.00	✓
TOTAL LABOUR CHARGES			2558.00	

R & R Seat cushion etc.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO PC7663K

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES	NPN		100.00 ?
2	SEALANT WINDOW PANEL	SEALANT - 4		80.00 <i>ner</i> ✓
3	WHEEL CAP REAR RH	40315-5YE0B <i>cur</i>	151.20	✓
4	REAR MUD FLAP RH	78810-3XA0A		<i>Dis</i> 105.50 ✓
5	REAR SIDE PANEL RH	G7422-3XBMA	1793.40	?
6	CLIP REAR BUMPER @ \$1.20 EACH	01553-10501 <i>ner</i>	7.20	✓
7	REAR BUMPER FASCIA	85022-3XA0A <i>cur/pe</i>	600.50	✓
SUB TOTAL			2552.30	0.00 285.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			510.46	0.00 0.00
GRAND TOTAL			2041.84	0.00 285.50
OVERALL TOTAL			2327.34	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO PC7663K

TOTAL LABOUR CHARGES	2558.00
TOTAL SPARE PARTS CHARGES	2327.34
GRAND TOTAL	4885.34 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.