



TTS EUROCARS pte ltd

A member of the TTS Motor Group

383 Sin Ming Drive, TTS Centre, S'pore 575717

Tel : 67572622 Fax : 67411626

TO	AXA Insurance Pte Ltd	DATE	14.12.2018
ATTN	MOTOR CLAIM DEPT	PAGE	1
MODEL	Mercedes benz E200	VEH NO	SGG1221C
YEAR	2017	C/N0	
		D.O.A	12/1/2019

S/NO	PARTS	Qty	
1	BONNET <i>Repair</i> X	1	X
2	BONNET HINGE RH X	1	X
3	BONNET HINGE LH X <i>AN</i>	1	X
4	BONNET INSULATOR X	1	X
5	BONNET INSULATOR CLIPS <i>MC</i>	1	31.7
6	BONNET LOGO <i>MC</i>	1	80.9
7	BONNET LOCK X	1	X
8	BONNET CATCH X <i>AN</i>	1	X
9	BONNET RUBBER STOPPER X	4	X
10	BONNET ABSORBER X	2	X
11	FRONT BUMPER <i>MC</i>	1	1155.85
12	FRONT BUMPER CLIPS <i>MC</i>	10	80
13	FRONT BUMPER GRILLE <i>MC</i>	1	239.33
14	FRONT BUMPER GRILLE BASE <i>CRA</i>	1	168.62
15	FRONT BUMPER GRILLE CHROME <i>MC</i>	1	280
16	FRONT GRILLE LOGO <i>MC</i>	1	131.5
17	FRONT BUMPER LOWER GRILLE <i>MC</i>	1	105.5
18	FRONT BUMPER LOWER GRILLE RH <i>MC</i>	1	67.5
19	FRONT BUMPER LOWER GRILLE LH <i>MC</i>	1	X
20	FRONT BUMPER NUMBER PLATE BASE <i>MC</i>	1	X
21	FRONT BUMPER SENSORS <i>2PCS - DM @180</i>	4	360
22	WIRE HARNESS FOR FRONT BUMPER SENSOR X	1	X
23	FRONT BUMPER TOW HOOK <i>cover - cut</i>	1	64.5
24	FRONT BUMPER REINFORCEMENT <i>2 - BT</i>	1	190
25	FRONT BUMPER SPONGE <i>2 - CRA</i>	1	152
26	FRONT BUMPER SIDE RETAINER RH <i>MC</i>	1	22.5
27	FRONT BUMPER SIDE RETAINER LH <i>MC</i>	1	22.5
28	FRONT BUMPER BRACKET RH X	1	X
29	FRONT BUMPER BRACKET LH X	1	X
30	FRONT BUMPER STIFFENER RH X <i>AN</i>	1	X
31	FRONT BUMPER STIFFENER LH X	1	X
32	FRONT BUMPER LOWER COVER X	1	X

1-
2-
3-
10-
11-
12-
39-
30-
14)

15 -	33	FRONT BUMPER LOWER GARNISH	X NN	1	X
16 -	34	FRONT FENDER RH	/ Bmc	1	961
	35	FRONT FENDER LH	/ Bmc	1	961
	36	FRONT LH DOOR	Repair X	1	X
	37	FRONT FENDER TOP GARNISH RH	X NN	1	X
	38	FRONT FENDER TOP GARNISH LH	X NN	1	X
	39	FRONT FENDER INNER SHIELD RH	X	1	X
	40	FRONT FENDER INNER SHIELD LH	X	1	X
	41	FRONT FENDER INNER SHIELD CLIPS	X 100 NN	20	X
18 -	42	HEADLAMP RH	/ CHA	1	3160
19 -	43	HEADLAMP LH	/ CHA	1	3160
	44	HEADLAMP BALLAST ASSY	X NN	2	X
	45	HEADLAMP CONTROL MODULE	X NN	2	X
	46	HEADLAMP LOWER BRACKET RH	X NN	1	X
	47	HEADLAMP LOWER BRACKET LH	X NN	1	X
20 -	48	FRONT SUPPORT PANEL	/ BT	1	780
	49	RADIATOR	X NN	1	X
21 -	50	A/C CONDENSER	/ Cut.	1	1440
	51	GEAR OIL COOLER	X NN	1	X
	52	TURBO INTER COOLER	X NN	1	X
	53	FRONT CENTRE BRACE PANEL	X NN	1	X
	54	RADIATOR FAN MOTOR	X	1	X
	55	RADIATOR FAN BLADE	X NN	1	X
	56	RADIATOR FAN HOUSING	X NN	1	X
	57	HORN	X	1	X
22 -	58	REAR BOOT	/ BT	1	2240
23 -	59	REAR BOOT CHROME MOULDING	/ Cut	1	145
24 -	60	REAR BOOT LOGO	/ Bmc	1	86
25 -	61	REAR BOOT EMBLEM	/ Bmc	1	48
	62	REAR BOOT HINGE RH	X NN	1	X
	63	REAR BOOT HINGE LH	X NN	1	X
photo - 23 -	64	REAR BOOT SWITCH	X / DE	1	240
	65	REAR BOOT LOCK	X NN	1	X
38 -	66	REAR BOOT STOPPER/ ADJUSTOR	2 PCS / BT	4	40
	67	REAR NUMBER PLATE LAMP	X NN	2	X
26 -	68	REAR BUMPER	/ TN	1	1880
27 -	69	REAR BUMPER REFLECTOR RH	/ Cut.	1	28
	70	REAR BUMPER REFLECTOR LH	X NN	1	X
49 -	71	REAR BUMPER REINFORCEMENT	X / BT	1	760
	72	REAR BUMPER SPONGE	X NN	1	X
	73	REAR BUMPER SENSOR	3 PCS / IM @ 180	4	540
	74	WIRE HARNESS FOR REAR BUMPER SENSOR	X NN	1	X
47 -	75	REAR BUMPER LOWER TRIM/ GARNISH	X / Cut	1	260
28 -	76	EXHAUST SLEEVE RH	/ Cut.	1	390
	77	EXHAUST SLEEVE LH	X NN	1	X

78	REAR BUMPER TOWING COVER	X NN	1	X
79	REAR BUMPER LOWER CHROME MOULDING	cut	1	320
80	REAR BUMPER BRACKET RH	X LNN	1	66
81	REAR BUMPER BRACKET LH	X LNN	1	66
82	REAR BUMPER SIDE RETAINER RH	- LMC	1	66
83	REAR BUMPER SIDE RETAINER LH	- LMC	1	66
84	REAR BUMPER STIFFENER RH	X LNN	1	X
85	REAR BUMPER STIFFENER LH	X LNN	1	X
86	REAR BUMPER SENSOR BRACKET	X NN	1	X
87	REAR END PANEL	LMC	1	1360
88	REAR END PANEL TOP GARNISH	X NN	1	X
89	REAR BOOT LID WEATHER STRIP	LMC	1	190
90	REAR BOOT LID LOCK CATCH	X NN	1	X
91	SPARE TYRE PANEL	X LNN	1	X
92	SPARE TYRE BOARD	X LNN	1	X
93	END PANEL TOP GARNISH CLIPS	LMC	4	32
94	REAR RH FENDER	apax x	1	X
95	TAIL LAMP RH	CLA	1	690
96	TAIL LAMP LH	X	1	X
97	REAR WINDSCREEN	X	1	X
98	REAR WINDSCREEN MOULDING	X LNN	1	X
99	REAR RH DOOR WEATHER STRIP (INNER)	X LNN	1	X
			Sub Total	\$ -
			Less 10%	\$ -
			Total	\$ -
LABOUR				
1	Sundries		\$	150.00
2	Electrical wiring check for proper functioning		\$	150.00
3	To Supply front number plate with holder	X NN	\$	70.00
4	To remove and replace front headlamp, adjust and align headlamp focus		\$	250.00
5	Run note - body cavity preservation (front bonnet, front rh fender, front lh fender, front support panel)		\$	350.00
6	Sealant for body panel - Bonnet, front rh fender, front lh fender		\$	250.00
7	To remove and refix/ replace radiator cooling system, conduct pressure test, check for leaks		\$	550.00
8	To remove and refix/ replace a/c condenser. Vacuum refill, conduct pressure test check for leaks		\$	550.00
9	To remove and replace turbo intercooler, conduct pressure test, check for leaks.		\$	550.00
10	Towing charges		\$	250.00
11	To remove and replace front headlamp wiper washer system		\$	350.00
12	To repair, replace front bonnet, front bumper, front support panel, headlamps, front rh fender, front lh fender, front rh chassis member, front lh chassis member, chassis member, front lh door and all other affected parts and areas		\$	3,000.00
13	To putty, sand, spray paint, polish and wax front bonnet, front rh fender, front lh fender, front bumper, front rh door, front rh fender inner panel		\$	2,800.00

24703.4
10% :
22233.06

20
30
50 x 260?
860 50
40
X NN
60
60
X NN
180
X NN
880
1500

120 260
802

	front lh fender inner panel, front rh chassis member, front lh chassis member and all other affected areas		
14	To check and adjust frontal chassis alignment, align and pull to specifications	\$	1,500.00
16	Sundries	\$	150.00
17	electrical wiring check for proper functioning	\$	150.00
18	Tuff kote - body cavity preservation (rear boot, rear end panel, spare tyre panel, rear rh and lh fender, tail panel rh, tail lamp panel lh and all other affected areas	\$	350.00
19	Sealant for body panel - rear boot, rear end panel, spare tyre panel, tail lamp panel, rear rh fender	\$	350.00
20	To remove and refix rear windscreen to facilitate repair, conduct water leak test	\$	450.00
21	Sealant for rear windscreen	\$	60.00
22	Inner seal for rear windscreen	\$	50.00
23	To supply and install rear solar film for rear windscreen	\$	350.00
24	To supply and instal rear number plate with holder <i>CBT</i>	\$	70.00
25	To remove and refix rear spare tyre board, fender inner trims, spare tyre compartments, tools, and equipment to facilitate repair	\$	450.00
26	To remove and refix rear passenger seats, seat belts, buckles and trims to facilitate repairs	\$	450.00
27	To remove and refix fuel tank, conduct leak test, calibrate fuel pump to facilitate repair	\$	450.00
28	To remove and refix rear exhaust tail pipe, check for leaks, to facilitate repair	\$	450.00
29	To repair, replace rear boot lid, rear bumper, rear end panel, spare tyre panel rear tail rh panel, rear tail lamp lh panel rear rh fender, rear lh fender, and all other affected parts and areas	\$	3,000.00
30	To putty, sand, spray paint and polish rear boot, rear bumper, rear end panel rear spare tyre panel, rear fender rh, rear fender lh, rear rh door, rh rocker panel, tail lamp panel rh, tail lamp panel lh and all other affected areas	\$	2,800.00
31	To conduct ecu programming, check and clear fault codes, restore programme modules	\$	550.00
32	CLEARING AND REMOVAL OF DEBRIS	\$	380.00
	Total	\$	21,280.00
	Grand Total	\$	21,280.00

27433.06

X NN
20
X NN
40
40
X NN
X } NN
X } NN
50 X 50
80
X
X } NN
X
1000
1000.
150.
X NN
5160
5200

Remarks

THIS QUOTE IS ONLY AN ESTIMATE FOR REPAIR, SHOULD ANY ADDITIONAL PARTS OR LABOUR INCURRED WE WILL INFORM YOU ACCORDINGLY PRIOR BEFORE WE PROCEED.

12 Days.
part by part.
before paint photos.
Gue Qiang - 82880282
16/1/2019.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TTS EUROCARS pte ltd

A member of the TTS Motor Group

383 Sin Ming Drive, TTS Centre, S'pore 575717

Tel : 67572622 Fax : 67411626

TO	AXA Insurance Pte Ltd	DATE	14.12.2018
ATTN	MOTOR CLAIM DEPT	PAGE	1
MODEL	Mercedes benz E200	VEH NO	SGG1221C
YEAR	2017	C/N0	
		D.O.A	12.12.2018

S/NO	SUPPLEMENTARY PARTS	Qty	
	PARTS		
1	BOOT MOULDING X NN	1	S 145.00
2	IMPACT ABSORBER (FRONT BUMPER SPONGE) X repeat	1	S 152.00
3	CROSS MEMBER (FRONT REINFORCEMENT) X repeat	1	S 490.00
4	ABSORBER (CHASSIS MEMBER EXTENSION) / BT	1	S 200.00
5	ABSORBER (CHASSIS MEMBER EXTENSION) / BT	1	S 230.00
6	STRIKER (RADIATOR BRACKET) / BT	1	S 90.00
7	ORNAMENTAL (FRONT BUMPER LOWER TRIM) / re	1	S 120.00
8	TRIM BUMPER (LOWER TRIM CHROME) / cut	1	S 120.00
9	ORNAMENTAL MOULDING (OUTER CHROME GRILLE) X NN	1	S 280.00
10	BASIC MOUNTING (LOWER GRILLE BASE) / mc	1	S 80.00
11	TRIM BUMPER REAR LOWER (REAR BUMPER LOWER EXTEND) X NN	1	S 260.00
12	BEAM (front bumper logo base) X NN	1	S 74.00
13	REAR CROSS MEMBER (REAR BUMPER REINFORCEMENT) X repeat	1	S 760.00
14	CONSOLE (FRONT BUMPER CENTRE BEAM) / BT	1	S 200.00
	Total		S 3,201.00
	LESS 10%		S 320.10
			S 2,880.90
	LABOUR		
			S -
	Total		S 2,880.90

REMARK

LABOUR INCURRED WE WILL INFORM YOU ACCORDINGLY PRIOR BEFORE WE PROCEED.

Front lower radiator Air Duct - CRA \$122
 Parking sensor Seal Ring - mc \$40
 Bumper Trim clips - mc. \$162
 Trunk Boot Lid Badge (star) - re \$74.

PRE INVOICE

AXA INSURANCE PTE LTD
08 Shenton Way
#24-01 AXA Tower
SINGAPORE 068811

DOCUMENT NO : IN19-000006
DATE : 12/02/2019

Vehicle No: SGG1221C
MERC E200
Mileage: 45247

Staff ID : KAVIDHA
Account No : AXA INSUR
JOB NO : TN19-000006

No	Description	quantity U	List Price	Disc %	Amount
5	1 Bonnet Insulator Clip	1	\$31.70		\$31.70
6	2 Bonnet Logo	1	\$80.90		\$80.90
11	3 Front Bumper	1	\$1,155.85		\$1,155.85
4	4 Rivet	10	\$80.00		\$80.00
13	5 Front Bumper Grille	1	\$239.33		\$239.33
14	6 Front Bumper Grille Base	1	\$168.62		\$168.62
(A) 7	7 Frt lower Radiator Air Duct - (A) - (A) (WA 0004)	1	\$122.00		\$122.00 (A)
16	8 Mercedes Benz Ambler	1	\$131.50		\$131.50
17	9 Frt Bumper Lower Grille	1	\$105.50		\$105.50
18	10 Lower Bumper Grille	1	\$67.50		\$67.50
21	11 E class parking sensor	5	\$900.00		\$900.00
(A) 12	12 Parking sensor Seal Ring - (A) - (A)	5	\$40.00		\$40.00 (A)
23	13 Towing Eye Cover	1	\$64.50		\$64.50
26+27	14 Mounting Bracket Bumper	2	\$45.00		\$45.00
34	15 Front LH Fender	1	\$961.00		\$961.00
35	16 Front RH Fender	1	\$961.00		\$961.00
(A) 17	17 Bumper Trim Clips - (A) - (A)	20	\$162.00		\$162.00 (A)
42	18 Headlamp RH Unit	1	\$3,160.00		\$3,160.00
43	19 Headlamp LH Unit	1	\$3,160.00		\$3,160.00
48	20 Front Panel Cross member	1	\$780.00		\$780.00
50	21 Condenser	1	\$1,440.00		\$1,440.00
58	22 Trunk Lid Cover	1	\$2,240.00		\$2,240.00
64	23 Rear Tailgate Boot Lock Cover	1	\$210.00		\$210.00
60	24 E 200 LOGO	1	\$86.00		\$86.00
61	25 Rear Boot Lid Badge (star)	1	\$48.00		\$48.00
68	26 Rear Trim Bumper	1	\$1,880.00		\$1,880.00
69	27 Reflector rear Bumper	1	\$28.00		\$28.00
76	28 Rear Tail Pipe	1	\$390.00		\$390.00
59	29 Boot Moulding	1	\$145.00		\$145.00
25	30 Impact Absorber - (A)	1	\$152.00		\$152.00
79	31 Rear Bumper Centre Chrome	1	\$320.00		\$320.00
82	32 Rear Bumper Mounting LH	1	\$66.00		\$66.00
83	33 Rear Bumper Mounting RH	1	\$66.00		\$66.00
87	34 Rear Body Panel	1	\$1,360.00		\$1,360.00
89	35 Rear Hatch Strip	1	\$190.00		\$190.00
93	36 Interior Panel Clips	4	\$32.00		\$32.00
95	37 Rear Lamp	1	\$690.00		\$690.00
66	38 Front Fender Spring	1	\$40.00		\$40.00

supplement

248	-39	Front Bumper Support	BT (TA)	1
54	-40	Reinforcement Absorber	BT 103918	1
55	-41	Frt bumper Absorber	BT 103946	1
56	-42	Radiator Bracket	BT 104536	1
57	-43	Frt Bumper Lower Trim	BT	1
58	-44	Frt Bumper Trim	CA	1
15	-45	Frt Chrome Grille		1
510	-46	Frt Bumper Mounting	NEC	1
75	-47	Lower Rear Bumper Trim		1
	-48	Frt Boot Lid Badge(Star)	BT	1
71	-49	Reinforcement Rear Cross Member	(Rear)	1
514	-50	Radiator Support Console	BT	1

\$490.00	\$490.00	
\$200.00	\$200.00	(A)
\$230.00	\$230.00	(A)
\$90.00	\$90.00	(A)
\$120.00	\$120.00	(A)
\$120.00	\$120.00	(A)
\$280.00	\$280.00	
\$80.00	\$80.00	(A)
\$260.00	\$260.00	
\$74.00	\$74.00	(A)
\$760.00	\$760.00	
\$200.00	\$200.00	(A)

Total Parts	\$24,703.40
10% parts Discount	\$2,470.34
Total Parts	\$22,233.06

Labour

1	Sundries	1	\$40.00	\$40.00
2	Electrical wiring check for proper Functioning	1	\$30.00	\$30.00
3	Remove/replace Frt Headlamp Adjust/align headlamp focus	1	\$250.00	\$250.00
4	Tuff kote body cavity preserv.	1	\$20.00	\$20.00
5	Remove/refix/replace radiator cooling system conduct pressure test	1	\$60.00	\$60.00
6	Remove/refix/replace a/c condenser Vaccum refill condct pressure test check for leaks	1	\$60.00	\$60.00
7	Towing Charges	1	\$180.00	\$180.00
8	Repair/replace Frt Bonnet Frt bumper Frt support panel headlamp, Frt RH Fender/Frt LH Fender Frt RH chassis memberfit LH chassis member/frt LH door and all other affected parts	1	\$880.00	\$880.00
9	E class Number Plate (special)	1	\$360.00	\$360.00
10	Putty,sand,spray paint polish wax frt bonnet, frt RH fender frt LH fender frt bumperfit rh dr, frt rh fender inner panel	1	\$1,500.00	\$1,500.00
11	Sundries	1	\$20.00	\$20.00
12	Tuff kote body cavity preserv. rear boot rear end panel, spare tyre panel, rear RH and LH fender tail panel LH and all other affected parts	1	\$40.00	\$40.00
13	Sealant for body panel-rear boot rear end panelspare tyre paneltail lamp panel rear RH fender	1	\$40.00	\$40.00
14	Remove/refix rear spare tyre board fender inner trims spare tyre compartment tools and equipment for repairs	1	\$80.00	\$80.00
15	Repair, replace rear boot lid, rear bumper	1	\$1,000.00	\$1,000.00

	rear end panel spare tyre panel rear tail rh panel rear tail lamp lh panel rear rh fender rear lh fender and all other affected parts			
16	Putty,sand,spray paint polish rear boot rear bumper rear end panel rear spare tyre panel rear fender rh rear fender lh rear rh door rh rocker panel tail lamp panel rh tail lamp panel lh and all affected parts	1	\$1,000.00	\$1,000.00
17	conduct ECU programming check and clear fault codes restore programming modules		\$150.00	\$150.00
18	clearing and removal of debris	1	\$380.00	\$380.00

Total Labour	\$6,090.00
Total Parts	\$22,233.06
Subtotal	\$28,323.06
Add 7% GST	\$1,982.61
Total	\$30,305.67

*** Acknowledgement by Customer ***

I confirm that the goods stated in this invoice have
been received by me in good working order and condition.

I further confirm that all services and /or repair jobs
Stated in this invoice are completed and done to my
Satisfaction.

TTS EUROCARS PTE LTD



Name/Signature/NRIC No/Co Stamp (where applicable)

Authorised Signature



TTS EUROCARS pte Ltd

Company Reg. No: 200413930H

3930-H

383 Sin Ming Drive, TTS Centre, Singapore 575717 Sales: +65 6842 2222 Admin: +65 6757 0122 Aftersales: +65 6757 2622 Fax: +65 6741 1626

Branch : No.15, Commonwealth Lane, Lot A1, Commonwealth Car Mall, Singapore 149554 Tel : +65 6462 1111 Fax : +65 6252 4834

For corporate, fleet & leasing enquiries, please contact +65 6462 1111 24-Hour Emergency Assistance: +65 6475 2722

Website: www.tts.com.sg