



TTS EUROCARS pte ltd

A member of the TTS Motor Group

383 Sin Ming Drive , TTS Centre . S'pore 575717

Tel : 67572622 Fax : 67411626

TO	AXA Insurance Pte Ltd	DATE	14.12.2018
ATTN	MOTOR CLAIM DEPT	PAGE	1
MODEL	Mercedes benz E200	VEH NO	SGG1221C
YEAR	2017	C/N0	
		D.O.A	12/1/2019

S/NO	PARTS	Qty	
1	BONNET <i>Repair x</i>	1	
2	BONNET HINGE RH <i>x</i>	1	
3	BONNET HINGE LH <i>x</i> <i>ANN</i>	1	
4	BONNET INSULATOR <i>x</i>	1	
5	BONNET INSULATOR CLIPS <i>/ MC</i>	1	
6	BONNET LOGO <i>/ MC</i>	1	
7	BONNET LOCK <i>x</i>	1	
8	BONNET CATCH <i>x</i> <i>ANN</i>	1	
9	BONNET RUBBER STOPPER <i>x</i>	4	
10	BONNET ABSORBER <i>x</i>	2	
11	FRONT BUMPER <i>/ DE</i>	1	
12	FRONT BUMPER CLIPS <i>/ MC</i>	10	
13	FRONT BUMPER GRILLE <i>/</i>	1	
14	FRONT BUMPER GRILLE BASE <i>/ CRA</i>	1	
15	FRONT BUMPER GRILLE CHROME <i>/</i>	1	
16	FRONT GRILLE LOGO <i>/</i>	1	
17	FRONT BUMPER LOWER GRILLE <i>/</i> <i>fre</i>	1	
18	FRONT BUMPER LOWER GRILLE RH <i>/</i>	1	
19	FRONT BUMPER LOWER GRILLE LH <i>?</i>	1	
20	FRONT BUMPER NUMBER PLATE BASE <i>/ DE</i>	1	
21	FRONT BUMPER SENSORS <i>2PCS / DM</i>	4	
22	WIRE HARNESS FOR FRONT BUMPER SENSOR <i>?</i>	1	
23	FRONT BUMPER TOW HOOK <i>cover / cut</i>	1	
24	FRONT BUMPER REINFORCEMENT <i>?</i>	1	
25	FRONT BUMPER SPONGE <i>??</i>	1	
26	FRONT BUMPER SIDE RETAINER RH <i>/ fre</i>	1	
27	FRONT BUMPER SIDE RETAINER LH <i>/</i>	1	
28	FRONT BUMPER BRACKET RH <i>?</i>	1	
29	FRONT BUMPER BRACKET LH <i>?</i>	1	
30	FRONT BUMPER STIFFENER RH <i>?</i>	1	
31	FRONT BUMPER STIFFENER LH <i>?</i>	1	
32	FRONT BUMPER LOWER COVER <i>?</i>	1	

33	FRONT BUMPER LOWER GARNISH ?	1	
34	FRONT FENDER RH / { Bmc	1	
35	FRONT FENDER LH / { Bmc	1	
36	FRONT LH DOOR Require X	1	
37	FRONT FENDER TOP GARNISH RH X { NN	1	
38	FRONT FENDER TOP GARNISH LH X { NN	1	
39	FRONT FENDER INNER SHIELD RH ?	1	
40	FRONT FENDER INNER SHIELD LH ?	1	
41	FRONT FENDER INNER SHIELD CLIPS / MC	20	
42	HEADLAMP RH / { CAA	1	
43	HEADLAMP LH / { CAA	1	
44	HEADLAMP BALLAST ASSY X { NN	2	
45	HEADLAMP CONTROL MODULE X { NN	2	
46	HEADLAMP LOWER BRACKET RH ?	1	
47	HEADLAMP LOWER BRACKET LH ?	1	
48	FRONT SUPPORT PANEL / BT	1	
49	RADIATOR ?	1	
50	A/C CONDENSER / Cut.	1	
51	GEAR OIL COOLER ?	1	
52	TURBINE INTER COOLER ?	1	
53	FRONT CENTRE BRACE PANEL X NN	1	
54	RADIATOR FAN MOTOR ?	1	
55	RADIATOR FAN BLADE ?	1	
56	RADIATOR FAN HOUSING ?	1	
57	HORN ?	1	
58	REAR BOOT / BT	1	
59	REAR BOOT CHROME MOULDING / Cut	1	
60	REAR BOOT LOGO / { MC	1	
61	REAR BOOT EMBLEM / { MC	1	
62	REAR BOOT HINGE RH X { NN	1	
63	REAR BOOT HINGE LH X { NN	1	
64	REAR BOOT SWITCH ?	1	
65	REAR BOOT LOCK ?	1	
66	REAR BOOT STOPPER/ ADJUSTOR 2 PCS / BT	4	
67	REAR NUMBER PLATE LAMP X NN	2	
68	REAR BUMPER / TN	1	
69	REAR BUMPER REFLECTOR RH / Cut.	1	
70	REAR BUMPER REFLECTOR LH ?	1	
71	REAR BUMPER REINFORCEMENT ?	1	
72	REAR BUMPER SPONGE ?	1	
73	REAR BUMPER SENSOR 3 PCS / RM	4	
74	WIRE HARNESS FOR REAR BUMPER SENSOR ?	1	
75	REAR BUMPER LOWER TRIM/ GARNISH ?	1	
76	EXHAUST SLEEVE RH / Cut.	1	
77	EXHAUST SLEEVE LH X NN	1	

78	REAR BUMPER TOWING COVER ?	1	
79	REAR BUMPER LOWER CHROME MOULDING / cut	1	
80	REAR BUMPER BRACKET RH ?	1	
81	REAR BUMPER BRACKET LH ?	1	
82	REAR BUMPER SIDE RETAINER RH = 4 MC	1	
83	REAR BUMPER SIDE RETAINER LH = 4 MC	1	
84	REAR BUMPER STIFFENER RH ?	1	
85	REAR BUMPER STIFFENER LH ?	1	
86	REAR BUMPER SENSOR BRACKET / MC	1	
87	REAR END PANEL / BNC	1	
88	REAR END PANEL TOP GARNISH X NN	1	
89	REAR BOOT LID WEATHER STRIP / MC	1	
90	REAR BOOT LID LOCK CATCH X NN	1	
91	SPARE TYRE PANEL ?	1	
92	SPARE TYRE BOARD X	1	
93	END PANEL TOP GARNISH CLIPS / MC	4	
94	REAR RH FENDER Repairs X	1	
95	TAIL LAMP RH / CLP	1	
96	TAIL LAMP LH ?	1	
97	REAR WINDSCREEN X	1	
98	REAR WINDSCREEN MOULDING X	1	
99	REAR RH DOOR WEATHER STRIP (INNER) X	1	
		Sub Total	\$ -
		Less 10%	\$ -
		Total	\$ -
LABOUR			
1	Sundries	\$	150.00
2	Electrical wiring check for proper functioning	\$	150.00
3	To Supply front number plate with holder X NN	\$	70.00
4	To remove and replace front headlamp, adjust and align headlamp focus	\$	250.00
5	Full note - body cavity preservation (front bonnet, front rh fender, front lh fender, front support panel)	\$	350.00
6	Sealant for body panel - Bonnet, front rh fender, front lh fender	\$	250.00
7	To remove and refix/ replace radiator cooling system, conduct pressure test, check for leaks	\$	550.00
8	To remove and refix/ replace a/c condenser. Vacuum refill, conduct pressure test check for leaks	\$	550.00
9	To remove and replace turbo intercooler, conduct pressure test, check for leaks.	\$	550.00
10	Towing charges	\$	250.00
11	To remove and replace front headlamp wiper washer system	\$	350.00
12	To repair, replace front bonnet, front bumper, front support panel, headlamps, front rh fender, front lh fender, front rh chassis member, front lh chassis member, chassis member, front lh door and all other affected parts and areas	\$	3,000.00
13	To putty, sand, spray paint, polish and wax front bonnet, front rh fender, front lh fender, front bumper, front rh door, front rh fender inner panel	\$	2,800.00

20
 30
 50 X NN
 40
 X NN
 60
 60
 X NN
 180
 X NN
 880
 1500

	front lh fender inner panel, front rh chassis member, front lh chassis member and all other affected areas	
14	To check and adjust frontal chassis alignment, align and pull to specifications	\$ 1,500.00
16	Sundries	\$ 150.00
17	electrical wiring check for proper functioning	\$ 150.00
18	Tuff kote - body cavity preservation (rear boot, rear end panel, spare tyre panel, rear rh and lh fender, tail panel rh, tail lamp panel lh and all other affected areas	\$ 350.00
19	Sealant for body panel - rear boot, rear end panel , spare tyre panel, tail lamp panel, rear rh fender	\$ 350.00
20	To remove and refix rear windscreen to facilitate repair, conduct water leak test	\$ 450.00
21	Sealant for rear windscreen	\$ 60.00
22	Inner seal for rear windscreen	\$ 50.00
23	To supply and install rear solar film for rear windscreen	\$ 350.00
24	To supply and instal rear number plate with holder	\$ 70.00
25	To remove and refix rear spare tyre board, fender inner trims, spare tyre compartments, tools, and equipment to facilitate repair	\$ 450.00
26	To remove and refix rear passenger seats, seat belts, buckles and trims to facilitate repairs	\$ 450.00
27	To remove and refix fuel tank, conduct leak test, calibrate fuel pump to facilitate repair	\$ 450.00
28	To remove and refix rear exhaust tail pipe, check for leaks, to facilitate repair	\$ 450.00
29	To repair, replace rear boot lid, rear bumper, rear end panel , spare tyre panel rear tail rh panel, rear tail lamp lh panel rear rh fender, rear lh fender, and all other affected parts and areas	\$ 3,000.00
30	To putty, sand, spray paint and polish rear boot, rear bumper, rear end panel rear spare tyre panel, rear fender rh , rear fender lh, rear rh door, rh rocker panel , tail lamp panel rh, tail lamp panel lh and all other affected areas	\$ 2,800.00
31	To conduct ecu programming, check and clear fault codes, restore programme modules	\$ 550.00
32	CLEARING AND REMOVAL OF DEBRIS	\$ 380.00
	Total	\$ 21,280.00
	Grand Total	\$ 21,280.00

X NN
 20
 X NN
 40
 40
 X NN
 X } NN
 X } NN
 50
 80
 X
 X } NN
 X
 1000
 1000 .
 150 .

Remarks

THIS QUOTE IS ONLY AN ESTIMATE FOR REPAIR, SHOULD ANY ADDITIONAL PARTS OR LABOUR INCURRED WE WILL INFORM YOU ACCORDINGLY PRIOR BEFORE WE PROCEED.

12 Days .
 part by part .
 before paint photos .
 Gue Qiang - 82880282
 16/1/2019 .

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: