

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5663T**AAD1901-106***Not Authored
6/ Sep @ 3200*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5663T

VF1ABL15AUC279756

RENAULT

LATITUDE

11.1.2019

EQ

4/11/2014

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>nd/bu</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	} X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99	
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99	} X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>n</i> 225.95	} X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95	
13	1 OUTER PANEL REAR (End Panel)	\$	<i>n</i> 1,471.77	
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56	
15	1 TAILLAMP LH	\$	<i>Sn</i> 552.55	
16	1 TAILLAMP PANEL LH	\$	<i>n</i> 986.70	} X
17	1 BOOT REAR	\$	<i>n</i> 2,872.68	
18	1 TAILLAMP RH	\$	<i>Sn</i> 552.55	
19	1 TAILLAMP PANEL RH	\$	<i>n</i> 986.70	

\$ 11,496.85**10% \$ 1,149.69****\$ 10,347.17****Special Nett**

1	1SET PARKING AID	\$	<i>Shen</i> 700.00	<i>600.00</i>
2	1SET REAR BUMPER CLIP	\$	<i>n</i> 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>n</i> 33.00	✓

Trans-cab Auto Services Pte Ltd**AAD1901-106**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5663T

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	na	17.82	X
11	2 REAR WINDSCREEN SELANT	\$	na	80.00	X
12	1 WINDSCREEN MOULDING	\$	na	100.00	X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
14	1 REAR BUMPER ADVERTISEMENT STICKER	\$	na	300.00	100.00
15	1 REAR BOOT ADVERTISEMENT STICKER	\$	na	300.00	X
TOTAL		\$		1,045.82	
TOTAL PARTS		\$		11,392.99	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	400
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	300
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00	60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00 X
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1901-106**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5663T

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *na* 170.00 *X*

To check steering geometry and computer wheel
alignment

\$ *na* 220.00 *X***TOTAL \$ 7,410.00****Over All Total \$ 29,150.15****(LUMP SUM)****Repair Days**~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: