

22/03/2002

ASS. REC. BY:

REF:

CS/TMI19000932/Nvd302

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Telma Gomez

of

TMI

Date/Time:

15/1/2019

Estimated Cost:

\$15,225.42

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 9999S

Insured:

STQ 5010E

at Workshop m/s

Comfort Delgros Engineering

Tel:

of

59 Loyang Drive

Policy No:

MU012989

Claim No:

M1900307

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/1/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SH9999S-X

STQ 5010E-X

Surveyor: N/A2 REF: TMI **ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____
 at Workshop m/s _____

of _____
 Insured: STU 5010E

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

X	X	X
N/S	O/S	

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 3H 99995 Yr Regn: 19 Jul 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____ c.c. 1,798

Make: TOYOTA PRIUS A/C: Insur. d / Std / NI / NA

Colour: BLUE T/Radi: Insured / Std / NI / NA

Sp. Reading: 242,174

Eng/No: _____

C/No: 31DKB3FU103561448

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAK

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/1/19 D.O.I. 18/1/19

Survey held at EDGE WAYANG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

25/1/19 FINALIZED PART BY PART REPAIR \$11,938.80 / 6 DAYS
 (Red 3815.29, 249)

RECEIVED 28 JAN 2019

Date/Time, File Pass to?

☐ : Prelim Report
☐ : Final Report

1) Date/Time, File Return to?

2) 28/1 - typist

Report Format: Merimen

Lump Sum / I.B.I: (\$ 11,938.80)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee: 250

Transportation: _____

S + RS. 51

Photos _____

Others 10

TOTAL 260

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invo (\$ _____)
☐ : Weekend (\$ _____)

98.52

1,311,391.5 L

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jan 2019 Sendback Est	14 Jan 2019 17:13 S\$15,225.42	15 Jan 2019 14:47 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		TAN OI YONG, ID: S0066016G							
Main Claimant:		CTPL							
Vehicle Reg. No.:		SH9999S	Date of Loss:	14/01/2019 07:00 - :59 [17 Months and 26 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / M1900307	Policy/Cover Note No.:	MU012989 (Comprehensive) Coverage: 18/12/2017 - 13/05/2019					
Vehicle Reg. No. (Insured):		SJQ5010E	Policy No. (Claimant):						
		Excess:	S\$600.00						
Repairer:		ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300							
Handling Insurer:		Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 24/01/2019]							
Adj Asg. Remarks:		OUR INSD HAVE NOT RPT THE ACCIDENT.							
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2019 14:11
Date Of Accident	14/01/2019 07:45
Exact Location Of Accident	YISHUN AVE 7 X YISHUN INDUSTRIAL PARK A
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH9999S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	TAN YOKE MENG
NRIC No	S6844132C
Date Of Birth	19/10/1968
Occupation	OUTDOOR
Date Of Driving Pass	28/12/1992
Driving Experience	26 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96436918
Fax Number	
Contact Number	
EMail Address	BIESSEDDY@GMAIL.COM

Address	BLK 715 WOODLANDS DRIVE 70 #07-162
Postcode	730715
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident: HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ5010E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	LEFT REAR

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	3P DRIVER
Approximate Age	
Injuries Sustain	WAIST PAIN
Injured person in which vehicle?	SJQ5010E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	TAN YOKE MENG
Approximate Age	51
Injuries Sustain	NECK PAIN
Injured person in which vehicle?	SJQ5010E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 14.01.2019@1030HRS


Reporting Centre Personnel's Signature
Name: Loke Wei Yang
NRIC/FIN No.: 141119

SKETCH PLAN



Along Yishun Ave 7 x Junction Yishun Industrial Park A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14.01.2019@0725HRS I was travelling along Yishun AVE 7 X Junction Yishun Industrial Park A with one male passenger onboard.

On the traffic junction I was travelling straight and the traffic light was green. I proceeded straight, upon crossing the Junction traffic light turns amber and I could not stop in time. Veh (B) SJQ 5010E did not gave way to my taxi(A) and collided onto my taxi entire front portion.
--

I have company video and photos at scene to support my claims .

I suffered neck pain after the accident and will consult a doctor later.

Veh(B) SJQ 5010E Male ~~passenger~~ driver

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 14.01.2019@1030HRS

Reporting Centre Personnel's Signature
Name:

Name: _____

NRIC/FIN No.: _____

Loke Wei Yiang

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305260031

MER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

REGN NO.: SH 9999S	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)	DATE/TIME IN 14.01.2019 09:55
YR OF MANU. 19.07.2017	TARGET DATE
CHASSIS CODE JTDKB3FU103561448	COMPLETION DATE/TIME:

INT CARD NO.


JOB DESCRIPTION

Accident Date: 14.01.2019
NATURE: 3P 14.01.19

/NO

LABOR CODE

DESCRIPTION



& PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ment Slip

Exit Pass

SH 9999S

LIMITS

Vehicle No.:

SH 9999S

ice Advisor

Signature/Date

Name of Service Advisor

Date

to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
 CTPL

Singapore

CP/P)
 LKK-

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	14/01/2019
Vehicle Reg. No.:	SH9999S	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 (A) Vehicle Reg. Date: 19/07/2017		
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZRS048503	Chassis No:	JTDKB3FU103561448
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	12,705.42
Miscellaneous Items	10.00
Labour	2,510.00
Paintwork Labour	0.00
Towing	15,754.09
Gross Total (S\$)	15,225.42
+ GST 7.00% (S\$)	1,065.78
Nett Amount (S\$)	16,291.20

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

@ 1715

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jan 2019)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH9999S/14/01/2019 17:13

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BONNET	20.00	0.00	*950.50 FL	DEF
2	2		*BONNET HINGE RH/LH	20.00	0.00	*115.40 FL	BT
3	1		*BONNET LOCK	20.00	0.00	*132.60 FL	BT
4	1		*BONNET HOOD CATCH	20.00	0.00	*8.60 FL	BT
5	1		*RADIATOR GRILLE	20.00	0.00	*438.00 FL	CRK
6	1		*RADIATOR GRILLE EMBLEM	20.00	0.00	*88.00 FL	CRK
7	2		*FOGLAMP RH/LH	20.00	0.00	*1,840.00 FL	DEF
8	1		*FRT BUMPER	20.00	0.00	*499.90 FL	CRK
9	1		*FRT BUMPER REINFORCEMENT	20.00	0.00	*696.40 FL	DEF
10	1		*FRT BUMPER REINFORCEMENT ABSORBER	20.00	0.00	*115.70 FL	DEF
11	1		*FRT BUMPER SPONGE	20.00	0.00	*78.80 FL	CRK
12	1		*FRT BUMPER CENTRE GRILLE	20.00	0.00	*301.90 FL	CRK
13	1		*FRT BUMPER LOWER GRILLE	20.00	0.00	*166.90 FL	DEF
14	10		*FRT BUMPER CLIPS	20.00	0.00	*22.00 FL	DEF
15	2		*FRT BUMPER SIDE RETAINER RH/LH	20.00	0.00	*154.00 FL	DEF
16	1		*FRT UNDER COVER	20.00	0.00	*180.80 FL	CRK
17	2		*FRT BUMPER HOLE COVER RH/LH	20.00	0.00	*56.80 FL	MIS
18	1		*FRT BUMPER EXTENTION BRACKET MOUNTING	20.00	0.00	*110.40 FL	XSVL
19	2		*FRT BUMPER SUPPORT RH/LH	20.00	0.00	*163.40 FL	BT
20	2		*HEADLAMP RH/LH	20.00	0.00	*6,910.00 FL	CRK
21	2		*HEADLAMP PANEL RH/LH	20.00	0.00	*480.20 FL	XSVL
22	1		*FRT BUMPER LOWER SUB REINFORCEMENT	20.00	0.00	*241.40 FL	BT
23	1		*TOP PANEL CENTRE	20.00	0.00	*364.90 FL	DEF
24	2		*TOP PANEL SIDE RH/LH	20.00	0.00	*138.40 FL	?
25	1		*BRACE PANEL	20.00	0.00	*75.20 FL	BT
26	2		*HEADLAMP BRACKET MOUNTING RH/LH	20.00	0.00	*51.00 FL	XSVL
27	1		*FRT FENDER SHIELD LH	20.00	0.00	*196.60 FL	XSVL
28	1		*FRT FENDER SHIELD CLIPS LH	20.00	0.00	*3.80 FL	NN
29	1		*FRT FENDER HYBRID EMBLEM	20.00	0.00	*53.50 FL	NEC
30	1		*FRT FENDER LH	20.00	0.00	*945.30 FL	DEF
31	1		*FRT NO.PLATE	0.00	0.00	*25.00 F	DD
32	1		*FRT NO.PLATE TRIM COVER	0.00	0.00	*30.00 F	CRK
33	1		*FRT NO.PLATE GARNISH	0.00	0.00	*99.00 F	CRK
34	1		*FRT BUMPER LOGO	0.00	0.00	*87.10 F	MIS

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	15,821.50
- List Item Discount on L Items (\$\$)	3,116.08
Total Parts (\$\$)	12,705.42

ComfortDelGro Engineering Pte Ltd/SH9999S/14/01/2019 17:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	1,200.00 600
2	SPRAY PAINTING	New	1,000.00 600
3	WIRING CHECK	New	60.00 30
4	TUFF KOTE	New	100.00 50
5	R/I AIR CON CONDENSER ETC	New	150.00 X 22
Gross Labour Cost (S\$)			2,510.00

ComfortDelGro Engineering Pte Ltd/SH9999S/14/01/2019 17:13. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NA2 LKK

15/1/19 1600

P/R

6 DAYS

CHECK ITEMS & HOTOS

ALL BEFORE/ANT PHOTOS

LKK Auto Consultancy hereby notify
the Repairer of the following:

- To resurvey before any survey taking
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental damage must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature :

Date:

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305260031

Date : 24/01/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SH 9999S

Date of Accident : 14-Jan-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SJQ5010E

2. The finalized amount shall be:

(a) Spare Parts after List discount \$10,648.80

(b) Labour Charges \$1,290.00

Total for Part-By-Part Repair Cost \$11,938.80

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 6 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : NAZ

Date : 25/1/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.01.2019

Time: 09:11:55

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305260031
 REGN NO : SH 9999S
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 19.07.2017
 DATE/TIME IN : 14.01.2019 09:55
 ACCIDENT DATE : 14.01.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-0572-G	BONNET	1	950.50	25.00	712.87	DEF
0002 04-01-0302-2972-G	BONNET HINGE RH	1	57.70	25.00	43.27	BT
0003 04-01-0302-2872-G	BONNET HINGE LH	1	57.70	25.00	43.27	BT
0004 04-01-0302-2402-G	BONNET LOCK	1	132.60	25.00	99.45	BT
0005 04-01-0302-2164-G	RADIATOR GRILLE	1	438.00	25.00	328.50	CRK
0006 04-01-0302-0988-G	RADIATOR GRILLE EMBLEM	1	88.00	25.00	66.00	MIS
0007 04-01-0302-2292-G	FRONT BUMPER	1	499.90	25.00	374.92	CRK
0008 04-01-0302-0635-G	FRONT BUMPER SPONGE	1	78.80	25.00	59.10	CUT
0009 04-01-0302-2062-G	RADIATOR LOWER GRILLE	1	166.90	25.00	125.17	DEF
0010 04-01-0302-2915-G	HEADLAMP RH	1	3,455.00	25.00	2,591.25	SR
0011 04-01-0302-2815-G	HEADLAMP LH	1	3,455.00	25.00	2,591.25	CRK
0012 04-01-0302-2297-G	FRT FENDER (HYBRID) LH	1	53.50	25.00	40.12	NEU
0013 FNPS	NO PLATE(S)W/TRIM COVER	1 N	55.00	2.50	55.00	DD/CRK

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.01.2019

Time: 09:11:55

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305260031
 REGN NO : SH 9999S
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(C
 DATE OF REGN : 19.07.2017
 DATE/TIME IN : 14.01.2019 09:55
 ACCIDENT DATE : 14.01.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014	04-01-0302-2170-G	FRT NO.PLATE GARNISH	1	99.00	9.25	99.00	CRK
0015	04-01-0302-0632-G	FRT BUMPER HOLE COVER LH	1	28.40	25.00	21.30	MIS
0016	04-01-0302-0633-G	FRT BUMPER HOLE COVER RH	1	28.40	25.00	21.30	MIS
0017	04-01-0302-4891-G	FOGLAMP LH	1	920.00	25.00	690.00	DEF
0018	04-01-0302-2298-G	FRT BUMPER REINFORCEMENT	1	696.40	25.00	522.30	DEF
0019	04-01-0302-2267-G	FRT BUMPER CLIPS	10	22.00	25.00	16.50	NEC
0020	04-01-0302-2871-G	FRT BUMPER SUPPORT LH	1	81.70	25.00	61.27	BT
0021	04-01-0302-2308-G	ENGINE UNDER NO.1**	1	452.80	25.00	339.60	TN (A)
0022	04-01-0302-2975-G	F/BUMPER LWR REINFORCEMEN	1	241.40	25.00	181.05	BT
0023	04-01-0302-2277-G	TOP PANEL CENTRE	1	364.90	25.00	273.67	BT
0024	04-01-0302-3801-G	FRT BUMPER RETAINER LH	1	77.00	25.00	57.75	DEF
0025	04-01-0302-3901-G	FRT BUMPER RETAINER RH	1	77.00	25.00	57.75	DEF

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.01.2019

Time: 09:11:55

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305260031
 REGN NO : SH 9999S
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(C
 DATE OF REGN : 19.07.2017
 DATE/TIME IN : 14.01.2019 09:55
 ACCIDENT DATE : 14.01.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0026 04-01-0302-0574-A	FRT FENDER LH	1	945.30	25.00	708.97	DEF
0027 21-01-0302-2013-A	BATTERY METADOR**	1	252.10	25.00	189.07	DEF (A)
0028 04-01-0302-2349-G	BRACE PANEL	1	75.20	25.00	56.40	BT
0029 04-01-0302-2307-G	FRT UNDER COVER	1	180.80	25.00	135.60	DEF
0030 28-01-0103-2013-A	BONNET APPS LOGO	1	87.10	25.00	87.10	NEC

SUB-TOTAL : 10,648.80

JOB NATURE

0000 L	PANEL BEATING	600.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	600.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00

1,280

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.01.2019

Time: 09:11:55

Page: 4

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305260031
REGN NO : SH 9999S
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 19.07.2017
DATE/TIME IN : 14.01.2019 09:55
ACCIDENT DATE : 14.01.2019


JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 20-05 TP MERIMEN 10.00

SUB-TOTAL : 1,290.00

TOTAL : 11,938.80


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :
AUTHORISED : YES / NO

...CLAIM SUBFOLDER...(Pending for Survey Report)
































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jan 2019 Sendback Est	22 Jan 2019 14:26 \$14,975.07	15 Jan 2019 14:47 Edit Adj Rpt	\$11,938.85 Edit Estimates	\$11,938.85 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	TAN OI YONG, ID: S0066016G								
Main Claimant:	CTPL								
Vehicle Reg. No.:	SH9999S	Date of Loss:	14/01/2019 07:00 - :59 [17 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1900307	Policy/Cover Note No.:	MU012989 (Comprehensive) Coverage: 18/12/2017 - 13/05/2019						
Vehicle Reg. No. (Insured):	SJQ5010E	Policy No. (Claimant):							
		Excess:	S\$600.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 24/01/2019]								
Adj Asg. Remarks:	OUR INSD HAVE NOT RPT THE ACCIDENT.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SH9999S (M1900307)
[SJQ5010E]
TP
CTPL
Jan 14 2019 7:00AM
[TAN OI YONG]
ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	22/01/19 14:26	Repairer Estimates		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
2	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
3	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
4	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
5	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
6	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
7	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
8	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
9	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
10	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
11	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
12	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
13	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
14	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
15	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
16	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
17	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
18	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
19	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
20	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
21	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
22	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
23	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
24	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
25	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
26	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
27	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
28	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
29	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
30	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
31	15/01/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>
32	25/01/19 11:02	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
33	25/01/19 11:02	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
34	25/01/19 11:02	Dismantled Parts		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	25/01/19 11:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	25/01/19 11:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	25/01/19 11:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	25/01/19 11:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	25/01/19 11:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	25/01/19 11:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	25/01/19 11:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	25/01/19 11:03	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
66	25/01/19 11:03	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
67	25/01/19 11:03	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
68	25/01/19 11:03	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
69	25/01/19 11:03	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
70	25/01/19 11:03	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
71	25/01/19 11:03	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
72	25/01/19 11:03	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
73	25/01/19 11:03	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	14/01/19 17:14	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/01/19 16:10	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19000932/NVD3E2

Date: 29/01/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MU012989

Claimant Vehicle No: SH9999S

Insured Vehicle No: SJQ5010E

Date of Loss: 14/01/2019

Nature of Claim: TP

Claim No: M1900307

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH9999S

Make & Model: TOYOTA PRIUS HYBRID, 1.8 (A)

Engine No: 1NMS048503

Reg. Date: 19/07/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU103561448

Colour: Blue

Odometer: 242174 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes

Engine Modification: No

Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,455.07	10,648.85	1,806.22	14.50
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	2,510.00	1,280.00	1,230.00	49.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,975.07	11,938.85	3,036.22	20.28
+ GST 7.00/7.00% (S\$)	1,048.25	835.72	212.53	20.27
Nett Amount (S\$)	16,023.32	12,774.57	3,248.75	20.28

INSPECTION

Date of Assignment: 15/01/2019 Present Location:

ComfortDelGro Engineering Pte Ltd
(Loyang)

Date Inspected: 15/01/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 6.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 5 cents -Finalise confirm amount: \$11,938.80

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2019)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH9999S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Deformed	950.50 FL	*950.50 FL
2	2		*BONNET HINGE RH/LH	Bent	115.40 FL	*115.40 FL
3	1		*BONNET LOCK	Bent	132.60 FL	*132.60 FL
4	1		*BONNET HOOD CATCH	Serviceable	8.60 FL	*- FL
5	1		*RADIATOR GRILLE	Cracked	438.00 FL	*438.00 FL
6	1		*RADIATOR GRILLE EMBLEM	Missing	88.00 FL	*88.00 FL
7	1		*FOGLAMP RH/LH	N/S Deformed	1,840.00 FL	*920.00 FL
8	1		*FRT BUMPER	Cracked	499.90 FL	*499.90 FL
9	1		*FRT BUMPER REINFORCEMENT	Deformed	696.40 FL	*696.40 FL
10	1		*FRT BUMPER REINFORCEMENT ABSORBER	Serviceable	115.70 FL	*- FL
11	1		*FRT BUMPER SPONGE	Cut	78.80 FL	*78.80 FL
12	1		*FRT BUMPER CENTRE GRILLE	Serviceable	301.90 FL	*- FL
13	1		*FRT BUMPER LOWER GRILLE	Deformed	166.90 FL	*166.90 FL
14	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
15	2		*FRT BUMPER SIDE RETAINER RH/LH	Deformed	154.00 FL	*154.00 FL
16	1		*FRT UNDER COVER	Cracked	180.80 FL	*180.80 FL
17	2		*FRT BUMPER HOLE COVER RH/LH	Missing	56.80 FL	*56.80 FL
18	1		*FRT BUMPER EXTENTION BRACKET MOUNTING	Serviceable	110.40 FL	*- FL
19	1		*FRT BUMPER SUPPORT RH/LH	N/S Bent	163.40 FL	*81.70 FL
20	2		*HEADLAMP RH/LH	N/S Cracked / O/S Scratched	6,910.00 FL	*6,910.00 FL
21	2		*HEADLAMP PANEL RH/LH	Serviceable	480.20 FL	*- FL
22	1		*FRT BUMPER LOWER SUB REINFORCEMENT	Bent	241.40 FL	*241.40 FL
23	1		*TOP PANEL CENTRE	Deformed	364.90 FL	*364.90 FL
24	2		*TOP PANEL SIDE RH/LH	Serviceable	138.40 FL	*- FL
25	1		*BRACE PANEL	Bent	75.20 FL	*75.20 FL
26	2		*HEADLAMP BRACKET MOUNTING RH/LH	Serviceable	51.00 FL	*- FL
27	1		*FRT FENDER SHIELD LH	Serviceable	196.60 FL	*- FL
28	1		*FRT FENDER SHIELD CLIPS LH	Not Necessary	3.80 FL	*- FL
29	1		*FRT FENDER HYBRID EMBLEM	Necessary	53.50 FL	*53.50 FL
30	1		*FRT FENDER LH	Deformed	945.30 FL	*945.30 FL
31	1		*FRT NO.PLATE	Dented	25.00 F	*25.00 F
32	1		*FRT NO.PLATE TRIM COVER	Cracked	30.00 F	*30.00 F
33	1		*FRT NO.PLATE GARNISH	Cracked	99.00 F	*99.00 F
34	1		*FRT BUMPER LOGO	Missing	87.10 F	*87.10 F
35	1		*ENGINE UNDER COVER - NO.1	Torn	452.80 FL	*452.80 FL
36	1		*BATTERY METADOR	Deformed	252.10 FL	*252.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					16,526.40	14,118.10
- List Item Discount on L Items 25.00/25.00% (\$\$)					4,071.33	3,469.25
Total Parts (\$\$)					12,455.07	10,648.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (\$\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	WIRING CHECK	New	60.00	30.00
4	TUFF KOTE	New	100.00	50.00
5	R/I AIR CON CONDENSER ETC	New	150.00	0.00
Gross Labour Cost (\$\$)			2,510.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >