

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0058/2019/GW
Date : 14-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SLS 7845 R**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Bhvvanesvaran S/O Muthu
Address : Apt Blk 752 Jurong West Street 74
#06-18
Singapore 640752
Telephone : HP +65 91120099
Type of Claim : Own Damage Claims
Policy No. : 1800152805
Vehicle No : **SJU 1838 P**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year :
Engine No :
Chassis No :
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Jan-19
Place of Accident : Slip road to Thomson Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJU 1838 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer ^{front} rear door's multi lock system and power window devices. Inspect for damages.	S/N \$ 280.00	✓
2	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 300.00	✓
3	To dismantle and renew rhs ^{front} rear door. To repair rhs front door. Re-organize crash management components. Reinstall all parts removed.	\$ 1,200.00	750 .
4	To respray rhs front door, door handle and rhs rear door.	\$ 1,600.00	1100
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,572.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJU 1838 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR-RH <i>reited</i>	\$ 2,152.00	✓
2	FRONT DOOR OUTER DOOR SEAL-RH <i>new</i>	\$ 185.00	✓
3	BONDING AGENT <i>?</i>	\$ 45.00	?
4	CLEANING SOLUTION <i>?</i>	\$ 65.00	?
5	APPLICATOR <i>?</i>	\$ 7.00	?
6	SEALING STRIP <i>Not in ?</i>	\$ 15.00	?
7	FRONT DOOR ATTACHMENT PART-RH <i>new</i>	\$ 1,179.00	X
8	FRONT DOOR CATCH-RH <i>3 new</i>	\$ 109.00	X
9	FRONT DOOR CATCH COVER-RH	\$ 12.00	X
10	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS CHARGES :		\$ 4,069.00	
TOTAL LABOUR CHARGES		\$ 3,572.00	
GRAND TOTAL		\$ 7,641.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lj

Surveyed Date

: 15/01/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Authorised Repairs, 04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant