

ASS. REC. BY:

REF:

TP

CS/TP19000943/Kvd302

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: S14D 93886 Yr Regn: 01, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Chevrolet Epica c.c. 1991Colour white A/C: Insured / Std / NI / NASp.Reading 332445 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KU1A 69RTBB 07228Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 31/1/14 D.O.I. 3/2/14

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>S14D 93886 - 013 / AXA14018585 / Kvd302-1</u>
	<u>16/1/19 LS \$7650 (Red 16, 297.59, 68%)</u>
	<u>16/1/19 Send invoice first before realase report to Trans-Cab</u>
	<u>RECEIVED 16 JAN 2019</u>

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2) 16/1 - typistReport Format: TPLump Sum / I.B.I.: (\$ 7650 1/2)Days Of Repair: 7

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

13x15=195170+1955019805/14

**Veron Chen (LKKAUTO)**

---

**From:** claims <claims@transcab.com.sg>  
**Sent:** Wednesday, 9 January 2019 10:57 AM  
**To:** SUR  
**Cc:** 'claims'  
**Subject:** RE: III Ref: MCT14011090/01/DP RE: TCS REF:AAD1402-003-Accident involving SHB6394T & SHD9388G on 31/1/2014-REQUEST FOR SURVEY REPORT.  
**Attachments:** AAD1402-003-ESTMAITE MARKING.pdf, SHD9388G 31.01.14 - GIA.pdf

Dear Sir/Mdm

We would like to request a copy of the survey report.

Addition information.

Accident involving SHB6394T & SHD9388G  
DOA 31/1/2014  
Location JUNCTION OF ROAD 1 AND ROAD 2 LOWER DELTA ROAD  
Model CHEVROLET EPICA-2.0 DSL TURBO (A)

Attached estimate marking and GIA report for your reference.

Thank You  
Best Regards,  
Calvin Er  
Finance Department  
TEL: 6603 1265 Ext.307

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Pooi Chin Han Daniel [mailto:[danielpooi@iii.com.sg](mailto:danielpooi@iii.com.sg)]  
**Sent:** Tuesday, 8 January, 2019 2:51 PM  
**To:** 'claims' <claims@transcab.com.sg>  
**Cc:** Sundari Nagarajan - III <[sundari@iii.com.sg](mailto:sundari@iii.com.sg)>; 'Jasmine Tan' <[jasminetan@transcab.com.sg](mailto:jasminetan@transcab.com.sg)>  
**Subject:** III Ref: MCT14011090/01/DP RE: TCS REF:AAD1402-003-Accident involving SHB6394T & SHD9388G on 31/1/2014

**Without Prejudice save as to cost**

Dear Calvin,

We refer to the above accident and your letter dated 3/12/2016

Please forward us the survey report to enable us to review the matter. In the meanwhile please hold hands.

*Daniel Pooi*

**Motor Claims Department**  
**India International Insurance Pte Ltd**  
64 Cecil Street #04-02 IOB Building  
Singapore 049711  
Tel: 6347 6100 Ext 202 Fax: 6224 4174  
**S&P 'A-' rated Company**



---

**From:** claims [<mailto:claims@transcab.com.sg>]  
**Sent:** Monday, 7 January, 2019 10:20 AM  
**To:** Pooi Chin Han Daniel <[danielpooi@iii.com.sg](mailto:danielpooi@iii.com.sg)>  
**Cc:** Sundari Nagarajan - III <[sundari@iii.com.sg](mailto:sundari@iii.com.sg)>; 'Jasmine Tan' <[jasminetan@transcab.com.sg](mailto:jasminetan@transcab.com.sg)>  
**Subject:** FW: TCS REF:AAD1402-003-Accident involving SHB6394T & SHD9388G on 31/1/2014

Without Prejudice

Dear Daniel,

Please refer to the preceding email.

Any updates for this case?

Attached LOD and GIA report for your reference.

Thank You  
Best Regards,  
Calvin Er  
Finance Department  
TEL: 6603 1265 Ext.307

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** claims [<mailto:claims@transcab.com.sg>]  
**Sent:** Thursday, 29 November, 2018 10:16 AM  
**To:** 'Pooi Chin Han Daniel' <[danielpooi@iii.com.sg](mailto:danielpooi@iii.com.sg)>; 'Sundari Nagarajan - III' <[sundari@iii.com.sg](mailto:sundari@iii.com.sg)>  
**Cc:** 'Jasmine Tan' <[jasminetan@transcab.com.sg](mailto:jasminetan@transcab.com.sg)>; [claims@transcab.com.sg](mailto:claims@transcab.com.sg)  
**Subject:** RE: TCS REF:AAD1402-003-Accident involving SHB6394T & SHD9388G on 31/1/2014

Without Prejudice

Dear Daniel

Attached LOD for your perusal and action.

Hope you can review this case and let us have your best offer.

Thank You  
Best Regards,  
Calvin Er  
Finance Department  
TEL: 6603 1265 Ext.307

\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)



**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

**From:** Pooi Chin Han Daniel [<mailto:danielpooi@iii.com.sg>]  
**Sent:** Thursday, 29 November, 2018 8:51 AM  
**To:** 'claims' <[claims@transcab.com.sg](mailto:claims@transcab.com.sg)>; Sundari Nagarajan - III <[sundari@iii.com.sg](mailto:sundari@iii.com.sg)>  
**Cc:** 'Jasmine Tan' <[jasminetan@transcab.com.sg](mailto:jasminetan@transcab.com.sg)>  
**Subject:** RE: TCS REF:AAD1402-003-Accident involving SHB6394T & SHD9388G on 31/1/2014

**Without Prejudice save as to cost**

Dear Calvin,

We refer to the above accident and your email below, we regret to inform you that we do not seem to have any records for any TPD claims for this case.

Could you please send a copy over to enable us to do a review?

Thank you.

*Daniel Pooi*

**Motor Claims Department**  
**India International Insurance Pte Ltd**  
64 Cecil Street #04-02 IOB Building  
Singapore 049711  
Tel: 6347 6100 Ext 202 Fax: 6224 4174  
**S&P 'A-' (stable) rated Company**



From: claims [<mailto:claims@transcab.com.sg>]

Sent: Tuesday, 27 November, 2018 3:42 PM

To: Sundari Nagarajan - III <[sundari@iii.com.sg](mailto:sundari@iii.com.sg)>; Pooi Chin Han Daniel <[danielpooi@iii.com.sg](mailto:danielpooi@iii.com.sg)>

Cc: 'Jasmine Tan' <[jasminetan@transcab.com.sg](mailto:jasminetan@transcab.com.sg)>; [claims@transcab.com.sg](mailto:claims@transcab.com.sg)

Subject: FW: TCS REF:AAD1402-003-Accident involving SHB6394T & SHD9388G on 31/1/2014

Without Prejudice

Dear Sirs

Please refer to the preceding email.

May we have an update for the latest claim settlement for this case?

Thank You

Best Regards,

Calvin Er

Finance Department

TEL: 6603 1265 Ext.307

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Thursday, 18 October, 2018 2:17 PM

To: Pooi Chin Han Daniel <[danielpooi@iii.com.sg](mailto:danielpooi@iii.com.sg)>; Sundari Nagarajan - III <[sundari@iii.com.sg](mailto:sundari@iii.com.sg)>

Cc: claims <[claims@transcab.com.sg](mailto:claims@transcab.com.sg)>

Subject: FW: TCS REF:AAD1402-003-Accident involving SHB6394T & SHD9388G on 31/1/2014

Dear Officer,

Please assist.

Best Regards,

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: claims [<mailto:claims@transcab.com.sg>]

Sent: 18 October, 2018 11:26 AM

To: Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

Cc: [jasminetan@transcab.com.sg](mailto:jasminetan@transcab.com.sg); [claims@transcab.com.sg](mailto:claims@transcab.com.sg)

Subject: TCS REF:AAD1402-003-Accident involving SHB6394T & SHD9388G on 31/1/2014

Dear Sir/Mdm

We are making a claim against the owner of SHB6394T.

May we have an update on the latest claim settlement for this case?

Thank You  
Best Regards,  
Calvin Er  
Finance Department  
TEL: 6603 1265 Ext.307

\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)



**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/02/2014 09:08
Date Of Accident	31/01/2014 08:40
Exact Location Of Accident	JUNCTION OF ROAD 1 AND ROAD 2 LOWER DELTA ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9388G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K

### Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 DSL TURBO (A)
Exact Purpose for which vehicle was being used at time of accident	Hire and Reward
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Taxi

### Insurance Company

Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12047359MFSH/3949
Cover Note Number	

### Driver

Name of Driver	BAY AH HWEE
NRIC No	S1167980C
Date Of Birth	13/05/1955
Occupation	Outdoor
Date Of Driving Pass	06/09/1978
Driving Experience	35 Years And 4 Months
Gender	Male
Mobile Number	(Local) +65-82811535
Fax Number	
Contact Number	
EEmail Address	NOEMAIL
Address	BLK 699B HOUGANG STREET 52 #13-53
Postcode	532699



Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Other - Relief
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	Collision- Head to Rear (TP Hit Insured)
Weather Conditions	Clear
Road Surface	Dry

#### Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	Yes
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No

#### Details of Police Action

Was the accident reported to the police?	Yes
If Yes, Please state which Police Station	
Police Station Name	Hougang Neighbourhood Police Centre
Police Station Address	ROAD: 60 Hougang Ave 9 , POSTCODE: 538775 , COUNTRY: Singapore
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	No
If Yes, against whom?	

#### Circumstances of Accident

Please refer to Police Report - T/20140131/4027

Are accident photos available for attachment?	Yes
---	-----

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB6394T
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

#### DETAILS OF INJURED PERSON 1

Name	BAY AH HWEE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHD9388G
Were seat belts worn?	Yes
Was injured conveyed to hospital by ambulance?	No



Address

Postcode

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

PLS. REFER TO POLICE REPORT

Edge to the price report

I/We declare the foregoing particulars are true in every respect.

JASME  
Witnessed by Reporting Centre  
Personnel

Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999



T/20140131/4027

1 of 3

Report No. T/20140131/4027

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/01/2014 13:35		Vide Report No.:		Station Diary No.: 30	
<b>Informant's Particulars</b>					
Name of Informant: BAY AH HWEE			Address: APT BLK 699B HOUGANG STREET 52 #13-53 SINGAPORE 532699		
ID Type / ID No.: NRIC NO / S1167980C			Contact No.: Home/Office:		Mobile: 82811535
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 58	Date of Birth: 13/05/1955	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi Driver			Driving Licence Information: Class: 2B,2A,2,3,4,5		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 31/01/2014 08:40	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 LOWER DELTA RD TIONG BAHRU RD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved									
Vehicle No.	Type	Make	Color	Condition	No. of Passenger	Insurance Company	Insurance No.	Effective Date	Expiry Date
SHB6394 T	Taxi	MERCEDES BENZ	White	Seriously Damaged	0				
SHD9388 G	Taxi	CHEVROLET	Red	Seriously Damaged	0				

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Station Of Origin:  
 Hougang N.P.C  
 60 Hougang Avenue 9 SINGAPORE 538775  
 Tel No: 1800-4890999



T/20140131/4027

2 of 3

Report No. T/20140131/4027

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	ONG KAM CHUAN	ID No.	S2019620C
Related Vehicle	SHB6394T (Taxi)	Contact No.	97114311
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	BAY AH HWEE	ID No.	S1167980C
Related Vehicle	SHD9388G (Taxi)	Contact No.	82811535
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	31/01/2014	Date Discharge	31/01/2014
No. of Days granted Medical Leave (MC)	03	Degree of Injury	Slight

**Brief Details.**

On 31/01/2014 at around 0840 hrs, I was driving, SHD9388G, along Lower Delta Road the extreme left lane. I then stopped my vehicle at the junction of Tiong Bahru Road. When the light turns green, I wanted to accelerate but before I accelerate, the vehicle, SHB6394T, from behind had hit onto my rear portion.

I then seek medical attention at Mount Alvernia Hospital and was given 3 days of medical leave.

Police Station Of Origin:  
 Hougang N.P.C  
 60 Hougang Avenue 9 SINGAPORE 538775  
 Tel No: 1800-4890999



T/20140131/4027

3 of 3



Report No. T/20140131/4027

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

 Signature Of Officer Recording The Report: MOHD AZMI BIN MOHD RIDWAN Signature : _____	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 31/01/2014 13:35
Officer In Charge Of Case: TP / AEIT / SUBALI BIN YAN Contact No.: 65476219	Classification Of Case:
Authentication Stamp NP168	

Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



## TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346

TEL NO.6287 8868 FAX NO.6366 8862

CO/GST REG NO.201019628G

SHD 9388G - III

Jasmine

Not Authorized  
1/10/14 @ 7650/

Vehicle No.:	SHD 9388G - Jasmine
Chassis No.:	LK1LA69RJBB072258*
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident:	31.01.2014
Third Party Insurer:	III

PART		LIST	
1	1	Rear Bumper	\$ Br/Tn 1,202.00 ✓
2	1	Rear Bumper Beam	\$ Br 239.94 ✓
3	1	Rear Bumper Centre Absorber	\$ CMA 260.00 ✓
4	1	Rear Bumper Side Retainer RH	\$ CMA 68.76 ✓
5	1	Rear Bumper Side Retainer LH	\$ Sm 68.76 X
6	1	Rear Bumper Side Support RH	\$ Dis 25.00 ✓
7	1	Rear Bumper Side Support LH	\$ Sm 25.00 X
8	1	Rear Bumper Reflectors LH	\$ Sm 119.74 X
9	1	Rear Bumper Reflectors RH	\$ Br 119.74 ✓
10	1	Rear Bumper Tow Hook Cover	\$ M/V 93.00 ✓
11	1	Rear Luggage Floor Panel	\$ R 973.00 X
12	1	Rear Luggage Floor Panel Insulator	\$ Sm 63.50 X
13	1	Rear Luggage Floor Panel Trim Board	\$ Sm 378.00 X
14	1	Rear End Panel Inner	\$ Br 336.84 ✓
15	1	Rear End Panel Outer	\$ Br 623.76 ✓
16	1	Rear End Panel Inner Trim	\$ Dis 263.84 ✓
17	1	Bootlid	\$ Br 973.00 ✓
18	1	Bootlid Weatherstrip	\$ Dis/Br 344.28 ✓
19	1	Bootlid Lock - Top	\$ Dis 466.56 ✓
20	1	Bootlid Lock - Bottom	\$ R 39.40 X
21	1	Bootlid 'CHEVROLET' Badge	\$ Sm 120.62 ✓
22	1	Bootlid Logo	\$ Sm 138.84 ✓
23	1	Bootlid 'EPICA LT' Badge	\$ Sm 119.84 ✓
24	1	Bootlid Reflector Centre	\$ Sm 217.97 X
25	1	Bootlid Reflector RH	\$ CMA 128.40 ✓
26	1	Bootlid Reflector LH	\$ Sm 128.40 X
27	1	Rear Tail Lamp LH	\$ Sm 479.30 X
28	1	Rear Tail Lamp Panel LH	\$ R 359.00 X
29	1	Rear Tail Lamp Panel RH	\$ Sm 479.30 X
30	1	Rear Tail Lamp Panel RH	\$ R 359.00 X
31	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$ R 1,110.00 X
32	1	Rear Fender LH	\$ R 1,145.00 X
33	1	Rear Fender Inner Trim LH	\$ Sm 298.00 X

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 9318G - III****Jasmine**

34	1	Rear Fender Inner Cowling LH	\$	76.60 X
35	1	Rear Fender RH	\$	1,145.00 ✓
36	1	Rear Fender Inner Trim RH	\$	298.00 ✓
37	1	Rear Fender Inner Cowling RH	\$	76.60 X
			<b>\$</b>	<b>13,363.99</b>
10%			<b>\$</b>	<b>1,336.40</b>
<b>Total</b>			<b>\$</b>	<b>12,027.59</b>

**Special Nett**

1 Set	Rear Bumper Parking Sensor	\$	300.00 ✓
1 Set	Rear Bumper Fastener Clip	\$	30.00 ✓
1 Set	Rear Boot Inner Trim Clip	\$	60.00 ✓
1	Rear Boot Sticker 'Trans-cab'	\$	30.00 ✓
1	Rear Boot Sticker '6555-3333'	\$	30.00 ✓
2 Set	Rear Fender Inner Trim Clip	\$	60.00 ✓
2	Rear Windscreen Sealant	\$	100.00 400ml ✓
1	Rear Windscreen Inner Sponge Seal	\$	100.00 ✓
1	Rear windscreen Inner Top garnish	\$	80.00 X
1 Set	Rear End Panel Cover Clip	\$	30.00 X
2 Set	Rear Fender Inner Cowling Clip	\$	60.00 X

**TOTAL \$ 880.00****TOTAL PARTS \$ 12,907.59**

Panel Beating, Knocking And Straightening The  
Necessary Portion, Remove And Renewal Of  
Parts, Adjust And Realign The Same

\$ 4,200.00 1100g

To Rust-Proofing Of The Affected Areas.

\$ 220.00 90g

To Check Electrical Lighting Concerned.

\$ 170.00 20g

Putty And Spray Painting Of The Affected  
Portion.

\$ 4,050.00 1000g

To Reinstall Rear Bumper Parking Sensor.

\$ 170.00 60g

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346

TEL NO.8287 6868 FAX NO.8368 8862

CO/GST REG NO.201019628G

SHD 9318G - III

Jasmine

To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, To Enable Repair.	\$	280.00 100%
Towing Fees.	\$	120.00 50%
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 60%
To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 60%
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	Ryota 170.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 120%
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00 X
To Repair And Realign Rear Exhaust Pipe.	\$	Ryota 170.00 X

<b>TOTAL</b>	<b>\$</b>	<b>11,040.00</b>
--------------	-----------	------------------

<b>Over All Total</b>	<b>\$</b>	<b>23,947.59</b>
-----------------------	-----------	------------------

**REPAIR DAYS**7 day,  
15 DAYS



**TRANS-CAB AUTO SERVICES PTE LTD**

NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 9388G - III****Jasmine**

*Not Authorized*  
*1/1/2014 8:45 AM*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHD 9388G - Jasmine****LK1LA69RJBB072258\*****CHEVROLET****EPICA 2.0****31.01.2014****III****PART****LIST**

1	1	Rear Bumper	\$	<i>Br/Tn</i> 1,202.00 ✓
2	1	Rear Bumper Beam	\$	<i>Br</i> 239.94 —
3	1	Rear Bumper Centre Absorber	\$	<i>CMA</i> 260.00 ✓
4	1	Rear Bumper Side Retainer RH	\$	<i>CMA</i> 68.76 ✓
5	1	Rear Bumper Side Retainer LH	\$	<i>Sm</i> 68.76 X
6	1	Rear Bumper Side Support RH	\$	<i>Dis</i> 25.00 —
7	1	Rear Bumper Side Support LH	\$	<i>Sm</i> 25.00 X
8	1	Rear Bumper Reflectors LH	\$	<i>Sm</i> 119.74 X
9	1	Rear Bumper Reflectors RH	\$	<i>Br</i> 119.74 ✓
10	1	Rear Bumper Tow Hook Cover	\$	<i>Br</i> 93.00 ✓
11	1	Rear Luggage Floor Panel	\$	<i>R</i> 973.00 X
12	1	Rear Luggage Floor Panel Insulator	\$	<i>nn</i> 63.50 X
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sm</i> 378.00 X
14	1	Rear End Panel Inner	\$	<i>Br</i> 336.84 —
15	1	Rear End Panel Outer	\$	<i>Br</i> 623.76 —
16	1	Rear End Panel Inner Trim	\$	<i>Dis</i> 263.84 —
17	1	Bootlid	\$	<i>Br</i> 973.00 ✓
18	1	Bootlid Weatherstrip	\$	<i>Dis/Br</i> 344.28 ✓
19	1	Bootlid Lock - Top	\$	<i>Dis</i> 466.56 —
20	1	Bootlid Lock - Bottom	\$	<i>R</i> 39.40 X
21	1	Bootlid 'CHEVROLET' Badge	\$	<i>Br</i> 120.62 —
22	1	Bootlid Logo	\$	<i>nn</i> 138.84 —
23	1	Bootlid 'EPICA LT' Badge	\$	<i>Br</i> 119.84 —
24	1	Bootlid Reflector Centre	\$	<i>Sm</i> 217.97 X
25	1	Bootlid Reflector RH	\$	<i>CMA</i> 128.40 —
26	1	Bootlid Reflector LH	\$	<i>Sm</i> 128.40 X
27	1	Rear Tail Lamp LH	\$	<i>Sm</i> 479.30 X
28	1	Rear Tail Lamp Panel LH	\$	<i>R</i> 359.00 X
29	1	Rear Tail Lamp RH	\$	<i>Sm</i> 479.30 X
30	1	Rear Tail Lamp Panel RH	\$	<i>R</i> 359.00 X
31	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00 X
32	1	Rear Fender LH	\$	<i>R</i> 1,145.00 X
33	1	Rear Fender Inner Trim LH	\$	<i>Sm</i> 298.00 X

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 9388G - III****Jasmine**

34	1	Rear Fender Inner Cowling LH	\$	76.60 X
35	1	Rear Fender RH	\$	1,145.00 ✓
36	1	Rear Fender Inner Trim RH	\$	298.00 ✓
37	1	Rear Fender Inner Cowling RH	\$	76.60 X
			<b>\$</b>	<b>13,363.99</b>
<b>10%</b>			<b>\$</b>	<b>1,336.40</b>
<b>Total</b>			<b>\$</b>	<b>12,027.59</b>

**Specical Nett**

1 Set	Rear Bumper Parking Sensor	\$	300.00 ✓
1 Set	Rear Bumper Fastener Clip	\$	30.00 ✓
1 Set	Rear Boot Inner Trim Clip	\$	60.00 ✓
1	Rear Boot Sticker 'Trans-cab'	\$	30.00 ✓
1	Rear Boot Sticker '6555-3333'	\$	30.00 ✓
2 Set	Rear Fender Inner Trim Clip	\$	60.00 ✓
2	Rear Windscreen Sealant	\$	100.00 400.00
1	Rear Windscreen Inner Sponge Seal	\$	100.00 ✓
1	Rear windscreen Inner Top garnish	\$	80.00 X
1 Set	Rear End Panel Cover Clip	\$	30.00 X
2 Set	Rear Fender Inner Cowling Clip	\$	60.00 X

**TOTAL \$ 880.00****TOTAL PARTS \$ 12,907.59**

Panel Beating, Knocking And Straightening The  
Necessary Portion, Remove And Renewal Of  
Parts, Adjust And Realign The Same

\$ 4,200.00 1100

To Rust-Proofing Of The Affected Areas.

\$ 220.00 900

To Check Electrical Lighting Concerned.

\$ 170.00 200

Putty And Spray Painting Of The Affected  
Portion.

\$ 4,050.00 1000

To Reinstall Rear Bumper Parking Sensor.

\$ 170.00 600

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 9388G - III****Jasmine**

To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, To Enable Repair.	\$	280.00 100/
Towing Fees.	\$	120.00 50/
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 60/
To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 60/
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	Repair 170.00 X
To Remove And Refit Rear W/ Screen Glass To Facilitate Bodywork Repair.	\$	170.00 120/
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00 X
To Repair And Realign Rear Exhaust Pipe.	\$	Repair 170.00 X

**TOTAL \$ 11,040.00****Over All Total \$ 23,947.59****REPAIR DAYS***7 day,*  
**15 DAYS**

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TRANS-CAB AUTO SERVICES PTE LTD

Ref : CS/TP19000943/Kvd3e2

NO.2 ANG MO KIO STREET 63SINGAPORE 569111

Date : 18-01-2019



Code : TP378

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	Veh. Inspected	SHD 9388G
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	03/02/2014

**2. Vehicle Particulars & Condition**

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KL1LA69RJBB072258	Colour	WHITE / RED
Odometer	332445	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	8 mm
L/H Front Tyre	195/65 R15	FALKEN	8 mm
R/H Rear Tyre	195/65 R15	FALKEN	8 mm
L/H Rear Tyre	195/65 R15	FALKEN	8 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	31/01/2014	Inspection Date	03/02/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>7 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9388G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	BENT / TORN	1,202.00	1,202.00
1	REAR BUMPER BEAM	BENT	239.94	239.94
1	REAR BUMPER CENTRE ABSORBER	CRACKED	260.00	260.00
1	REAR BUMPER SIDE RETAINER RH	CRACKED	68.76	68.76
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	68.76	-
1	REAR BUMPER SIDE SUPPORT RH	DISTORTED	25.00	25.00
1	REAR BUMPER SIDE SUPPORT LH	SERVICEABLE	25.00	-
1	REAR BUMPER REFLECTORS LH	SERVICEABLE	119.74	-
1	REAR BUMPER REFLECTORS RH	BROKEN	119.74	119.74
1	REAR BUMPER TOW HOOK COVER	MISSING	93.00	93.00
1	REAR LUGGAGE FLOOR PANEL	TO REPAIR SEE LABOUR	973.00	-
1	REAR LUGGAGE FLOOR PANEL INSULATOR	NOT NECESSARY	63.50	-
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	378.00	-
1	REAR END PANEL INNER	BENT	336.84	336.84
1	REAR END PANEL OUTER	BENT	623.76	623.76
1	REAR END PANEL INNER TRIM	DISTORTED	263.84	263.84
1	BOOTLID	BUCKLED	973.00	973.00
1	BOOTLID WEATHERSTRIP	DISTORTED / CUT	344.28	344.28
1	BOOTLID LOCK - TOP	DENTED	466.56	466.56
1	BOOTLID LOCK - BOTTOM	TO REPAIR SEE LABOUR	39.40	-
1	BOOTLID 'CHEVROLET' BADGE	NECESSARY	120.62	120.62
1	BOOTLID LOGO	NECESSARY	138.84	138.84
1	BOOTLID 'EPICA LT' BADGE	NECESSARY	119.84	119.84
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR RH	CRACKED	128.40	128.40
1	BOOTLID REFLECTOR LH	SERVICEABLE	128.40	-
1	REAR TAIL LAMP LH	SERVICEABLE	479.30	-
1	REAR TAIL LAMP PANEL LH	TO REPAIR SEE LABOUR	359.00	-
1	REAR TAIL LAMP RH	SERVICEABLE	479.30	-
1	REAR TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	359.00	-
1	REAR EXHAUST BOX (MUFFLER A-EXH, RR)	TO REPAIR SEE LABOUR	1,110.00	-

Report Ref No. CS/TP19000943/Kvd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM LH	SERVICEABLE	298.00	-
1	REAR FENDER INNER COWLING LH	SERVICEABLE	76.60	-
1	REAR FENDER RH	BUCKLED	1,145.00	1,145.00
1	REAR FENDER INNER TRIM RH	CRACKED	298.00	298.00
1	REAR FENDER INNER COWLING RH	SERVICEABLE	76.60	-
	LESS 10% DISCOUNT		-1,336.40	-696.74
			12,027.59	6,270.68
	<b>SPECIAL NETT ITEMS</b>			
1	SET REAR BUMPER PARKING SENSOR (SN)	DENTED	300.00	300.00
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	30.00	30.00
1	SET REAR BOOT INNER TRIM CLIP (SN)	NECESSARY	60.00	60.00
1	REAR BOOT STICKER 'TRANS-CAB' (SN)	NECESSARY	30.00	30.00
1	REAR BOOT STICKER '6555-3333' (SN)	NECESSARY	30.00	30.00
2	SET REAR FENDER INNER TRIM CLIP (SN)	NECESSARY	60.00	60.00
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER TOP GARNISH (SN)	SERVICEABLE	80.00	-
1	SET REAR END PANEL COVER CLIP (SN)	NOT NECESSARY	30.00	-
2	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	60.00	-
			880.00	650.00
	<b>LABOUR</b>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR LUGGAGE FLOOR PANEL, BOOTLID LOCK - BOTTOM, REAR TAIL LAMP PANEL LH, REAR TAIL LAMP PANEL RH, REAR EXHAUST BOX (MUFFLER A-EXH, RR) AND REAR FENDER LH.		4,200.00	1,100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	90.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,050.00	1,000.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		280.00	100.00
	TOWING FEES.		120.00	50.00

Report Ref No. CS/TP19000943/Kvd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	REPEATED	170.00	-
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO SUPPLY AND RE-FO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	REPEATED	170.00	-
			11,040.00	2,660.00
<b>GRAND TOTAL</b>			<b>23,947.59</b>	<b>9,580.68</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,650.00</b>

Report Ref No. CS/TP19000943/Kvd3e2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.