

REF:

NTUC NS/INC19000944/Egd3e2

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured

Policy No:

Claims No:

Sum Insured

Excess:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	Q/S

Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs:

7

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 6202D

Vt Regn:

4/11/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C.

1798

Colour:

maroon

A/C

Insured / Std / NI / NA

Sp Reading

TRatio:

Insured / Std / NI / NA

Eng.No:

CNo

JTDKN36U105766537

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Order / Jammed / Leaked / Burnt orBrake: ☒ Order / Jammed / Leaked / Burnt orModi: Nil / ☒ R / STD A/Rim or

Tyre Size

F: 195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A

12/1/19

D.O.I

15/1/19

Survey held at

Sund

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: Action / Instruction

SHD 6202D - NS / INC17011586 / K1422

DA 13062017

01/19/2019

SLK 6202U

x 4650

19/7/19

Fapt about

4650

47 d.w

(Fed \$17145.39, 79%)

SLK 6202U

RECEIVED 22 JUL 2019

Date/Time: File Pass to:

☐

Prel. Report

11/12/19

☐

Final Report

Date/Time: File Return to:

21

Days Of Repair:

7

Resurvey No. of Trip:

2

Survey Fee

Transportation

1.00 + 0.00 = 1.00

1.00

1.00

1.00

1.00

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Insp (\$)

☐

Workshop (\$)

Report Format:

7P

Lump Sum / I.B.T. (\$)

4650

160

160

TP Claims against NTUC Income: Follow-Through Survey

Date : 19/07/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1027613-003	SMRT TAXIS PTE LTD	SHD 6202D	SLK 6202U	12/01/2019	20:50	\$ 21,795.34
2	MT/1029866-003	SMRT TAXIS PTE LTD	SHF 92H	SLC 5120X	27/01/2019	12:30	\$ 12,647.64
3	MT/1035233-002	SMRT TAXIS PTE LTD	SHB 246C	SMC 8115E	09/03/2019	0:50	\$ 8,608.74

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5099361202		DIABLO OON WEI JIE	S9037836H	GPC	drive CLASSIC	SLK6202U	SLK6202U	27/03/2018	26/03/2019

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 19 July 2019 12:07 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); SUR; CS A Team
Subject: RE: SHD6202D

Dear Poh Suan,

WITHOUT PREJUDICE

Confirm Lump Sum \$4,650.00 before GST and 7 repair days.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Monday, 15 July 2019 5:27 PM
To: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHD6202D

Hi All,

Attached herewith the repair estimate of SHD 6202D having Case No: TAX/01/19/2059.

There is no change to the approved amount of \$4,650 @ 7 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Sent: Monday, 15 July 2019 5:26 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2019 10:59
Date Of Accident	12/01/2019 20:50
Exact Location Of Accident	ALJUNIED ROAD JUNCTION MERPATI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6202D
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	NG CHENG KIAT
NRIC No	S1705922Z
Date Of Birth	26/01/1965
Occupation	OUTDOOR
Date Of Driving Pass	25/11/1996
Driving Experience	22 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	212
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES N.P.C
Police Station Address	ROAD: TAMPINES N.P.C , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190113/2038 On 12/01/2019 at about 8:50pm, I was driving along Aljunied Road towards the direction of Lorong 22 Geylang on the most left lane with no passenger on board. It is two lane road. Suddenly as I was driving straight on the most left lane at about 30km/hr, a car (SLK6202U) had collided onto the right middle side of my taxi. I had alighted my taxi and exchanged particulars with the other party driver. No ambulance or Traffic police attended to us as no one was injured. There is front-in-car camera in my taxi but I am not sure if it is working during the time of accident. I had inform my taxi company about the matter already. Both the right door and right passenger door could not be open after the accident. After the accident had occurred, the driver had shifted his car slightly forward. On 13/01/2019 I felt pain on my body after the accident as such I had went to seek medical consultation and was given 3 days medical certificate.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK6202U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	DIABLO OON WEIJIE
NRIC/Passport Number	S9037836H
Contact Number	

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	NG CHENG KIAT
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHD6202D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT - 7/20190113/238

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190113/2038

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

1 of 3
Report No. T/20190113/2038

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/01/2019 12:13		Vide Report No.:		Station Diary No.: 39
Informant's Particulars				
Name of Informant: NG CHENG KIAT		Address: APT BLK 212 TAMPINES STREET 23 #02-137 SINGAPORE 520212		
ID Type / ID No.: NRIC NO / S1705922Z		Contact No.: Home/Office: Mobile: 98711331		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 53	Date of Birth: 26/01/1965	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 12/01/2019 20:50	Type of Location: T-Junction
Location: Along Road 1 Traveling Toward Road 2 ALJUNIED ROAD LORONG 22 GEYLANG T-Junction of Merpati Road				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHD6202D	TAXI	TOYOTA	HYBRID	Maroon		0
SLK6202U	Car	HYUNDAI	HYBRID	White		0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190113/2038

Police Station Of Origin:

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

2 of 3

Report No. T/20190113/2038

CONTINUATION OF REPORT

Driver:			
Name	NG CHENG KIAT		ID No. S1705922Z
Related Vehicle	SHD6202D (TAXI)		Contact No. 98711331
Hospital/Clinic	UNIVERSAL MEDICAL CLINIC		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	13/01/2019	Date Discharge	13/01/2019
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver:			
Name	DIABLO OON WEIJIE		ID No. S9037836H
Related Vehicle	SLK6202U (Car)		Contact No. 87761512
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 12/01/2019, at about 8:50pm, I was driving along Aljunied Road towards the direction of Lorong 22 Gelyang on the most left lane with no passenger on board. It is a two lane road.

Suddenly as I was driving straight on the most left lane at about 30km/hr, a car (SLK6202U) had collided onto the right middle side of my Taxi. I had alighted my Taxi and exchanged particulars with the other party driver. No ambulance or Traffic police attended to us as no one was injured. There is front in-car camera in my Taxi but I am not sure if it is working during the time of accident. I had inform my Taxi company about the matter already. Both the right driver door and right passenger door could not be open after the accident. After the accident had occurred, the driver had shifted his car slightly forward.

On 13/01/2019, I felt pain on my body after the accident as such I had went to seek medical consultation and was given 3 days medical certificate.



**SINGAPORE
POLICE FORCE**



T/20190113/2038

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529662
Tel No: 1800-5871999

3 of 3

Report No. T/20190113/2038

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
G /
Staff Sgt CHAN DE MING

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
13/01/2019 12:13

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Classification Of Case:

Authentication Stamp
NP168





Case Details

Case Reference Number :

TAX/01/19/2059

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6202D

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-5350-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 12/01/2019 12:50 PM

Vehicle Age(In Months) : 38

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	670.80	Replace	* BUC
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	* NEL
One Time Key In	Main			DOOR LOCK FRT/RH	1	575.80	575.80	25.00	431.85	Replace	0	0	Check	* X NN
One Time Key In	Main			DOOR WEATHER STRIP FRT/RH	1	171.20	171.20	25.00	128.40	Replace	0	0	Check	* X NN
One Time Key In	Main			WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	1	277.80	277.80	25.00	208.35	Replace	0	0	Check	* X NN
One Time Key In	Main			DOOR HINGE LOWER FRT/RH	1	80.50	80.50	25.00	60.38	Replace	0	0	Check	* X NN
One Time Key In	Main			DOOR HINGE UPPER FRT/RH	1	80.50	80.50	25.00	60.38	Replace	0	0	Check	* X NN
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Check	* X NN
One Time Key In	Main			DOOR LOCK STRIKER	1	40.50	40.50	25.00	30.38	Replace	0	0	Check	* X NN

Total Spare Part Cost 11,428.60

Surveyor Total 2,099.70

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 9,142.88

Final Sur Total 1,579.75

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			DOOR RH FRT TRIM BOARD	1	649.70	649.70	25.00	487.28	Replace	0	0	Check • X N/A
One Time Key In	Main			DOOR REGULATOR MOTOR FRONT RH	1	947.80	947.80	10.00	853.02	Replace	0	0	Check • X N/A
One Time Key In	Main			DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1	224.80	224.80	25.00	168.60	Replace	0	0	Check • X N/A
One Time Key In	Main			WIRE RHF, DOOR	1	436.40	436.40	10.00	392.76	Replace	0	0	Check • X N/A
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	1	505.20	Replace • BUC
One Time Key In	Main			SILL MEMBER OUTER RH	1	519.80	519.80	25.00	389.85	Replace	0	0	Check • X N/A
One Time Key In	Main			PILLAR, CTR BODY	1	307.70	307.70	25.00	230.77	Replace	0	0	Check • X N/A
One Time Key In	Main			REINFORCEMENT, CTR PILLAR	1	530.50	530.50	25.00	397.88	Replace	0	0	Check • X N/A
One Time Key In	Main			DOOR RRRH	1	954.50	954.50	25.00	715.88	Replace	1	715.88	Replace • BUC
One Time Key In	Main			HINGE UPPER RHR, DOOR	1	81.70	81.70	25.00	61.28	Replace	0	0	Check • X N/A
One Time Key In	Main			HINGE LOWER RHR, DOOR	1	52.00	52.00	25.00	39.00	Replace	0	0	Check • X N/A
One Time Key In	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Check • X N/A
One Time Key In	Main			DOOR LOCK RR/RH	1	709.30	709.30	25.00	531.97	Replace	0	0	Check • X N/A
One Time Key In	Main			DOOR OUTER HANDLE RRRH	1	69.80	69.80	25.00	52.35	Replace	0	0	Not Give • X N/A
One Time Key In	Main			DOOR INNER HANDLE REAR/RH	1	138.90	138.90	25.00	104.18	Replace	0	0	Check • X N/A

Total Spare Part Cost 11,428.60

Surveyor Total 2,999.70

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 9,142.88

Final Sur Total 1,679.76

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			DOOR LOCK STRIKER	1	40.50	40.50	25.00	30.38	Replace	0	0	Check • X AM
One Time Key In	Main			DOOR REAR RH TRIM BOARD	1	590.10	590.10	25.00	442.58	Replace	0	0	Check • X AM
One Time Key In	Main			DOOR WEATHER STRIP RR/RH	1	171.20	171.20	25.00	128.40	Replace	0	0	Check • X AM
One Time Key In	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Check • X AM
One Time Key In	Main			DOOR REGULATOR MOTOR REAR RH	1	947.80	947.80	10.00	853.02	Replace	0	0	Check • X AM
One Time Key In	Main			DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1	224.80	224.80	25.00	168.60	Replace	0	0	Check • X AM
One Time Key In	Main			WIRE RHR, DOOR	1	280.20	280.20	10.00	252.18	Replace	0	0	Check • X AM
One Time Key In	Main			TAPE OUT WIN FRAME RHF, DOOR	1	45.60	45.60	25.00	34.20	Replace	1	34.20	Replace • NEC
One Time Key In	Main			TAPE OUT WIN FRAME RHR, DOOR	1	32.30	32.30	25.00	24.22	Replace	1	24.22	Replace • NEC
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace • NEC
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair • X R
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace • NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace • NEC
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give • X AM
One Time Key In	Main			WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Not Give • X AM

Total Spare Part Cost 11,428.60

Surveyor Total 2,099.70

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 9,142.88

Final Sur Total 1,679.76

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	0	0	Not Give <i>X/10/1</i>
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give <i>X/10/1</i>
Total Spare Part Cost									11,428.60		Surveyor Total	2,099.70	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									9,142.88		Final Sur Total	1,679.75	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH PORTION	1,183.00	700 <i>/</i>	
Total:		1,183.00	700.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY FRONT DOOR RH	378.00	200 <i>/</i>	
2	TO RESPRAY ROCKER PANEL MOULDING	180.00	100 <i>/</i>	
3	TO RESPRAY SILL MEMBER RH	180.00	0	
4	TO RESPRAY RH REAR DOOR	378.00	200 <i>/</i>	
5	TO RESPRAY CENTRE PILLAR RH	180.00	0	
6	TO RESPRAY REAR FENDER RH	378.00	200 <i>/</i>	
7	TO RESPRAY RIM	180.00	0	
Total:		1,854.00	700.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	55.00	0	
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40 <i>/</i>	
Total:		1,441.00	385.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40 ✓	
4	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	TO TRANSFER DOOR MECHANISM	240.00	100 ✓	
6	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00 ✓	
7	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0	
8	TO REMOVE AND REFIT WIRE HARDESS	200.00	80 ✓	
9	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
10	TO REMOVE / REFIT SEAT	120.00	0	
11	TO REPLACE SUNDRY PARTS	100.00	0	
12	TO WASH AND VACUUM	60.00	0	
Total:		1,441.00	385.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	9,142.88	1,579.75
Total Labour Cost	1,183.00	700.00
Total Spray Painting	1,854.00	700.00
Other	1,441.00	385.00
Overall Total	13,620.88	3,464.75
Lump Sum Repair Option	✓	✓
Lump Sum Total	13,600.00	3,450.00
Surveyor Approved Amount		3,450.00
No of Repair Days*	9	4
Remarks	-	L/S repair, photo after paint.
Surveyor Name		Haase ja

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature


16/1/19

Save

Clear

Survey Date

15/01/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHD6202D
Case Reference Number	TAX/01/19/2059
Registration Date	4/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	NG CHENG KIAT
Type of Accident	Head To Side
Accident Date and Time	12/1/2019 8:50 PM
Accident Reported Date and Time	14/1/2019 11:02 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	12/1/2019 9:30 PM
Replacement Vehicle issued?	No
Job Card Number	24099685
Special Instruction to ARC, if any	TOWED \$40
Prepared Date and Time	15/1/2019 8:45 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,533.00	\$900.00
Total Spray Cost	\$2,034.00	\$800.00
Total Spare Part Cost	\$13,060.67	\$3,731.80
Total Other Cost	\$1,441.00	(\$751.60)
TOTAL COST	\$18,068.67	\$4,650.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	13.0	7.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	15/01/2019 5:01 PM	15/01/2019 3:24 PM
Signature		
Remarks	Initial estimate = 9 days Request number of days to extend 4 days	L/S repair, photo after paint.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0232	Invoice Number	
Quotation Date	15.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE AND REPLACE ABOVE ITEM & REPAIR CENTRE BODY RH PORTION	\$350.00	\$200.00 / (590)
TO REPAIR RH PORTION	\$1,183.00	\$700.00 /
Total Labour	\$1,533.00	\$900.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY CENTER PILLAR RH	\$180.00	\$100.00 / (590)
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00 /
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00 /
TO RESPRAY SILL MEMBER RH	\$180.00	\$0.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00 /
TO RESPRAY CENTRE PILLAR RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00 /
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,634.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$1,166.80)
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$40.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$100.00 /
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$125.00 /
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$80.00 /
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,441.00	(\$781.80)



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 95 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63655592
 Estimator Telephone Number : 64662233
 Accident Reporting Number : 69632672

Date Generated : 19/07/2019

User ID : P0000000

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace ✓
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace ✓
		69030-47070	DOOR LOCK FRT/RH	0.00	\$575.80	0.00	\$0.00	Replace	Check X
		67861-47030	DOOR WEATHER STRIP FRT/RH	0.00	\$171.20	0.00	\$0.00	Replace	Check X
		62311-47030	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	0.00	\$277.80	0.00	\$0.00	Replace	Check X
		68720-12151	DOOR HINGE LOWER FRT/RH	0.00	\$80.50	0.00	\$0.00	Replace	Check X
		68710-12151	DOOR HINGE UPPER FRT/RH	0.00	\$80.50	0.00	\$0.00	Replace	Check X
		68610-47021	CHECK ASSY, FR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Check X
		69410-33010	DOOR LOCK STRIKER	0.00	\$40.50	0.00	\$0.00	Replace	Check X
		67610-47211	DOOR RH FRT TRIM BOARD	0.00	\$649.70	0.00	\$0.00	Replace	Check X
		85710-47120F	DOOR REGULATOR MOTOR FRONT RH	0.00	\$947.80	0.00	\$0.00	Replace	Check X
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check X
		82151-47440	WIRE RHF, DOOR	0.00	\$436.40	0.00	\$0.00	Replace	Check X
		75851-47900	MOULDING BODY, RH	1.00	\$673.60	25.00	\$505.20	Replace	Replace ✓
		61403-47030	SILL MEMBER OUTER RH	0.00	\$519.80	0.00	\$0.00	Replace	Check X
		61311-47030	PILLAR, CTR BODY	0.00	\$307.70	0.00	\$0.00	Replace	Check X
		61037-47060	REINFORCEMENT, CTR PILLAR	0.00	\$530.50	0.00	\$0.00	Replace	Check X
		67003-47080	DOOR RR/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace ✓
		68750-20121	HINGE UPPER RHR, DOOR	0.00	\$81.70	0.00	\$0.00	Replace	Check X
		68770-52031	HINGE LOWER RHR, DOOR	0.00	\$52.00	0.00	\$0.00	Replace	Check X
		68630-47031	CHECK ASSY, RR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Check X
		69050-47080	DOOR LOCK RR/RH	0.00	\$709.30	0.00	\$0.00	Replace	Check X
		69211-74020	DOOR OUTER HANDLE RR/RH	0.00	\$69.80	0.00	\$0.00	Replace	Not Given X
		69203-47020	DOOR INNER HANDLE REAR/RH	0.00	\$138.90	0.00	\$0.00	Replace	Check X
		69410-33010	DOOR LOCK STRIKER	0.00	\$40.50	0.00	\$0.00	Replace	Check X
		67630-47260	DOOR REAR RH TRIM BOARD	0.00	\$590.10	0.00	\$0.00	Replace	Check X
		67871-47030	DOOR WEATHER STRIP RR/RH	0.00	\$171.20	0.00	\$0.00	Replace	Check X
		68630-47031	CHECK ASSY, RR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Check X
		85710-47120	DOOR REGULATOR MOTOR REAR RH	0.00	\$947.80	0.00	\$0.00	Replace	Check X
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check X
		82153-47300	WIRE RHR, DOOR	0.00	\$280.20	0.00	\$0.00	Replace	Check X
		75921-47020	TAPE OUT WIN FRAME RHF, DOOR	1.00	\$45.60	25.00	\$34.20	Replace	Replace ✓
		75923-47020	TAPE OUT WIN FRAME RHR, DOOR	1.00	\$32.30	25.00	\$24.23	Replace	Replace ✓
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace ✓
		61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair R
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace ✓
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
		42811-47140	WHEEL DISC	0.00	\$1,454.20	0.00	\$0.00	Replace	Not Given X

	62710-47130	QUARTER GLASS RR/RH	0.00	\$846.50	0.00	\$0.00	Replace	Not Given X
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
Total				\$14,611.24		\$2,099.71		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1.00	\$224.80	25.00	\$168.60	Replace	Replace ✓
		69050-47080	DOOR LOCK RR/RH	1.00	\$709.30	25.00	\$531.98	Replace	Replace ✓
		68770-52031	HINGE LOWER RHR, DOOR	1.00	\$52.00	25.00	\$39.00	Replace	Replace ✓
		68750-20121	HINGE UPPER RHR, DOOR	1.00	\$81.70	25.00	\$61.28	Replace	Replace ✓
		61311-47030	PILLAR, CTR BODY	1.00	\$307.70	25.00	\$230.78	Replace	Replace ✓
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1.00	\$224.80	25.00	\$168.60	Replace	Replace ✓
		69030-47070	DOOR LOCK FRT/RH	1.00	\$575.80	25.00	\$431.85	Replace	Replace ✓
Total					2,176.10		1,632.09		

(Sum)
 62
 026
 67
 58
 088
 07
 070

3731.80
 + 900.00
 + 1185.00

5816.80

- 20%

4653.44

415 \$4650/-

2795.34

Contractor	WEGA ENGINEERING PTE LTD		
Accident Case Number	74X / 01 / 19 / 2059	Date of Collection	16 / 1 / 19
Vehicle No	SHD 6202 D	Date of Request	18 / 1 / 19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	3 DAYS

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price	(Supp)
1	6326, 27, 28	Door Lock Rnt Aft		\$ 575.80 Dis	✓ 431.85
2	6331, 32	Door Regulator Motor Rnt Aft		\$ 947.80 SVC	✗
3	6329, 30	Door Regulator Sub Assy Rnt Aft		\$ 224.80 BT	✓ 168.60
4	6310, 15, 16, 17, 18	Pillar Centre Body		\$ 307.70 DEF	✓ 239.78
5	6333, 34	Hinge Upper Rear Door		\$ 81.70 BT	✓ 61.78
6	6335, 36, 37	Hinge Lower Rear Door		\$ 52.00 BT	✓ 39.00
7	6323, 24, 25	Door Lock Rear Aft		\$ 709.30 Dis	✓ 531.98
8	6321, 22	Door Regulator Motor Rear Aft		\$ 947.80 SVC	✗

<<<Please submit photographs for damaged parts>>>

I. (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

Contractor	WEGA ENGINEERING PTE LTD		
Accident Case Number	TRX / 01 / 19 / 2059	Date of Collection	16/1/19
Vehicle No	SHD 6202 D	Date of Request	18/1/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	6319, 20			
2		Door Regulator RL Assy Rear RH		\$22480 BT
3		To Repay Centre Pillar RH		\$18000 \$100
4		To Request Labour To Replace &		
5		Repair Centre Pillar And.		
6		working Day.		\$35000 \$200
7				
8				

(SMP)

168.64

(SMP)

(SMP)

I (Name) CHIA

<<<Please submit photographs for damaged parts>>>

21/1/19

(Position) ADVISOR

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19000944/Eqd3e2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189558		Date: 24-07-2019	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLK 6202U	Veh. Inspected	SHD 6202D
Policy No.	5099361202	Coverage (\$)	0.00
Claim No.	MT/1027613-003	Excess (\$)	0.00
Assign From		Assign Date	15/01/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTDKN36U105766537	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/01/2019	Inspection Date	15/01/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52963356E GST Reg. No. 20-0405911-H



Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6202D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DOOR FRT/RH (DISC 25%)	BUCKLED	894.40	670.80
1	MOULDING BODY, RH (DISC 25%)	BUCKLED	673.60	505.20
1	DOOR RR/RH (DISC 25%)	BUCKLED	954.50	715.88
1	TAPE OUT WIN FRAME RHF, DOOR (DISC 25%)	NECESSARY	45.60	34.20
1	TAPE OUT WIN FRAME RHR, DOOR (DISC 25%)	NECESSARY	32.30	24.23
1	DOOR REGULATOR SUB-ASSY, FRT/REAR RH (DISC 25%)	BENT	224.80	168.60
1	DOOR LOCK RR/RH (DISC 25%)	DISTORTED	709.30	531.98
1	HINGE LOWER RHR, DOOR (DISC 25%)	BENT	52.00	39.00
1	HINGE UPPER RHR, DOOR (DISC 25%)	BENT	81.70	61.28
1	PILLAR, CTR BODY (DISC 25%)	DEFORMED	307.70	230.78
1	DOOR REGULATOR SUB-ASSY, FRT/REAR RH (DISC 25%)	BENT	224.80	168.60
1	DOOR LOCK FRT/RH (DISC 25%)	DISTORTED	575.80	431.85
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	DOOR LOCK FRT/RH	NOT NECESSARY	575.80	-
1	DOOR WEATHER STRIP FRT/RH	NOT NECESSARY	171.20	-
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	NOT NECESSARY	277.80	-
1	DOOR HINGE LOWER FRT/RH	NOT NECESSARY	80.50	-
1	DOOR HINGE UPPER FRT/RH	NOT NECESSARY	80.50	-
1	CHECK ASSY, FR DOOR	NOT NECESSARY	150.30	-
1	DOOR LOCK STRIKER	NOT NECESSARY	40.50	-
1	DOOR RH FRT TRIM BOARD	NOT NECESSARY	649.70	-
1	DOOR REGULATOR MOTOR FRONT RH	NOT NECESSARY	947.80	-
1	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	NOT NECESSARY	224.80	-
1	WIRE RHF, DOOR	NOT NECESSARY	436.40	-
1	SILL MEMBER OUTER RH	NOT NECESSARY	519.80	-
1	PILLAR, CTR BODY	NOT NECESSARY	307.70	-

Report Ref No. NS/INC19000944/Eqd3e2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REINFORCEMENT, CTR PILLAR	NOT NECESSARY	530.50	-
1	HINGE UPPER RHR, DOOR	NOT NECESSARY	81.70	-
1	HINGE LOWER RHR, DOOR	NOT NECESSARY	52.00	-
1	CHECK ASSY, RR DOOR	NOT NECESSARY	150.30	-
1	DOOR LOCK RR/RH	NOT NECESSARY	709.30	-
1	DOOR OUTER HANDLE RR/RH	NOT NECESSARY	69.80	-
1	DOOR INNER HANDLE REAR/RH	NOT NECESSARY	138.90	-
1	DOOR LOCK STRIKER	NOT NECESSARY	40.50	-
1	DOOR REAR RH TRIM BOARD	NOT NECESSARY	590.10	-
1	DOOR WEATHER STRIP RR/RH	NOT NECESSARY	171.20	-
1	CHECK ASSY, RR DOOR	NOT NECESSARY	150.30	-
1	DOOR REGULATOR MOTOR REAR RH	NOT NECESSARY	947.80	-
1	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	NOT NECESSARY	224.80	-
1	WIRE RHR, DOOR	NOT NECESSARY	280.20	-
1	TYRE	NOT NECESSARY	126.74	-
1	WHEEL DISC	NOT NECESSARY	1,484.20	-
1	QUARTER GLASS RR/RH	NOT NECESSARY	846.50	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	FENDER RR/RH	TO REPAIR SEE LABOUR	766.80	-
			16,787.34	3,731.80
	LABOUR			
	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)		125.00	125.00
	PANEL BEATING & BODY WORK, INCLUSIVE OF THE REPAIR OF FENDER RR/RH.		1,533.00	900.00
	SPRAY PAINT.		2,034.00	800.00
	TOWING CHARGE.		56.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	40.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	40.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING	NOT NECESSARY	120.00	-
	TO TRANSFER DOOR MECHANISM.		240.00	100.00
	TO REMOVE & REFIT REAR QUARTER GLASS RH	NOT NECESSARY	120.00	-

Report Ref No. NS/INC19000944/Eqd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No. 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT WIRE HARNESS.		200.00	80.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	NOT NECESSARY	120.00	-
	TO REMOVE / REFIT SEAT.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			5,008.00	2,085.00
GRAND TOTAL			21,795.34	5,816.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,650.00

Report Ref No. NS/INC19000944/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.