

ASS. REC. BY:

REF:

CCT119000950/R/sd3ch

Special Instructions:

Surveyor
Menmen

Rasul

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

16/1/19 @ 11:57am

Estimated Cost:

Bill to:

①

TP+WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKG 731SD

Insured:

at Workshop m/s:

Trans Eurokars

Tel:

6331 0683

of

5 ubi close

Policy No:

DMPCSN 30927418022

Claim No:

SNM19D200267col

Sum Insured:

Excess:

\$3,500.00

Make of Veh:

(Client's Record)

D.O.A. 08/01/2019,

Insp: 27A Tanjong Pagar

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:02pm @ 16/1/19

Person Contacted:

Eva

Vehicle IN/OUT

Date/Time

Action/Instruction

✓

) Estimate

consistency of damages

SKG 731SD-X

17/01/19

@ 14:27 p.m. - revised IA to Chong Boon Sen
via menmen.

17/01/19

@ 14:29 p.m. mandate requested authorize repair
to Chong Boon Sen via menmen.

18/01/19

@ 10:20 a.m. revert authorize repair to Eva (Gpwr) via email.

Pera

REF:

CT9

680614

VEHICULE

From: 16/1/19

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKG 7315D
at Workshop n/s: Trans Eurokars
of: 27A Tanjung Perjuna

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

\$3,500.00

(Client's Record)

Make of Veh:

EVA
check damage consistency.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

140K

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

12

days

Res:

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA / (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Vehicle

SKG 7315D

Yr Range: 2012 MAR

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: PORSCHE CAYENNE T.T VL WS. 3598

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 116 751 T/Radio: Insured / Std / NI / NA

Eng/No:

C/Nr: WP1222922CLA06578

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 295/302R22

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 08/01/19 D.O.I. 16/01/19

Survey held at: TRANS EUROKARS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

04/04/19 Confirmed R/P \$ 56,921.68 @ 12 days with Resul
(\$ 15,559.73 Red - 22%)

RECEIVED 07 MAY 2019

[Signature]
4/4/2019.

Date/Time File Pass to?

☐

Preli. Report

1. Typist

☒

Final Report

Date/Time File Return to?

2.

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Insp. (\$

☐

Workshop (\$

Report Format:

Lump Sum / L.B. (\$

56,921.68 R/P

Days Of Repair: 12

Resurvey No. of Trip: 2

Survey Fee:

220

Transportation:

3. ... - R/L ...

4. ...

5. ...

6. ...

7. ...

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2019		16 Jan 2019 11:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LOW KOK SIONG, ID: S1796806H, Tel: +6592293838, Email: KELVIN5340@HOTMAIL.COM		
Vehicle Reg. No.:	SKG7315D	Date of Loss:	08/01/2019 14:00 - :59
Claim Type:	OD / SNM19D200267C01	Policy/Cover Note No.:	DMPCSN30927418022 (Comprehensive)
		Excess:	S\$3,500.00
Repairer:	Trans Eurokars Pte Ltd (HQ) 5 Ubi Close, 408605 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/01/2019]		
Driver/Custodian:	LOW KOK SIONG (51 / Male), NRIC: S1796806H, Tel: +6592293838		
Adj Asg. Remarks:	survey revert economical to repair consistency of damages		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	6806H
Vehicle Details	
Vehicle No.:	SKG7315D
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jan 2019
Vehicle Make:	PORSCHE
Vehicle Model:	CAYENNE TIPTRONIC (V6) WITH SUNROOF
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	C07686
Chassis No.:	WP1ZZZ92ZCLA06575
Maximum Power Output:	220.0 kW (295 bhp)
Open Market Value:	\$87,636.00
Original Registration Date:	16 Mar 2012
First Registration Date:	16 Mar 2012
Transfer Count:	1
Actual ARF Paid:	\$87,636.00
Intended PARF/COE Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Mar 2022
PARF Rebate Amount:	\$56,963.00
Intended COE Details	
COE Expiry Date:	15 Mar 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$79,304.00
COE Rebate Amount:	\$25,031.00
Total Rebate Amount:	\$81,994.00

The information contained herein is correct as at 17 Jan 2019

OK

140,000
81,994

58,006

Chong Boon Sen

From: eva.kok@eurokars.com.sg
Sent: Wednesday, 16 January, 2019 9:38 AM
To: Chong Boon Sen
Cc: janice.syn@porsche.com.sg; rickteo@eurokars.com.sg
Subject: RE: od claims skg7315d doa: 8.1.19
Attachments: ESTIMATE-SKG7315D.pdf; SAS2532431.PDF

Hi,

Please refer to the attached estimate for your perusal.

Thank you

Regards,



Eva Kok

Insurance Claims Officer
27A Tanjong Penjuru
Singapore 609042
T: (65) 6331 0680 D: (65) 6331 0683 F: (65) 6331 0690
E: eva.kok@eurokars.com.sg W: www.eurokarsgroup.com

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: 16 January 2019 9:34 AM
To: Eva Kok <eva.kok@eurokars.com.sg>
Cc: Janice Syn <janice.syn@porsche.com.sg>; Rick Teo <rickteo@eurokars.com.sg>
Subject: od claims skg7315d doa: 8.1.19
Importance: High

Dear Eva,

Can assist to reprovide OD estimate pls?

Regards,

Chong Boon Sen

Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 5 April 2019 12:10 PM
To: jessicahs@eurokars.com.sg; Rasul (LKKAuto); CS A Team; Admin A
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg; rickteo@eurokars.com.sg
Subject: RE: FINALIZATION CTI OD - SKG7315D.xlsx
Attachments: CHINA TAIPING (DV)_0001.pdf

Dear Jessica,

Confirmed final fig \$56,921.68 @ 12 days of repairs before excess \$3,500/- & GST.

Attached DV, please filled in and revert us.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Shir@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg [mailto:jessicahs@eurokars.com.sg]
Sent: Friday, 29 March 2019 10:02 AM
To: Rasul@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg; rickteo@eurokars.com.sg
Subject: RE: FINALIZATION CTI OD - SKG7315D.xlsx

Dear Rasul,

Please assist and let us have your instruction to close our invoice.

Thank you very much.

Regards,

JESSICA SHASTRI

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: jessicahs@eurokars.com.sg

Website: www.eurokarsgroup.com

From: Jessica Harry Shastri
Sent: 25 March 2019 3:29 PM
To: 'Rasul (LKKAuto)' <Rasul@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: Janice Syn <janice.syn@porsche.com.sg>; Eva Kok <eva.kok@eurokars.com.sg>; Rick Teo

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 18 January 2019 3:54 PM
To: eva.kok@eurokars.com.sg
Cc: stanley@eurokars.com.sg; rickteo@eurokars.com.sg; jessicahs@eurokars.com.sg;
SUR
Subject: SKG 7315D OD (CTI)

Dear Eva,

As instructed by our client, please proceed to repair the insured vehicle **SKG 7315D (Excess \$ 3,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKG7315D (SNM19D200267C01)**

OD
Jan 8 2019 2:00PM
[LOW KOK SIONG]
Trans Eurokars Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **04/04/2019 11:20 AM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$57008.89) - SKG7315D - Claim Handler: Chong Boon Sen

Approved:57008.89:Proceed to authorize repairs UP TO \$57,008.89 BEFORE Excess of \$3,500.00. RE-INSPECTION OF VEHICLE REQUIRED.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SKG7315D (SNM19D200267C01)**

OD

Jan 8 2019 2:00PM

[LOW KOK SIONG]

Trans Eurokars Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **18/01/2019 10:20 AM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$47137.60) - SKG7315D - Claim Handler: Chong Boon Sen

Approved:47137.60:Proceed to authorize repairs UP TO \$47,137.60 BEFORE Excess of \$3,500.00. RE-INSPECTION OF VEHICLE REQUIRED.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 02 Apr 2019

Preliminary Advice

Vehicle No	: SKG7315D	Accident Date	: 08/01/2019
Make	: PORSCHE CAYENNE	Policy No.	: DMPCSN30927418022
Assignment Date	: 16/01/2019	Excess	: S\$3,500.00
Date of Inspection	: 16/01/2019	Est. Duration of Repair	: 12 days
Inspection At	: Trans Eurokars Pte Ltd (HQ) 5 Ubi Close Singapore 408605		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	72,481.41 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	46,860.22 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	10,148.67
Total	:S\$	57,008.89

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	81,994.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,006.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplemenatry amount is \$ 9,871.29

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 17 Jan 2019

Preliminary Advice

Vehicle No	: SKG7315D	Accident Date	: 08/01/2019
Make	: PORSCHE CAYENNE	Policy No.	: DMPCSN30927418022
Assignment Date	: 16/01/2019	Excess	: S\$3,500.00
Date of Inspection	: 16/01/2019	Est. Duration of Repair	: 12 days
Inspection At	: Trans Eurokars Pte Ltd (HQ) 5 Ubi Close Singapore 408605		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	62,610.12
Revised Amount	:S\$	36,988.93
Check Items (Estimated)	:S\$	10,148.67
Total	:S\$	47,137.60

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	81,994.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,006.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/01/2019 19:55
Date Of Accident	08/01/2019 14:30
Exact Location Of Accident	ALONG AYE TO CITY BEFORE CLEMENTI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG7315D
Insured/Policyholder	
Name Of Registered Owner	LOW KOK SIONG
NRIC No	S1796806H
Email Address	KELVIN5340@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-92293838
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	PORSCHE
Model	CAYENNE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	LOW KOK SIONG
NRIC No	S1796806H
Date Of Birth	31/08/1967
Occupation	INDOOR
Date Of Driving Pass	16/03/1990
Driving Experience	28 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92293838
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	KELVIN5340@HOTMAIL.COM

Address

BLK 202 CLEMENTI AVE 6 #05-55 SINGAPORE 120202

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP7902X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TANKER

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/1/2019 around 14:30 hrs. I was driving along AYE towards city, before Clementi Ser, Vehicle B that was ~~in front~~ in front of me applied sudden brake, I couldn't brake in time and hit onto the rear portion of Vehicle B.

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

China Taiping Insurance (S) Pte Ltd 3 Anson Rd, #16-00 Springleaf Tower Singapore 079909		NAME : Mr Low Kok Siong	WIP : 41561
ATTN : MOTOR CLAIMS		ADDRESS : Blk 202 Clementi Avenue 6 #05-55 Singapore 120202	EXCESS : DATE : 11.01.2019
FAX :		TEL :	
VEH NO :	SKG7315D	DATE IN :	CONTACT PERSON : EVA 63310683
CHASSIS NO :	WP12Z792ZCLA06575	MILEAGE :	TYPE OF CLAIM : OD
MODEL :	Cayenne Tiptronic	DATE REG. : 16.03.2012	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	FRONT FENDER LH <i>new /</i>	1		\$ 1,480.20
2	FRONT FENDER RH <i>repair bf /</i>	1		\$ 1,480.20
3	LENS-HD SCREW FENDER LH <i>new /</i>	3		\$ 4.80
4	EXPANSION RIVET <i>new /</i>	6		\$ 13.20
5	CLIP <i>new /</i>	6		\$ 11.40
6	FENDER BRACKET LH <i>new /</i>	1		\$ 8.90
7	LENS-HEAD SCREW <i>new /</i>	5		\$ 6.50
8	FENDER SUPPORT LH <i>new /</i>	1		\$ 41.70
9	FRONT BUMPER <i>new /</i>	1		\$ 1,174.80
10	SENSOR PARKASSIST <i>new /</i>	2 <i>2x1</i>	538-46	\$ 1,076.80
11	SENSOR GASKET <i>new /</i>	4		\$ 18.00
12	BUMPER GARNISH CENTRE UPPER <i>new /</i>	1		\$ 205.80
13	BUMPER GARNISH CENTRE LOWER <i>new /</i>	1		\$ 205.80
14	BUMPER GRILLE <i>new /</i>	1		\$ 194.80
15	EXPANSION RIVET <i>new /</i>	10		\$ 5.00
16	FOAM PART <i>new /</i>	1		\$ 73.00
17	HEADLAMP RETAINER LH (UNDER) <i>? car /</i>	1		\$ 43.50
18	HEADLAMP RETAINER RH (UNDER) <i>? car /</i>	1		\$ 43.50
19	BUMPER SIDE RETAINER LH <i>new /</i>	1		\$ 43.50
20	BUMPER SIDE RETAINER RH <i>new /</i>	1		\$ 43.50
21	AIR GUIDE COVER LH <i>? car /</i>	1		\$ 219.40
22	AIR GUIDE COVER RH <i>? car /</i>	1		\$ 219.40
23	BUMPER GRILLE SUPPORT LH <i>? car /</i>	1		\$ 123.20
24	BUMPER GRILLE SUPPORT RH <i>? car /</i>	1		\$ 123.20
25	FASTENING CLAMP BUMPER <i>? car /</i>	2		\$ 75.20
26	WATER DEFLECTOR AIR INLET LH <i>? car /</i>	1		\$ 35.50
27	GARNISH UPPER LH <i>? car /</i>	1		\$ 59.10
28	GARNISH UPPER RH <i>? car /</i>	1		\$ 59.10
29	GARNISH LOWER LH <i>? car /</i>	1		\$ 59.10
30	GARNISH LOWER RH <i>? car /</i>	1		\$ 59.10
31	EXPANSION RIVET <i>new /</i>	4		\$ 6.00
32	FRONT BUMPER SPOILER <i>new /</i>	1		\$ 712.10
33	FRONT NUMBER PLATE BRACKET <i>new /</i>	1		\$ 82.20
34	EXPANSION RIVET <i>new /</i>	6		\$ 3.00

35	TOW COVER LH	MIS /	1	P958-505-155-00-G2L	\$	70.70
36	TOW COVER RH	MIS /	1	P958-505-156-00-G2L	\$	70.70
37	BUMPER REINFORCEMENT	RA /	1	P958-505-109-01-	\$	1,256.40
38	REINFORCEMENT ADJUSTER LH	gt /	1	P958-505-879-00-	\$	41.10
39	REINFORCEMENT ADJUSTER RH	RA /	1	P958-505-880-00-	\$	41.10
40	FRONT TOP SUPPORT PANEL	? CRA /	1	P958-505-594-02-	\$	567.50
41	TOP SUPPORT PANEL BRACKET (FRONT)	? CRA /	1	P958-504-731-00-	\$	117.50
42	LOCK CARRIER (FRONT)	? CRA /	1	P958-505-799-01-	\$	94.70
43	BONNET	RA /	1	P958-511-011-06-GRV	\$	3,690.60
44	BONNET HOOK UPPER	X ?	1	P958-511-480-00-	\$	80.40
45	BONNET HINGE LH	X } XSUC	1	P958-511-301-02-	\$	112.80
46	BONNET HINGE RH	X }	1	P958-511-302-02-	\$	112.80
47	BONNET CABLE FRONT	at /	1	P958-511-531-11-	\$	35.30
48	BONNET LOWER LOCK	? X XSUC	1	P958-511-509-02-	\$	201.40
49	COMBINATION SCREW	X } NA	2	PWHT-000-425- -	\$	3.60
50	COMBINATION SCREW	X }	1	PN -908-073-01-	\$	1.30
51	ENGINE TOP COVER RH	at /	1	P958-556-442-00-01C	\$	98.00
52	ENGINE TOP COVER LH	X SUC	1	P958-556-583-00-01C	\$	98.00
53	EXPANSION RIVET	at /	10	PWHT-004-750- -	\$	22.00
54	ENGINE FRONT COVER	at /	1	P958-556-806-01-989	\$	46.90
55	PORSCHE EMBLEM	at /	1	P9P1-853-601- -	\$	248.60
56	EMBLEM SEAL	at /	1	P7L5-853-611-B -	\$	12.40
57	HOOD BADGE NUT	at /	2	PWHT-004-974- -	\$	3.00
58	O-RING	at /	2	P955-573-749-00-	\$	9.00
59	P955-572-094-00/O RING	at /	2	P955-573-749-01-	\$	9.60
60	CONDENSER	? bt /	1	P958-573-111-02-	\$	1,679.10
61	FENDER SUPPORT PANEL LH	? X SUCX	1	P958-501-457-00-GRV	\$	267.40
62	FENDER SUPPORT PANEL RH	? X XSUC	1	P958-501-458-00-GRV	\$	267.40
63	FENDER UPPER REINFORCEMENT LH	? bt /	1	P958-501-551-00-GRV	\$	100.90
64	FENDER UPPER REINFORCEMENT RH	? bt /	1	P958-501-552-00-GRV	\$	100.90
65	P000-043-204-85-/CAVITY PRESERVATION	X SUC NA	1	P000-043-305-51-	\$	75.30
66	FRONT BUMPER WIRING HARNESS	? at /	1	P958-612-331-10-	\$	372.30
67	HORN (LOW-PITCH)	? at /	1	P958-951-183- -	\$	129.70
68	HORN (HIGH-PITCH)	? at /	1	P958-635-106-01-	\$	95.20
69	HORN ADAPTER	? CRA /	2	P970-612-935-00-	\$	37.40
70	HORN SUPPORT (LOW-PITCH)	? bt /	1	P958-951-183- -	\$	129.70
71	HORN SUPPORT (HIGH-PITCH)	? X SUC	1	P958-635-161-00-	\$	-
72	HEXAGON NUT	? X NA	2	P900-034-001-04-	\$	9.00
73	HEXAGON-HEAD BOLT	? X NA	2	PN -104-139-05-	\$	4.40
74	HEADLAMP NOZZLE	CRA ?	2	P958-628-180-00-	\$	306.00
75	NOZZLE, HEADLAMP WASHER (LH)	at /	1	P958-628-161-00-	\$	55.20
76	NOZZLE, TRIM COVER LH	MIS /	1	P958-628-301-00-G2X	\$	69.30
77	OVAL-HEAD SCREW	at /	8	PWHT-003-954- -	\$	5.60
78	NOZZLE, HEADLAMP WASHER (RH)	CRA /	1	P958-628-162-00-	\$	55.20
79	NOZZLE, TRIM COVER RH	MIS /	1	P958-628-302-00-G2X	\$	69.30
80	OVAL-HEAD SCREW	at /	8	PWHT-003-954- -	\$	5.60
81	P958-631-177-00-/HEADLAMP LH	RA /	1	P958-631-177-02-	\$	3,267.10
82	P958-631-178-00-/HEADLAMP RH	RA /	1	P958-631-178-02-	\$	3,267.10
83	HEADLAMP SUPPORT	? CRA /	2	P958-631-194-02-	\$	86.00
84	HEADLAMP MOUNTING LEVEL LH	? X } XSUC	1	P958-631-519-00-	\$	313.10
85	HEADLAMP MOUNTING LEVEL RH	? X }	1	P958-631-520-00-	\$	313.10

86	DIRECTION INDICATOR LIGHT LH	CRS ? ✓ neu /	1	P958-631-101-00-	\$	79.50
87	DIRECTION INDICATOR LIGHT RH	CRS ? ✓ neu /	1	P958-631-102-00-	\$	79.50
88	ADDITIONAL HEADLAMP LH	880 ✓	1	P958-631-181-00-	\$	836.90
89	ADDITIONAL HEADLAMP RH	880 ✓	1	P958-631-182-00-	\$	836.90
90	FOG LAMP	✓ CR4	2	P955-631-163-00-	\$	804.60
91	MOBIL 1 STICKER	neu /	1	P7PP-010-786-T-	\$	6.30
92	AIR CONDITIONER STICKER	neu /	1	P958-701-141-00-	\$	11.80
93	WARNING SIGN STICKER	neu /	1	P7PP-010-006-A-	\$	5.90
94	RADIATOR SECURE PIN	? ✓ neu /	2	P958-106-667-00-	\$	6.20
95	RADIATOR SECURE PIN SLEEVE	? ✓ neu /	2	P958-106-665-00-	\$	21.60
96	RADIATOR BUSHING UPPER	? ✓ neu /	2	P958-106-651-00-	\$	18.60
97	RADIATOR SUPPORT UPPER RH	? ✓ neu /	1	P958-106-662-02-	\$	12.00
98	ROUND HEAD SCREW	? ✓ neu /	2	PWHT-003-956-	\$	4.80
99	RADIATOR FAN COWLING	? ✓ CR4	1	P958-106-061-20-	\$	2,988.10
100	RADIATOR SUPPORT UPPER LH	? ✓ neu /	1	P958-106-661-01-	\$	10.40
101	OVAL-HEAD SCREW	? ✓ neu /	2	PN -101-243-06-	\$	2.20
102	PAN-HEAD SCREW	? ✓ neu /	4	PN -910-700-01-	\$	18.00
103	RADIATOR SUPPORT LOWER	? ✓ neu /	2	P958-106-660-00-	\$	54.20
104	RADIATOR BUSHING LOWER	? ✓ neu /	2	P7PD-121-275-	\$	52.80
105	RADIATOR FRAME	? ✓ bt	1	P958-106-141-01-	\$	365.90
106	COOLANT PIPE TOP	? ✓ XSV	1	P958-106-311-10-	\$	121.80
107	P000-043-301-12-/ANTIFREEZE PROTECTION	neu /	6	P000-043-305-15-	\$	190.20
108	RADIATOR AIR GUIDE CENTRE	? ✓ CR4	1	P958-575-323-20-	\$	284.00
109	EXPANSION RIVET	? ✓ neu /	3	PWHT-004-750-	\$	6.60
110	SEALING WEDGE LH	? ✓ neu /	1	P958-110-563-00-	\$	15.00
111	SEALING WEDGE RH	? ✓ neu /	1	P958-110-564-00-	\$	15.00
112	GAITER RH	? ✓ neu /	1	P958-110-252-10-	\$	58.00
113	INTAKE MANIFOLD PIPE LH	? ✓ bt	1	P958-110-271-00-	\$	57.50
114	GAITER LH	? ✓ neu /	1	P958-110-251-00-	\$	57.50
115	WINDOW CLEANER STICKER	? ✓ neu /	1	P955-701-160-00-	\$	7.80

TOTAL PARTS

\$ 33,166.80

LESS 10%

\$ 3,316.68

TOTAL PARTS COST

\$ 29,850.12

Labour Description

1	TO REMOVE / REPLACE BONNET, FRONT BUMPER, LH/RH FRONT FENDER, LH/RH FENDER SUPPORT PANEL & TO REPAIR LH/RH FRONT DOORS AFFECTED BY THE ACCIDENT.	9360	\$ 18,720.00
2	TO RESPRAY BONNET, FRONT BUMPER, LH/RH FRONT FENDER, LH/RH FENDER SUPPORT PANEL & LH/RH FRONT DOORS.	6800	\$ 8,000.00
3	TO SUPPLY SPRAY THEROSTAT SEALANT ON THE CUTTING AREAS.	100	\$ 350.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	100	\$ 250.00
5	TO REMOVE & REPLACE FRONT SUPPORT PANEL, CONDENSER, RADIATOR & RADIATOR FAN ASSY.	1560	\$ 3,220.00
6	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	300	\$ 500.00

7	TO TRANSFER THE PARKING SENSORS.	an X	\$	500.00
8	TO SUPPLY 1 PC CHASSIS STICKER.	NETT nu	\$	150.00
9	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.	NETT ms	\$	70.00
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$	200.00
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$	600.00
12	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NETT	\$	250.00
13	SUNDRIES.	NETT	\$	50.00
		TOTAL LABOUR	\$	-
		TOTAL PARTS	\$	-
		TOTAL	\$	-
		LESS EXCESS	\$	-
		TOTAL AFTER EXCESS	\$	-
		GST 7%	\$	-
		GRAND TOTAL	\$	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

72481.41

[Signature]
21/1/19

Farul
Hp 90010068

12 days
P/P

EXCESS: 3500

REVERT

16/01/19 @ 1550

Resurvey & paint

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



China Taiping Insurance (S) Pte Ltd 3 Anson Rd, #16-00 Springleaf Tower Singapore 079909 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Low Kok Siong ADDRESS : Blk 202 Clementi Avenue 6 #05-55 Singapore 120202 TEL :		WIP : EXCESS : DATE :	
VEH NO :	SKG7315D	DATE IN :		CONTACT PERSON :	EVA
CHASSIS NO :	WP1ZZZ92ZCLA06575	MILEAGE :		TYPE OF CLAIM :	OD
MODEL :	Cayenne Tiptronic	DATE REG.:	16.03.2012	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	PRICES
1	TRANSMISSION OIL COOLER <i>bt</i>	1	P958-307-015-01- \$ 1,699.40
2	O RING OIL COOLER <i>new</i>	2	PN -906-660-01- \$ 6.60
3	TRANSMISSION OIL TIPTRONIC <i>bt</i>	1	P000-043-306-24- \$ 130.90
4	BRACKET WING LEFT <i>bt</i>	1	P958-502-091-00-GRV \$ 669.80
5	BRACKET WING RIGHT <i>FA</i>	1	P958-502-092-00-GRV \$ 669.80
6	P958-503-610-00-GRV/SUPPORT WING PRIME C <i>bt</i>	1	P958-503-610-01-GRV \$ 41.70
7	CONTROL UNIT HEADLAMP <i>cut</i>	1	P958-618-381-01- \$ 1,499.70
8	RADIATOR <i>bt</i>	1	P958-106-132-10- \$ 2,859.20
9	WATER HOSE COMPLETE RETURN <i>cut</i>	1	P958-106-401-11- \$ 513.70
10	COOLING WATER TUBE <i>cut</i>	1	P958-106-402-11- \$ 451.20
11	AIR CLEANER COMPLETE LEFT <i>new</i>	1	P958-110-021-00- \$ 1,141.70
12	BELT ROLLER <i>cut</i>	1	P955-102-276-00- \$ 303.00
13	OIL COOLER POWER STEERING <i>bt</i>	1	P958-347-069-00- \$ 981.40
TOTAL			\$ 10,968.10
LESS 10 %			\$ 1,096.81
TOTAL AFTER LESS			\$ 9,871.29

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Subsequent work(s) must be resurveyed and approved in final approval from Insurance Company

Authorised by Repairer

Signature

Date



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

China Taiping Insurance (S) Pte Ltd		NAME : Mr Low Kok Siong		WIP : 41561	
3 Anson Rd, #16-00 Springleaf Tower		ADDRESS : Blk 202 Clementi Avenue 6		EXCESS :	
Singapore 079909		#05-55		DATE: 11.01.2019	
		Singapore 120202			
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SKG7315D	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP1ZZZ92ZCLA06575	MILEAGE :		TYPE OF CLAIM :	OD
MODEL :	Cayenne Tiptronic	DATE REG.:	16.03.2012	POLICY NO. :	

NATURE OF WORKS

Parts Description					
S/NO	QTY			REVISED	PRICES
1	FRONT FENDER LH	1	P958-503-031-03-GRV	\$ 1,480.20	\$ 1,480.20
2	FRONT FENDER RH	1	P958-503-032-03-GRV	\$ 1,480.20	\$ 1,480.20
3	LENS-HD SCREW FENDER LH	3	PN -910-432-01-	\$ 4.80	\$ 4.80
4	EXPANSION RIVET	6	PWHT-004-750- -	\$ 13.20	\$ 13.20
5	CLIP	6	P958-503-719-00-	\$ 11.40	\$ 11.40
6	FENDER BRACKET LH	1	P958-503-459-00-GRV	\$ 8.90	\$ 8.90
7	LENS-HEAD SCREW	5	PN -910-423-02-	\$ 6.50	\$ 6.50
8	FENDER SUPPORT LH	1	P958-503-609-01-GRV	\$ 41.70	\$ 41.70
9	FRONT BUMPER	1	P958-505-221-31-G2L	\$ 1,174.80	\$ 1,174.80
10	SENSOR PARKASSIST	2	P150-919-275-C -G2L	\$ 538.40	\$ 1,076.80
11	SENSOR GASKET	4	P7PP-919-133- -	\$ 18.00	\$ 18.00
12	BUMPER GARNISH CENTRE UPPER	1	P958-505-973-00-989	\$ 205.80	\$ 205.80
13	BUMPER GARNISH CENTRE LOWER	1	P958-505-974-00-989	\$ 205.80	\$ 205.80
14	BUMMPER GRILLE	1	P958-505-683-01-	\$ 194.80	\$ 194.80
15	EXPANSION RIVET	10	PN -038-549-4 -	\$ 5.00	\$ 5.00
16	FOAM PART	1	P958-505-550-01-	\$ 73.00	\$ 73.00
17	HEADLAMP RETAINER LH (UNDER)	1	P958-505-889-00-	\$ 43.50	\$ 43.50
18	HEADLAMP RETAINER RH (UNDER)	1	P958-505-890-00-	\$ 43.50	\$ 43.50
19	BUMPER SIDE RETAINER LH	1	P958-505-049-00-	\$ 43.50	\$ 43.50
20	BUMPER SIDE RETAINER RH	1	P958-505-050-00-	\$ 43.50	\$ 43.50
21	AIR GUIDE COVER LH	1	P958-505-333-00-989	\$ 219.40	\$ 219.40
22	AIR GUIDE COVER RH	1	P958-505-334-00-989	\$ 219.40	\$ 219.40
23	BUMPER GRILLE SUPPORT LH	1	P958-505-681-00-	\$ 123.20	\$ 123.20
24	BUMPER GRILLE SUPPORT RH	1	P958-505-682-00-	\$ 123.20	\$ 123.20
25	FASTENING CLAMP BUMPER	2	P958-505-829-00-	\$ 75.20	\$ 75.20
26	WATER DEFLECTOR AIR INLET LH	1	P958-505-245-00-	\$ 35.50	\$ 35.50
27	GARNISH UPPER LH	1	P958-505-685-00-989	\$ 59.10	\$ 59.10
28	GARNISH UPPER RH	1	P958-505-686-00-989	\$ 59.10	\$ 59.10
29	GARNISH LOWER LH	1	P958-505-877-00-989	\$ 59.10	\$ 59.10
30	GARNISH LOWER RH	1	P958-505-878-00-989	\$ 59.10	\$ 59.10
31	EXPANSION RIVET	4	PN -038-501-3 -	\$ 6.00	\$ 6.00
32	FRONT BUMPER SPOILER	1	P958-505-061-00-	\$ 712.10	\$ 712.10
33	FRONT NUMBER PLATE BRACKET	1	P958-701-105-00-989	\$ 82.20	\$ 82.20
34	EXPANSION RIVET	6	PN -038-549-4 -	\$ 3.00	\$ 3.00

35	TOW COVER LH	1	P958-505-155-00-G2L	\$ 70.70	\$ 70.70
36	TOW COVER RH	1	P958-505-156-00-G2L	\$ 70.70	\$ 70.70
37	BUMPER REINFORCEMENT	1	P958-505-109-01-	\$ 1,256.40	\$ 1,256.40
38	REINFORCEMENT ADJUSTER LH	1	P958-505-879-00-	\$ 41.10	\$ 41.10
39	REINFORCEMENT ADJUSTER RH	1	P958-505-880-00-	\$ 41.10	\$ 41.10
40	FRONT TOP SUPPORT PANEL	1	P958-505-594-02-	\$ 567.50	\$ 567.50
41	TOP SUPPORT PANEL BRACKET (FRONT)	1	P958-504-731-00-	\$ 117.50	\$ 117.50
42	LOCK CARRIER (FRONT)	1	P958-505-799-01-	\$ 94.70	\$ 94.70
43	BONNET	1	P958-511-011-06-GRV	\$ 3,690.60	\$ 3,690.60
44	BONNET HOOK UPPER	1	P958-511-480-00-	\$ -	\$ 80.40
45	BONNET HINGE LH	1	P958-511-301-02-	\$ -	\$ 112.80
46	BONNET HINGE RH	1	P958-511-302-02-	\$ -	\$ 112.80
47	BONNET CABLE FRONT	1	P958-511-531-11-	\$ 35.30	\$ 35.30
48	BONNET LOWER LOCK	1	P958-511-509-02-	\$ -	\$ 201.40
49	COMBINATION SCREW	2	PWHT-000-425- -	\$ -	\$ 3.60
50	COMBINATION SCREW	1	PN -908-073-01-	\$ -	\$ 1.30
51	ENGINE TOP COVER RH	1	P958-556-442-00-01C	\$ 98.00	\$ 98.00
52	ENGINE TOP COVER LH	1	P958-556-583-00-01C	\$ -	\$ 98.00
53	EXPANSION RIVET	10	PWHT-004-750- -	\$ 22.00	\$ 22.00
54	ENGINE FRONT COVER	1	P958-556-806-01-989	\$ 46.90	\$ 46.90
55	PORSCHE EMBLEM	1	P9P1-853-601- -	\$ 248.60	\$ 248.60
56	EMBLEM SEAL	1	P7L5-853-611-B -	\$ 12.40	\$ 12.40
57	HOOD BADGE NUT	2	PWHT-004-974- -	\$ 3.00	\$ 3.00
58	O-RING	2	P955-573-749-00-	\$ 9.00	\$ 9.00
59	P955-572-094-00-/O RING	2	P955-573-749-01-	\$ 9.60	\$ 9.60
60	CONDENSER	1	P958-573-111-02-	\$ 1,679.10	\$ 1,679.10
61	FENDER SUPPORT PANEL LH	1	P958-501-457-00-GRV	\$ -	\$ 267.40
62	FENDER SUPPORT PANEL RH	1	P958-501-458-00-GRV	\$ -	\$ 267.40
63	FENDER UPPER REINFORCEMENT LH	1	P958-501-551-00-GRV	\$ 100.90	\$ 100.90
64	FENDER UPPER REINFORCEMENT RH	1	P958-501-552-00-GRV	\$ 100.90	\$ 100.90
65	P000-043-204-85-/CAVITY PRESERVATION	1	P000-043-305-51-	\$ -	\$ 75.30
66	FRONT BUMPER WIRING HARNESS	1	P958-612-331-10-	\$ 372.30	\$ 372.30
67	HORN (LOW-PITCH)	1	P958-951-183- -	\$ 129.70	\$ 129.70
68	HORN (HIGH-PITCH)	1	P958-635-106-01-	\$ 95.20	\$ 95.20
69	HORN ADAPTER	1	P970-612-935-00-	\$ 37.40	\$ 37.40
70	HORN SUPPORT (LOW-PITCH)	1	P958-951-183- -	\$ 129.70	\$ 129.70
71	HORN SUPPORT (HIGH-PITCH)	1	P958-635-161-00-	\$ -	\$ -
72	HEXAGON NUT	2	P900-034-001-04-	\$ -	\$ 9.00
73	HEXAGON-HEAD BOLT	2	PN -104-139-05-	\$ -	\$ 4.40
74	HEADLAMP NOZZLE	2	P958-628-180-00-	\$ 306.00	\$ 306.00
75	NOZZLE, HEADLAMP WASHER (LH)	1	P958-628-161-00-	\$ 55.20	\$ 55.20
76	NOZZLE, TRIM COVER LH	1	P958-628-301-00-G2X	\$ 69.30	\$ 69.30
77	OVAL-HEAD SCREW	8	PWHT-003-954- -	\$ 5.60	\$ 5.60
78	NOZZLE, HEADLAMP WASHER (RH)	1	P958-628-162-00-	\$ 55.20	\$ 55.20
79	NOZZLE, TRIM COVER RH	1	P958-628-302-00-G2X	\$ 69.30	\$ 69.30
80	OVAL-HEAD SCREW	8	PWHT-003-954- -	\$ 5.60	\$ 5.60
81	P958-631-177-00-/HEADLAMP LH	1	P958-631-177-02-	\$ 3,267.10	\$ 3,267.10
82	P958-631-178-00-/HEADLAMP RH	1	P958-631-178-02-	\$ 3,267.10	\$ 3,267.10
83	HEADLAMP SUPPORT	2	P958-631-194-02-	\$ 86.00	\$ 86.00
84	HEADLAMP MOUNTING LEVEL LH	1	P958-631-519-00-	\$ -	\$ 313.10
85	HEADLAMP MOUNTING LEVEL RH	1	P958-631-520-00-	\$ -	\$ 313.10

1	TO REMOVE / REPLACE BONNET, FRONT BUMPER, LH/RH FRONT FENDER, LH/RH FENDER SUPPORT PANEL & TO REPAIR LH/RH FRONT DOORS AFFECTED BY THE ACCIDENT.	\$ 9,360.00	\$ 18,720.00
2	TO RESPRAY BONNET, FRONT BUMPER, LH/RH FRONT FENDER, LH/RH FENDER SUPPORT PANEL & LH/RH FRONT DOORS.	\$ 6,800.00	\$ 8,000.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	\$ 100.00	\$ 350.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 100.00	\$ 250.00
5	TO REMOVE & REPLACE FRONT SUPPORT PANEL, CONDENSER, RADIATOR & RADIATOR FAN ASSY.	\$ 1,560.00	\$ 3,120.00
6	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	\$ 300.00	\$ 500.00
7	TO TRANSFER THE PARKING SENSORS.	\$ -	\$ 500.00
8	TO SUPPLY 1 PC CHASSIS STICKER	\$ 150.00	\$ 150.00
9	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.	\$ 70.00	\$ 70.00
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 200.00	\$ 200.00
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
12	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	\$ 250.00	\$ 250.00
13	SUNDRIES.	\$ 50.00	\$ 50.00
TOTAL LABOUR		\$ 19,540.00	\$ 32,760.00
TOTAL PARTS		\$ 37,381.68	\$ 39,718.44
TOTAL		\$ 56,921.68	\$ 72,478.44
LESS EXCESS		\$ 3,500.00	\$ -
TOTAL AFTER EXCESS		\$ 53,421.68	
GST 7%		\$ 3,739.52	\$ -
GRAND TOTAL		\$ 57,161.20	\$ -

NUMBER OF DAYS: 12 WORKING DAYS(EXCLUDE WAITING FOR PARTS,SURVEY,AUTHORIZATION,SAT,SUN & PH)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2019		16 Jan 2019 11:57 Edit Adj Rpt	S\$56,921.68 Edit Estimates	S\$56,921.68 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LOW KOK SIONG , ID: S1796806H, Tel: +6592293838, Email: KELVIN5340@HOTMAIL.COM									
Vehicle Reg. No.: SKG7315D		Date of Loss: 08/01/2019 14:00 - :59 [81 Months and 23 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM19D200267C01		Policy/Cover Note No.: DMPCSN30927418022 (Comprehensive)							
		Excess: S\$3,500.00							
Repairer: Trans Eurokars Pte Ltd (HQ) 5 Ubi Close, 408605 Ubi - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 25/01/2019]									
Driver/Custodian: LOW KOK SIONG (51 / Male) , NRIC: S1796806H, Tel: +6592293838 Email: KELVIN5340@HOTMAIL.COM									
Adj Asg. Remarks: survey revert economical to repair consistency of damages									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (04/04/2019): Alert - Adj Mandate Approved (S\$57008.89) - SKG7315D - Claim Handler: Chong Boon... - CHINA_TAIPING (18/01/2019): Alert - Adj Mandate Approved (S\$47137.60) - SKG7315D - Claim Handler: Chong Boon...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKG7315D (SNM19D200267C01)

OD

Jan 8 2019 2:00PM

[LOW KOK SIONG]

Trans Eurokars Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		☒	
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print				
1	08/01/19 19:59	Accident Statement			Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print				
1	17/01/19 14:27	Adjuster Immediate Advice			Load HTM				
2	02/04/19 14:11	Adjuster Immediate Advice			Load HTM				
						3 per page		☒	
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print				
1	08/01/19 19:58	Accident Photo [Linked Accident Report Documents]			Load JPG	☒			
2	08/01/19 19:58	Accident Photo [Linked Accident Report Documents]			Load JPG	☒			
3	08/01/19 19:58	Accident Photo [Linked Accident Report Documents]			Load JPG	☒			
4	08/01/19 19:58	Accident Photo [Linked Accident Report Documents]			Load JPG	☒			
5	08/01/19 19:58	Accident Photo [Linked Accident Report Documents]			Load JPG	☒			
6	08/01/19 19:58	Accident Photo [Linked Accident Report Documents]			Load JPG	☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print				
1	17/01/19 14:24	Odometer Reading			Load JPG	☒			
2	17/01/19 14:24	Chassis Number			Load JPG	☒			
3	17/01/19 14:24	General View			Load JPG	☒			
4	17/01/19 14:24	General View			Load JPG	☒			
5	17/01/19 14:24	General View			Load JPG	☒			
6	17/01/19 14:24	General View			Load JPG	☒			
7	17/01/19 14:24	General View			Load JPG	☒			
8	17/01/19 14:24	General View			Load JPG	☒			
9	17/01/19 14:24	General View			Load JPG	☒			
10	17/01/19 14:24	General View			Load JPG	☒			
11	17/01/19 14:24	General View			Load JPG	☒			
12	17/01/19 14:24	General View			Load JPG	☒			
13	17/01/19 14:24	General View			Load JPG	☒			
14	17/01/19 14:24	General View			Load JPG	☒			
15	17/01/19 14:24	General View			Load JPG	☒			
16	17/01/19 14:24	General View			Load JPG	☒			
17	17/01/19 14:24	General View			Load JPG	☒			
18	17/01/19 14:24	General View			Load JPG	☒			
19	17/01/19 14:24	General View			Load JPG	☒			
20	17/01/19 14:24	General View			Load JPG	☒			
21	17/01/19 14:24	General View			Load JPG	☒			
22	17/01/19 14:24	General View			Load JPG	☒			
23	17/01/19 14:24	General View			Load JPG	☒			
24	17/01/19 14:24	General View			Load JPG	☒			

Assessment Reports			1 per page	☒
No.	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
25	17/01/19 14:24	General View	 Load JPG	☒
26	17/01/19 14:24	General View	 Load JPG	☒
27	17/01/19 14:24	General View	 Load JPG	☒
28	17/01/19 14:24	General View	 Load JPG	☒
29	17/01/19 14:24	General View	 Load JPG	☒
30	17/01/19 14:24	General View	 Load JPG	☒
31	17/01/19 14:24	General View	 Load JPG	☒
32	17/01/19 14:24	General View	 Load JPG	☒
33	17/01/19 14:24	General View	 Load JPG	☒
34	17/01/19 14:24	General View	 Load JPG	☒
35	17/01/19 14:24	General View	 Load JPG	☒
36	17/01/19 14:24	General View	 Load JPG	☒
37	17/01/19 14:24	General View	 Load JPG	☒
38	17/01/19 14:24	General View	 Load JPG	☒
39	17/01/19 14:24	General View	 Load JPG	☒
40	17/01/19 14:24	General View	 Load JPG	☒
41	17/01/19 14:24	General View	 Load JPG	☒
42	17/01/19 14:24	General View	 Load JPG	☒
43	17/01/19 14:24	General View	 Load JPG	☒
44	17/01/19 14:24	General View	 Load JPG	☒
45	17/01/19 14:24	General View	 Load JPG	☒
46	17/01/19 14:24	General View	 Load JPG	☒
47	17/01/19 14:24	General View	 Load JPG	☒
48	17/01/19 14:24	General View	 Load JPG	☒
49	17/01/19 14:24	General View	 Load JPG	☒
50	17/01/19 14:24	General View	 Load JPG	☒
51	17/01/19 14:24	General View	 Load JPG	☒
52	17/01/19 14:24	General View	 Load JPG	☒
53	17/01/19 14:24	General View	 Load JPG	☒
54	17/01/19 14:24	General View	 Load JPG	☒
55	17/01/19 14:24	General View	 Load JPG	☒
56	17/01/19 14:24	General View	 Load JPG	☒
57	17/01/19 14:24	General View	 Load JPG	☒
58	17/01/19 14:24	General View	 Load JPG	☒
59	17/01/19 14:24	General View	 Load JPG	☒
60	17/01/19 14:24	General View	 Load JPG	☒
61	17/01/19 14:24	General View	 Load JPG	☒
62	17/01/19 14:24	General View	 Load JPG	☒
63	17/01/19 14:24	General View	 Load JPG	☒
64	17/01/19 14:24	General View	 Load JPG	☒
65	17/01/19 14:24	General View	 Load JPG	☒
66	17/01/19 14:24	General View	 Load JPG	☒
67	17/01/19 14:24	General View	 Load JPG	☒
68	17/01/19 14:24	General View	 Load JPG	☒
69	17/01/19 14:24	General View	 Load JPG	☒
70	17/01/19 14:24	General View	 Load JPG	☒
71	17/01/19 14:24	General View	 Load JPG	☒
72	17/01/19 14:24	General View	 Load JPG	☒
73	17/01/19 14:24	General View	 Load JPG	☒
74	17/01/19 14:24	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
75	17/01/19 14:24	General View		☒
76	17/01/19 14:24	General View		☒
77	17/01/19 14:24	General View		☒
78	17/01/19 14:24	General View		☒
79	17/01/19 14:24	General View		☒
80	17/01/19 14:24	General View		☒
81	17/01/19 14:24	General View		☒
82	17/01/19 14:24	General View		☒
83	17/01/19 14:24	General View		☒
84	17/01/19 14:24	General View		☒
85	17/01/19 14:24	General View		☒
86	17/01/19 14:24	General View		☒
87	17/01/19 14:24	General View		☒
88	17/01/19 14:24	General View		☒
89	17/01/19 14:24	General View		☒
90	17/01/19 14:24	General View		☒
91	17/01/19 14:24	General View		☒
92	17/01/19 14:24	General View		☒
93	17/01/19 14:24	General View		☒
94	17/01/19 14:24	General View		☒
95	17/01/19 14:24	General View		☒
96	17/01/19 14:24	General View		☒
97	17/01/19 14:24	General View		☒
98	17/01/19 14:24	General View		☒
99	17/01/19 14:24	General View		☒
100	17/01/19 14:24	General View		☒
101	17/01/19 14:24	General View		☒
102	17/01/19 14:24	General View		☒
103	17/01/19 14:24	General View		☒
104	17/01/19 14:24	General View		☒
105	17/01/19 14:24	General View		☒
106	17/01/19 14:24	General View		☒
107	17/01/19 14:24	General View		☒
108	17/01/19 14:24	General View		☒
109	17/01/19 14:24	General View		☒
110	17/01/19 14:24	General View		☒
111	17/01/19 14:24	General View		☒
112	02/04/19 14:16	Reinspection Photo		☒
113	02/04/19 14:16	Reinspection Photo		☒
114	02/04/19 14:16	Reinspection Photo		☒
115	02/04/19 14:16	Reinspection Photo		☒
116	02/04/19 14:16	Reinspection Photo		☒
117	02/04/19 14:16	Reinspection Photo		☒
118	02/04/19 14:16	Reinspection Photo		☒
119	02/04/19 14:16	Reinspection Photo		☒
120	02/04/19 14:16	Reinspection Photo		☒
121	02/04/19 14:16	Reinspection Photo		☒
122	02/04/19 14:16	Reinspection Photo		☒
123	02/04/19 14:16	Reinspection Photo		☒
124	02/04/19 14:16	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
125	02/04/19 14:16	Reinspection Photo		☒
126	02/04/19 14:16	Reinspection Photo		☒
127	02/04/19 14:16	Reinspection Photo		☒
128	02/04/19 14:16	Reinspection Photo		☒
129	02/04/19 14:16	Reinspection Photo		☒
130	02/04/19 14:16	Reinspection Photo		☒
131	02/04/19 14:16	Reinspection Photo		☒
132	02/04/19 14:16	Reinspection Photo		☒
133	02/04/19 14:16	Reinspection Photo		☒
134	02/04/19 14:16	Reinspection Photo		☒
135	02/04/19 14:16	Reinspection Photo		☒
136	02/04/19 14:16	Reinspection Photo		☒
137	02/04/19 14:16	Reinspection Photo		☒
138	02/04/19 14:16	Reinspection Photo		☒
139	02/04/19 14:16	Reinspection Photo		☒
140	02/04/19 14:16	Reinspection Photo		☒
141	02/04/19 14:16	Reinspection Photo		☒
142	02/04/19 14:16	Reinspection Photo		☒
143	02/04/19 14:16	Reinspection Photo		☒
144	02/04/19 14:16	Reinspection Photo		☒
145	02/04/19 14:16	Reinspection Photo		☒
146	02/04/19 14:16	Reinspection Photo		☒
147	02/04/19 14:16	Reinspection Photo		☒
148	02/04/19 14:16	Reinspection Photo		☒
149	02/04/19 14:16	Reinspection Photo		☒
150	02/04/19 14:16	Reinspection Photo		☒
151	02/04/19 14:16	Reinspection Photo		☒
152	02/04/19 14:16	Reinspection Photo		☒
153	02/04/19 14:16	Reinspection Photo		☒
154	02/04/19 14:16	Reinspection Photo		☒
155	02/04/19 14:16	Reinspection Photo		☒
156	02/04/19 14:16	Reinspection Photo		☒
157	02/04/19 14:16	Reinspection Photo		☒
158	02/04/19 14:16	Reinspection Photo		☒
159	02/04/19 14:16	Reinspection Photo		☒
160	02/04/19 14:16	Reinspection Photo		☒
161	02/04/19 14:16	Reinspection Photo		☒
162	02/04/19 14:16	Reinspection Photo		☒
163	02/04/19 14:16	Reinspection Photo		☒
164	02/04/19 14:16	Reinspection Photo		☒
165	02/04/19 14:16	Reinspection Photo		☒
166	02/04/19 14:16	Reinspection Photo		☒
167	02/04/19 14:16	Reinspection Photo		☒
168	02/04/19 14:16	Reinspection Photo		☒
169	02/04/19 14:16	Reinspection Photo		☒
170	02/04/19 14:16	Reinspection Photo		☒
171	02/04/19 14:16	Reinspection Photo		☒
172	02/04/19 14:16	Reinspection Photo		☒
173	02/04/19 14:16	Reinspection Photo		☒
174	02/04/19 14:16	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
175	02/04/19 14:16	Reinspection Photo	 Load JPG	☒
176	02/04/19 14:16	Reinspection Photo	 Load JPG	☒
177	02/04/19 14:16	Reinspection Photo	 Load JPG	☒
178	02/04/19 14:16	Reinspection Photo	 Load JPG	☒
179	02/04/19 14:16	Reinspection Photo	 Load JPG	☒
180	02/04/19 14:16	Reinspection Photo	 Load JPG	☒
181	02/04/19 14:16	Reinspection Photo	 Load JPG	☒
182	02/04/19 14:16	Reinspection Photo	 Load JPG	☒
183	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
184	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
185	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
186	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
187	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
188	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
189	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
190	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
191	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
192	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
193	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
194	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
195	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
196	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
197	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
198	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
199	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
200	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
201	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
202	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
203	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
204	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
205	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
206	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
207	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
208	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
209	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
210	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
211	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
212	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
213	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
214	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
215	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
216	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
217	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
218	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
219	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
220	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
221	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
222	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
223	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
224	02/04/19 14:17	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
225	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
226	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
227	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
228	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
229	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
230	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
231	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
232	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
233	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
234	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
235	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
236	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
237	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
238	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
239	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
240	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
241	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
242	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
243	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
244	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
245	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
246	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
247	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
248	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
249	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
250	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
251	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
252	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
253	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
254	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
255	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
256	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
257	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
258	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
259	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
260	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
261	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
262	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
263	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
264	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
265	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
266	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
267	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
268	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
269	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
270	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
271	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
272	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
273	02/04/19 14:17	Reinspection Photo	 Load JPG	☒
274	02/04/19 14:17	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
275	02/04/19 14:17	Reinspection Photo		☒
276	02/04/19 14:17	Reinspection Photo		☒
277	02/04/19 14:17	Reinspection Photo		☒
278	02/04/19 14:17	Reinspection Photo		☒
279	02/04/19 14:17	Reinspection Photo		☒
280	02/04/19 14:17	Reinspection Photo		☒
281	02/04/19 14:17	Reinspection Photo		☒
282	02/04/19 14:17	Reinspection Photo		☒
283	02/04/19 14:17	Reinspection Photo		☒
284	02/04/19 14:17	Reinspection Photo		☒
285	02/04/19 14:17	Reinspection Photo		☒
286	02/04/19 14:17	Reinspection Photo		☒
287	02/04/19 14:17	Reinspection Photo		☒
288	02/04/19 14:17	Reinspection Photo		☒
289	02/04/19 14:17	Reinspection Photo		☒
290	02/04/19 14:17	Reinspection Photo		☒
291	02/04/19 14:17	Reinspection Photo		☒
292	02/04/19 14:17	Reinspection Photo		☒
293	02/04/19 14:17	Reinspection Photo		☒
294	02/04/19 14:17	Reinspection Photo		☒
295	02/04/19 14:17	Reinspection Photo		☒
296	02/04/19 14:17	Reinspection Photo		☒
297	02/04/19 14:17	Reinspection Photo		☒
298	02/04/19 14:17	Reinspection Photo		☒
299	02/04/19 14:17	Reinspection Photo		☒
300	02/04/19 14:17	Reinspection Photo		☒
301	02/04/19 14:17	Reinspection Photo		☒
302	02/04/19 14:17	Reinspection Photo		☒
303	02/04/19 14:17	Reinspection Photo		☒
304	02/04/19 14:17	Reinspection Photo		☒
305	02/04/19 14:17	Reinspection Photo		☒
306	02/04/19 14:17	Reinspection Photo		☒
307	02/04/19 14:17	Reinspection Photo		☒
308	02/04/19 14:17	Reinspection Photo		☒
309	02/04/19 14:17	Reinspection Photo		☒
310	02/04/19 14:17	Reinspection Photo		☒
311	02/04/19 14:17	Reinspection Photo		☒
312	02/04/19 14:17	Reinspection Photo		☒
313	02/04/19 14:17	Reinspection Photo		☒
314	02/04/19 14:17	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/01/19 09:48	OD CONTACT		
2	16/01/19 09:48	ESTIMATE		
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	08/01/19 19:58	Sketch Plan [Linked Accident Report Documents]		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/19 14:26	ESTIMATE .pdf		
2	02/04/19 14:17	SUPPLEMENTARY.pdf		
3	05/04/19 13:33	ESTIMATE & SUPPLEMENTARY MARKED.pdf		

Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	08/01/19 19:59	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	08/01/19 19:58	Accident Photo		Load JPG	☒
2	08/01/19 19:58	Accident Photo		Load JPG	☒
3	08/01/19 19:58	Accident Photo		Load JPG	☒
4	08/01/19 19:58	Accident Photo		Load JPG	☒
5	08/01/19 19:58	Accident Photo		Load JPG	☒
6	08/01/19 19:58	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	08/01/19 19:58	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19000950/R1SD3E2

Date: 23/05/2019

REFERENCE

Insured/Claimant: LOW KOK SIONG Policy No: DMPCSN30927418022

Date of Loss: 08/01/2019 Nature of Claim: OD Claim No: SNM19D200267C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKG7315D**
Make & Model: PORSCHE CAYENNE, 3.0 (A) Engine No: C07686
Reg. Date: 16/03/2012 (Man. Year: 2011) Chassis No: WP1ZZZ92ZCLA06575
Colour: Black Odometer: 116751 km
Engine Capacity: 3598 cc
Market Value/New Car Price: S\$140,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/30Z R22 Rear Tyre Size: 295/30Z R22
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,991.41	37,651.68	2,339.73	5.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	32,490.00	19,270.00	13,220.00	40.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	72,481.41	56,921.68	15,559.73	21.47
- Excess (S\$)	3,500.00	3,500.00	0.00	0.00
(S\$)	68,981.41	53,421.68	15,559.73	22.56
+ GST 7.00/7.00% (S\$)	4,828.70	3,739.52	1,089.18	22.56
Nett Amount (S\$)	73,810.11	57,161.20	16,648.91	22.56

INSPECTION

Date of Assignment: 16/01/2019

Date Inspected: 16/01/2019 Inspected At:

Trans Eurokars Pte Ltd (HQ)
5 Ubi Close
Singapore 408605

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2019)
Parts:	M1-SUV	PORSCHE CAYENNE 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG7315D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Buckled	1,480.20 FL	*1,480.20 FL
2	1		*FRONT FENDER RH	Bent	1,480.20 FL	*1,480.20 FL
3	3		*LENS-HD SCREW FENDER LH	Necessary	4.80 FL	*4.80 FL
4	6		*EXPANSION RIVET	Necessary	13.20 FL	*13.20 FL
5	6		*CLIP	Necessary	11.40 FL	*11.40 FL
6	1		*FENDER BRACKET LH	Necessary	8.90 FL	*8.90 FL
7	5		*LENS-HEAD SCREW	Necessary	6.50 FL	*6.50 FL
8	1		*FENDER SUPPORT LH	Necessary	41.70 FL	*41.70 FL
9	1		*FRONT BUMPER	Deformed	1,174.80 FL	*1,174.80 FL
10	1		*SENSOR PARKASSIST (4PCS)	Not Working-2PCS ONLY	1,076.80 FL	*538.40 FL
11	4		*SENSOR GASKET	Necessary	18.00 FL	*18.00 FL
12	1		*BUMPER GARNISH CENTRE UPPER	Deformed	205.80 FL	*205.80 FL
13	1		*BUMPER GARNISH CENTRE LOWER	Deformed	205.80 FL	*205.80 FL
14	1		*BUMPER GRILLE	Deformed	194.80 FL	*194.80 FL
15	10		*EXPANSION RIVET	Necessary	5.00 FL	*5.00 FL
16	1		*FOAM PART	Cracked	73.00 FL	*73.00 FL
17	1		*HEADLAMP RETAINER LH (UNDER)	Cracked	43.50 FL	*43.50 FL
18	1		*HEADLAMP RETAINER RH (UNDER)	Cracked	43.50 FL	*43.50 FL
19	1		*BUMPER SIDE RETAINER LH	Necessary	43.50 FL	*43.50 FL
20	1		*BUMPER SIDE RETAINER RH	Necessary	43.50 FL	*43.50 FL
21	1		*AIR GUIDE COVER LH	Cracked	219.40 FL	*219.40 FL
22	1		*AIR GUIDE COVER RH	Cracked	219.40 FL	*219.40 FL
23	1		*BUMPER GRILLE SUPPORT LH	Cracked	123.20 FL	*123.20 FL
24	1		*BUMPER GRILLE SUPPORT RH	Cracked	123.20 FL	*123.20 FL
25	2		*FASTENING CLAMP BUMPER	Cracked	75.20 FL	*75.20 FL
26	1		*WATER DEFLECTOR AIR INLET LH	Cracked	35.50 FL	*35.50 FL
27	1		*GARNISH UPPER LH	Cut	59.10 FL	*59.10 FL
28	1		*GARNISH UPPER RH	Cut	59.10 FL	*59.10 FL
29	1		*GARNISH LOWER LH	Cut	59.10 FL	*59.10 FL
30	1		*GARNISH LOWER RH	Cut	59.10 FL	*59.10 FL
31	4		*EXPANSION RIVET	Necessary	6.00 FL	*6.00 FL
32	1		*FRONT BUMPER SPOILER	Cracked	712.10 FL	*712.10 FL
33	1		*FRONT NUMBER PLATE BRACKET	Missing	82.20 FL	*82.20 FL
34	6		*EXPANSION RIVET	Necessary	3.00 FL	*3.00 FL
35	1		*TOW COVER LH	Missing	70.70 FL	*70.70 FL
36	1		*TOW COVER RH	Missing	70.70 FL	*70.70 FL
37	1		*BUMPER REINFORCEMENT	Bent	1,256.40 FL	*1,256.40 FL
38	1		*REINFORCEMENT ADJUSTER LH	Bent	41.10 FL	*41.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REINFORCEMENT ADJUSTER RH	Bent	41.10 FL	*41.10 FL
40	1		*FRONT TOP SUPPORT PANEL	Cracked	567.50 FL	*567.50 FL
41	1		*TOP SUPPORT PANEL BRACKET (FRONT)	Cracked	117.50 FL	*117.50 FL
42	1		*LOCK CARRIER (FRONT)	Cracked	94.70 FL	*94.70 FL
43	1		*BONNET	Bent	3,690.60 FL	*3,690.60 FL
44	1		*BONNET HOOK UPPER	Serviceable	80.40 FL	*- FL
45	1		*BONNET HINGE LH	Serviceable	112.80 FL	*- FL
46	1		*BONNET HINGE RH	Serviceable	112.80 FL	*- FL
47	1		*BONNET CABLE FRONT	Cut	35.30 FL	*35.30 FL
48	1		*BONNET LOWER LOCK	Serviceable	201.40 FL	*- FL
49	2		*COMBINATION SCREW	Not Necessary	3.60 FL	*- FL
50	1		*COMBINATION SCREW	Not Necessary	1.30 FL	*- FL
51	1		*ENGINE TOP COVER RH	Cut	98.00 FL	*98.00 FL
52	1		*ENGINE TOP COVER LH	Serviceable	98.00 FL	*- FL
53	10		*EXPANSION RIVET	Necessary	22.00 FL	*22.00 FL
54	1		*ENGINE FRONT COVER	Cut	46.90 FL	*46.90 FL
55	1		*PORCHE EMBLEM	Necessary	248.60 FL	*248.60 FL
56	1		*EMBLEM SEAL	Necessary	12.40 FL	*12.40 FL
57	2		*HOOD BADGE NUT	Necessary	3.00 FL	*3.00 FL
58	2		*O-RING	Necessary	9.00 FL	*9.00 FL
59	2		*P955-572-094-00-/O RING	Necessary	9.60 FL	*9.60 FL
60	1		*CONDENSER	Bent	1,679.10 FL	*1,679.10 FL
61	1		*FENDER SUPPORT PANEL LH	Serviceable	267.40 FL	*- FL
62	1		*FENDER SUPPORT PANEL RH	Serviceable	267.40 FL	*- FL
63	1		*FENDER UPPER REINFORCEMENT LH	Bent	100.90 FL	*100.90 FL
64	1		*FENDER UPPER REINFORCEMENT RH	Bent	100.90 FL	*100.90 FL
65	1		*P000-043-204-85-/CAVITY PRESERVATION	Not Necessary	75.30 FL	*- FL
66	1		*FRONT BUMPER WIRING HARNESS	Cut	372.30 FL	*372.30 FL
67	1		*HORN (LOW-PITCH)	Not Working	129.70 FL	*129.70 FL
68	1		*HORN (HIGH-PITCH)	Not Working	95.20 FL	*95.20 FL
69	2		*HORN ADAPTER	Cracked	37.40 FL	*37.40 FL
70	1		*HORN SUPPORT (LOW-PITCH)	Bent	129.70 FL	*129.70 FL
71	1		*HORN SUPPORT (HIGH-PITCH) (NPA)	Serviceable	0.00 FL	*- FL
72	2		*HEXAGON NUT	Not Necessary	9.00 FL	*- FL
73	2		*HEXAGON-HEAD BOLT	Not Necessary	4.40 FL	*- FL
74	2		*HEADLAMP NOZZLE	Cracked	306.00 FL	*306.00 FL
75	1		*NOZZLE, HEADLAMP WASHER (LH)	Cut	55.20 FL	*55.20 FL
76	1		*NOZZLE, TRIM COVER LH	Missing	69.30 FL	*69.30 FL
77	8		*OVAL-HEAD SCREW	Necessary	5.60 FL	*5.60 FL
78	1		*NOZZLE, HEADLAMP WASHER (RH)	Cracked	55.20 FL	*55.20 FL
79	1		*NOZZLE, TRIM COVER RH	Missing	69.30 FL	*69.30 FL
80	8		*OVAL-HEAD SCREW	Necessary	5.60 FL	*5.60 FL
81	1		*P958-631-177-00-/HEADLAMP LH	Broken	3,267.10 FL	*3,267.10 FL
82	1		*P958-631-178-00-/HEADLAMP RH	Broken	3,267.10 FL	*3,267.10 FL
83	2		*HEADLAMP SUPPORT	Cracked	86.00 FL	*86.00 FL
84	1		*HEADLAMP MOUNTING LEVEL LH	Serviceable	313.10 FL	*- FL
85	1		*HEADLAMP MOUNTING LEVEL RH	Serviceable	313.10 FL	*- FL
86	1		*DIRECTION INDICATOR LIGHT LH	Not Working	79.50 FL	*79.50 FL
87	1		*DIRECTION INDICATOR LIGHT RH	Serviceable	79.50 FL	*- FL
88	1		*ADDITIONAL HEADLAMP LH	Broken	836.90 FL	*836.90 FL
89	1		*ADDITIONAL HEADLAMP RH	Broken	836.90 FL	*836.90 FL
90	2		*FOG LAMP	Cracked	804.60 FL	*804.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
91	1		*MOBIL 1 STICKER	Necessary	6.30 FL	*6.30 FL
92	1		*WARNING SIGN STICKER	Necessary	5.90 FL	*5.90 FL
93	2		*RADIATOR SECURE PIN	Necessary	6.20 FL	*6.20 FL
94	2		*RADIATOR SECURE PIN SLEEVE	Necessary	21.60 FL	*21.60 FL
95	2		*RADIATOR BUSHING UPPER	Necessary	18.60 FL	*18.60 FL
96	1		*RADIATOR SUPPORT UPPER RH	Necessary	12.00 FL	*12.00 FL
97	2		*ROUND HEAD SCREW	Necessary	4.80 FL	*4.80 FL
98	1		*RADIATOR FAN COWLING	Cracked	2,988.10 FL	*2,988.10 FL
99	1		*RADIATOR SUPPORT UPPER LH	Necessary	10.40 FL	*10.40 FL
100	2		*OVAL-HEAD SCREW	Necessary	2.20 FL	*2.20 FL
101	4		*PAN-HEAD SCREW	Necessary	18.00 FL	*18.00 FL
102	2		*RADIATOR SUPPORT LOWER	Necessary	54.20 FL	*54.20 FL
103	2		*RADIATOR BUSHING LOWER	Necessary	52.80 FL	*52.80 FL
104	1		*RADIATOR FRAME	Bent	365.90 FL	*365.90 FL
105	1		*COOLANT PIPE TOP	Serviceable	121.80 FL	*- FL
106	6		*P000-043-301-12-/ANTIFREEZE PROTECTION	Necessary	190.20 FL	*190.20 FL
107	1		*RADIATOR AIR GUIDE CENTRE	Cracked	284.00 FL	*284.00 FL
108	3		*EXPANSION RIVET	Necessary	6.60 FL	*6.60 FL
109	1		*SEALING WEDGE LH	Necessary	15.00 FL	*15.00 FL
110	1		*SEALING WEDGE RH	Necessary	15.00 FL	*15.00 FL
111	1		*GAITER RH	Necessary	58.00 FL	*58.00 FL
112	1		*INTAKE MANIFOLD PIPE LH	Bent	57.50 FL	*57.50 FL
113	1		*GAITER LH	Necessary	57.50 FL	*57.50 FL
114	1		*WINDOW CLEANER STICKER	Necessary	7.80 FL	*7.80 FL
115	1		*TRANSMISSION OIL COOLER	Bent	1,699.40 FL	*1,699.40 FL
116	2		*O RING OIL COOLER	Necessary	6.60 FL	*6.60 FL
117	1		*TRANSMISSION OIL TIPTRONIC	Bent	130.90 FL	*130.90 FL
118	1		*BRACKET WING LEFT	Bent	669.80 FL	*669.80 FL
119	1		*BRACKET WING RIGHT	Bent	669.80 FL	*669.80 FL
120	1		*P958-503-610-00-GRV/SUPPORT WING PRIME C	Bent	41.70 FL	*41.70 FL
121	1		*CONTROL UNIT HEADLAMP	Cut	1,499.70 FL	*1,499.70 FL
122	1		*RADIATOR	Bent	2,859.20 FL	*2,859.20 FL
123	1		*WATER HOSE COMPLETE RETURN	Cut	513.70 FL	*513.70 FL
124	1		*COOLING WATER TUBE	Cut	451.20 FL	*451.20 FL
125	1		*AIR CLEANER COMPLETE LEFT	Deformed	1,141.70 FL	*1,141.70 FL
126	1		*BELT ROLLER	Cut	303.00 FL	*303.00 FL
127	1		*OIL COOLER POWER STEERING	Bent	981.40 FL	*981.40 FL
128	1		*CHASSIS STICKER	Necessary	150.00 FS	*150.00 FS
129	1		*NUMBER PLATE WITH CASING	Missing	70.00 FS	*70.00 FS
130	1		*SUNDRIES	Necessary	50.00 FS	*50.00 FS
131	1		*AIR CONDITIONER STICKER	Necessary	11.80 FL	*11.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$) **44,404.90** **41,805.20**
 - List Item Discount on L Items 10.00/10.00% (S\$) **4,413.49** **4,153.52**

Total Parts (S\$) **39,991.41** **37,651.68**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE / REPLACE BONNET, FRONT BUMPER, LH / RH FRONT FENDER, LH / RH FENDER SUPPORT PANEL & TO REPAIR LH / RH FRONT DOORS AFFECTED BY THE ACCIDENT	New	18,720.00	9,360.00
2	TO RESPRAY BONNET, FRONT BUMPER, LH / RH FRONT FENDER, LH / RH FENDER SUPPORT PANEL & LH / RH FRONT DOORS	New	8,000.00	6,800.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	350.00	100.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	100.00
5	TO REMOVE & REPLACE FRONT SUPPORT PANEL, CONDENSER, RADIATOR & RADIATOR FAN ASSY	New	3,120.00	1,560.00
6	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM	New	500.00	300.00
7	TO TRANSFER THE PARKING SENSORS	New	500.00	0.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	200.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
10	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP	New	250.00	250.00
Gross Labour Cost (S\$)			32,490.00	19,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >