

ASS. REC. BY:

REF: es/smo19000953/Asd3/12

Special Instruction:

Surveyor:

Meimen

ASSIGNMENT (Office)

From (Person):

Thelma Choo

of

SMO

Date/Time: 15/1/19 @ 4.44pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKD 5453S

Insured:

SLF 2034R

at Workshop m/s

Premium Carz

Tel:

6636 9100

of

1 Kaki Bukit Ave 6 # 01-90 Autobay

Policy No:

D18MTPV01014187

Claim No:

CMTD1900346

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/01/2019

CA / REV. / REP. / REV 24 HRS

up

17/01/19 @ 12.45pm-1.30pm ow

H.O.D. Endorsement:

Date/Time:

9.46am @ 16/1/19

Person Contacted:

An fong

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKD 5453S-X

SLF 2034R-X

18/01/19

@ 17:43 p.m. revert pending estimate from repairs to Thelma via meimen.

REF: SMO

ASSIGNMENT

From: Date: 17/01/2019

Estimated Cost:

OD: ☒ WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: 8KD 5453S
at Workshop m/s: Premium Carz
of: 1 kaki Bukit Ave 6 # 01-90

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

12-45pm - 1-30pm
owner waiting

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS / up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SKD5453S Yr Regn: 2011 Reg

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180 c.c. 1597.

Colour: Red. A/C: Insured / Std / NI / NA

Sp. Reading: 119782. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2042452A-601669

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size: F: 215/60R17.

R: 215/60R17

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 17/01/19.

Survey held at: Premium Carz.

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Samps.

final fig \$250 (Red, \$288.20, 54%)

RECEIVED 14 FEB 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 14/2 - typst

Days Of Repair: 1

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Other:

) TOTAL

Report Format:

Lump Sum / I.B.I. \$ \$250/-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

250
10

260

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 11 Feb 2019

Preliminary Advice

Insured Vehicle No	: SLF2034R	Accident Date	: 13/01/2019
TP Vehicle No	: SKD5453S	Assignment Date	: 15/01/2019
Make	: MERCEDES-BENZ C180	Est. Duration of Repair	: 1 day
Date of Inspection	: 17/01/2019		
Inspection At	: PREMIUM CARZ SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	538.20
Revised Amount	:S\$	250.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	250.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☒ Other comments :The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2019		15 Jan 2019 16:44 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	C SUTHAKARAN S/O CHATU, ID: S2624679B		
Main Claimant:	OUK TRANSPORTATION, Co. Reg. No.: 5336164S8		
Vehicle Reg. No.:	SKD5453S	Date of Loss:	13/01/2019 22:00 - :59
Claim Type:	TP / CMTD1900340	Policy/Cover Note No.:	D18MTPV01014187 (Comprehensive)
Vehicle Reg. No. (Insured):	SLF2034R	Policy No. (Claimant):	
		Excess:	
Repairer:	Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki, 417883 Kaki Bukit - Tel: 66369100		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/01/2019]		
Adj Asg. Remarks:	-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SKD5453S (CMTD1900340)
[SLF2034R]**

TP

OUK TRANSPORTATION
Jan 13 2019 10:00PM
[C SUTHAKARAN S/O CHATU]
Premium Carz Services Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 18/01/2019 17:43 PM.
To thelma.choo@sompo.com.sg
CC sur@lkkauto.com
Subject SKD5453S (CMTD1900340) [SLF2034R] TP

Fastech Auto Pte Ltd

Dear Thelma,

Please be informed that we have inspected the vehicle SKD 5453S on 17/01/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

Premium Carz
Co. Reg. No. 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel: 6636 9100 Fax: 6636 9113

Date: 14/01/2018

TO: Somp Insurance (Singapore) Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Our Customer: Ouk Transportation
Vehicle No: SKD54535
Model: Mercedes Benz C180
Manufacture Year: 2011
Date of Accident: 13/01/2019
Total Estimate Repair Days: 2
Total Pages: 1

Attn: Motor Claims Department
Fax: 6221 3147

Re: Repair Estimate For Third Party Claim against SLF2034R

No.	Item Descriptions	Qty	Unit Price	Amount	
A.	Spare Parts				
1	Rear door RH <i>Repair</i>	1	repair	repair	+
2	Rear door chrome RH <i>bea</i>	1	\$98.00	\$98.00	+
	Sub-Total			\$98.00	
	Less 10%			\$9.80	
	Total for Parts			\$88.20	
B.	Labour				
1	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$200.00	x
2	Spray painting all affected parts & areas.			\$250.00	✓
	Total Labour			\$450.00	
	Total Repair Cost			\$538.20	

Admin
P/p 17/01/19
or P/p
P/p \$250.

Yours faithfully,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Aun Teng

f Premium Carz Services Pte Ltd

Surveyor's Details

Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19000953/ASD3N2

Date: 14/02/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01014187
Claimant Vehicle No :	SKD5453S	Insured Vehicle No :	SLF2034R
Date of Loss:	13/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900340

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD5453S	Engine No:	27191031347460
Make & Model:	MERCEDES-BENZ C180, 1.6 (A)	Chassis No:	WDD2040452A601669
Reg. Date:	14/12/2011 (Man. Year: 2011)	Odometer:	119782 km
Colour:	Red		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	88.20	0.00	88.20	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	450.00	250.00	200.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	538.20	250.00	288.20	53.55

INSPECTION

Date of Assignment:	15/01/2019	
Date Inspected:	17/01/2019	Inspected At: Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Singapore 417883

Estimated Period of Repair: 1.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2019)
Parts: 143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD5453S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH (NPA)	Repair	0.00 FL	*- FL
2	1		*REAR DOOR CHROME RH	Not Necessary	98.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					98.00	0.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					9.80	0.00
Total Parts (\$\$)					88.20	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	200.00	-
2	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	250.00	250.00
Gross Labour Cost (\$\$)			450.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >