

INS. CASE OWNER:

CC

4, upc

1900

0968

D pa3n2

LKK:

IDAC:

ASSIGNMENT

Surveyor:

AUST

DOI:

12/1/19

Date / Time:

15/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GABA 6913Y

Name of Insured:

KIANTEEN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 12/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKC 6454M



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kurz work
Kurz work
Kurz work

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

23/1/19
CHSKC 6454M - C63/M56/15013247 / upbdl: 00A 314/13
GABA 6913Y - N41/M213006360/M27: 00A 314/13

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

10/4/19

FILE PASS TO BRYAN TO FINALISE

18/04/19

Jenny 2/3 4000 - with 6 days of
repair
Driver reported steering problem??

18/4/19

FILE PASS TO TYPE MANDATE

10/7/19

FILE PASS TO HMK TO CLOSE

* All 21 doc signed by owner / driver ?

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

21

Repair Cost:

SS 4000.00

Loss of Rental (LOR):

SS 460.00

(

8 days)

x \$120

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 7.45

Medical:

SS -

Disbursement:

SS -

Legal Cost

SS -

(e.g. Tow/ Independent)

Total:

SS 4967.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 4967.45

Name 1:

Kurz Works Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP \$450

CH 10/7/19

CBE 2022 May
2007 May

Year/Plat *2004* / *MA*
 Type *Van* / Cycle / Bus / Van / Heavy / Light / Prime Mover /
 Truck / Trailer or
 Make *Mitsubishi Lene* Year *1584*
 Color *Gray* Ad. Insured / Std / NI / NA
 Cap. Loading *267969* T/A. Ldr. Insured / Std / NI / NA
 Equip. No. *4G18JB2857*
 Chassis *JMYSTCS3A7U011674*
 Gen. Cond. *Good* / Fair / Poor / Burnt
 Steering *Good* / Jammed / Leaked / Burnt or
 Brake *Good* / Jammed / Leaked / Burnt or
 Model *HL 1584* / STD / ARNm or

14%	0%	

Type Size E: 205/45 R16
 R: — 11 —
 B5 / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
 TOYO / YOKO or LingLong
 Front Rear
 R/Bal S mm R/Bal S mm
 S mm L/Bal S mm
 D.O.A. 12/01/2019 D.O.I. 17/01/2019
 Survey held at Teamwork Page ubi

0/3 Front

Longac GBA 6913.Y

MV 21K
L7A 16.7K
WL 4.3K

Insured reported steering
issue??

R/s - \$4000 (real \$4997.80 / 46%)

☐ : Prelim. Report
☐ : Final Report

Resurvey No. of Trip:

Temperature in

E-mail: Stan.H.Hof@tue.nl

Add Fee:	<input type="text"/>	Sale Inq:	<input type="text"/>
	<input type="text"/>	Info Inq:	<input type="text"/>
	<input type="text"/>	Fee Inq:	<input type="text"/>
	<input type="text"/>	MC, C, and	<input type="text"/>

Acknowledgements



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/19/19/VC05/021322
Our ref: CC4/LPC19000968/Dpa3

Date: 18/01/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKC 6454M


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/01/2019 at the premises of M/s Teamwork Garage Pte Ltd - Ubi and have the following to report:-

Workshop Estimate Amount	: S\$	10,883.50
Revised Estimate Amount	: S\$	4,203.30
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	4,203.30
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
O/S Front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

ANG BRYAN TANI
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0114G

Vehicle Details

Vehicle No.: SKC6454M

Vehicle to be Exported: Yes

Intended Deregistration Date: 12 Jan 2019

Vehicle Make: MITSUBISHI

Vehicle Model: LANCER 1.6 A

Primary Colour: Grey

Manufacturing Year: 2007

Engine No.: 4G18JB2857

Chassis No.: JMYSTCS3A7U011674

Maximum Power Output: 79.0 kW (105 bhp)

Open Market Value: \$12,130.00

Original Registration Date: 07 May 2007

First Registration Date: 07 May 2007

Transfer Count: 2

Actual ARF Paid: \$12,833.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 06 May 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$25,333.00

COE Rebate Amount: \$16,801.00

Total Rebate Amount: \$16,801.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Jan 2019

OK

TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
 3RD PARTY CLAIM ESTIMATION

LONPAC INSURANCE BHD
 300 BEACH ROAD
 07 THE CONCOURSE, #17-04
 SINGAPORE 199555


Vehicle number	SKC6454M
Make / Model	MITSUBISHI/LANCER
Chassis number	JMYSTCS3A7U011674
Accident date	12 January 2019
Reference	KM1901-40

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER <i>crack</i>	710.00 ✓
2	FRONT BUMPER SIDE BEAM <i>hit</i>	60.00 X
1	FRONT BUMPER REINFORCEMENT <i>metal Dented</i>	239.00 ✓
1	FRONT BUMPER LOWER LIP <i>crack / cut</i>	653.00 ✓
1	FRONT BUMPER GRILLE BASE <i>hit</i>	159.00 X
1	FRONT BUMPER GRILLE MESH <i>hit</i>	67.00 X
1	FRONT BUMPER LOWER GARNISH MOULDING <i>hit</i>	38.00 X
1	FRONT BUMPER LOWER INNER GARNISH <i>hit</i>	78.00 X
1	FRONT RH FOG LAMP COVER <i>2x hit mounting deformed</i>	58.00 ✓
1	FRONT BUMPER FOG LAMP RH <i>2x hit mounting</i>	579.00 ✓
1	FRONT GRILLE EMBLEM <i>hit</i>	49.00 X
1	FRONT SUPPORT PANEL <i>hit</i>	675.00 X
1	FRONT RH HEADLAMP <i>Scratched / broken</i>	636.00 ✓
1	FRONT RH FENDER <i>Dented</i>	561.00 ✓
1	FRONT RH FENDER INNER SHIELD <i>hit</i>	101.00 ✓
1	AIRCON CONDENSER <i>hit</i>	1219.00 X
1	RADIATOR <i>hit</i>	931.00 X
1	AIRCON SUCTION PIPE <i>hit</i>	176.00 X
1	AIRCON DISCHARGE PIPE <i>hit</i>	190.00 X
1	FRONT RH SHOCK ABSORBER <i>hit disturbed</i>	695.00 ✓
1	FRONT RH KNUCKLE ARM <i>hit disturbed</i>	390.00 ✓
1	FRONT RH KNUCKLE BEARING <i>hit Dam</i>	159.00 X ✓
1	FRONT RH LOWER ARM <i>hit disturbed</i>	392.00 X ✓
		8815.00
Less 10 %		881.50
Subtotal		7933.50
Balance C/F		7933.50
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		7933.50
1 SET	FRONT BUMPER CLIP <i>hit</i>	50.00 30/-
1 SET	FRONT FENDER INNER SHIELD CLIP <i>hit</i>	30.00 20/-
1 BOT	COOLANT <i>hit</i>	60.00 X
1	RIM <i>hit rim</i>	600.00 X X
1 BOT	BRAKE FUIID <i>hit</i>	50.00 X
Subtotal		790.00
Balance C/F		8723.50

5173.00
 4655.70

50.00

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	8723.50
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	60.00 30/-
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	150.00 Hk
4	CHECK FRONT WHEEL ALIGNMENT	150.00 Hk
5	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	150.00 60/-
6	PANEL BEATING ON AFFECTED AREAS	200.00 150/-
7	SPRAY PAINTING ON AFFECTED AREAS	1200.00 500/-
8	APPLY ANTI RUST ON AFFECTED AREAS	450.00 400/-
		100.00 40/-
	17/01/2019 @ 1130hrs	
	Not Author	
	1180.00	
	Subtotal	2160.00
	Grand total	10883.50

2/5mm 6 day.

 LKk Adv

Repair Unit 4K.

5885.70
 2/5 4,000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 15 January 2019 4:07 PM
To: dARREN; MT_Claim_SG; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Subject: RE: Our Ref: 18/19/19/VC05/021322 RE: OUR REF ; KM1901-40 // YOUR REF : GBA6913A ACCIDENT INVOLVING GBA6913A AND SKC6454M
Attachments: 20190114143258484.pdf

Without Prejudice


Dear Sir

Thank you for your confirmation on the appointment of a Single Joint Expert.

Dear Catherine/Nivitha

Please arrange Bryan Ang to conduct TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: dARREN [mailto:karzworkspl.sg@gmail.com]
Sent: Tuesday, 15 January, 2019 4:04 PM
To: ONG LI LI; MT_Claim_SG
Cc: 'KARZ WORKS PTE LTD'
Subject: RE: Our Ref: 18/19/19/VC05/021322 RE: OUR REF ; KM1901-40 // YOUR REF : GBA6913A ACCIDENT INVOLVING GBA6913A AND SKC6454M
Importance: High

Dear Sir,

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK - BRYAN ANG

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

*Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop

From: ONG LI LI [mailto:long@lonpac.com]

Sent: Tuesday, January 15, 2019 3:47 PM

To: dARREN <karzworkspl.sg@gmail.com>; MT_Claim_SG <mt_claim@lonpac.com>

Subject: Our Ref: 18/19/19/VC05/021322 RE: OUR REF ; KM1901-40 // YOUR REF : GBA6913A ACCIDENT INVOLVING GBA6913A AND SKC6454M

Without Prejudice

Save as to Costs

Dear Darren

Our Insured vehicle no. should be GBA6913Y.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: dARREN [<mailto:karzworkspl.sg@gmail.com>]

Sent: Tuesday, 15 January, 2019 3:14 PM

To: MT_Claim_SG

Cc: 'KARZ WORKS PTE LTD'

Subject: RE: OUR REF ; KM1901-40 // YOUR REF : GBA6913A ACCIDENT INVOLVING GBA6913A AND SKC6454M

Importance: High

WITHOUT PREJUDICE

Dear Sir,

REMINDER

Please let us have a list of surveyor to proceed with PRI

From: karz [<mailto:karzworkspl.sg@gmail.com>]

Sent: Monday, January 14, 2019 2:36 PM

To: mt_claim@lonpac.com

Cc: karzworkspl.sg@gmail.com

Subject: OUR REF ; KM1901-40 // YOUR REF : GBA6913A ACCIDENT INVOLVING GBA6913A AND SKC6454M

WITHOUT PREJUDICE

OUR REF ; KM1901-40 // YOUR REF : GBA6913A

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SKC6454M

ACCIDENT INVOLVING GBA6913A AND SKC6454M

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction – Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Mei Kwan (LKKAuto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 22 January, 2019 1:00 PM
To: Mei Kwan (LKKAuto)
Cc: MT_Claim_SG; Admin A; CS A Team; Hsiao Tong (LKKAuto)
Subject: RE: Our Ref: 18/19/19/VC05/021322 RE: OUR REF ; KM1901-40 // YOUR REF : GBA6913Y ACCIDENT INVOLVING GBA6913A AND SKC6454M
Attachments: GBA6913Y 120119 (2).PDF

Follow Up Flag: Follow up
Flag Status: Completed


Categories: HMK

Dear Mei Kwan

Please see attached for our Insured's GIA report.

Kindly take note of our correct vehicle no.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 22 January, 2019 10:23 AM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A; CS A Team; Hsiao Tong (LKKAuto)
Subject: RE: Our Ref: 18/19/19/VC05/021322 RE: OUR REF ; KM1901-40 // YOUR REF : GBA6913A ACCIDENT INVOLVING GBA6913A AND SKC6454M

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 18/19/19/VC05/021322
LKK REF: CC4/LPC19000968/Dpa3

Dear Sir / Madam,

We refer to the above matter.


Enclosed revert of vehicle: SKC 6454M

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: dARREN [<mailto:karzworkspl.sg@gmail.com>]

Sent: Tuesday, 15 January, 2019 4:04 PM

To: ONG LI LI; MT_Claim_SG

Cc: 'KARZ WORKS PTE LTD'

Subject: RE: Our Ref: 18/19/19/VC05/021322 RE: OUR REF ; KM1901-40 // YOUR REF : GBA6913A ACCIDENT INVOLVING GBA6913A AND SKC6454M

Importance: High

Dear Sir,

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK - BRYAN ANG

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

*Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop

From: ONG LI LI [<mailto:long@lonpac.com>]

Sent: Tuesday, January 15, 2019 3:47 PM

To: dARREN <karzworkspl.sg@gmail.com>; MT_Claim_SG <mt_claim@lonpac.com>

Subject: Our Ref: 18/19/19/VC05/021322 RE: OUR REF ; KM1901-40 // YOUR REF : GBA6913A ACCIDENT INVOLVING GBA6913A AND SKC6454M

Without Prejudice

Save as to Costs

Dear Darren

Our Insured vehicle no. should be GBA6913Y.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
-----	------	---------------

WITHOUT PREJUDICE

OUR REF ; KM1901-40 // YOUR REF : GBA6913A

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SKC6454M
ACCIDENT INVOLVING GBA6913A AND SKC6454M

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction – Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Tuesday, 9 July 2019 3:30 PM
To: Keith Lian; karzworkssg@gmail.com
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: Your Ref: SKC6454M *Our Ref: CC4/LPC19000968/Dpa3q2[ACCIDENTINVOLVING GBA6913Y & SKC6454M ON 12/01/2019]
Attachments: DV.pdf

Without Prejudice

Dear Keith,

As spoken, DV re-send.

Thank you.

Best Regards,

Carlur Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jia Le (LKK Auto)
Sent: Thursday, 27 June 2019 3:51 PM
To: 'Keith Lian'; karzworkssg@gmail.com
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: Your Ref: SKC6454M *Our Ref: CC4/LPC19000968/Dpa3q2[ACCIDENTINVOLVING GBA6913Y & SKC6454M ON 12/01/2019]

Without Prejudice

Dear Keith,

Apologies for the late reply.

Attached herewith the DV and return the original to us once you signed.

Thank you.

Best Regards,

Carlur Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Keith Lian [<mailto:karzworks.sg@gmail.com>]
Sent: Friday, 21 June 2019 3:31 PM
To: Jia Le (LKK Auto); karzworkssg@gmail.com
Cc: Hsiao Tong (LKKAuto); Admin A

Subject: RE: Your Ref: SKC6454M *Our Ref: CC4/LPC19000968/Dpa3q2[ACCIDENTINVOLVING
GBA6913Y & SKC6454M ON 12/01/2019

WITHOUT PREJUDICE

Dear sir ,

We would like to remind you guys that we have yet to receive the DV for this matter.

Please let us have your most favourable DV soonest.

Thank you and have a nice day.

Sent from Mail for Windows 10

From: Keith Lian

Sent: Friday, 31 May 2019 11:01 AM

To: Jia Le (LKK Auto); karzworkssg@gmail.com

Cc: Hsiao Tong (LKKAuto); Admin A

Subject: RE: Your Ref: SKC6454M *Our Ref: CC4/LPC19000968/Dpa3q2[ACCIDENTINVOLVING
GBA6913Y & SKC6454M ON 12/01/2019

WITHOUT PREJUDICE

Dear sir ,

We refer to your offer stated below , it is acceptable.

Please let us have your most favorable DV soonest.

Thank you and have a nice day.

Sent from Mail for Windows 10

From: Jia Le (LKK Auto)

Sent: Thursday, 30 May 2019 5:12 PM

To: karzworkssg@gmail.com

Cc: Hsiao Tong (LKKAuto); Admin A

Subject: Your Ref: SKC6454M *Our Ref: CC4/LPC19000968/Dpa3q2 [ACCIDENTINVOLVING
GBA6913Y & SKC6454M ON 12/01/2019

Without Prejudice

Dear Sir/Mdm,

We refer to the above matter.

We confirm settlement as follows: -

1. Cost of Repair	\$ 4,000.00
2. Loss of Rental (8days x \$120)	\$ 960.00
3. LTA/GIA Search Fee	\$ 7.45
TOTAL	\$ 4,967.45

Please confirm acceptance.

“Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.”

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

KARZ WORKS PTE LTD

53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

(TEL) 68445934 (FAX) 68442474 (E-MAIL) KARZWORKSSG@GMAIL.COM

LETTER OF AUTHORITY

Dear Sirs,

ACCIDENT INVOLVING MOTOR VEHICLES NO SKC6454M & GBA6913Y ALONG
Exit of YM70 towards Main Road ^{of Yishun Ave 4} ON 12/01/19

I hereby authorize you to release the sum of \$ _____ being the settlement sum for my
property damage claim only to my solicitors _____.

Yours faithfully,



Owner's signature/Company stamp (If applicable)

Name:

NRIC/FIN/UEN No:

KARZ WORKS PTE LTD

53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

(TEL) 68445934 (FAX) 68442474 (E-MAIL) KARZWORKSSG@GMAIL.COM

MOTOR CLAIM DISCHARGE

X

INSURED: AXA
VEHICLE REG NO: SKC 6454 M
ACCIDENT CLAIM NO: _____
POLICY NO: GA350233

I/We acknowledged that I/we have taken the delivery of the Vehicle stated above from the repairers.

All repairs necessary as a result of the accident in which the said vehicle was involved in have been completed to my/our satisfaction and that E/we have no further claim on the above company in respect thereof.

Date & Time of collection: 25/01/19 @ 1800

Am

Owner's signature (Company stamp if applicable)

Name:

NRIC No:

KARZ WORKS PTE LTD, Stamp and signature

Name:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19000968/Dpa3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 16-08-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 6913Y	Veh. Inspected	SKC 6454M	
Policy No.	Z18V0500081	Coverage (\$)	0.00	
Claim No.	18/19/19/VC05/021322	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	15/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JMYSTCS3A7U011674	Colour	GREY	
Odometer	267969	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R16	LING LONG	5 mm	
L/H Front Tyre	205/45 R16	LING LONG	5 mm	
R/H Rear Tyre	205/45 R16	LING LONG	5 mm	
L/H Rear Tyre	205/45 R16	LING LONG	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/01/2019	Inspection Date	17/01/2019	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 6454M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CRACKED	710.00	710.00
2	FRONT BUMPER SIDE BEAM	NOT NECESSARY	60.00	-
1	FRONT BUMPER REINFORCEMENT	DENTED	239.00	239.00
1	FRONT BUMPER LOWER LIP	CRACKED / CUT	653.00	653.00
1	FRONT BUMPER GRILLE BASE	NOT NECESSARY	159.00	-
1	FRONT BUMPER GRILLE MESH	NOT NECESSARY	67.00	-
1	FRONT BUMPER LOWER GARNISH MOULDING	NOT NECESSARY	38.00	-
1	FRONT BUMPER LOWER INNER GARNISH	NOT NECESSARY	78.00	-
1	FRONT RH FOG LAMP COVER	MOUNTING DEFORMED	58.00	58.00
1	FRONT BUMPER FOG LAMP RH	MOUNTING BENT	579.00	579.00
1	FRONT GRILLE EMBLEM	NOT NECESSARY	49.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	675.00	-
1	FRONT RH HEADLAMP	SCRATCHED / BROKEN	636.00	636.00
1	FRONT RH FENDER	DENTED	561.00	561.00
1	FRONT RH FENDER INNER SHIELD	TORN	101.00	101.00
1	AIRCON CONDENSER	NOT NECESSARY	1,219.00	-
1	RADIATOR	NOT NECESSARY	931.00	-
1	AIRCON SUCTION PIPE	NOT NECESSARY	176.00	-
1	AIRCON DISCHARGE PIPE	NOT NECESSARY	190.00	-
1	FRONT RH SHOCK ABSORBER	DISTORTED	695.00	695.00
1	FRONT RH KNUCKLE ARM	DISTORTED	390.00	390.00
1	FRONT RH KNUCKLE BEARING	DAMAGED	159.00	159.00
1	FRONT RH LOWER ARM	DISTORTED	392.00	392.00
	LESS 10% DISCOUNT		-881.50	-517.30
			7,933.50	4,655.70
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	30.00	20.00
1	BOT COOLANT (SN)	NOT NECESSARY	60.00	-

Report Ref No. CC4/LPC19000968/Dpa3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RIM (SN)	TO REPAIR SEE LABOUR	600.00	-
1	BOT BRAKE FULD (SN)	NOT NECESSARY	50.00	-
			790.00	50.00
	LABOUR			
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE,RENEW CONDENSER AND TOP UP GAS.	NOT NECESSARY	150.00	-
	REMOVE ,RENEW RADIATOR AND TOP UP COOLANT.	NOT NECESSARY	150.00	-
	CHECK FRONT WHEEL ALIGNMENT.		150.00	60.00
	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS.		200.00	150.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF RIM.		1,200.00	500.00
	SPRAY PAINTING ON AFFECTED AREAS.		450.00	400.00
	APPLY ANTI RUST ON AFFECTED AREAS.		100.00	40.00
			2,460.00	1,180.00
GRAND TOTAL			11,183.50	5,885.70
RECOMMENDED COST OF REPAIR SUM				4,000.00

Report Ref No. CC4/LPC19000968/Dpa3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.