

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

3RD PARTY CLAIM ESTIMATION

LONPAC INSURANCE BHD
300 BEACH ROAD
07 THE CONCOURSE, #17-04
SINGAPORE 199555

Vehicle number	SKC6454M
Make / Model	MITSUBISHI/LANCER
Chassis number	JMYSTCS3A7U011674
Accident date	12 January 2019
Reference	KM1901-40

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER <i>crack</i>	710.00 ✓
2	FRONT BUMPER SIDE BEAM <i>W/L</i>	60.00 X
1	FRONT BUMPER REINFORCEMENT <i>not needed</i>	239.00 ✓
1	FRONT BUMPER LOWER LIP <i>crack / cut</i>	653.00 ✓
1	FRONT BUMPER GRILLE BASE <i>W/L</i>	159.00 X
1	FRONT BUMPER GRILLE MESH <i>W/L</i>	67.00 X
1	FRONT BUMPER LOWER GARNISH MOULDING <i>W/L</i>	38.00 X
1	FRONT BUMPER LOWER INNER GARNISH <i>W/L</i>	78.00 X
1	FRONT RH FOG LAMP COVER <i>2x 1st mounting deformed</i>	58.00 ✓
1	FRONT BUMPER FOG LAMP RH <i>2x 1st mounting</i>	579.00 ✓
1	FRONT GRILLE EMBLEM <i>W/L</i>	49.00 X
1	FRONT SUPPORT PANEL <i>W/L</i>	675.00 X
1	FRONT RH HEADLAMP <i>Scratched / broken</i>	636.00 ✓
1	FRONT RH FENDER <i>Deformed</i>	561.00 ✓
1	FRONT RH FENDER INNER SHIELD <i>trim</i>	101.00 ✓
1	AIRCON CONDENSER <i>W/L</i>	1219.00 X
1	RADIATOR <i>W/L</i>	931.00 X
1	AIRCON SUCTION PIPE <i>W/L</i>	176.00 X
1	AIRCON DISCHARGE PIPE <i>W/L</i>	190.00 X
1	FRONT RH SHOCK ABSORBER <i>W/L</i>	695.00 X
1	FRONT RH KNUCKLE ARM <i>W/L</i>	390.00 X
1	FRONT RH KNUCKLE BEARING <i>W/L</i>	159.00 X
1	FRONT RH LOWER ARM <i>W/L</i>	392.00 X
		8815.00
Less 10 %		881.50
Subtotal		7933.50
Balance C/F		7933.50
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		7933.50
1 SET	FRONT BUMPER CLIP <i>W/L</i>	50.00 <i>30/-</i>
1 SET	FRONT FENDER INNER SHIELD CLIP <i>W/L</i>	30.00 <i>20/-</i>
1 BOT	COOLANT <i>W/L</i>	60.00 X
1	RIM <i>W/L</i>	600.00 X
1 BOT	BRAKE FULID <i>W/L</i>	50.00 X
Subtotal		790.00
Balance C/F		8723.50

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	8723.50
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	150.00 H/H
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	150.00 H/H
4	CHECK FRONT WHEEL ALIGNMENT	150.00 H/H
5	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	200.00 H/H
6	PANEL BEATING ON AFFECTED AREAS	1200.00 500/-
7	SPRAY PAINTING ON AFFECTED AREAS	450.00 400/-
8	APPLY ANTI RUST ON AFFECTED AREAS	100.00 40/-
17/01/2019 @ 1130hrs		
N/A		
Subtotal		2160.00
Grand total		10883.50

2/Sum 4 day.
 3 ngs
 LKK Adv
 8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modifications is allowed
- Surveyor to be present during resurvey and