

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0074/2019/NK
Date : 16-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no: SLW 9285 Y

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Ms Chan Yuen Mun
Address : Blk 23 Yishun St 51
#04-07 Signature @ Yishun
Singapore 768086
Telephone : (HP) + 65 81271358
Type of Claim : Third Party Claims
Policy No. : 1700055222-01
Vehicle No : **SLS 4422 Y**
Model Code : A3 SEDAN 1.0 TFSI
Model / Year : Sep-17
Engine No : CHZ 528845
Chassis No : WAUZZZ8V9J1013081
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Jan-19
Place of Accident : CTE Towards AYE Before AMK 3 Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 4422 Y

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00 600
3	To respray rear bumper.	\$ 800.00 600
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 2,172.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 4422 Y

S/N Parts Description		Damaged Parts & Prices S/Nett	
1	REAR BUMPER <i>beh d</i>	\$	1,793.00 ✓
2	STICKY PAD <i>nen</i>	4 \$	21.00 ✗
3	REAR BUMPER FIXING SETS <i>nen</i>	\$	175.00 +
4	WHEEL HOUSING LINERS ADAPTER LH / RH <i>2 ne</i>	2 \$	68.00 ✗
5	REAR BUMPER GUIDE SECTION LH / RH <i>2 ne</i>	2 \$	30.00 ✗
6	LOCKING MECHANISM <i>nen</i>	2 \$	53.00 ✗
7	REAR BUMPER SPOILER <i>at</i>	\$	216.00 ✓
8	REAR LIGHT REFLECTOR RH <i>2 ne</i>	\$	38.00 ✗
9	REAR BUMPER REINFORCEMENT <i>2 ne</i>	\$	522.00 ✗
10	REAR BUMPER BRACKET LH / RH	2 \$	51.00 ✗
11	REAR BUMPER GUIDE SECTION LH / RH <i>2 ne</i>	2 \$	120.00 ✗
12	REAR BUMPER SENSOR INNER/ OUTER	2 \$	462.00 ✗
13	SEAL RINGS <i>nen</i>	4 \$	12.00 ✗
14	SUNDRIES <i>7</i>	\$	300.00 7
TOTAL SPARE PARTS CHARGES		:	\$ 3,861.00
TOTAL LABOUR CHARGES			\$ 2,172.00
GRAND TOTAL			\$ 6,033.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 22/01/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

Please Note

: This estimate is based on visual inspection of the affected
Should we require further labour charges and spare parts
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant