

13/02/2019

INS. CASE OWNER:

CC 3/AIG1900 6970, Kpb352

LKK:

IDAC:

Surveyor:

Kennech

DOI:

ASSIGNMENT

15/1/19

Date / Time:

15/1/19

Registered in Merimen:

16/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUB 6383 C

Claim No.:

927809000150

Name of Insured:

Mingwah Wah Nam (A) DAWIBL KE

Policy No.:

NOV461549-07

Insured Tel No.:

HP:

Make / Model:

Audi

Excess Sec II :\$S

D.O.A.:

11/1/19

Place of Accident:

Penang Rd.

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Mingwah

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SUB 9852R



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans
Cub

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

11/1/19
MT9169x42R - 44 (Mingwah) 2034/Kpb3 08.00/1/19
0166356C-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE: 18/1/19 UEMA

After call ltr to OE: 18/1/19 (Email)

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

\$S

changing lane

Loss of Rental (LOR):

\$S

(days)

Loss of Use (LOU):

\$S

(\$ x days)

Loss of Income (LOI):

\$S

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

\$S

Medical:

\$S

Disbursement:

\$S

(e.g. Tow/ Independent)

Legal Cost

\$S

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$S

Global Sum \$S:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$S

Name 1:

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

COPY SENT
11/1/19ah
14/1/19

ASS. REC. BY:

REF:

AIGI

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

16/1 File pass to Car
11 Imp 849001

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Veh No:

S/HB 9853R

Yr Regn:

08, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Lander c.c

1995

Colour:

M white / R

A/C:

Insured / Std / NI / NA

Sp. Reading

344741

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-1AB215AUC 273452

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modl:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

14/1/19

D.O.I.

15/1/19

Survey held at

Des. of Damages:

Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Red = 12,572.25 / 7290



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG19000970/Kpb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 16-01-2019		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 6383C	Veh. Inspected	SHB 9853R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	16/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/01/2019	Inspection Date	15/01/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9853R**AAD1901-114***Not Notarised
6/ Sep @ 4900*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9853R

VF1ABL15AUC273452

RENAULT

LATITUDE

11.1.2019

AIG

20/8/2013

PART**LIST**

- | | |
|---|---------------------------|
| 1 | BUMPER COVER FRT |
| 1 | BUMPER SPOILER FRT |
| 1 | BUMPER ABSORBER FRT |
| 1 | BUMPER RETAINER FRT RH |
| 1 | BUMPER SUPPORT FRT |
| 1 | BUMPER UNDERTRAY FRT |
| 1 | BUMPER GRILLE LOWER FRT |
| 1 | BUMPER FOG LAMP GRILLE RH |
| 1 | BUMPER BEAM FRT |
| 1 | HEADLAMP RH |
| 1 | HEADLAMP PANEL FRT RH |
| 1 | FENDER PANEL FRT RH |
| 1 | WHEELARCH FRT RH |
| 1 | FENDER BRACKET LOWER RH |
| 1 | FENDER INSULATOR RH |
| 1 | DOOR PANEL FRT RH |
| 1 | WIPER RESERVOIR |
| 1 | WIPER RESERVOIR NECK |
| 1 | WIPER RESERVOIR MOTOR |

\$	<i>Bu</i> 1,259.42 ✓
\$	<i>Sn</i> 181.75 X
\$	<i>Sn</i> 394.68 X
\$	<i>Di</i> 150.77 ✓
\$	<i>Sn</i> 123.88 X
\$	<i>Sn</i> 472.83 X
\$	<i>Sn</i> 266.80 X
\$	<i>Sn</i> 207.21 X
\$	<i>R</i> 914.08 X
\$	<i>Sn</i> 1,184.43 X
\$	<i>R</i> 152.15 X
\$	<i>B</i> 783.83 ✓
\$	<i>Sn</i> 278.84 X
\$	<i>Sn</i> 15.79 X
\$	<i>Sn</i> 130.84 X
\$	<i>B</i> 2,844.66 ✓
\$	<i>Sn</i> 348.25 X
\$	<i>Sn</i> 136.11 X
\$	<i>Sn</i> 270.06 X
TOTAL \$	10,116.39 <i>10116.38</i>
10% \$	1,011.64
\$	9,104.75 <i>9104.74</i>

Special Nett

- | | |
|------|----------------------------|
| 1SET | BUMPER CLIP FRT |
| 1 | BUMPER BRACKET CLIP FRT RH |
| 1 | BUMPER SUPPORT CLIP FRT RH |
| 1SET | BUMPER GRILLE LOWER CLIP |

\$	<i>Me</i> 66.00 ✓
\$	<i>nn</i> 12.00 X
\$	<i>nn</i> 10.50 X
\$	<i>nn</i> 69.00 X

Trans-cab Auto Services Pte Ltd

AAD1901-114

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9853R

1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00 <i>60sn</i>
1	FRONT RIGHT DOOR STICKER 'CHASSIS'	\$	<i>nn</i> 50.00 <i>15sn</i>
		\$	<u>157.50</u> <i>287.50</i>

TOTAL \$ 9,262.25**TOTAL PARTS****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00 <i>500l</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>880l</i>
To rust-proofing of the affected areas.	\$	170.00 <i>60l</i>
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>20l</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 <i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1901-114

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9853R

To vacuum, replace, refix and recharge Air
Intercooler

\$ *nn* 170.00 X

TOTAL \$ 8,210.00

Over All Total \$ 17,472.25

LUMP SUM (REPAIR DAY)

18602-284
~~10 DAYS~~

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Monday, 18 March 2019 3:40 PM
To: 'NGAIHANLEE@YAHOO.COM.SG'
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: OUR REF: CC3/AIG19000970/Kpb3***INVOLVING SLB 6383C & SHB 9853R ON 11/01/2019****

Our Ref: CC3/AIG19000970/Kpb3

18 March 2019

MAUNG NGAI HAN@DANIEL LEE

Dear Sir/Madam,

ACCIDENT INVOLVING SLB 6383C & SHB 9853R ON 11/01/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 28/03/2019, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Cecilia Chong (LKK Auto)

From: Lee, Ming-Yao <MingYao.Lee@aig.com>
Sent: Wednesday, 27 March 2019 9:33 AM
To: Cecilia Chong (LKK Auto)
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: OUR REF: CC3/AIG19000970/Kpb3*** INVOLVING SLB 6383C & SHB 9853R ON 11/01/2019

Hi Cecilia,

Agreed with your assessment. Please proceed.

Regards,
Lee Ming Yao
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1769
MingYao.Lee@AIG.com | www.aig.sg



Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]
Sent: 27 March 2019 09:29
To: Lee, Ming-Yao <MingYao.Lee@aig.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FW: OUR REF: CC3/AIG19000970/Kpb3*** INVOLVING SLB 6383C & SHB 9853R ON 11/01/2019

Dear Mingyao,

As refer to the email sent to you on 19/03/2019, kindly let us have your comment or instruction asap as OI was asking for the update by us. Thanks

Best Regards,
Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cecilia Chong (LKK Auto)

Sent: Tuesday, 19 March 2019 9:13 AM

To: 'Lee, Ming-Yao' <MingYao.Lee@aig.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: OUR REF: CC3/AIG19000970/Kpb3*** INVOLVING SLB 6383C & SHB 9853R ON 11/01/2019

Your ref: **9398090001SG**

Our Ref: CC3/AIG19000970/Kpb3

Dear Ming Yao,

ACCIDENT INVOLVING SLB 6383C(OI) & SHB 9853R(TP) ON 11/01/2019

We refer to the above matter.

Third party driver reported that he was driving straight along Penang Road. He was on the second lane and suddenly our insured swerved into his lane and hit onto his taxi's right side portion.

Our insured driver reported that he was driving along Penang Road on the middle lane. Suddenly third party on his left cut into his lane.

Our Insured had submitted a copy of video footage to show that he is driving within his own lane and suddenly Third Party cut into his lane resulting a collision. We are of the view that our insured is not liable for the accident.

In view of the above, we are intending to reject Third Party claim.

Kindly let us have your comments/ instruction/ approval.

Thank you.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 27 March 2019 10:31 AM
To: 'claims'
Cc: Admin A; Hsiao Tong (LKKAuto)
Subject: <REJECTION> Your Ref: (SHB9853R) *Our Ref: CC3/AIG19000970/Kpb3 [ACCIDENT INVOLVING SLB 6383C(AIG) & SHB 9853R ON 11/01/2019]
Attachments: SLB 6383C OI VID.avi; INSURED STATEMENT.pdf

Your Ref: (SHB9853R)
Our Ref: CC3/AIG19000970/Kpb3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SLB 6383C(AIG) & SHB 9853R ON 11/01/2019

We refer to the above matter.

Attached is a copy of our insured car video footage and accident statement for your easy reference. We have reviewed the matter and we are of the view that our driver is not liable for the accident. Our driver was driving at his own lane and your client cut into his lane resulting the collision.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jan 2019 Edit Reg		15 Jan 2019 00:00 Edit Adj Rpt	S\$4,900.00 Edit Estimates	S\$4,900.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)**CLAIM SUBFOLDER DETAILS****[Created by adjuster]**

Insured:	MAUNG NGAI HAN @ DANIEL LEE, ID: S8271222D		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHB9853R	Date of Loss:	11/01/2019 21:00 - :59 [64 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9398090001SG	Policy/Cover Note No.:	2100460549 (Comprehensive)
Vehicle Reg. No. (Insured):	SLB6383C	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@alg.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/01/2019]		

ASSOCIATED MAIL RECEIVED[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHB9853R (9398090001SG)**
[SLB6383C]
TP
TRANS-CAB SERVICES PTE LTD
Jan 11 2019 9:00PM
[MAUNG NGAI HAN @ DANIEL LEE]
Trans-cab Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	19/03/19 08:47		Accident Video Footage from Insured												1	Load AVI				
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	19/03/19 08:52		Accident Photo LKK SURVEY PHOTO												1	Load PDF				
2	01/04/19 11:41		Accident Photo												1	Load JPG		<input checked="" type="checkbox"/>		
3	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
4	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
5	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
6	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
7	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
8	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
9	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
10	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
11	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
12	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
13	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
14	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
15	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
16	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
17	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
18	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
19	01/04/19 11:41		General View												1	Load JPG		<input checked="" type="checkbox"/>		
Documentation															1 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	17/01/19 09:28		TP ESTIMATE- MARKED												1	Load PDF				
2	17/01/19 09:28		TP GIA REPORT												1	Load PDF				
3	27/03/19 14:16		REJECT OF TP CLAIM APPROVAL												1	Load PDF				
4	27/03/19 14:16		NOTIFY WS OF REJECTING TP CLAIM												1	Load PDF				
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail		Print		
1	17/01/19 14:10		OI GIA REPORT												1	Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

OI AVF Uploaded

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19000970/KPB3S2
Date: 23/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100460549
Claimant Vehicle No: SHB9853R Insured Vehicle No: SLB6383C
Date of Loss: 11/01/2019 Nature of Claim: TP Claim No: 9398090001SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB9853R
Make & Model: RENAULT LATITUDE, 2.0 L (A) Engine No: M9R8839C000277
Reg. Date: 20/08/2013 (Man. Year: 2013) Chassis No: VF1ABL15AUC273452
Colour: Metallic White/Red Odometer: 344741 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Giti 8 mm Rear Left Side: Giti 8 mm
Front Right Side: Giti 8 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,392.24	4,675.81	4,716.43	50.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,210.00	1,460.00	6,750.00	82.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,602.24	6,135.81	11,466.43	65.14
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	17,602.24	4,900.00	12,702.24	72.16
+ GST 7.00/7.00% (S\$)	1,232.16	343.00	889.16	72.16
Nett Amount (S\$)	18,834.40	5,243.00	13,591.40	72.16

INSPECTION

Date of Assignment: 15/01/2019
Date Inspected: 15/01/2019 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=783290&extid=292741&CFID=53244809&C... 1/4

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT RH	Distorted	150.77 FL	*150.77 FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
8	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
9	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
10	1		*HEADLAMP RH	Serviceable	1,184.43 FL	*- FL
11	1		*HEADLAMP PANEL FRT RH	Repair	152.15 FL	*- FL
12	1		*FENDER PANEL FRT RH	Bent	783.83 FL	*783.83 FL
13	1		*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
14	1		*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	*- FL
15	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
16	1		*DOOR PANEL FRT RH	Bent	2,844.66 FL	*2,844.66 FL
17	1		*WIPER RESERVOIR	Serviceable	348.25 FL	*- FL
18	1		*WIPER RESERVOIR NECK	Serviceable	136.11 FL	*- FL
19	1		*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*- FL
20	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
21	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
22	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
23	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
24	1		*FRONT RIGHT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
25	1		*FRONT RIGHT DOOR STICKER CHASSIS	Necessary	50.00 FS	*15.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	10,403.88	5,179.68
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,011.64	503.87
Total Parts (\$\$)	9,392.24	4,675.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL PF PARTS, ADJUST AND REALIGN THE SAME.	New	3,000.00	500.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	3,000.00	880.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	60.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
5	TO CHECK STEERING AND GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
8	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
9	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	New	380.00	0.00
10	TO REPLACE, REFIX, AND TOP UP COOLANT FOR RADIATOR.	New	170.00	0.00
11	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	New	170.00	0.00
Gross Labour Cost (S\$)			8,210.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >