

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9853R**AAD1901-114***Not Notified
11 Sep @ 4900*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9853R

VF1ABL15AUC273452

RENAULT

LATITUDE

11.1.2019

AIG

20/8/2013

PART**LIST**

1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>Di</i> 150.77 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43 X
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>B</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84 X
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79 X
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84 X
1	DOOR PANEL FRT RH	\$	<i>B</i> 2,844.66 ✓
1	WIPER RESERVOIR	\$	<i>Sn</i> 348.25 X
1	WIPER RESERVOIR NECK	\$	<i>Sn</i> 136.11 X
1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i> 270.06 X
TOTAL		\$	10,116.39
10%		\$	1,011.64
		\$	9,104.75

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>nn</i> 12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>nn</i> 10.50 X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00 X

Trans-cab Auto Services Pte Ltd

AAD1901-114

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9853R

1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00 <i>60sn</i>
1	FRONT RIGHT DOOR STICKER 'CHASSIS'	\$	<i>nn</i> 50.00 <i>15sn</i>

\$	157.50
----	--------

TOTAL	\$	9,262.25
--------------	-----------	-----------------

TOTAL PARTS**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00 <i>5000</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>8800</i>
To rust-proofing of the affected areas.	\$	170.00 <i>600</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 <i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1901-114**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9853R

To vacuum, replace, refix and recharge Air
Intercooler

\$ *nn* 170.00 X**TOTAL \$ 8,210.00****Over All Total \$ 17,472.25****LUMP SUM (REPAIR DAY)**~~10 DAYS~~*4 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: